

ASS. REC. BY:

REF: CS3/CTI19014690/Plcd307

Special Instruction:

Survey: RASUASSIGNMENT (Office)From (Person): Elaine cheong of CTI Date/Time: 2018/19@144pm

Estimated Cost: _____ Bill to: _____

OD ☒ / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: FBG 5240E Insured: GBJ 5030Dat Workshop in/s B's Performance Tel: 6347 5920of 7 soon lee street #01-38Policy No: DMCVSN19199219000 Claim No: SNM19D203082C02

Sign insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 29/06/2019
(Client's Record)

CA / REV / REP. / REV 24 HRS

1up)

H.O.D. Endorsement: _____

Date/Time: 1130am@21/6/19 Person Contacted: Father Vehicle ☒ IN/OUT

Date/Time	Action/Instruction
	<u>Vehicle X</u>
	<u>FBG 5240E - NA / CTI19011634 / 13</u>
	<u>GBJ 5030D - NA / CTI19011634 / 13</u>
	<u>Dismantle: 23/8/2019</u>
	<u>After repair: 11/9/2019</u>

DOR: 29/6/2019DUR: 29/6/2019

ASSIGNED BY: PRG

REF: _____


1175

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: FBG 52406
 at Workshop m/s B'S PERFORMANCE
 of 7, SUMMIT ST #01-38
 Insured: CTI
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: FBG 52406 Yr Regn: 2012 / Aug
 Type: M.Car ☒ M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: SYM GTS 200 C.C. 172
 Colour: BLACK A/C: Insured / Std / NI / NA
 Sp Reading: _____ T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: RFGLM18WXCS001861
 Gen. Cond: Good / ☒ Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / ☒ S/Rim / STD A/Rim or
 Tyre Size: F: 110/90-13
 R: 130/70-12
 BS / DUN / EXNOVA / GY / FS / LIZA / ☒ MIC OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front Rear
 R/Bal. 4 mm R/Bal. 4 mm
 L/Bal. mm L/Bal. mm
 D.O.A. 30/06/19 D.O.I. 28/08/19
 Survey held at B'S PERFORMANCE
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>- 3k-4k / 4 days</u>

Date/Time, File Pass to?

☐ : Preli. ReportDays Of Repair: 14

1) _____

☐ : Final ReportResurvey No. of Trip: 2

Date/Time, File Return to?

2) _____

Add Fee: ☐ : Site Insp (\$)

Survey Fee:

Transportation:

S + PS: \$

Photos

Notes

Total

Report Format: PRG

Lum Sum / E.B.: _____

☐ : Interview (\$)☐ : Tech. Insp (\$)☐ : Wheel work (\$)

150

150

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	27 Sep 2019		27 Sep 2019 16:52 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	
Main Claimant:	CHINNUSAMY SUBRAMANIAN, ID: S73681173
Vehicle Reg. No.:	FBG5240E
Claim Type:	TP / SNM19D203082C02
Vehicle Reg. No. (Insured):	GBJ5030D
Policy/Cover Note No.:	DMCVSN19199219000
Policy No. (Claimant):	MSD/VMS/18-389425-CA
Excess:	S\$0.00
Repairer:	B's Performance Pte Ltd (HQ) 7 SOON LEE STREET, #01-38 ISPACE, 627668 Pioneer - Tel: 6397 5920
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]
Claimant's Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 08/10/2019]

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Nivitha (LKK Auto)

From: Elaine Cheong <elaine.cheong@sg.cntaiping.com>
Sent: Tuesday, 20 August 2019 1:44 PM
To: lavanya@irblaw.com.sg; assignments
Cc: 'IRB LAW LAWYER - MB'; sheila@irblaw.com.sg; Lavanya; 'B Performance'
Subject: RE: OUR REF: SNM19D203082-GBJ5030D-CML - FW: [IRB ref: MB/LK/RA -2019013175] [China ref: Please advise] - ACCIDENT ON 29.06.2019 INVOLVING GBJ 5030D AND FBG 5240E ALONG SIMS WAY

WITHOUT PREJUDICE

Dear Lavanya,

Please request workshop to contact our surveyor to conduct the post repair inspection before returning the vehicle to the claimant.

Aside to LKK,

Please refer to the email below.

Kindly assist to conduct the post repair survey and liaise with the third party workshop accordingly.

Thank you.

Regards,

Elaine Cheong
Executive (Motor Claims)
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower
Singapore 079909
Co. Reg. No. 200208384E
DID: 6389 6530
Fax: 6224 7478 / 6224 7175
Email: elaine.cheong@sg.cntaiping.com
Website: www.sg.cntaiping.com

From: Lavanya [mailto:lavanya@irblaw.com.sg]
Sent: Tuesday, 20 August, 2019 9:59 AM
To: 'B Performance' <bsperformancepteltd@gmail.com>
Cc: 'IRB LAW LAWYER - MB' <baiross@irblaw.com.sg>; sheila@irblaw.com.sg; Elaine Cheong <elaine.cheong@sg.cntaiping.com>
Subject: OUR REF: SNM19D203082-GBJ5030D-CML - FW: [IRB ref: MB/LK/RA -2019013175] [China ref: Please advise] - ACCIDENT ON 29.06.2019 INVOLVING GBJ 5030D AND FBG 5240E ALONG SIMS WAY

Dear Ms. Latha,

We refer to the above matter and to our telephone conversations of yesterday and today. We also refer to our e-mail addressed to Ms. Elaine Cheong from China Taiping Insurance.

During the conversation, you informed us that neither China Taiping Insurance nor any surveyors, on behalf of China Taiping Insurance, contacted you in relation to the PRS. After the expiry of 6 days since our

notification on 13 August 2019, we have informed China Taiping Insurance of our client's intention to proceed with the repairs of his motorcycle.

Pursuant to the E-mail, please proceed with the repairs. However, as informed, please inform us once the repairs are conducted so that we may give reasonable time to China Taiping Insurance to conduct any post-repair inspection, if any.

Please do not hesitate to contact us in case of any queries.

Thank you.

Best regards,

Lavanya
Foreign Lawyer (India)

Sent for and on behalf of Mr. Mohamed Baiross



I.R.B. LAW LLP
T: 6298 2537 (ext 109)
F: 6298 2547
E: lavanya@irblaw.com.sg
W: www.irblaw.com.sg
117A Jalan Sultan Singapore 199007. (Main office)
119 Jalan Sultan, Singapore 199008 (Branch Office)

We are registered in Singapore with limited liability (T12LL0483A)

[This e-mail is confidential and may also be privileged. If you are not the intended recipient, please delete it and notify us immediately. You should not copy or use it for any purpose, nor disclose its contents to any other person. Thank you.]

From: Lavanya <lavanya@irblaw.com.sg>
Sent: Monday, August 19, 2019 6:05 PM
To: 'Elaine Cheong' <elaine.cheong@sg.cntaiping.com>
Cc: 'Claims Dept of CTI' <claimsdept@sg.cntaiping.com>; 'Alfred Toh' <alfred.toh@sg.cntaiping.com>; 'Chee So Chow' <sochow.chee@sg.cntaiping.com>; 'IRB LAW LAWYER - MB' <baiross@irblaw.com.sg>; 'Sheila Tan' <sheila@irblaw.com.sg>; 'B Performance' <bsperformancepteltd@gmail.com>
Subject: RE: OUR REF: SNM19D203082-GBJ5030D-CML - FW: [IRB ref: MB/LK/RA -2019013175] [China ref: Please advise] - ACCIDENT ON 29.06.2019 INVOLVING GBJ 5030D AND FBG 5240E ALONG SIMS WAY

Dear Elaine,

We refer to the above matter.

We note that we have yet to receive any reply from you. Further, you have neither engaged your surveyors to contact our client's workshop.

As such, the workshop will proceed to repair our client's vehicle without further reference to you.

Please contact our client's workshop should you wish to do a post-repair inspection. For your ease of reference, the contact details are as follows:

B'S Performance Pte Ltd
7 Soon Lee Street
#01-38 iSpace
Singapore 627608
Contact person: Latha
Tel : 6397 5920
Email : bsperformancepteltd@gmail.com

Best regards,

Lavanya
Foreign Lawyer (India)

Sent for and on behalf of Mr. Mohamed Baiross



I.R.B. LAW LLP
T: 6298 2537 (ext 109)
F: 6298 2547
E: lavanya@irblaw.com.sg
W: www.irblaw.com.sg
117A Jalan Sultan Singapore 199007. (Main office)
119 Jalan Sultan, Singapore 199008 (Branch Office)

We are registered in Singapore with limited liability (T12LL0483A)

[This e-mail is confidential and may also be privileged. If you are not the intended recipient, please delete it and notify us immediately. You should not copy or use it for any purpose, nor disclose its contents to any other person. Thank you.]

From: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Sent: Tuesday, August 13, 2019 3:55 PM
To: Elaine Cheong <elaine.cheong@sg.cntaiping.com>; Alfred Toh <alfred.toh@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>; lavanya@irblaw.com.sg
Subject: OUR REF: SNM19D203082-GBJ5030D-CML - FW: [IRB ref: MB/LK/RA -2019013175] [China ref: Please advise] - ACCIDENT ON 29.06.2019 INVOLVING GBJ 5030D AND FBG 5240E ALONG SIMS WAY
Importance: High

Dear Elaine,

Please conduct PRS for FBG5240E.

Note : officer in charge – Elaine Cheong 63896530.

Thank you

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 63896116 | F: (65) 62247175

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Lavanya [<mailto:lavanya@irblaw.com.sg>]
Sent: Tuesday, August 13, 2019 11:21 AM
To: Claims Dept of CTI
Cc: baiross@irblaw.com.sg; 'Sheila Tan'; bsperformancepteltd@gmail.com
Subject: [IRB ref: MB/LK/RA -2019013175] [China ref: Please advise] - ACCIDENT ON 29.06.2019 INVOLVING GBJ 5030D AND FBG 5240E ALONG SIMS WAY
Importance: High

Dear Sirs,

We act for **Mr. Chinnusamy Subramanian** ("our client").

We enclose herewith our self-explanatory letter of today for your attention.

Best regards,

Lavanya
Foreign Lawyer (India)

Sent for and on behalf of Mr. Mohamed Baiross



I.R.B. LAW LLP
T: 6298 2537 (ext 109)
F: 6298 2547
E: lavanya@irblaw.com.sg
W: www.irblaw.com.sg
117A Jalan Sultan Singapore 199007. (Main office)
119 Jalan Sultan, Singapore 199008 (Branch Office)

We are registered in Singapore with limited liability (T12LL0483A)

[This e-mail is confidential and may also be privileged. If you are not the intended recipient, please delete it and notify us immediately. You should not copy or use it for any purpose, nor disclose its contents to any other person. Thank you.]

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.

For more information please visit <http://www.symanteccloud.com>

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	117J
Vehicle Details	
Vehicle No.:	FBG5240E
Vehicle to be Exported:	No
Intended Deregistration Date:	22 Aug 2019
Vehicle Make:	SYM
Vehicle Model:	GT5200
Primary Colour:	Black
Manufacturing Year:	2012
Engine No.:	KB609780
Chassis No.:	RFGLM18WXC5001861
Maximum Power Output:	-
Open Market Value:	\$2,247.00
Original Registration Date:	21 Aug 2012
First Registration Date:	21 Aug 2012
Transfer Count:	3
Actual ARF Paid:	\$338.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	20 Aug 2022
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$2,081.00
COE Rebate Amount:	\$623.00
Total Rebate Amount:	\$623.00

The information contained herein is correct as at 22 Aug 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	10/08/2019 11:10
Date Of Accident	30/06/2019 03:20
Exact Location Of Accident	ALONG SIMS WAY
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBG5240E
Insured/Policyholder	
Name Of Registered Owner	CHINNUSAMY SUBRAMANIAN
Passport No/FIN	S7368117J
Email Address	SUBRASUBAR88@GMAIL.COM
Mobile Phone No	(LOCAL) +65-92953942
Alternative Phone No	OFFICE-92953942

Vehicle Particulars

Manufacturer	SYM
Model	GTS 200
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	MSD/VMS/18-389425-CA
Cover Note Number	

Driver

Name of Driver	CHINNUSAMY SUBRAMANIAN
Passport No/FIN	S7368117J
Date Of Birth	25/05/1973
Occupation	OUTDOOR
Date Of Driving Pass	10/04/2010
Driving Experience	9 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92953942
Fax Number	
Contact Number	OFFICE-92953942
Email Address	SUBRASUBAR88@GMAIL.COM

Address	BLK 722 JURONG WEST AVE 5 #06-126
Postcode	640722
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	AIRPORT POLICE DIVISION
Police Station Address	ROAD: 35 AIRPORT BOULEVARD , POSTCODE: 819645 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 65460000 - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBJ5030D
Vehicle Make/Model/Colour	PANEL VAN
Details Of Properties	FRONT PORTION DAMAGED
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	NA
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name	CHINNUSAMY SUBRAMANIAN
Approximate Age	46
Injuries Sustain	REFER REPORT
Injured person in which vehicle?	FBG5240E
Were seat belts worn?	NO
Was this injured conveyed to hospital by ambulance?	YES
Address	BLK 722 JURONG WEST AVE 5 #06-126
Postcode	640722

Sketch Plan

SKETCH PLAN

(A) FB615240E
(B) FB635030D

8

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

LIOSAGE PLATE: FB615240E	ACCIDENT DATE & TIME: 30-16-2019 13:00hrs
CONTACT NUMBER: 9295 3442	E-MAIL ADDRESS: SubraDuterriff@gmail.com
LOCATION: Along Road 1 Bunc Way	
Refer Police Report - 7/20190703/2016	
NOTE: PLEASE NOTE THAT YOUR INSURER MAY HAVE 14 DAYS TIME FRAME FOR YOU TO SUBMIT AN OWN DAMAGE CLAIM UNDER YOUR OWN POLICY. PLEASE CHECK YOUR POLICY FOR MORE INFORMATION.	
Please state:	
<input type="checkbox"/> Claim Own Policy	<input checked="" type="checkbox"/> Claim Third Party
<input type="checkbox"/> Claim ODP at other workshop	<input type="checkbox"/> Reporting Only

DECLARATION

(We declare the foregoing particulars are true in every respect.)

Subra
Policyholder's Signature
Date & Time:

X
Driver's Signature
(If driver is not the policyholder)
Date & Time:

Subra
Reporting Centre Personnel's Signature
Name:
NIC/FIN No.:

Subra
10/8/2019


Accident Sketch Plan

SKETCH PLAN


IMPORTANT NOTICE


1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed** by the **Policyholder** and/or the **Authorized Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any willful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy benefits**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that:
 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this Form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims, collectively the "Purposes";
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
 - (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
 - (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

X


Policyholder's Signature
Date & Time:

X


Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Common Statement



**SINGAPORE
POLICE FORCE**

Police Station Of Origin
Airport Police, Airport Police Post
35 Airport Boulevard SINGAPORE 819645
Tel No: 1800-5450000



T/00190703/2019

1 of 3

Report No: T/00190703/2019

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 03/07/2019 07:31		Vide Report No.:		Station Diary No. 14
Informant's Particulars				
Name of Informant: CHINNUSAMY SUBRAMANIAN		Address: APT BLK 722 JURONG WEST AVENUE 5 #06-126 SINGAPORE 640722		
ID Type / ID No. NRIC NO / S73581117J		Contact No. Home/Office: Mobile: 92953942		
Nationality: INDIAN		Email: subrasubra88@gmail.com		
Sex: Male	Age: 48	Date of Birth: 25/05/1973	Type of Informant: Rider	
Race: Indian		Language:	Institution / School Name:	
Occupation: TOWER CRANE OPERATOR		Driving Licence Information: Class: 2B.1 Date of Expiry:		

General Information of the Accident

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 30/06/2019 03:20	Type of Location: Straight Road
Location: Along Road 1 SIMS WAY				
Incident happen at Ajunied flyover (PTE) towards Tuas near to exit 12				
Weather: Clear	Road Surface: Dry	Road Speed Limit: 90 Km/h		
Traffic Flow: One Way	Traffic Control: Not Controlled	Traffic Volume: No Traffic		
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBG5240E	Motorcycle	SYM	GTS200	Black	Slightly Damaged	0
GBJ5030D	Van				Slightly Damaged	0


Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No.	Effective	Expiry Date
FBG5240E	MSIG INSURANCE (SINGAPORE) PTE LTD	72121930	07/09/2018	06/09/2019

Common Statement



SINGAPORE
POLICE FORCE



T/20190703/2016

Police Station Of Origin:
Airport Police, Airport Police Post
35 Airport Boulevard SINGAPORE 819645
Tel No: 1800-5480000

2 of 3

Report No. T/20190703/2016

CONTINUATION OF REPORT

Brief Details.

On 30/6/19 at about 0320hrs, I was riding my motorbike on the third lane at about 70-80km/hr along the incident location when all of the sudden 01 grey in colour van bearing vehicle 'GBJ5030D' hit my motorbike from the rear causing me to flung off from my motorbike. I sustain fracture on my left ankle, right wrist and left arm. Member of public came to assist me in my injuries. Traffic Police and the ambulance subsequently arrived and I was conveyed to Tan Tock Seng Hospital. I had a surgery on my left closed fracture ankle and was warded 2 days, I was also given 10 days of Medical Certification from 30/6/19 to 9/7/19. I am going back to Coimbatore, India on 3/7/19 for surgery on my wrist and left arm and will be back in about 2-3 months.

Common Statement



SINGAPORE
POLICE FORCE

Police Station Of Origin:
Airport Police, Airport Police Post
35 Airport Boulevard SINGAPORE 819645
Tel No: 1800-5480000



T/20190703/2019

3 of 3

Report No. T/20190703/2019

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

APD /

Sgt 1 KOH WEN HONG

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

03/07/2019 07:31

Officer In Charge Of Case:

TP / GIT /

Sr Staff Sgt MA JUNXIANG

Contact No.: 65478251

Classification Of Case:

Authentication Stamp

MP168



SINGAPORE
POLICE FORCE

SIGNATURE

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	27 Sep 2019		27 Sep 2019 16:52 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	Co. Reg. No.: -								
Main Claimant:	CHINNUSAMY SUBRAMANIAN, ID: S7368117								
Vehicle Reg. No.:	FBG5240E	Date of Loss:	30/06/2019 03:00 - :59 [82 Months and 9 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D203082C02	Policy/Cover Note No.:	DMCVSN19199219000						
Vehicle Reg. No. (Insured):	GBJ5030D	Policy No. (Claimant):	MSD/VMS/18-389425-CA						
		Excess:	S\$0.00						
Repairer:	B's Performance Pte Ltd (HQ) 7 SOON LEE STREET, #01-38 1SPACE, 627668 Pioneer - Tel: 6397 5920								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Claimant's Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 08/10/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*FBG5240E (SNM19D203082C02)
[GBJ5030D]

TP

CHINNUSAMY SUBRAMANIAN

Jun 30 2019 3:00AM

[-]

B's Performance Pte Ltd

Upload Documents

Upload Photos

Compose New Letter

View

View in Browser

Assessment Reports

1 per page

No	Finalized On	STA INSPECTION PTE LTD (Boon Lay)		Thumbnail	Print
1	10/08/19 11:30	Accident Statement		Load HTML	

Photos/Images

3 per page

No	Finalized On	STA INSPECTION PTE LTD (Boon Lay)		Thumbnail	Print
1	10/08/19 11:23	Accident Photo [Linked Accident Report Documents]		Load JPG	
2	10/08/19 11:23	Accident Photo [Linked Accident Report Documents]		Load JPG	
3	10/08/19 11:23	Driving License [Linked Accident Report Documents]		Load JPG	
4	10/08/19 11:23	Accident Photo [Linked Accident Report Documents]		Load JPG	
5	10/08/19 11:23	Accident Photo [Linked Accident Report Documents]		Load JPG	
6	10/08/19 11:23	Accident Photo [Linked Accident Report Documents]		Load JPG	
7	10/08/19 11:23	Accident Photo [Linked Accident Report Documents]		Load JPG	
8	10/08/19 11:23	Accident Photo [Linked Accident Report Documents]		Load JPG	
9	10/08/19 11:23	Accident Photo [Linked Accident Report Documents]		Load JPG	
10	10/08/19 11:23	Accident Photo [Linked Accident Report Documents]		Load JPG	
11	10/08/19 11:23	Accident Photo [Linked Accident Report Documents]		Load JPG	
12	10/08/19 11:23	Accident Photo [Linked Accident Report Documents]		Load JPG	
























































Reorder





















































LKK Auto Consultants Pte Ltd (HQ)


Thumbnail

Print


1	27/09/19 17:40	General View		Load JPG	
2	27/09/19 17:40	General View		Load JPG	
3	27/09/19 17:40	General View		Load JPG	
4	27/09/19 17:40	General View		Load JPG	
5	27/09/19 17:40	General View		Load JPG	
6	27/09/19 17:40	General View		Load JPG	
7	27/09/19 17:40	General View		Load JPG	
8	27/09/19 17:40	General View		Load JPG	
9	27/09/19 17:40	General View		Load JPG	
10	27/09/19 17:40	General View		Load JPG	
11	27/09/19 17:40	General View		Load JPG	
12	27/09/19 17:40	General View		Load JPG	
13	27/09/19 17:40	General View		Load JPG	
14	27/09/19 17:40	General View		Load JPG	
15	27/09/19 17:40	General View		Load JPG	
16	27/09/19 17:40	General View		Load JPG	
17	27/09/19 17:40	General View		Load JPG	
18	27/09/19 17:40	General View		Load JPG	
19	27/09/19 17:40	General View		Load JPG	
20	27/09/19 17:40	General View		Load JPG	
21	27/09/19 17:40	General View		Load JPG	
22	27/09/19 17:40	General View		Load JPG	
23	27/09/19 17:40	General View		Load JPG	













Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Boon Lay)	Thumbnail	Print
				<input checked="" type="checkbox"/>
24	27/09/19 17:40	General View	 Load JPG	<input checked="" type="checkbox"/>
25	27/09/19 17:40	General View	 Load JPG	<input checked="" type="checkbox"/>
26	27/09/19 17:40	General View	 Load JPG	<input checked="" type="checkbox"/>
27	27/09/19 17:40	General View	 Load JPG	<input checked="" type="checkbox"/>
28	27/09/19 17:40	General View	 Load JPG	<input checked="" type="checkbox"/>
29	27/09/19 17:40	General View	 Load JPG	<input checked="" type="checkbox"/>
30	27/09/19 17:40	General View	 Load JPG	<input checked="" type="checkbox"/>
31	27/09/19 17:40	General View	 Load JPG	<input checked="" type="checkbox"/>
32	27/09/19 17:40	General View	 Load JPG	<input checked="" type="checkbox"/>
33	27/09/19 17:40	General View	 Load JPG	<input checked="" type="checkbox"/>
34	27/09/19 17:40	General View	 Load JPG	<input checked="" type="checkbox"/>
35	27/09/19 17:40	General View	 Load JPG	<input checked="" type="checkbox"/>
36	27/09/19 17:40	General View	 Load JPG	<input checked="" type="checkbox"/>
37	27/09/19 17:40	General View	 Load JPG	<input checked="" type="checkbox"/>
38	27/09/19 17:40	General View	 Load JPG	<input checked="" type="checkbox"/>
39	27/09/19 17:40	General View	 Load JPG	<input checked="" type="checkbox"/>
40	27/09/19 17:40	General View	 Load JPG	<input checked="" type="checkbox"/>
41	27/09/19 17:40	General View	 Load JPG	<input checked="" type="checkbox"/>
42	27/09/19 17:40	General View	 Load JPG	<input checked="" type="checkbox"/>
43	27/09/19 17:40	General View	 Load JPG	<input checked="" type="checkbox"/>
44	27/09/19 17:40	General View	 Load JPG	<input checked="" type="checkbox"/>
45	27/09/19 17:40	General View	 Load JPG	<input checked="" type="checkbox"/>
46	27/09/19 17:40	General View	 Load JPG	<input checked="" type="checkbox"/>
47	27/09/19 17:40	General View	 Load JPG	<input checked="" type="checkbox"/>
48	27/09/19 17:40	General View	 Load JPG	<input checked="" type="checkbox"/>
49	27/09/19 17:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	27/09/19 17:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	27/09/19 17:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	27/09/19 17:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	27/09/19 17:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	27/09/19 17:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	27/09/19 17:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	27/09/19 17:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	27/09/19 17:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	27/09/19 17:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	27/09/19 17:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	27/09/19 17:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	27/09/19 17:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	27/09/19 17:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	27/09/19 17:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	27/09/19 17:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	27/09/19 17:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	27/09/19 17:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	27/09/19 17:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	27/09/19 17:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	27/09/19 17:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	27/09/19 17:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	27/09/19 17:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	27/09/19 17:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
73	27/09/19 17:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
74	27/09/19 17:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
75	27/09/19 17:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
76	27/09/19 17:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
77	27/09/19 17:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
78	27/09/19 17:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>






Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Boon Lay)	Thumbnail	Print
79	27/09/19 17:43	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
80	27/09/19 17:43	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
81	27/09/19 17:43	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
82	27/09/19 17:43	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
83	27/09/19 17:43	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
84	27/09/19 17:43	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
85	27/09/19 17:43	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
86	27/09/19 17:43	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
87	27/09/19 17:43	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
88	27/09/19 17:43	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
89	27/09/19 17:43	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
90	27/09/19 17:43	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
91	27/09/19 17:43	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
92	27/09/19 17:43	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
93	27/09/19 17:43	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
94	27/09/19 17:43	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
95	27/09/19 17:43	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
96	27/09/19 17:43	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
97	27/09/19 17:43	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
98	27/09/19 17:43	Photo After Spray		<input checked="" type="checkbox"/>
99	27/09/19 17:43	Photo After Spray		<input checked="" type="checkbox"/>
100	27/09/19 17:43	Photo After Spray		<input checked="" type="checkbox"/>
101	27/09/19 17:43	Photo After Spray		<input checked="" type="checkbox"/>
102	27/09/19 17:43	Photo After Spray		<input checked="" type="checkbox"/>
103	27/09/19 17:43	Photo After Spray		<input checked="" type="checkbox"/>
104	27/09/19 17:43	Photo After Spray		<input checked="" type="checkbox"/>
105	27/09/19 17:43	Photo After Spray		<input checked="" type="checkbox"/>
106	27/09/19 17:43	Photo After Spray		<input checked="" type="checkbox"/>
107	27/09/19 17:43	Photo After Spray		<input checked="" type="checkbox"/>
108	27/09/19 17:43	Photo After Spray		<input checked="" type="checkbox"/>
109	27/09/19 17:43	Photo After Spray		<input checked="" type="checkbox"/>
110	27/09/19 17:43	Photo After Spray		<input checked="" type="checkbox"/>
111	27/09/19 17:43	Photo After Spray		<input checked="" type="checkbox"/>
112	27/09/19 17:43	Photo After Spray		<input checked="" type="checkbox"/>
113	27/09/19 17:43	Photo After Spray		<input checked="" type="checkbox"/>
114	27/09/19 17:43	Photo After Spray		<input checked="" type="checkbox"/>
115	27/09/19 17:43	Photo After Spray		<input checked="" type="checkbox"/>
116	27/09/19 17:43	Photo After Spray		<input checked="" type="checkbox"/>
117	27/09/19 17:43	Photo After Spray		<input checked="" type="checkbox"/>
118	27/09/19 17:43	Photo After Spray		<input checked="" type="checkbox"/>
119	27/09/19 17:43	Photo After Spray		<input checked="" type="checkbox"/>
120	27/09/19 17:43	Photo After Spray		<input checked="" type="checkbox"/>
121	27/09/19 17:43	Photo After Spray		<input checked="" type="checkbox"/>
122	27/09/19 17:43	Photo After Spray		<input checked="" type="checkbox"/>
123	27/09/19 17:43	Photo After Spray		<input checked="" type="checkbox"/>
124	27/09/19 17:43	Photo After Spray		<input checked="" type="checkbox"/>
125	27/09/19 17:43	Photo After Spray		<input checked="" type="checkbox"/>
126	27/09/19 17:43	Photo After Spray		<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Boon Lay)	Thumbnail	Print
1	10/08/19 11:26	Sketch Plan [Linked Accident Report Documents]		<input checked="" type="checkbox"/>
2	10/08/19 11:26	Accident Sketch Plan [Linked Accident Report Documents]		<input checked="" type="checkbox"/>
3	10/08/19 11:27	Common Statement [Linked Accident Report Documents]		<input checked="" type="checkbox"/>
4	10/08/19 11:27	Common Statement [Linked Accident Report Documents]		<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Boon Lay)	Thumbnail	Print
5	10/08/19 11:27	Common Statement <small>[Linked Accident Report Documents]</small>	 Load JPG	<input checked="" type="checkbox"/>

Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Boon Lay)	Thumbnail	Print
1	10/08/19 11:30	Accident Statement	 Load HTM	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Boon Lay)	Thumbnail	Print
1	10/08/19 11:23	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	10/08/19 11:23	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	10/08/19 11:23	Driving License	 Load JPG	<input checked="" type="checkbox"/>
4	10/08/19 11:23	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	10/08/19 11:23	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	10/08/19 11:23	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	10/08/19 11:23	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	10/08/19 11:23	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
9	10/08/19 11:23	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
10	10/08/19 11:23	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
11	10/08/19 11:23	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
12	10/08/19 11:23	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Boon Lay)	Thumbnail	Print
1	10/08/19 11:26	Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
2	10/08/19 11:26	Accident Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
3	10/08/19 11:27	Common Statement	 Load JPG	<input checked="" type="checkbox"/>
4	10/08/19 11:27	Common Statement	 Load JPG	<input checked="" type="checkbox"/>
5	10/08/19 11:27	Common Statement	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CT119014690/R1CD3E2

Date: 16/10/2019

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSN19199219000

Claimant
Vehicle No : FBG5240EInsured
Vehicle No : GBJ5030D

Date of Loss: 30/06/2019

Nature of Claim: TP

Claim
No: SNM19D203082C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: FBG5240E

Make & Model: SYM GTS 200, 172cc

Engine No: KB609780

Reg. Date: 21/08/2012 (Man. Year: 2012)

Chassis No: RFGLM18WXCS001861

Colour: Black

Odometer: 0 km

Engine Capacity: 172 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 110/90-13

Rear Tyre Size: 130/70-12

Front Left Side: Michelin 4 mm

Rear Left Side: Michelin 4 mm

Front Right Side: 0 mm

Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth.

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 27/09/2019

Date Inspected: 21/08/2019 Inspected At:

B's Performance Pte Ltd (HQ)
7 SOON LEE STREET, #01-38
ISPACE
Singapore 627668

Estimated Period of Repair: 4.0 days

Adjuster: MOHD RASUL

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000.00 - \$4,000.00

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 16 Oct 2019)	
Parts:	N/A	SYM GTS 200 172cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBG5240E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >