



TP Claims against NTUC Income: Follow-Through Survey

Date : 28/08/2019

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	Date of Accident	Estimate
1	MT/1058784-002	COMFORT TRANSPORTATION PTE LTD	SHC2223A	SJR92005	21/08/2019	\$ 2,251.93
2	MT/1058925-002	CITYCAB PTE LTD	SHA233U	SKV8847A	21/08/2019	\$ 2,602.64
3	MT/1059829-001	COMFORT TRANSPORTATION PTE LTD	SHD3625L	SJH5186D	22/08/2019	\$ 1,933.85
4	MT/1059135-002	COMFORT TRANSPORTATION PTE LTD	SHA4719J	SJR7693R	22/08/2019	\$ 4,284.75
5	MT/1058712-002	COMFORT TRANSPORTATION PTE LTD	SH7169J	SHC6321Z	20/08/2019	\$ 9,545.63
6	MT/1059834-001	COMFORT TRANSPORTATION PTE LTD	SHC1574T	SLE3769C	23/08/2019	\$ 2,011.18

Claim received from LKK Auto

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	21/08/2019 10:52
Date Of Accident	20/08/2019 16:20
Exact Location Of Accident	NEWTON CIRCUS NEAR TO BUKIT TIMAH RD JUNCTION
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SH7169J
<b>Insured/Policyholder</b>	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

### Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

### Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18088936MFSH
Cover Note Number	

### Driver

Name of Driver	TAY TENG KEE
NRIC No	S1153394I
Date Of Birth	13/11/1955
Occupation	OUTDOOR
Date Of Driving Pass	26/07/1977
Driving Experience	42 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96660662
Fax Number	
Contact Number	
Email Address	PETER_TAY1122@GMAIL.COM

Address	BLK 153 MEI LING STREET #11-22
Postcode	140153
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

#### General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : - GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

PLS REFER TO ATTACHED

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHC6321Z
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	TAN BIN HUAT
NRIC/Passport Number	S1268202F
Contact Number	97958564
Address	
Postcode	
Insurance Company Name	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Nature Of Damage	FRT LEFT

No. Of Passenger (Including Driver)

## Sketch Plan Pg. 1

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE LTD  
CO. REG. NO. 199303621K

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:


Reporting Centre Personnel's Signature  
Name: Loke Wei Yeng  
NRIC/FIN No.: 2118119

GIA/ABC SketchPlanForm\_V3



# Sketch Plan Pg. 2

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 20/8/19 at about 16:20 hrs, I was driving at above said location with a female pax onboard. Shortly veh in front brake to stop and I follow suit. Suddenly I felt an impact from behind. Veh B front left portion collided onto the rear right portion of my taxi. Scene photo taken and exchange particular. No injury at the point of accident.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION (PTE) LTD  
CO. REG. NO. 1993038211

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



Loke Wei Yieng

COMFORT SketchPlanForma\_V3









member of COMFORTDELGRO

Date/Time: 20.08.2019 11:56

Page : 1

Team: ARC Repair TP(CLSO)1

**JOB CARD**

Sales Order:

JC NO.: 305326377

COMER

COMFORT TRANSPORTATION PTE LTD

AS 7010045

COMER NO. 383 SIN MING DRIVE

RESS Singapore SINGAPORE 575717

65508755

(R) (O)

(P)

OUNT CARD NO.

NTUC

REGN NO: SH 7169J

MILEAGE

MAKE: TOYOTA

FUEL

E.....1/2.....F

MODEL PRIUS HYBRID(G4) 20.08.2019 17:15

YR OF MANU 23.08.2017

TARGET DATE

CHASSIS CODE JTDKB3FUX03563389


COMPLETION DATE/TIME:

Accident Date: 20.08.2019

NATURE: 3P 20.08.2019

JOB DESCRIPTION

S/NO LABOR CODE DESCRIPTION



WORKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Delivery Slip

Exit Pass

No.: SH 7169J

LKE

Vehicle No.:

SH 7169J

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

turned to Service Reception upon collection

To be kept by Security Guard

## REPAIR ESTIMATE

VEHICLE No: SH 7169J

21/8/2019 12:59

MAKE :

MODEL : TOYOTA PRIUS

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT
REAR TRUNK LID COVER <i>X sue</i>			\$ 1,126.60
REAR TRUNK LID LOCK <i>X sue</i>			\$ 457.90
REAR TRUNK LID GLASS (BLACK COLOR) <i>X sue</i>			\$ 733.50
GARNISH SUB-ASSY, BACK DOOR, OUTSIDE			\$ 889.70
REAR TRUNK LID LOGO(PRIUS) <i>- nll</i>			\$ 52.90
REAR TRUNK LID LOGO(HYBRID) <i>- nll</i>			\$ 52.90
REAR TRUNK LID LOGO(TOYOTA STAR) <i>- nll</i>			\$ 47.00
REAR BUMPER <i>behind</i>			\$ 458.60
REAR BUMPER UNDER COVER <i>- lra</i>			\$ 552.60
REAR BUMPER SIDE RETAINER <i>X m</i>			\$ 112.70
REAR BUMPER TOWING COVER <i>- ct</i>			\$ 82.70
REAR BUMPER CLIPS <i>+ m</i>			\$ 22.00
RETAINER, REAR BUMPER, SIDE, RH <i>+ sue</i>			\$ 94.80
SEAL, REAR BUMPER SIDE, RH <i>- m</i>			\$ 148.40
TAIL LAMP ASSY (UPPER) (RH) <i>X sue</i>			\$ 557.90
TAIL LAMP ASSY (LOWER) (RH) <i>- sue</i>			\$ 548.40
REAR WINDSCREEN GLASS WITH MOULDING <i>X sue</i>			\$ 1,778.30
REAR TYRE RIM ,RH <i>be - hazard</i>			\$ 1,555.00
Fonde Rear (RH) X repair			
SUB TOTAL			\$ 9,271.90
LESS 25%			\$ 2,317.98
DISCOUNTED TOTAL			\$ 6,953.93
REAR TRUNK LID APPS STICKER <i>- nll</i>			\$ 40.00
REAR TRUNK LID COMFORT & TEL NO. STICKER <i>- m</i>			\$ 60.00
REAR BUMPER REVERSE SENSOR <i>- s lks</i>			\$ 135.70
REAR BUMPER RUBBER MAT <i>- m</i>			\$ 50.00
REAR WINDSCREEN SEALANT <i>X m</i>			\$ 46.00
			\$ 331.70
LABOUR CHARGE			
Panel Beating			\$ 800.00
Spray Painting Charge			\$ 1,200.00
Wiring Charge			\$ 50.00
Tuff Kote			\$ 50.00
Remove/Refix Reverse Sensor			\$ 80.00
Rear Wheel Alignment			\$ 80.00
TOTAL LABOUR			\$ 2,260.00
ESTIMATE TOTAL			\$ 9,545.63

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Kee/Kalvin

L.Ce

NTUC

Auto Insurance hence notify  
 of the following:  
 • To resurvey damaged parts during resurvey  
 • Parts prices are subject to confirmation  
 • Third party survey is on a "Without Prejudice"  
 • No illegal modification(s) is allowed  
 • Supplementary item(s) must be resurveyed and  
 is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

Kalvin (Kee)  
 21/8/19 1330 hrs  
 3 Days.  
 PIP  
 Before Paint photo

NETT 36  
 NETT 54  
 NETT 122.12  
 NETT  
 NETT

400  
 600  
 20  
 X m  
 20  
 X m

9916-58

TYPE OF CASE : TP-SHC6321Z  
SURVEY BY : LKK/Kalwin Ang  
DATE : 21/8/19

[illegible]

COMFORTDELGRO ENGINEERING PTE LTD  
REPAIR ESTIMATE

Date: 27.08.2019  
Time: 18:38:38  
Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010045  
ADDRESS : COMFORT TRANSPORTATION PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65508755

JOB NO : 305326377  
REGN NO : SH 7169J  
MILEAGE : 0000000000  
MAKE : TOYOTA  
MODEL : PRIUS HYBRID(G4)  
DATE OF REGN : 23.08.2017  
DATE/TIME IN : 20.08.2019 17:15  
ACCIDENT DATE : 20.08.2019

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0302-2269-G	PRIG4 ORNAMENT SUB-ASSY B	1	47.00	25.00	35.25
0002 04-01-0302-2271-G	PRIG4 PLATE-BACK DOOR NAM	1	52.90	25.00	39.67
0003 04-01-0302-2270-G	PRIG4 PLATE-BACK DOOR NAM	1	52.90	25.00	39.67
0004 28-01-0302-2013-A	PRIVC REAR BONNET APP TAX	1	40.00	10.00	36.00
0005 28-01-0302-0006-A	PRIVC REAR BOOT 65521111	1	30.00	10.00	27.00
0006 28-01-9999-2025-A	APP LOGO REAR BONNET CTPL	1	30.00	10.00	27.00
0007 04-01-0302-2282-G	PRIG4 COVER REAR BUMPER	1	458.60	25.00	343.95
0008 04-01-0302-2287-G	PRIG4 GUARD-REAR BUMPER C	1	552.60	25.00	414.45
0009 04-01-0302-2286-G	PRIG4 COVER REAR BUMPER-T	1	82.70	25.00	62.02
0010 04-01-0302-2965-G	PRIG4 FILLER-REAR BUMPER	1	148.40	25.00	111.30
0011 04-01-0302-0795-G	PRIG4 LENS AND BODY REAR	1	548.40	25.00	411.30
0012 03-01-0302-2020-G	PRIG4 WHEEL DISC	1	1,555.00	25.00	1,166.25
0013 09-01-0302-2005-A	PRIG4 REVERSE SENSOR ASSY	1	135.70	10.00	122.13

## REPAIR ESTIMATE

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
 CUSTOMER: 7010045  
 ADDRESS : COMFORT TRANSPORTATION PTE LTD  
 383 SIN MING DRIVE  
 SINGAPORE SINGAPORE 575717  
 65508755

JOB NO : 305326377  
 REGN NO : SH 7169J  
 MILEAGE : 0000000000  
 MAKE : TOYOTA  
 MODEL : PRIUS HYBRID  
 DATE OF REGN : 23.08.2017  
 DATE/TIME IN : 20.08.2019 17:1  
 ACCIDENT DATE : 20.08.2019

## JOB / PARTS DESCRIPTION

## QTY IND UNIT-PRICE DISC% AMOUNT

0014 04-01-0302-2346-G PRIG4 GARNISH SUB ASSY BA 1 889.70 25.00 667.27

0015 04-01-0302-2288-G PRIG4 REINFORCEMENT SUB-A 1 318.80 25.00 239.10

0016 03-01-0302-2057-G PRIG4 CAP WHEEL 1 175.80 25.00 131.85

SUB-TOTAL : 3,874.21

## JOB NATURE

0000 L	REAR BUMPER MAT	50.00
0001 L	PANEL BEATING	400.00
0002 23-502	SPRAYPAINT ON AFFECTED AREA	600.00
0003 17-01	CHECK ALL LIGHTING	20.00
0004 20-22	REMOVE/REFIX REVERSE SENSOR	30.00

SUB-TOTAL : 1,100.00

COMFORTDELGRO ENGINEERING PTE LTD

Date: 27.08.2019

REPAIR ESTIMATE

Time: 18:38:38

Page: 3

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010045  
ADDRESS : COMFORT TRANSPORTATION PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65508755

JOB NO : 305326377  
REGN NO : SH 7169J  
MILEAGE : 0000000000  
MAKE : TOYOTA  
MODEL : PRIUS HYBRID  
DATE OF REGN : 23.08.2017  
DATE/TIME IN : 20.08.2019 17:1  
ACCIDENT DATE : 20.08.2019

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

TOTAL : 4,974.21

MVA NAME & SIGNATURE  
DATE :

AUTHORISED : YES / NO  
SURVEYOR NAME & SIGNATURE  
DATE :



Our Job Ref No 305326377

Date : 27.08.19

## COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969  
Fax: 6546 8156

### FINALIZATION FORM

To : LKK

Fax :

Attn : Mr KALVIN ANG

Vehicle Reg No. SH7169J CTPL

20.08.19

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: NTUC SHC6321Z
2. The finalized amount shall be:
  - (a) Spare Parts after List discount \$3,874.23
  - (b) Labour Charges \$1,100.00
  - Total for Part-By-Part Repair Cost \$4,974.23
  - (c) Lumpsum Repair (if applicable)  
Total for Lumpsum repair cost after Less: 20%  
Final Lumpsum Repair cost

3. Estimated normal period for repairs: 3 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Name : LIM KWOK ENG

Tel : 62148316

Fax : 65468156

Signature : 

Name : KALVIN

Date : 28/8/19

### For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
4. LTA Search Fee				
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:



## National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC19014738/K1vf3s2

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE Date: 10-09-2019  
189556



Code: INC4

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 6321Z	Veh. Inspected	SH 7169J
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1058712-002	Excess (\$)	0.00
Assign From		Assign Date	21/08/2019

### 2. Vehicle Particulars & Condition

Make & Model	TOYOTA PRIUS	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JTDKB3FUX03563389	Colour	BLUE
Odometer	222082	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	DAVANTI	7 mm
L/H Front Tyre	195/65 R15	DAVANTI	7 mm
R/H Rear Tyre	195/65 R15	DAVANTI	7 mm
L/H Rear Tyre	195/65 R15	DAVANTI	7 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.
--

### 5. General Information

Accident Date	20/08/2019	Inspection Date	21/08/2019
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

**ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SH 7169J**

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	REAR TRUNK LID COVER	SERVICEABLE	1,126.60	-
1	REAR TRUNK LID LOCK	SERVICEABLE	457.90	-
1	REAR TRUNK LID GLASS (BLACK COLOR)	SERVICEABLE	733.50	-
1	GARNISH SUB-ASSY, BACK DOOR, OUTSIDE	CRACKED	889.70	889.70
1	REAR TRUNK LID LOGO (PRIUS)	NECESSARY	52.90	52.90
1	REAR TRUNK LID LOGO (HYBRID)	NECESSARY	52.90	52.90
1	REAR TRUNK LID LOGO (TOYOTA STAR)	NECESSARY	47.00	47.00
1	REAR BUMPER	DEFORMED	458.60	458.60
1	REAR BUMPER UNDER COVER	CRACKED	552.60	552.60
1	REAR BUMPER SIDE RETAINER	SERVICEABLE	112.70	-
1	REAR BUMPER TOWING COVER	CUT	82.70	82.70
10	REAR BUMPER CLIPS	NOT NECESSARY	22.00	-
1	RETAINER, REAR BUMPER, SIDE, RH	SERVICEABLE	94.80	-
1	SEAL, REAR BUMPER SIDE, RH	CRACKED	148.40	148.40
1	TAIL LAMP ASSY (UPPER) (RH)	SERVICEABLE	557.90	-
1	TAIL LAMP ASSY (LOWER) (RH)	CRACKED	548.40	548.40
1	REAR WINDSCREEN GLASS WITH MOULDING	SERVICEABLE	1,778.30	-
1	REAR TYRE RIM, RH	GRAZED	1,555.00	1,555.00
1	FENDER REAR (RH) (NPA)	TO REPAIR SEE LABOUR	-	-
1	REAR BUMPER REINFORCEMENT	BENT	318.80	318.80
1	REAR WHEEL COVER RH	MISSING	175.80	175.80
	LESS 25% DISCOUNT		-2,441.62	-1,220.70
			7,324.88	3,662.10
<b><u>NETT ITEMS</u></b>				
1	REAR TRUNK LID APPS STICKER (N)	NECESSARY	40.00	40.00
1	REAR TRUNK LID COMFORT & TEL NO. STICKER (N)	NECESSARY	60.00	60.00
1	REAR BUMPER REVERSE SENSOR (N)	SHORTED	135.70	135.70
	LESS 10% DISCOUNT		-	-23.57
			235.70	212.13

Report Ref No. NS/INC19014738/K1vf3s2



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>SPECIAL NETT ITEMS</b>			
1	REAR BUMPER RUBBER MAT (SN)	NECESSARY	50.00	50.00
1	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	46.00	-
			96.00	50.00
	<b>LABOUR</b>			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF FENDER REAR (RH).		800.00	400.00
	SPRAY PAINTING CHARGE.		1,200.00	600.00
	WIRING CHARGE.		50.00	20.00
	TUFF KOTE.	NOT NECESSARY	50.00	-
	REMOVE / REFIX REVERSE SENSOR.		80.00	30.00
	REAR WHEEL ALIGNMENT.	NOT NECESSARY	80.00	-
			2,260.00	1,050.00
	<b>GRAND TOTAL</b>		<b>9,916.58</b>	<b>4,974.23</b>
	<b>RECOMMENDED COST OF REPAIRS (CONFIRMED)</b>			<b>4,974.23</b>

Report Ref No. NS/INC19014738/K1vf3s2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE,  
MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.