

Section A - Accident Details	
Registration Number	SHD6101L
Case Reference Number	TAX/08/19/2066
Registration Date	28/11/2017
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	CHUA KAN MENG(CAI JIANMING)
Type of Accident	Head to Rear
Accident Date and Time	20/8/2019 12:00 PM
Accident Reported Date and Time	20/8/2019 2:42 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24102929
Special Instruction to ARC, if any	REAR PORTION
Prepared Date and Time	20/8/2019 7:04 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$507.00	\$200.00
Total Spray Cost	\$1,098.00	\$300.00
Total Spare Part Cost	\$3,727.94	\$1,455.17
Total Other Cost	\$360.00	\$40.00
TOTAL COST	\$5,692.94	\$1,995.17 (P/P)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	5.0	3.0
Prepared / Adjusted By	Tuck Foo Kok	STEVE CHEN (LKK) / AIG
ARC / Surveyor Sign Off Date	23/08/2019 1:13 PM	23/08/2019 2:14 PM
Signature		
Remarks	Total number of repair days = 3 days. SUP = 0 day.	P/P repair, take before spray. Finalize sent to stevechen@lkkauto.com

Section C - Quotation and Accident Invoice Details			
Quotation Number	QN-1909-0263	Invoice Number	
Quotation Date	17.09.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates		
Part 1 - Labour Works		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	\$507.00	\$200.00
Total Labour	\$507.00	\$200.00

Part 2 - Spray Painting & Panel Beating Related Works		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY FILLER RR BUMPER LH	\$180.00	\$0.00
TO RESPRAY FILLER RR BUMPER RH	\$180.00	\$0.00
TO RESPRAY BUMPER BEAM	\$180.00	\$0.00
TO RESPRAY TAILGATE OUTSIDE GARNISH	\$180.00	\$100.00
Total Spray Painting & Panel Beating	\$1,098.00	\$300.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO WASH AND VACUUM	\$60.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO REPLACE SUNDRY PARTS	\$100.00	\$20.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$0.00
Total Other Costs	\$360.00	\$40.00

Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
			PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace ✓
		52159479 13	COVER, RR BUMPER ASSY	1.00	\$423.90	25.00	\$317.93	Replace	Replace ✓
		52023470 30	REAR BUMPER REINFORCEMENT	0.00	\$318.80	0.00	\$0.00	Replace	Check ✗
		52575470 40	RETAINER, RR BUMPER, RH	1.00	\$112.70	25.00	\$84.53	Replace	Replace ✓
		52576470 40	RETAINER, RR BUMPER, LH	1.00	\$111.50	25.00	\$83.63	Replace	Replace ✓
		52591470 50	SEAL, RR BUMPER, RH	0.00	\$85.20	0.00	\$0.00	Replace	Not Given ✗
		52592470 40	SEAL, RR BUMPER, LH	0.00	\$85.20	0.00	\$0.00	Replace	Not Given ✗
		52161180 10	CLIPS PIECE, FRT & RR BUMPER	10.00	\$1.50	25.00	\$11.25	Replace	Replace ✓
		52453470 10	GUARD, RR BUMPER, LOWER	1.00	\$558.30	25.00	\$418.73	Replace	Replace ✓
		52565479 00	FILLER, RR BUMPER, RH	0.00	\$119.90	0.00	\$0.00	Replace	Not Given ✗
		52566479 00	FILLER, RR BUMPER, LH	0.00	\$119.90	0.00	\$0.00	Replace	Not Given ✗
		81591470 10	LENS & BODY ASSY, RR BUMPER, LH	0.00	\$486.80	0.00	\$0.00	Replace	Not Given ✗
		81561471 51	LENS & BODY, REAR COMBINATION LAMP, LH	0.00	\$438.10	0.00	\$0.00	Replace	Not Given ✗

		76801471 10A1	TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-	1.00	\$891.20	100.00	\$0.00	Replace	Repair	✓
		89997301 00	ANTENNA, ELECTRICAL KEY	0.00	\$60.30	0.00	\$0.00	Replace	Check	X
			SENSOR REVERSE	0.00	\$180.00	0.00	\$0.00	Replace	Check	X
Total					\$4,053.30		\$1,036.07			

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		52023470 30	REAR BUMPER REINFORCEMENT	1.00	\$318.80	25.00	\$239.10	Replace	Replace ✓
			SENSOR REVERSE	1.00	\$180.00	0.00	\$180.00	Replace	Replace ✓
Total					498.80		419.10		

$$\begin{array}{r}
 1455.17 \\
 + 200.00 \\
 + 340.00 \\
 \hline
 1995.17
 \end{array}$$



Case Details

Case Reference Number : TAX08/19/2066
 Type of Repair : Accident Repair
 Vehicle Registration Number : SHD8101L

Company Type : SMRT Taxis Pte Ltd
 Estimation ID : EST-8143-ID
 Assigned By : Taxi Claims Manager Team

Insurance Company Name : AIG Asia Pacific Insurance Pte Ltd
 Accident Date and Time : 20/08/2019 04:00 AM
 Vehicle Age(In Months) : 21

Documents / Photographs

View Documents / Photographs

Total Documents: 0

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation						Surveyor Approval				
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			PIXEL STICKER	2	80.00	120.00	0.00	120.00	Replace	2	0.00	Replace	✓ / N/A
One Time Key In	Main			COVER, RR BUMPER ASSY	1	423.90	423.90	25.00	317.92	Replace	1	317.92	Replace	✓ / 00
One Time Key In	Main			REAR BUMPER REINFORCEMENT	1	318.80	318.80	25.00	239.10	Replace	0	0	Check	✓ X N/A
One Time Key In	Main			RETAINER, RR BUMPER, RH	1	112.70	112.70	25.00	84.53	Replace	1	84.53	Replace	✓ X N/A
One Time Key In	Main			RETAINER, RR BUMPER, LH	1	111.50	111.50	25.00	83.63	Replace	1	83.63	Replace	✓ X N/A
One Time Key In	Main			SEAL, RR BUMPER, RH	1	85.20	85.20	25.00	63.90	Replace	0	0	Not Given	✓ X N/A
One Time Key In	Main			SEAL, RR BUMPER, LH	1	85.20	85.20	25.00	63.90	Replace	0	0	Not Given	✓ X N/A
One Time Key In	Main			CLIP & PIECE, FRT & RR BUMPER	10	1.50	15.00	25.00	11.25	Replace	10	11.25	Replace	✓ / N/A
One Time Key In	Main			GUARD, RR BUMPER, LOWER	1	558.30	558.30	25.00	418.72	Replace	1	418.72	Replace	✓ / N/A

Total Spare Part Cost 3,308.84

Surveyor Total 916.05

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 3,308.84

Final Sur Total 916.05

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			FILLER, RR BUMPER, RH	1	119.90	119.90	25.00	89.93	Replace	0	0	Not Givn	X NAI
One Time Key In	Main			FILLER, RR BUMPER, LH	1	119.90	119.90	25.00	89.93	Replace	0	0	Not Givn	X NAI
One Time Key In	Main			LENS & BODY ASSY, RR BUMPER, LH	1	486.80	486.80	10.00	438.12	Replace	0	0	Not Givn	X NAI
One Time Key In	Main			LENS & BODY, REAR COMBINATION LAMP, LH	1	438.10	438.10	10.00	394.29	Replace	0	0	Not Givn	X NAI
One Time Key In	Main			TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY	1	891.20	891.20	25.00	668.40	Replace	1	0	Repair	X R
One Time Key In	Main			ANTENNA, ELECTRICAL KEY	1	60.30	60.30	25.00	45.22	Replace	0	0	Check	X NAI
One Time Key In	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	0	0	Check	X NAI
Total Spare Part Cost									3,308.84	Surveyor Total 916.05				
Lump Sum Discount (%)									0.00	Lump Sum Dis (%) 0				
Final Spare Part Cost									3,308.84	Final Sur Total 916.05				

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR REAR PORTION	507.00	200	
Total:			507.00	200.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY REAR BUMPER	378.00	200	
2	Main	TO RESPRAY FILLER RR BUMPER LH	180.00	0	
3	Main	TO RESPRAY FILLER RR BUMPER RH	180.00	0	
4	Main	TO RESPRAY BUMPER BEAM	180.00	0	
Total:			1,098.00	200.00	

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
5	Main	TO RESPRAY TAILGATE OUTSIDE GARNISH	160.00	100	
Total:			1,098.00	300.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO WASH AND VACUUM	60.00	0	
2	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20	AK
3	Main	TO REPLACE SUNDRY PARTS	100.00	20	AK
4	Main	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0	
Total:			360.00	40.00	

Summary

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spare Part Detail	3,308.84	916.05
Total Labour Cost	507.00	200.00
Total Spray Painting	1,098.00	300.00
Other	360.00	40.00
Overall Total	5,273.84	1,456.05
Lump Sum Repair Option		
Lump Sum Total	0.00	1,456.05
Surveyor Approved Amount		1,456.05
No of Repair Days*	5	3
Remarks		P/P repair, take before spray. Finalize sent to stevechen@tikkauto.com
Surveyor Name		STEVE CHEN
Signature		

Estimator Assessment(\$)

Surveyor Assessment(\$)

Survey Date

21/08/2019

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

REQUEST FOR SUPPLEMENTARY PARTS

Contractor:			
Accident Case Number	TAX 08/19/2066	Date of Collection	1 / 1
Vehicle No	SALO 6101 L	Date of Request	22/08/2019
Vehicle Model	TOYOTA PRIUS	Number of Days to Extend (if any)	90

S/N	Part Number	Part Description	Quantity	Unit Price
		REAR BUMPER REINFORCEMENT	1 pc	✓ 00
		REVERSE SENSOR	1 set	✓ 180

\$239.10
\$180

<<<Please submit photographs for damaged parts>>>

I, (Name) _____

(Position) _____

do solemnly and sincerely declare that:- Supplementary Parts are raised for replacement for the aforesaid vehicle.

Signature of person making this declaration
(to be signed in front of an authorised witness)

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

For SMRT Staff

Acknowledge By	ARC Executive / Supervisor / SA	
Approval By	Surveyor / In-house Staff	
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC	Form 22 / PO / WOC / Reservation / Number
Photo Submitted	YES / NO	Date of submission