

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705

FAX Number: 63685592

Estimator Telephone Number: 68662623

Accident Reporting Number: 68662672

Date Generated : 20/08/2019
User ID : PehEngHock

		Prepared Date	- 1				
avoice Amount							
uotation Number		Invoice Number					
	Section C - Quotation a	interferent i printerio est austri	ce Details				
Device the second secon							
Remarks							
ilgnature	×		×				
ARC / Surveyor Sign Off Date	20/08/2019 3:05 PM						
Prepared / Adjusted By	ARC Manager Team						
tumber of Repair Days	4.0						
ump Sum Total	\$0,00		\$0.00				
OTAL COST	\$2,077.66		\$0.00				
otal Other Cost	\$60,00		\$0.00				
otal Spare Part Cost	\$417.66		\$0.00				
otal Spray Cost	\$1,000.00		\$0.00				
Total Labour Cost	\$600.00		\$0.00				
Summary of Repair Estimates	Quotation from ARC		Adjusted by Survey	or, if applicable			
	Section B - Summa	ary of Repair Esti	mates				
Repair Completion Date and Time							
Work Shop							
Mileage							
Chassis Number	BE641JK30029						
Prepared Date and Time	SHC2332T - III 8/20/2019 1:43 PM	SHC2332T - III					
Job Card Number Special Instruction to ARC, if any	24102926 PC3469G- R/H SIDE						
Replacement Vehicle issued?	No						
Vehicle is Towed Back? Towed Back Date and Time	No						
Survey by							
s Surveyor Required?	No						
Accident Reported Date and Time		8/2/2019 4:46 PM					
Accident Date and Time		8/1/2019 12:30 PM					
Type of Accident		Side Swipe					
Name of Driver		Khoo Kok Wah					
Model		MITSUBISHI ROSA 4.9L					
Make		MITSUBISHI					
Company Type		Bus-Plus Services Pte Ltd					
Registration Date		6/25/2015					
Case Reference Number		BPS/08/19/3001					
		PC3469G					
Registration Number							



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705

FAX Number: 63685592

Estimator Telephone Number: 68662623

Accident Reporting Number: 68662672

Date Generated : 20/08/2019
User ID : PehEngHock

的基础是对			Secti	on D - Deta	ails of Repair E	stimates		SELVACIONES SELVENTES A PROPERTIES	
Part 1 - Labor	ur Works	/63/52/53/59/69:					A. 182 (4.18 (52) (63)		
Job Scope			Quotation from AR				Adjusted by Surveyor, if applicable		
TO REPAIR ALL AFFECTED AREA			\$600.00					×21.0606750577.0504657.1444.	
Total Labour			\$600,00						
Part 2 - Spray	/ Painting & P	anei Beating Reis	ted Works			62 (146 (1977)) (1977) (1977) (1977)			
Job Scope		Quotation from ARC				Adjusted by Surveyor, if applicable			
TO RESPRAY ALL AFFECTED AREA			\$1,000.00				Beginning proprieting on the Politica (Colored to A	ann an an an Aire ann an Aire an Aire an Aire ann an Aire an Aire ann an Aire an Aire an Aire an Aire an Aire a	
Total Spray Painting & Panel Beating			\$1,000.00						
Part 3 - Other	Costs - Accid	dent and Accident	Repair Related Expens	se j		G-163537-976			
Job Scope			Quotation from ARC				Adjusted by Surveyor, if applicable		
TO CHECK WIRING AND SYSTEM FUNCTION			\$60.00						
Total Other Costs			\$60.00						
Part 4 - Spare	Parts / Mater	ial Usage		D1570-8916921					
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
			BODY SIGNAL LAMP RH	2.00	\$208.83	0.00	\$417.66	Replace	
Total					\$208.83		\$417.66		
Added Spare	Parts / Materi	al Usage After Su	rveyor Signed off						646625
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total	0 - CONTRACTOR (NO. 9)	The Committee of the Co	region processors and a Standard System Control	and supplied of the State	etta Tabellusakon faltakon eta 19.000 a	AND ASSESSED FROM SPECIAL PROPERTY.	1 1/6/2 101/4 9//2007 9/2/6/	000 But 500 to 500 A 560 A 560 A 560 A 500 A	n i i Perantinguni Kantria debili