

ASS. REC. BY:

REF:

CS/MSG1904757/R24f3<sup>92</sup>

Special Instruction:

Reserve  
photo  
attach

Surajoy

Rasu

## ASSIGNMENT (Office)

From (Person): Nor Azlan Binti Noordin of ms16 Date/Time: 22.8.19 14.04p.m

Estimated Cost: Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No: SJB 9327U Insured:

at Workshop m/s Borneo motor Tel: 98476179

of 2 Pandan Crescent

Policy No: 29096439QMY Claim No:

Sum Insured: Excess: \$500.00

Make of Veh: D.O.A. 21.8.19

(Client's Record)

CA / REV / REP. / REV 24 HRS H.O.D. Endorsement:

Date/Time: 22.8.19 2.44p.m Person Contacted: Francis Vehicle: IN/OUT

Date/Time	Action/Instruction ( ✓ ) Estimate
	SJB 9327U: NA/INC11022819/W1 D.O.A: 26/11/2011
23/8/19	send to Mandate Request by Merimen
23/8/19	Merimen approved
26/8/19	send email please proceed to repair to Borneo Motor
6/9/19	Confirm Final \$7170.54 before Excess

ASS:PEC BY:

PABU

REF:

CS/MSG 9014757/R19 f3

7820

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

☒ OD / TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: SJB 93274at Workshop m/s BORNEO MOTORof 2, 1st Pannan CrescentInsured: MSIH

Policy No. \_\_\_\_\_


Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: 500

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.Bal. or Market Value: 80K

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / ☒ REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SJB 93274 Yr Regn: 2017 / NOVType: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: TOYOTA PRIUS HYBRID 1.8 c.c. 1798Colour: BLUE A/C: Insured / Std / NI / NASp. Reading: 26343 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: JTDKB3FU903880748Gen. Cond: Good / ☒ Fair / Poor / BurntSteering: ☒ Inorder / Jammed / Leaked / Burnt orBrake: ☒ Inorder / Jammed / Leaked / Burnt orModi: Nil / ☒ S/Rim / STD A/Rim orTyre Size: F: 195/65R15

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / ☒ YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 21/08/19 D.O.I. 22/08/19Survey held at BORNEO MOTOR

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S FRt

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Confirm Final \$ 7170-54 (Red 4000-16, 36%)

RECEIVED 06 SEP 2019

Date/Time, File Pass to?



: Preli. Report

1)



: Final Report

Date/Time, File Return to?

2)

6/9/19 - Typist

Report Format: \_\_\_\_\_

Lump Sum / LBJ: \_\_\_\_\_

P/P = \$ 7170-54Days Of Repair: 5Resurvey No. of Trip: 1

Add Fee:



: Site Insp (\$)



: Interview (\$)



: Tech. Invs (\$)



: Weekend (%)

Survey Fee:

Transportation:

S + PS \$

Photos

Others

TOTAL

20011

## ...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	22 Aug 2019 11:52		22 Aug 2019 14:04 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <div style="float: right;">[Created by insurer]</div>									
Insured:	LOH KIAN HIN, ID: S7634782D, Tel: +6581684360, Email: NEWHEART76@GMAIL.COM								
Vehicle Reg. No.:	SJB9327U	Date of Loss:	21/08/2019 16:00 - :59 [20 Months and 22 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD	Policy/Cover Note No.:	29096439QMY (Comprehensive) Coverage: 30/11/2018 - 29/11/2019						
		Excess:	S\$500.00						
Repairer:	Borneo Motors (S) Pte Ltd (Pandan) 2 Pandan Crescent, 128462 West Coast - Tel: 66311857								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Nor Azian Binte Noordin - 6594 2558]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 23/08/2019]								
Driver/Custodian:	LOH KIAN HIN (42 / Male) , NRIC: S7634782D, Tel: +6581684360 Email: NEWHEART76@GMAIL.COM								
Adj Asg. Remarks:	Car in, please survey and revert. Please contact us ASAP if you cannot attend this assignment.								
<b>ASSOCIATED MAIL RECEIVED</b> <div style="float: right;"> <a href="#">View All</a> <a href="#">Compose Case Mail</a> </div>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <div style="float: right;"> <a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a> </div>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Note: This document has not been finalised.  
**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Nor Azian Binte Noordin

Date: 23 Aug 2019

**Preliminary Advice**

Vehicle No : SJB9327U  
Make : TOYOTA PRIUS  
Assignment Date : 22/08/2019  
Date of Inspection : 22/08/2019  
Inspection At : BORNEO MOTORS (S) PTE LTD (PANDAN)  
2 PANDAN CRESCENT  
SINGAPORE 128462

Accident Date : 21/08/2019  
Policy No. : 29096439QMY  
Excess : S\$500.00  
Est. Duration of Repair : 5.00

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages n/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	11,170.70
Revised Amount	:S\$	7,170.55
Check Items (Estimated)	:S\$	1,360.17
Total	:S\$	8,530.72
Lump Sum Repair	:S\$	

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	80,000.00
COE / PARF Rebate	:S\$	57,193.00
Salvage Value	:S\$	
Margin for Repair	:S\$	22,807.00

**Remarks**

- ( X ) The vehicle is economical/not economical for repair.
- ( ) The above survey was conducted on a 'without prejudice' basis.

## Yvonne Wong (LKK Auto)

---

**From:** Yvonne Wong (LKK Auto)  
**Sent:** Monday, August 26, 2019 10:31 AM  
**To:** francis.cher@borneomotors.com.sg  
**Cc:** SUR  
**Subject:** VEHICLE NO SJB9327U DOA: 21/08/2019 MSIG

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle SJB9327U (**excess \$500/-**).

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

\*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Yvonne Wong (Ms) | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [yvonnewong@lkkauto.com](mailto:yvonnewong@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	22/08/2019 08:56
Date Of Accident	21/08/2019 16:00
Exact Location Of Accident	MARINE BOULEVARD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJB9327U
<b>Insured/Policyholder</b>	
Name Of Registered Owner	LOH KIAN HIN
NRIC No	S7634782D
Email Address	NEWHEART76@GMAIL.COM
Mobile Phone No	(LOCAL) +65-81684360
Alternative Phone No	OFFICE-81684360

### Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

### Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	29096439QMY
Cover Note Number	

### Driver

Name of Driver	LOH KIAN HIN
NRIC No	S7634782D
Date Of Birth	30/10/1976
Occupation	INDOOR
Date Of Driving Pass	26/03/2011
Driving Experience	8 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81684360
Fax Number	
Contact Number	OFFICE-81684360
Email Address	NEWHEART76@GMAIL.COM

Address	BLK 32 YIO CHU KANG RD #01-08
Postcode	545551
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	NO
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : IRENE LOW GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

PLEASE REFER TO ATTACHED SKETCH PLAN AND STATEMENT.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJJ2957E
Vehicle Make/Model/Colour	HONDA FIT WHITE
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	NG HIN KEONG
NRIC/Passport Number	S1702180Z
Contact Number	90701077
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "**Personal Information**") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "**Insurers**"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "**Purposes**")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time:

21/8/2019  
4.45pm

Driver's Signature

(If driver is not the policyholder)

Date & Time:


Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:



# SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Around 4pm when my car is making a left turn into Bayfront Avenue from Marina Boulevard, my car is banged into by SJS 2957E which is not supposed to be driving straight according to the lane direction / instruction.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

21/8/2019

4.45 PM

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

MS16 29096439 QMY

TYPE OF CLAIM: ☒ DOD ☐ OD/UL ☐ DS

MCA: \_\_\_\_\_

## MOTOR ACCIDENT REPORT

Date Of Report: 21/8/2019 Time: 4.45pm Date Of Accident: 21/8/2019 Time: 4pm

Exact Location Of Accident: Marina Boulevard

Country/State of Loss: Singapore ☒ / Wilayah Persekutuan ☐ / Selangor Darul Ehsan ☐ / Negeri Sembilan ☐ / Melaka ☐ / Pahang ☐ /

## OWN VEHICLE DETAILS (INSURED/POLICY HOLDER)

Vehicle Registration Number: SJB 9327U Co. Reg. No(for Co. Vehicle)/NRIC/PP/FIN No:

Name Of Registered Owner: LOH KIAN HIN

Mobile Number: 81684360 Alternative No: Email Address: newheart76@gmail.com

## Vehicle Particulars

Manufacturer: Toyota ☒ Lexus ☐ Suzuki ☐ Hino ☐ Model: Prius 1.8Exact Purpose for which vehicle was being used at time of accident: Normal Usage ☒ Other ☐ (please specify):Are you claiming under your own insurance policy for repair to your vehicle? Yes ☒ Reporting Only ☐ Third Party ☐Vehicle Category: Private Car ☒ Commercial Vehicle ☐ Others ☐ Claim against 3rd Party Later

## Insurance Company

Name of Insurance Company: msib

Type Of Coverage: Comprehensive ☒ Third Party ☐ Third Party Fire and/or Theft ☐Fleet Policy: Yes ☐ No ☒ Policy / Cover Note No: 29096439 QMY

## DRIVER DETAILS AT POINT OF ACCIDENT

Name of Driver: LOH KIAN HIN NRIC/ Passport / FIN No: S7634782D

Date Of Birth: 30/10/1976 Occupation: Indoor ☒ Outdoor ☐Date Of Driving Pass: 26/03/2011 Gender: Male ☒ Female ☐

Mobile Number: 81684360 Fax No: Alternative No:

Address: Blk 32 Yio Chu Kang Road, #A-08 Postal Code: 545551

Email Address: newheart76@gmail.com

Was driver an employee of the Insured's Company? Yes ☐ No ☒ State relationship of the driver with the insured:

Vehicle Registration Number of Driver's Own Vehicle (if applicable): SJB 9327U

Insurance Company of Driver's Own Vehicle (if applicable):

## GENERAL INFORMATION OF THE ACCIDENT

Type Of Accident: Being hit by another car which is going straight when my car is turning left

Number of Passengers in the above vehicle (Including Driver): 2 If more than 2 Pax Please fill ANNEX B

## PASSENGER 1

Name: Irene Low Gender: Male ☐ Female ☒Weather Conditions: Clear ☒ Raining ☐ Others ☐ (If others, please state condition):Road Surface: Wet ☐ Dry ☒ Others ☐ (If others, please state condition):Was any body injured in the Accident? No ☒ Yes ☐Was any injured conveyed to hospital by ambulance? No ☒ Yes ☐Was any foreign vehicle involved in this accident? No ☒ Yes ☐ Vehicle No: Vehicle type:

Number of vehicles involved in the accident: 1

Was there any witness? No ☒ Yes ☐ If yes, please furnish witness details column below

Witness Name: Contact No.: Email:

Was there any other vehicle or property damaged? No ☐ Yes ☐Was there any video captured by Car Camera? No ☐ Yes ☐ Are accident scene photos available for attachment? No ☐ Yes ☐Was the accident reported to the police? No ☐ Yes ☐ (If yes, please state which Police Station):Was notice of intended Prosecution given? No ☐ Yes ☐ (If yes, please state against whom):I have been approached by unknown person(s) soliciting/offering accident claims assistance. No ☐ Yes ☐

## DETAILS OF OTHER VEHICLE PROPERTY 1 (Please fill Annex A if more vehicles involved)

Vehicle Registration Number: SJJ 2957E Vehicle Make/Model/Colour: White (Honda Fit)

Details Of Properties Damage in Accident:

Vehicle Category:

Name of Driver: Ng Hin Keong

NRIC/Passport/FIN Number: S1702180Z Contact Number: 90701077

Address: Postal Code:

Insurance Company Name:

Nature Of Damage: No. Of Passenger (Including Driver):

**MSIG**

MSIG Insurance (Singapore) Pte. Ltd.  
 4 Shenton Way, # 21-01, SGX Centre 2, Singapore 068807  
 Tel: +65 6827 7888, Fax: +65 6827 7800  
 Co. Reg. No. 200412212G GST Reg. No. 20-0412212G

## Certificate of Insurance

ROAD TRANSPORT ACT 1987 (MALAYSIA)  
 THE MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (FEDERATION OF MALAYSIA)  
 THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP. 189 OF THE REVISED EDITION)  
 (REPUBLIC OF SINGAPORE)  
 THE MOTOR VEHICLES (THIRD-PARTY RISK AND COMPENSATION) RULES, 1996 EDITION (REPUBLIC OF SINGAPORE)  
 OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF.

Form M.X.1  
 Individual Ownership

**MOTOR MAX PLUS**  
**Comprehensive**

Certificate No. B 29096439 QMY

Excess : SGD500  
 Windscreen Excess : SGD100

1. Index Mark and Registration Number of Vehicle  
 SJB9327U

2. Name of Policyholder  
 Loh Kian Hin

3. Effective Date of the Commencement of Insurance for the purposes of the Act  
 30/11/2018

4. Date of Expiry of Insurance  
 29/11/2019

5. Persons or Classes of Persons entitled to drive\*

Loh Kian Hin  
 Any other person provided he is driving on the Policyholder's order or with the Policyholder's permission.

\* Provided that the person driving is permitted in accordance with the licensing or other laws or laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to use\*

Use only for social domestic and pleasure purposes and for the Policyholder's business.  
 The Policy does not cover use for hire or reward racing pace-making reliability trial speed-testing the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

\* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

PLEASE NOTE ALL CLAIMS RELATED REPAIR CAN BE CARRIED OUT AT ANY WORKSHOP OF YOUR CHOICE OR AT ANY MSIG AUTHORISED WORKSHOP LISTED IN THE ATTACHED.

This Certificate is not transferable to a new owner of the vehicle. If for any reason the Policy is terminated during its currency, the Certificate must be returned to the Insurer within 7 days of the termination or if the Certificate has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189).

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia) or any Amendment, Act or Acts passed in substitution thereof.

MSIG Insurance (Singapore) Pte. Ltd.  
 Approved Insurers

  
 for Chief Executive Officer

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type: Singapore NRIC  
Owner ID: 782D

### Vehicle Details

Vehicle No.: SJB9327U  
Vehicle to be Exported: Yes  
Intended Deregistration Date: 23 Aug 2019  
Vehicle Make: TOYOTA  
Vehicle Model: PRIUS HYBRID 1.8 CVT  
Primary Colour: Blue  
Manufacturing Year: 2017  
Engine No.: 2ZR8296942  
Chassis No.: JTDKB3FU903580748  
Maximum Power Output: 90.0 kW (120 bhp)  
Open Market Value: \$37,869.00  
Original Registration Date: 30 Nov 2017  
First Registration Date: 30 Nov 2017  
Transfer Count: 0  
Actual ARF Paid: \$15,017.00

### Intended PARF Rebate Details

PARF Eligibility: Yes  
PARF Eligibility Expiry Date: 29 Nov 2027  
PARF Rebate Amount: \$11,262.00

### Intended COE Rebate Details

COE Expiry Date: 29 Nov 2027  
COE Category: B - Car above 1600cc or 97kW (130bhp)  
COE Period(Years): 10  
QP Paid: \$57,414.00  
COE Rebate Amount: \$45,931.00  
Total Rebate Amount: \$57,193.00

The information contained herein is correct as at 23 Aug 2019

OK

**DOWNTOWN EAST**  
31 AUG - 01 SEP 2019  
10AM TO 8PM

**WIN a 2D1N stay at Amara Sanctuary Resort Sentosa!**  
**AND**  
**MOBIL 1 Engine Oil Giveaway!**

**Post an Advertisement**  
Sell it yourself! Advertise it at just  
**\$58 until it's SOLD!**

Post an Ad

Advertiser Login

Ways of Selling

Ultra Low Mileage Of 4,238 Km Only! New Condition.



Ultra Low Mileage Of 4,238 Km Only! Never Again Sale. Do Not Miss!  
Direct Owner Starla

**Think One Automobile**

**NEW & USED COMMERCIAL VEHICLES**

Browse by Category

5 vehicles

TOYOTA PRIUS

Sort by Date Posted

40 results/page

Advanced Search

Search Selection

TOYOTA PRIUS

Any

Any

2017

Any

Any

Any

Available



Toyota Prius Hybrid 1.8A S

\$84,800

\$10,850 /yr

24-Mar-2017

1,797 cc

25,000 km

Hatchback

Available

Fuel Type: Petrol-Electric

Cheapest, Lowest Depreciation, Low Mileage, Loan Package, Well Maintained By Previous Owner! High Trade In Are Welcome. Tip Top Condition! 100% Accident Free. View To Believe It, Call Now Before Sold!

Posted: 03-Aug-2019 Tags: 2017 Toyota Prius, 2017 toyota prius, Toyota Prius, toyota prius, Toyota, Prius, prius, Used Toyota



Toyota Prius Hybrid 1.8A

\$74,800

\$9,520 /yr

28-Mar-2017

1,798 cc

50,830 km

Hatchback

Available

Fuel Type: Petrol-Electric

Special Offer On 24th & 25th August Only. Come With 2 Years Third Party Warranty, Easy And Flexible In House Loan And Balloon Scheme Available, No Gimmicks! Low Fuel Consumption At 27km Per Litre, Keyless Entry/Start, Reverse Camera, Auto HID Headlights, L...

Posted: 20-Aug-2019 Tags: 2017 Toyota Prius, 2017 toyota prius, Toyota Prius, toyota prius, Toyota, Prius, prius, Used Toyota



Toyota Prius C Hybrid 1.5A

\$69,800

\$8,570 /yr

28-Jun-2017

1,497 cc

Hatchback

Available

Fuel Type: Petrol-Electric

Full Loan Available At \$1k Plus, We Can Help To Convert To Z10 Usage If Needed. In House Loan Or Bank Loan Available! Balloon Scheme Available! Fast, Easy And Flexible Loan Approval! We Are sgCarMart Premium Dealer! Buy With Confidence! Viewing And Test Drive Avail...

Posted: 20-Aug-2019 Tags: 2017 Toyota Prius, 2017 toyota prius, Toyota Prius, toyota prius, Toyota, Prius, prius, Used Toyota



Toyota Prius Alpha Hybrid 1.8A S

\$99,800

\$12,100 /yr

06-Sep-2017

1,797 cc

MPV

Available

Fuel Type: Petrol-Electric

Well Maintained Unit, No Repairs Needed!

Posted: 13-Aug-2019 Tags: 2017 Toyota Prius, 2017 toyota prius, Toyota Prius, toyota prius, Toyota, Prius, prius, Used Toyota



140-degree Wide Angle Camera With Wifi

i-Drive brand new 2-Channel Full HD Digital Recorder to clearly record everything that happens on the road.  
Find out more!



Toyota Prius Hybrid 1.8A S

\$82,000

\$9,550 /yr

18-Dec-2017

1,797 cc

Hatchback

Available

Fuel Type: Petrol-Electric

With Reverse Camera And Sub Woofer, Keyless Entry And Start.

Posted: 15-Aug-2019 Tags: 2017 Toyota Prius, 2017 toyota prius, Toyota Prius, toyota prius, Toyota, Prius, prius, Used Toyota

Save this search criteria, to get email alerts whenever a match is found.

Make

Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

Veh Type

Status

For old advertisements, view Expired ads

Compare

40 results/page



Borneo Motors (Singapore) Pte Ltd

Online Service Booking :  
www.toyota.com.sgToyota Bodycare Centre  
No. 2 Pandan Crescent  
Singapore 128462Tel no.: 6631 1188  
Customer DetailCo Reg No : 196700086Z  
GST Reg No : MR-8500000-9**ESTIMATE**

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota account &amp; more!

Account Detail	Account No	
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept	S1000004 / ICCUA1 Document No 0 Document Date 22/08/2019	Mr Loh Kian Hin (Luo Jianxing) 32 Yio Chu Kang Road #01-08 Singapore 545551 Mobile: 81684360

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
17	AHXEBW	S2	30/11/2017	SJB9327U	0	47941	50D/SJB9327U/21081
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		

JTDKB3FU903580748	22R8296942	60	Francis Cher T S	--/--/----	0.00	--/--/----	0.00
-------------------	------------	----	------------------	------------	------	------------	------

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES POLICY NO.:29096439 ACC DATE:21.08.19 TOW/DRIVE IN: EXCESS: DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORIZED ON:				30 50.00
2	B	BP-LAB2 REPLACE AND REFOCUS HEADLAMP.				180.00
3	B	BP-MECH2 RESET AND REPROGRAMME ECU.				180.00
4	B	BP-MECH2 CONDCUT WHEEL ALIGNMENT.				180.00
5	B	BP-LAB2 REMOVE ALL NECESSARY DAMAGED PARTS TO REPLACE, REPAIR, STRAIGHTEN FRT BUMPER, L/F FENDER, FRT SUPPORT PANEL AND AFFECTED PORTION OF CAR.				1440 2880.00
6	B	BP-RES2 SPRAY PAINT ON DAMAGED AFFECTED PORTION OF CAR.				1180 2360.00
7	1	T52119-47962 COVER, FR BUMPER	1.00	516.00	15.00	438.60
8	2	T52116-47050 SUPPORT, FR BUMPER	1.00	82.30	15.00	69.95
9	3	T53112-47240 GRILLE, RADIATOR,	1.00	170.10	15.00	144.58
10	4	T53802-47100 FENDER SUB-ASSY, FR	1.00	977.80	15.00	831.13
11	5	T53876-47110 LINER, FR FENDER, LH	1.00	202.50	15.00	172.12

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle.	Parts	Less
		Labour	
		Materials	
		Lubrication/Fluid	
		Others	Amount Due

PLEASE TEAR ALONG PERFORATED LINE

4041309

4041309

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED  
VEHICLE TO LEAVE THE COMPANY PREMISES.DATE  
TIME  
22/08/2019  
08:16

VEHICLE NO

SJB9327U

CUSTOMER

SIGNATURE  
FOR BORNEO MOTORS (SINGAPORE) PTE LTD**Borneo Motors**





Borneo Motors (Singapore) Pte Ltd

Online Service Booking :  
www.toyota.com.sgToyota Bodycare Centre  
No. 2 Pandan Crescent  
Singapore 128462  
Tel no.: 6631 1188  
Customer DetailCo Reg No : 196700086Z  
GST Reg No : MR-8500000-9**ESTIMATE**

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ML account &amp; more!

Account Detail	Account No	
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept	S1000004 / ICCUA1	
	Document No	0
	Document Date	22/08/2019
		Mr Loh Kian Hin (Luo Jianxing) 32 Yio Chu Kang Road #01-08 Singapore 545551 Mobile: 81684360

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
17	AHXEBW S2	ZVW50R	30/11/2017	SJB9327U	0	47941	50D/SJB9327U/21081
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		

JTDKB3FU903580748	22R8296942	60	Francis Cher T S	--/--/----	0.00	--/--/----	0.00
-------------------	------------	----	------------------	------------	------	------------	------

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
12	6	T81185-47691 UNIT, HEADLAMP <i>CR</i>	1.00	2637.60	15.00	2241.96
13	7	T81220-47020 LAMP ASSY, FOG, LH <i>? X su</i>	1.00	951.40	15.00	808.69
14	8	T52618-47090 ABSORBER, FR BUMPER, <i>? X su</i>	1.00	132.70	15.00	112.79
15	9	T75374-47150 EMBLEM, SIDE PANEL <i>re</i>	1.00	54.60	15.00	46.41
16	0	T42602-47180 CAP SUB-ASSY, WHEEL <i>su</i>	1.00	212.20	15.00	180.37
17	1	T53101-47081 GRILLE SUB-ASSY, <i>? X su</i>	1.00	346.00	15.00	294.10
<p>Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.</p> <p><i>Resul</i> <i>Hp 900/10068</i> <i>5 days</i> <i>22/08/19 @ 1650</i> <i>EXEERS: 500</i> <i>Revert</i> <i>Resurvey before paint</i></p>						

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour 5,340.70 Materials 5,830.00 Lubrication/Fluid 0.00 Others 0.00 0.00	11,170.70
		GST 7.00%	781.95
		Less	0.00
		Amount Due	11,952.65

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED  
VEHICLE TO LEAVE THE COMPANY PREMISES.DATE 22/08/2019  
TIME 08:16VEHICLE NO  
SJB9327U  
CUSTOMERSIGNATURE  
FOR BORNEO MOTORS (SINGAPORE) PTE LTD**Borneo Motors**

# TOYOTA

Borneo Motors (Singapore) Pte Ltd

Online Service Booking:  
www.toyota.com.sg

Toyota Bodycare Centre  
No. 2 Pandan Crescent  
Singapore 128462  
Tel no.: 6631 1188  
Customer Detail

## ESTIMATE

Id : 196700086Z  
g No : MR-8500000-9

Load "My Toyota SG" app on Playstore or Appstore to access your Toyota account & more!

MSIG Insurance (Singapore) Pte Ltd  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807  
Attn: Motor Claims Dept

Account No  
S1000004/ICCUA1  
Document No  
0  
Document Date  
22/08/2019


Mr Loh Kian Hin (Luo Jianxing)  
32 Yio Chu Kang Road  
#01-08  
Singapore 545551  
Mobile: 81684360

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
17	ANXEBW	S2	2VW50R	30/11/2017	SJB9327U	0	47941 50D/SJB9327U/21081
Chassis No		Engine No		Terms	Service Engineer	Vehicle In	Collected On

JTDBK3FU903580748 22R8296942 60 Francis Cher T S --/--/-- 0.00 --/--/-- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES POLICY NO.:29096439 ACC DATE:21.08.19 TOW/DRIVE IN: EXCESS: DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORIZED ON:				30 50.00
2	B	BP-LAB2 REPLACE AND REFOCUS HEADLAMP.				180.00
3	B	BP-MECH2 RESET AND REPROGRAMME ECU.				180.00
4	B	BP-MECH2 CONDCUT WHEEL ALIGNMENT.				180.00
5	B	BP-LAB2 REMOVE ALL NECESSARY DAMAGED PARTS TO REPLACE, REPAIR, STRAIGHTEN FRT BUMPER, L/F FENDER, FRT SUPPORT PANEL AND AFFECTED PORTION OF CAR.				1440 2880.00
6	B	BP-RES2 SPRAY PAINT ON DAMAGED AFFECTED PORTION OF CAR.				1180 2360.00
7	1	T52119-47962 COVER, FR BUMPER	1.00	516.00	15.00	438.60
8	2	T52116-47050 SUPPORT, FR BUMPER	1.00	82.30	15.00	69.95
9	3	T53112-47240 GRILLE, RADIATOR,	1.00	170.10	15.00	144.58
10	4	T53802-47100 FENDER SUB-ASSY, FR	1.00	977.80	15.00	831.13
11	5	T53876-47110 LINER, FR FENDER, LH	1.00	202.50	15.00	172.12

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts	Less
		Labour	
		Materials	
		Lubrication/Fluid	
		Others	Amount Due

PLEASE TEAR ALONG PERFORATED LINE

4041309

4041309

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED  
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE  
TIME 22/08/2019  
08:16

VEHICLE NO

SJB9327U

CUSTOMER

SIGNATURE  
FOR BORNEO MOTORS (SINGAPORE) PTE LTD

FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Inchcape

Inchcape

Borneo Motors



# TOYOTA

Reg No : 196700086Z  
Reg No : MR-8500000-9

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ML account & more!

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :  
www.toyota.com.sg

Toyota Bodycare Centre  
No. 2 Pandan Crescent  
Singapore 128462  
Tel no.: 6631 1188

## ESTIMATE

Account Detail		Account No	Customer Detail
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept		S1000004 / ICCUA1	
		Document No	
		0	Mr Loh Kian Hin (Luo Jianxing) 32 Yio Chu Kang Road #01-08 Singapore 545551 Mobile: 81684360
		Document Date	
		22/08/2019	


Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
17	AHXEBW	S2	30/11/2017	SJB9327U	0	47941	SOD/SJB9327U/21081
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
JTDKB3FU903580748	2ZR8296942	60	Francis Cher T S	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
12	6	T81185-47691 UNIT, HEADLAMP CR	1.00	2637.60	15.00	2241.96
13	7	T81220-47020 LAMP ASSY, FOG, LH	1.00	951.40	15.00	808.69
14	8	T52618-47090 ABSORBER, FR BUMPER,	1.00	132.70	15.00	112.79
15	9	T75374-47150 EMBLEM, SIDE PANEL	1.00	54.60	15.00	46.41
16	0	T42602-47180 CAP SUB-ASSY, WHEEL	1.00	212.20	15.00	180.37
17	1	T53101-47081 GRILLE SUB-ASSY, ?	1.00	346.00	15.00	294.10

*Handwritten signature and date 22/8/19*

*Handwritten notes:*  
Rasul  
Hp 900/0068  
5 days  
22/08/19 @ 1650  
EXEERS: 500  
Revert  
Resurvey before paint

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts	11,170.70
		Labour	5,340.70
		Materials	5,830.00
		Lubrication/Fluid	0.00
		Others	0.00
			GST 7.00%
			Less
			0.00
			Amount Due
			11,952.65

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED  
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE  
TIME 22/08/2019  
08:16

VEHICLE NO  
SJB9327U

CUSTOMER

SIGNATURE  
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

Inchcape

4041310

4041310



Co Reg No : 196700086Z  
GST Reg No : MR-8500000-9

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ML account & more!

Attn: Rasul  
5 days. Final Bill

# TAX INVOICE

Borneo Motors (Singapore) Pte Lt

Online Service Booking:  
www.toyota.com.sg

Toyota Bodycare Centre  
No. 2 Pandan Crescent  
Singapore 128462


Tel no.: 6631 1188  
Customer Detail

Account Detail	Account No	
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept	S1000004 / ICCUA1 Document No 38041485 Document Date 05/09/2019	Mr Loh Kian Hin (Luo Jianxing) 32 Yio Chu Kang Road #01-08 Singapore 545551 Mobile: 81684360

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
17	AHxebw	S2	30/11/2017	SJB9327U	26343	47941	50D/SJB9327U/21081
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
OTDKB3FU903580748	2ZR8296942	60	Francis Cher T S	28/08/2019 14.47	05/09/2019 10.03		

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES POLICY NO.:29096439 ACC DATE:21.08.19 TOW/DRIVE IN: EXCESS:\$500 DATE-IN: DATE SURVEY:22.08.19 NO OF REPAIR DAYS:5 DAYS BY:RASUL AUTHORISED ON:23.08.19	*			30.00
2	B	BP-LAB2 REPLACE AND REFOCUS HEADLAMP.	*			180.00
3	B	BP-MECH2 RESET AND REPROGRAMME ECU.	18			180.00
4	B	BP-MECH2 CONDCUT WHEEL ALIGNMENT.	18			180.00
5	B	BP-LAB2 REMOVE ALL NECESSARY DAMAGED PARTS TO REPLACE, REPAIR, STRAIGHTEN FRT BUMPER, L/F FENDER, FRT SUPPORT PANEL AND AFFECTED PORTION OF CAR.	*			1440.00
6	B	BP-RES2 SPRAY PAINT ON DAMAGED AFFECTED PORTION OF CAR.	*			1180.00
7	V	EXC Excess element of insurance repair to be paidby the insured party	88			-500.00
8	1	U52119-47962 COVER, FR BUMPER	1.00	516.00	15.00	438.60
9	2	U53876-47110 LINER, FR FENDER, LH	1.00	202.50	15.00	172.12
10	3	T52116-47050 SUPPORT, FR BUMPER	1.00	82.30	15.00	69.95

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 5 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE MAIL YOUR CHEQUE TO 2 PANDAN CRESCENT, LEVEL 10 INCHCAPE CENTRE, SINGAPORE 128462 4039419

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED  
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 05/09/2019  
TIME 10:03

VEHICLE NO

SJB9327U

CUSTOMER

SIGNATURE  
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motor



Co Reg No : 196700086Z  
GST Reg No : MR-8500000-9

## TAX INVOICE

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :  
www.toyota.com.sg

Toyota Bodycare Centre  
No. 2 Pandan Crescent  
Singapore 128462  
Tel no.: 6631-1188

Account Detail	Account No	Customer Detail
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept	S1000004 / ICCU1 Document No 38041485 Document Date 05/09/2019	Mr Loh Kian Hin (Luo Jianxing) 32 Yio Chu Kang Road #01-08 Singapore 545551 Mobile: 81684360

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
17	AHXEBW	S2	30/11/2017	SJB9327U	26343	47941	50D/SJB9327U/21081
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
JTDKB3FU903580748	2ZR8296942	60	Francis Cher T S	28/08/2019 14.47	05/09/2019 10.03		

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
11	4	T53802-47100 FENDER SUB-ASSY, FR	1.00	977.80	15.00	831.13
12	5	T81185-47691 UNIT, HEADLAMP	1.00	2637.60	15.00	2241.96
13	6	T75374-47150 EMBLEM, SIDE PANEL	1.00	54.60	15.00	46.41
14	7	T42602-47180 CAP SUB-ASSY, WHEEL	1.00	212.20	15.00	180.37

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts 3,980.54 Labour 3,190.00 Materials 0.00 Lubrication/Fluid 0.00 Others 0.00	6,670.54 GST 7.00% 466.94 Less 0.00 Amount Due 7,137.48

PLEASE MAIL YOUR CHEQUE TO 2 PANDAN CRESCENT, LEVEL 10 INCHCAPE CENTRE, SINGAPORE 128462

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED  
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 05/09/2019  
TIME 10:03

VEHICLE NO  
SJB9327U

CUSTOMER

SIGNATURE  
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	22 Aug 2019		22 Aug 2019 14:04 <a href="#">Edit Adj Rpt</a>	<b>S\$7,170.54</b> <a href="#">Edit Estimates</a>	<b>S\$7,170.54</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>					
<b>CLAIM SUBFOLDER DETAILS</b>			[Created by insurer]						
Insured: <b>LOH KIAN HIN</b> , ID: S7634782D, Tel: +6581684360, Email: NEWHEART76@GMAIL.COM									
Vehicle Reg. No.: <b>SJB9327U</b>		Date of Loss: 21/08/2019 16:00 - :59 [20 Months and 22 Days From LTA Reg Date (Man Yr)]							
Claim Type: <b>OD / 603588</b>		Policy/Cover Note No.: 29096439QMY (Comprehensive) Coverage: 30/11/2018 - 29/11/2019							
		Excess: S\$500.00							
Repairer: <b>Borneo Motors (S) Pte Ltd (Pandan)</b> 2 Pandan Crescent, 128462 West Coast - Tel: 66311857									
Handling Insurer: <b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Nor Azian Binte Noordin</b> - 6594 2558]									
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MOHD RASUL</b> ] ... [Final Rpt due 21/09/2019]									
Driver/Custodian: <b>LOH KIAN HIN (42 / Male)</b> , NRIC: S7634782D, Tel: +6581684360 Email: NEWHEART76@GMAIL.COM									
Adj Asg. Remarks: Car in, please survey and revert. Please contact us ASAP if you cannot attend this assignment.									
<b>ASSOCIATED MAIL RECEIVED</b>				<a href="#">View All</a> <a href="#">Compose Case Mail</a>					
• MSIG_SG (23/08/2019): Alert - Adj Mandate Approved (S\$7170.55) - SJB9327U - Claim Handler: Nor Azian B...									
<b>ALL ASSOCIATED TASKS</b>			<a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>						
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									





































## Claim Documents







\*SJB9327U (603588)  
OD  
Aug 21 2019 4:00PM  
[LOH KIAN HIN]  
Borneo Motors (S) Pte Ltd

<a href="#">Upload Documents</a> <a href="#">Upload Photos</a> <a href="#">Compose New Letter</a>			<b>View</b> <a href="#">View in Browser</a>	
<b>Video</b>			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Borneo Motors (S) Pte Ltd (Pandan)	Thumbnail	Print
1	22/08/19 09:21	<b>Video - Accident</b> [Linked Accident Report Documents]	Load MP4	
<b>Assessment Reports</b>			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Borneo Motors (S) Pte Ltd (Pandan)	Thumbnail	Print
1	22/08/19 09:03	<b>Accident Statement</b>	Load HTM	
2	22/08/19 09:23	<b>Addendum Sheet</b>	Load JPG	<input checked="" type="checkbox"/>
3	22/08/19 09:23	<b>Accident Statement Addm. #1</b>	Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	23/08/19 13:50	<b>Adjuster Immediate Advice</b>	Load HTM	
<b>Photos/Images</b>			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Borneo Motors (S) Pte Ltd (Pandan)	Thumbnail	Print
1	22/08/19 09:03	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
2	22/08/19 09:03	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
3	22/08/19 09:03	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
4	22/08/19 09:03	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
5	22/08/19 09:03	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
6	22/08/19 09:03	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
7	22/08/19 09:03	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
8	22/08/19 09:03	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
9	22/08/19 09:03	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
10	22/08/19 09:03	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
11	22/08/19 09:03	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
12	22/08/19 09:03	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	06/09/19 10:05	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
2	06/09/19 10:05	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
3	06/09/19 10:05	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
4	06/09/19 10:05	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
5	06/09/19 10:05	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
6	06/09/19 10:05	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
7	06/09/19 10:05	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
8	06/09/19 10:05	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
9	06/09/19 10:05	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
10	06/09/19 10:05	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
11	06/09/19 10:05	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
12	06/09/19 10:05	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
13	06/09/19 10:05	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
14	06/09/19 10:05	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
15	06/09/19 10:05	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>



Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Borneo Motors (S) Pte Ltd (Pandan)	Thumbnail	Print
16	06/09/19 10:05	General View	 Load JPG	<input checked="" type="checkbox"/>
17	06/09/19 10:05	General View	 Load JPG	<input checked="" type="checkbox"/>
18	06/09/19 10:05	General View	 Load JPG	<input checked="" type="checkbox"/>
19	06/09/19 10:05	General View	 Load JPG	<input checked="" type="checkbox"/>
20	06/09/19 10:05	General View	 Load JPG	<input checked="" type="checkbox"/>
21	06/09/19 10:05	General View	 Load JPG	<input checked="" type="checkbox"/>
22	06/09/19 10:05	General View	 Load JPG	<input checked="" type="checkbox"/>
23	06/09/19 10:05	General View	 Load JPG	<input checked="" type="checkbox"/>
24	06/09/19 10:05	General View	 Load JPG	<input checked="" type="checkbox"/>
25	06/09/19 10:05	General View	 Load JPG	<input checked="" type="checkbox"/>
26	06/09/19 10:05	General View	 Load JPG	<input checked="" type="checkbox"/>
27	06/09/19 10:05	General View	 Load JPG	<input checked="" type="checkbox"/>
28	06/09/19 10:05	General View	 Load JPG	<input checked="" type="checkbox"/>
29	06/09/19 10:05	General View	 Load JPG	<input checked="" type="checkbox"/>
30	06/09/19 10:05	General View	 Load JPG	<input checked="" type="checkbox"/>
31	06/09/19 10:05	General View	 Load JPG	<input checked="" type="checkbox"/>
32	06/09/19 10:05	General View	 Load JPG	<input checked="" type="checkbox"/>
33	06/09/19 10:05	General View	 Load JPG	<input checked="" type="checkbox"/>
34	06/09/19 10:05	General View	 Load JPG	<input checked="" type="checkbox"/>
35	06/09/19 10:05	General View	 Load JPG	<input checked="" type="checkbox"/>
36	06/09/19 10:05	General View	 Load JPG	<input checked="" type="checkbox"/>
37	06/09/19 10:05	General View	 Load JPG	<input checked="" type="checkbox"/>
38	06/09/19 10:05	General View	 Load JPG	<input checked="" type="checkbox"/>
39	06/09/19 10:05	General View	 Load JPG	<input checked="" type="checkbox"/>
40	06/09/19 10:05	General View	 Load JPG	<input checked="" type="checkbox"/>
41	06/09/19 10:06	General View	 Load JPG	<input checked="" type="checkbox"/>
42	06/09/19 10:06	General View	 Load JPG	<input checked="" type="checkbox"/>
43	06/09/19 10:06	General View	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	22/08/19 11:38	Request for survey frm Borneo Motors	 Load PDF	
2	22/08/19 11:38	ESTIMATE	 Load PDF	
3	22/08/19 11:42	COE / PARF Value	 Load PDF	
4	22/08/19 11:45	Valid DL	 Load PDF	
5	22/08/19 11:45	Valid Road Tax	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	23/08/19 11:01	ESTIMATE	 Load PDF	

## Linked Accident Report Documents

Video			View	View in Browser
No	Finalized On	Borneo Motors (S) Pte Ltd (Pandan)	Thumbnail	Print
1	22/08/19 09:21	Video - Accident	 Load MP4	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Borneo Motors (S) Pte Ltd (Pandan)	Thumbnail	Print
1	22/08/19 09:03	Accident Statement	 Load HTM	
2	22/08/19 09:23	Addendum Sheet	 Load JPG	<input checked="" type="checkbox"/>
3	22/08/19 09:23	Accident Statement Addm. #1	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Borneo Motors (S) Pte Ltd (Pandan)	Thumbnail	Print
1	22/08/19 09:03	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	22/08/19 09:03	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>

## Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>				
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer				
Note: Remarks are private unless you show it to other parties.				



## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way, #21-01 SGX Centre 2  
Singapore 068807

Our File No: CS/MSG19014757/R1YF3S2

Date: 12/09/2019

## REFERENCE

Insured/Claimant:	LOH KIAN HIN	Policy No:	29096439QMY	Claim No:	603588
Date of Loss:	21/08/2019	Nature of Claim:	OD		

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SJB9327U	Engine No:	2ZR8296942
Make & Model:	TOYOTA PRIUS, 1.8 HYBRID CVT (A)	Chassis No:	JTDKB3FU903580748
Reg. Date:	30/11/2017 (Man. Year: 2017)	Odometer:	26343 km
Colour:	Blue		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	S\$80,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

## CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,390.70	4,010.54	1,380.16	25.60
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,780.00	3,160.00	2,620.00	45.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>11,170.70</b>	<b>7,170.54</b>	<b>4,000.16</b>	<b>35.81</b>
<b>- Excess (S\$)</b>	<b>500.00</b>	<b>500.00</b>	<b>0.00</b>	<b>0.00</b>
<b>(S\$)</b>	<b>10,670.70</b>	<b>6,670.54</b>	<b>4,000.16</b>	<b>37.49</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>746.95</b>	<b>466.94</b>	<b>280.01</b>	<b>37.49</b>
<b>Nett Amount (S\$)</b>	<b>11,417.65</b>	<b>7,137.48</b>	<b>4,280.17</b>	<b>37.49</b>

## INSPECTION

Date of Assignment:	22/08/2019		
Date Inspected:	22/08/2019	Inspected At:	Borneo Motors (S) Pte Ltd (Pandan) 2 Pandan Crescent Singapore 128462
Estimated Period of Repair:	5.0 days		

Adjuster: MOHD RASUL

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

## Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 12 Sep 2019)
<b>Parts:</b>	144	TOYOTA PRIUS 1.8 HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SJB9327U)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER,FR BUMPER	Deformed	438.60 FS	*438.60 FS
2	1		*SUPPORT,FR BUMPER	Necessary	69.95 FS	*69.95 FS
3	1		*GRILLE,RADIATOR	Serviceable	144.58 FS	*- FS
4	1		*FENDER,SUB-ASSY,FR	Bent	831.13 FS	*831.13 FS
5	1		*LINER,FR FENDER,LH	Cut	172.12 FS	*172.12 FS
6	1		*UNIT,HEADLAMP	Cracked	2,241.96 FS	*2,241.96 FS
7	1		*LAMP ASSY,FOG,LH	Serviceable	808.69 FS	*- FS
8	1		*ABSORBER,FR BUMPER	Serviceable	112.79 FS	*- FS
9	1		*EMBLEM,SIDE PANEL	Necessary	46.41 FS	*46.41 FS
10	1		*CAP SUB-ASSY,WHEEL	Scorched	180.37 FS	*180.37 FS
11	1		*GRILLE,SUB-ASSY	Serviceable	294.10 FS	*- FS
12	1		*SUNDRIES	Necessary	50.00 FS	*30.00 FS
F=Franchise part. S=SpcNett.						
<b>Total Parts (S\$)</b>					<b>5,390.70</b>	<b>4,010.54</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	REPLACE AND REFOCUS HEADLAMP	New	180.00	180.00
2	RESET AND REPROGRAMME ECU	New	180.00	180.00
3	CONDUCT WHEEL ALIGNMENT	New	180.00	180.00
4	REMOVE ALL NECESSARY DAMAGED PARTS TO REPLACE,REPAIR,STRAIGHTEN FRT BUMPER,L/F FENDER,FRT SUPPORT PANEL AND AFFECTED PORTION OF CAR	New	2,880.00	1,440.00
5	SPRAY PAINT ON DAMAGED AFFECTED PORTION OF CAR	New	2,360.00	1,180.00
Gross Labour Cost (\$\$)			<b>5,780.00</b>	<b>3,160.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >