

2/03/2019

ASS. REC. BY:

REF: CS/SM019014759 / FvF322

Special Instruction:

Surveyor: Ram

ASSIGNMENT (Office)

From (Person): Gnoh Pau Loong

of SMO

Date/Time: 22.8.19 12.30p.m

Estimated Cost: Bill to:

OD/TP/FWS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: FS 1188P

Insured: YL 9071B

at Workshop m/s Bike Dynamics

Tel: 67496637

of BIK 6 Defu Lane 10 # 01-554

Policy No: D18MTPC VE 002149

Claim No: CMTD 1900197

Sum Insured:

Excess:

Make of Veh:

D.O.A. 4.1.2019

(Client's Record)

rup"

23.8.2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 22.8.19 1.41p.m

Person Contacted: Lo Gan

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

YL 9071B : X

FS 1188P : NA/INC 1610251/4 D.O.A: 2016/12/06

28/8/19

Informed Pau Loong pending workshop est by merimen

13/9/19

@ 157pm Offer IS \$1700k

REF: SMD

ASS. REC. BY:

ASSIGNMENT

From:

Date: 23-8-2019

Veh No:

PS 1188 P

Yr Regn: mar / 2015

Estimated Cost:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No:

PS 1188 P

Make:

Yamaha mt 09

C.C 847

at Workshop m/s

Bike dynamics

Colour:

Blue

A/C: Insured / Std / NI / NA

of

Blk 6 Defu Lan 10 # 01-554

Sp. Reading

meter Spoil

T/Radio: Insured / Std / NI / NA

Insured:

Eng/No:

Policy No.

C/No:

JYARN296000013177

Claims No.

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: Inorder / Jammed / Leaked / Burnt or

(Client's Record)

Brake: Inorder / Jammed / Leaked / Burnt or

Make of Veh:


After 12.00p.m

Modi:

Nil / S/Rim / STD A/Rim or

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Tyre Size:

F: 120/70 R17

R: 180/55 R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Resso

Bal. or Market Value:

Front

Rear

IDAC Accident Rpt:

Consistent?: Yes or No

R/Bal.

A mm

R/Bal.

A mm

GIA / PR Seen:

Consistent?: Yes or No

L/Bal.

- mm

L/Bal.

- mm

Est. Repairs:

days

Res.: Yes or No

D.O.A. 04/01/2019

D.O.I. 23/08/19

Lum Sum:

%

3 Val.: Yes or No

Survey held at

BIKE DYNAMIC

CA / REV / REP. / 24 HRS

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Date:

Person Contacted:

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	LS: \$1850 confirm with edmund on 19/09/2019 (Red 2197, 549)
	Repair days: 4 days
	MV: \$15000
	PV: \$3062
	NV: \$12000

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

2019-typist

Days Of Repair: 4

Resurvey No. of Trip: 1

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech. Invs (\$)

☐

: Weekend (\$)

Survey Fee:

290

Transportation:

S + RS: \$1

Photos

Others

11

TOTAL

261

Report Format:

merimen

Lump Sum / L.B.I. (\$)

1850/2

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	07 Jan 2019		22 Aug 2019 12:30 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	NS TRADING PTE LTD, Co. Reg. No.: 198804586M		
Main Claimant:	LEE SAMUEL, ID: S8718987B		
Vehicle Reg. No.:	FS1188P	Date of Loss:	04/01/2019 11:00 - :59
Claim Type:	TP / CMTD1900197	Policy/Cover Note No.:	D18MTPCVE002149 (TP, Fire & Theft)
Vehicle Reg. No. (Insured):	YL9071B	Policy No. (Claimant):	
		Excess:	
Repairer:	Bike Dynamic Centre (HQ) BLK 6 DEFU LANE 10 #01-554, 539187 Defu Lane - Tel: 67496637		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by GNOH PAU LOONG - 63295217]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 02/09/2019]		
Driver/Custodian (Insured):	LI QING (), NRIC: G2625050T, Tel: +6584058910 Email:		
Adj Asg. Remarks:	WS: EILEEN 67496637 - PLS NOTE VEH WILL BE IN TMR, 23/8		

ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

There are no mail for this case.



ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

View Sent Message

This mail is associated with :

***FS1188P (CMTD1900197)**
[YL9071B]

TP
LEE SAMUEL
Jan 4 2019 11:00AM
[NS TRADING PTE LTD]
Bike Dynamic Centre

[Resend](#)[View Recipients](#)[Print Message](#)[Delete Message](#)[Forward](#)

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 28/08/2019 14:38 PM.
To PauLoong
Subject TP SURVEY FS 1188P

Dear Pau Loong,

Please be informed that we have inspected the vehicle FS 1188P on 23/8/2019.

We are pending estimate from repairer.

Best Regards,
Veron Chen

DOCUMENTS SUMMARY

There are no documents.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	987B

Vehicle Details

Vehicle No.:	FS1188P
Vehicle to be Exported:	No
Intended Deregistration Date:	26 Aug 2019
Vehicle Make:	YAMAHA
Vehicle Model:	MT-09A ABS
Primary Colour:	Blue
Manufacturing Year:	2015
Engine No.:	N701E032821
Chassis No.:	JYARN296000013177
Maximum Power Output:	-
Open Market Value:	\$7,491.00
Original Registration Date:	24 Mar 2015
First Registration Date:	24 Mar 2015
Transfer Count:	1
Actual ARF Paid:	\$1,124.00

Intended PARF Rebate Details

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	23 Mar 2025
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$5,501.00
COE Rebate Amount:	\$3,062.00
Total Rebate Amount:	\$3,062.00

The information contained herein is correct as at 26 Aug 2019

OK



(/)

Bike model

Type

Price From

Price To

Class

Any

Any

Any

Any

Any

MORE SEARCH OPTIONS

Q SEARCH VIEW ALL (/LISTING/USEDBIKES/LISTING/)



Yamaha MT-09

Listing Type	Paid Ad	SELLER INFORMATION
Brand	Yamaha (/listing/usedbike/brand/yamaha/)	
Model	Yamaha MT-09 (/listing/usedbike/model/yamaha-mt-09/)	
Engine Capacity	847cc	
Classification	Class 2 (/listing/usedbike/model/motorcycle-for-sale/class/class-2/)	
Registration Date	06/11/2015	New Southern Motor (/directory/company/new-southern-motor/290) View all used bikes (7) (/listing/usedbikes/listing/?user=62889) Blk 1008 Bukit Merah Lane 3 #01-12 S(159762) Address: (http://maps.google.com/?q=Blk 1008 Bukit Merah Lane 3 #01-12 S(159762)) Phone: 62722433 Name Ben/Boon/Boy +65 62722433
COE Expiry Date	05/11/2025 (6 years 2 months left)	
Mileage	-	
No. of owners	-	
Type of Vehicle	Street Bikes (/listing/usedbike/model/motorcycle-for-sale/street-bikes/)	

REPORT ERROR (/LISTING/LISTING/ERROR/USEDBIKE/10123/)
+ ADD TO SHORTLIST Like 0 Share
SHARE (WHATSAPP://SEND?TEXT=HTTPS://WWW.SGBIKEMART.COM.SG/LISTING/USEDBIKE/)

Price: SGD\$15800

THE SCHEDULE

Motorcycle Insurance Policy

This Policy sets out the terms of a contract between NTUC Income Insurance Co-operative Limited (INCOME) and you (the Insured named in the schedule to this Policy).

The statements, information and declaration provided by you at the time of proposal shall form the basis of this contract. We (INCOME) will provide the insurance set out in this Policy in respect of events occurring during the Period of Insurance shown in the Schedule and any further period for which we may accept a renewal premium.

The provision of this insurance is subject to:

1. any Endorsement specified as operative in the Schedule
2. the Conditions and General Exclusions of this Policy, and
3. the payment of the premium specified in the Schedule.

This Policy, the Schedule and the Certificate of Insurance are to be read together as one document.

GST Reg No. M4-0003030-8

Policy Number	: 5070752363-04	
The Policyholder	: LEE SAMUEL BLK 102 #07-136 JURONG EAST STREET 13 SINGAPORE 600102	
Period of Insurance	: 24 Mar 2019 To 23 Mar 2020	
Sum Insured	: Market Value of Insured Vehicle at Time of Loss	
Premium (inclusive GST)	: S\$471.15	
Interest Insured		
Cover Type	: Third Party, Fire & Theft	
Named Driver (1)	: LEE SAMUEL	
Named Driver (2)	: N/A	
Make/Model	: YAMAHA/MT-01	
Capacity	: 850cc	Number of Seater : 2
Registration Number	: FS1188P	Registration Year : 2015
Chassis Number	: JYARN296000013177	Insure with COE : YES
Excess (Section 1)	: N/A	NCD Entitlement : 15%
Excess (Section 2)	: N/A	Loyalty Discount : 5%
Hire Purchase Company	: BIKE DYNAMIC CENTRE	

Memo A : N/A


Endorsement Operative: M2

Agency	: WTT INSURANCE AGENCIES PTE LTD (00000614933)
Date of Issue	: 01 Mar 2019 15:07 hrs
Reprint	: 01 Mar 2019 15:08 hrs

DUTY OF DISCLOSURE

We would remind you that you must disclose to us, fully and faithfully, the facts you know or ought to know, otherwise you may not receive any benefit from your Policy.

Signed in Singapore by order of the Board of Directors



Chief Executive

REPUBLIC OF SINGAPORE DRIVING LICENCE



Licence Number: **S8718987B**

Name: **LEE YAN SONG (LI YANSONG)**

Birth Date: **03 Jul 1987**

Issue Date: **28 Dec 2005**

001390299E

REPUBLIC OF SINGAPORE

IDENTITY CARD NO. **S8718987B**

Name: **LEE SAMUEL**

李室玟

Race: **CHINESE**

Date of birth: **03-07-1987**

Country/Place of birth: **SINGAPORE**

Sex: **M**

S8718987B






YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES

Class	Description	Valid Until
Class 1B	MOTORCYCLES NOT EXCEEDING 200 CC	28 Dec 2005
Class 1A	MOTORCYCLES BETWEEN 201 CC AND 400 CC	28 Apr 2009
Class 2	MOTORCYCLES EXCEEDING 400 CC	19 Mar 2015
Class 3	MOTOR CARS AND MOTOR TRACTORS THE WEIGHT OF WHICH UNLADEN DOES NOT EXCEED 2500 KILOGRAMS	14 Sep 2015

S / No. 9000228203

NP 428A

Licence No: S8718987B



5584156

NRIC No. **S8718987B**

Date of issue: **18-03-2016**

APT BLK 293C BUKIT BATOK STREET 21 #36-528
SINGAPORE 653293

NRIC No: **S8718987B** Date: **30/01/2019**




SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	05/01/2019 12:52
Date Of Accident	04/01/2019 11:45
Exact Location Of Accident	INSIDE 11 TUAS AVE 2
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FS1188P
Insured/Policyholder	
Name Of Registered Owner	LEE SAMUEL
NRIC No	S8718987B
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-88000891
Alternative Phone No	OFFICE-88000891

Vehicle Particulars

Manufacturer	YAMAHA
Model	MT-09-847CC

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category MOTORCYCLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	5070752363-03
Cover Note Number	

Driver

Name of Driver	LEE SAMUEL
NRIC No	S8718987B
Date Of Birth	03/07/1987
Occupation	OUTDOOR
Date Of Driving Pass	23/12/2005
Driving Experience	13 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-88000891
Fax Number	
Contact Number	OFFICE-88000891
Email Address	NOEMAIL

Address	102 JURONG EAST STREET 13 #07-136
Postcode	S600102
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE SEE ATTACHED SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	CCTV FROM PREMISES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YL9071B
Vehicle Make/Model/Colour	LORRY
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow Insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) Investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

IDAC BUKIT BATOK (VAC)
511 Bukit Batok Street 23
Singapore 659545
Tel: 6560 3312 Fax: 6569 0722
Email: vacbb@singnet.com.sg

- 5 JAN 2019

Policyholder's Signature

Date & Time: 5/1/19 BOSARS


Driver's Signature

(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature

Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 04/01/19 at about 1144 hrs my bike registration number FS1188P was park inside 111 was ave 2 then this Lorry YL9011B reverse and hit my bike at the lot. the accident footage was captured by the building's cctv.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

-5 JAN 2019

IDAC BUKIT BATOK (VAC)
511 Bukit Batok Street 23
Singapore 659545
Tel: 6560 3312 Fax: 6569 0777
Email: vac@idac.singnet

Policyholder's Signature

Date & Time: 5/1/19 1205 hrs

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

6283361

QUOTATION FOR REPAIR : FS1188P

<u>Qty</u>	<u>Description</u>	<u>Repairer's Estimate</u>
1 pc	RNG ENGINE COVER	220.00 cut ✓
1 pc	EXHAUST PROTECTOR	200.00 xnn ✓
1 pc	SIGNAL RIGHT FRONT	120.00 Br ✓ \$75
1 pc	FRONT RIGHT MIRROR	105.00 scr ✓ \$40
1 pc	METER	850.00 SC ✓
2 pc	BALANCER	125.00 cut ✓ \$25
1 pc	FRAME SLIDER	150.00 scr ✓ \$120
1 pc	FRONT AXLE SLIDER	185.00 scr ✓ \$125
1 pc	FRONT RIGHT FOOTREST	98.00 cut ✓ \$78
		<hr/> 2,053.00
		\$1533
		10% : \$153.3
		<hr/> 2,053.00
		List Item: \$1379.70
		<hr/>
	<u>Nett items</u>	
1 pc	Fork Oil Shield	48.00 xnn
1 pc	Fork Dust Cover	48.00 xnn
2 pc	number plate	28.00 \$10 (Front only) nec
1 pc	Kappa 58L box	580.00 00 ✓
2 Bottle	Fork Oil	40.00 xnn
	Total parts	<hr/> 2,797.00
		Nation: \$590
		<hr/>
	Steering Cone	55.00 nec ✓
	towing to alignment body frame (2 way)	90.00 xnn
	Alignment Body Frame	380.00 xnn
	Towing fees	45.00 xnn
	Front rim realign	80.00 ✓
	Workmanship	600.00 \$300
	Total parts and labour charges	<hr/> 4,047.00
		8 days
		Labour: \$385

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Ram (LKK)

88622778

Ram@LKKAuto.com

Total: \$2354.70

20%: \$470.94

L/S: \$1850.00 *

Signature
11/9/19

(L/S)

repairing: 4 days

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	07 Jan 2019		22 Aug 2019 12:30 Edit Adj Rpt	\$1,850.00 Edit Estimates	\$1,850.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	NS TRADING PTE LTD, Co. Reg. No.: 198804586M								
Main Claimant:	LEE SAMUEL, ID: S8718987B								
Vehicle Reg. No.:	FS1188P	Date of Loss: 04/01/2019 11:00 - :59 [45 Months and 11 Days From LTA Reg Date (Man Yr)]							
Claim Type:	TP / CMTD1900197	Policy/Cover Note No.: D18MTPCVE002149 (TP, Fire & Theft)							
Vehicle Reg. No. (Insured):	YL9071B	Policy No. (Claimant):							
		Excess:							
Repairer:	Bike Dynamic Centre (HQ) BLK 6 DEFU LANE 10 #01-554, 539187 Defu Lane - Tel: 67496637								
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by GNOH PAU LOONG - 63295217]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by PARASURAM SHANMUGAM] ... [Final Rpt due 02/09/2019]								
Driver/Custodian (Insured):	LI QING (), NRIC: G2625050T, Tel: +6584058910 Email:								
Adj Asg. Remarks:	WS: EILEEN 67496637 - PLS NOTE VEH WILL BE IN TMR, 23/8								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents






























***FS1188P (CMTD1900197)
[YL9071B]**

TP

LEE SAMUEL

**Jan 4 2019 11:00AM
[NS TRADING PTE LTD]
Bike Dynamic Centre**

Upload Documents Upload Photos Compose New Letter		View View in Browser <input type="button" value="v"/>
Assessment Reports		1 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)
1	22/08/19 12:29	Accident Statement From: SC - Reg. No: YL9071B, Claimant: NS TRADING PTE LTD
		Thumbnail <input checked="" type="checkbox"/> <input type="button" value="Load HTM"/>
Photos/Images		3 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)
1	29/08/19 17:52	General View
2	29/08/19 17:52	General View
3	29/08/19 17:52	General View
4	29/08/19 17:52	General View
5	29/08/19 17:52	General View
6	29/08/19 17:52	General View
7	29/08/19 17:52	General View
8	29/08/19 17:52	General View
9	29/08/19 17:52	General View
10	29/08/19 17:52	General View
11	29/08/19 17:52	General View
12	29/08/19 17:52	General View
13	29/08/19 17:52	General View
14	29/08/19 17:52	General View
15	29/08/19 17:52	General View
16	29/08/19 17:52	General View
17	29/08/19 17:52	General View
18	29/08/19 17:52	General View
19	29/08/19 17:52	General View
20	29/08/19 17:52	General View
21	29/08/19 17:52	General View
22	29/08/19 17:52	General View
23	29/08/19 17:52	General View
24	29/08/19 17:52	General View
25	29/08/19 17:52	General View
26	29/08/19 17:52	General View
27	29/08/19 17:52	General View
28	29/08/19 17:52	General View
29	29/08/19 17:52	General View
30	29/08/19 17:52	General View
31	29/08/19 17:52	General View
32	29/08/19 17:52	General View
33	29/08/19 17:52	General View
34	29/08/19 17:52	General View
35	29/08/19 17:52	General View
36	29/08/19 17:52	General View
37	29/08/19 17:52	General View
38	29/08/19 17:52	General View
39	29/08/19 17:52	General View

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
40	29/08/19 17:52	General View	 Load JPG	<input checked="" type="checkbox"/>
41	20/09/19 11:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
42	20/09/19 11:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
43	20/09/19 11:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	20/09/19 11:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	20/09/19 11:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	20/09/19 11:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	20/09/19 11:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	20/09/19 11:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	20/09/19 11:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	20/09/19 11:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	20/09/19 11:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	20/09/19 11:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	20/09/19 11:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	20/09/19 11:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	20/09/19 11:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	20/09/19 11:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	20/09/19 11:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	20/09/19 11:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	20/09/19 11:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	20/09/19 11:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	20/09/19 11:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	20/09/19 11:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	20/09/19 11:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	20/09/19 11:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	20/09/19 11:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	21/08/19 16:25	FAX PRI W ENCLS DTD 21.08.19 FR CATHERINE LIM LLC - FS1188P	 Load PDF	
2	22/08/19 12:30	Pre-Repair Survey - AGREED LKK	 Load PDF	
3	02/10/19 20:47	PD LOD W ENCLS DT 30.09.19 FR CATHERINE LIM LLC - FS1188P PD LOD W ENCLS DT 30.09.19 FR CATHERINE LIM LLC - FS1188P	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO19014759/FVF3E2

Date: 07/10/2019

REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D18MTPCVE002149
Claimant Vehicle No :	FS1188P	Insured Vehicle No :	YL9071B
Date of Loss:	04/01/2019	Nature of Claim:	TP
		Claim No:	CMTD1900197

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FS1188P		
Make & Model:	YAMAHA MT-09, 847cc	Engine No:	N701E032821
Reg. Date:	24/03/2015 (Man. Year: 2015)	Chassis No:	JYARN296000013177
Colour:	Blue	Odometer:	0 km
Engine Capacity:	847 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	120/70R17	Rear Tyre Size:	180/55R17
Front Left Side:	Pirelli 4 mm	Rear Left Side:	ROSSO 4 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,852.00	2,024.70	827.30	29.01
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,195.00	380.00	815.00	68.20
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,047.00	2,404.70	1,642.30	40.58
Approved Total (Overridden) (S\$)		1,850.00		
(S\$)	4,047.00	1,850.00	2,197.00	54.29
+ GST 7.00/7.00% (S\$)	283.29	129.50	153.79	54.29
Nett Amount (S\$)	4,330.29	1,979.50	2,350.79	54.29

INSPECTION

Date of Assignment: 22/08/2019

Date Inspected: 23/08/2019 Inspected At:

Bike Dynamic Centre (HQ)
BLK 6 DEFU LANE 10 #01-554
Singapore 539187

Estimated Period of Repair: 4.0 days

Adjuster: PARASURAM SHANMUGAM

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 07 Oct 2019)	
Parts:	N/A	YAMAHA MT-09 847cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FS1188P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RNG ENGINE COVER	Cut	220.00 F	*220.00 FL
2	1		*EXHAUST PROTECTOR	Not Necessary	200.00 F	*- FL
3	1		*SIGNAL RIGHT FRONT	Broken	120.00 F	*75.00 FL
4	1		*FRONT RIGHT MIRROR	Scratched	105.00 F	*40.00 FL
5	1		*METER	Short Circuit	850.00 F	*850.00 FL
6	2		*BALANCER	Cut	125.00 F	*25.00 FL
7	1		*FRAME SLIDER	Scratched	150.00 F	*120.00 FL
8	1		*FRONT AXLE SLIDER	Scratched	185.00 F	*125.00 FL
9	1		*FRONT RIGHT FOOTREST	Cut	98.00 F	*78.00 FL
10	1		*FORK OIL SHIELD	Not Necessary	48.00 FS	*- FS
11	1		*FORK DUST COVER	Not Necessary	48.00 FS	*- FS
12	1		*NUMBER PLATE (2 Pcs)	Front Necessary	28.00 FS	*10.00 FS
13	1		*KAPPA 58L BOX	Dented	580.00 FS	*580.00 FS
14	2		*BOTTLE FORK OIL	Not Necessary	40.00 FS	*- FS
15	1		*STEERING CONE	Necessary	55.00 FS	*55.00 FS
					Sub Total (\$\$)	2,852.00 2,178.00
					- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00 153.30
					Total Parts (\$\$)	2,852.00 2,024.70

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	ALIGNMENT BODY FRAME	New	380.00	0.00
2	TOWING FEES	New	45.00	0.00
3	FRONT RIM REALIGN	New	80.00	80.00
4	WORKMANSHIP	New	600.00	300.00
5	TOWING TO ALIGNMENT BODY FRAME (2 WAY)	New	90.00	0.00
Gross Labour Cost (S\$)			1,195.00	380.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >