



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:STACEY			Ref: CC4/ASM19014767/Kba3q2 Date: 17/05/2021 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHF 710H	Veh. Inspected	SGA 239R
	Policy No.	VFX/P1680520	Coverage (\$)	0.00
	Claim No.	S9M01XTQ	Excess (\$)	0.00
	Assign From		Assign Date	22/08/2019
2. Vehicle Particulars & Condition				
	Make & Model	VOLKSWAGEN PASSAT (A)	c.c	1798
	Engine No.	HIDDEN	Year of Reg.	2012
	Chassis No.	WVWZZZ3CZCE544843	Colour	METALLIC GREY
	Odometer	131255 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	235/45Z R17	FALKEN	6 mm
	L/H Front Tyre	235/45Z R17	FALKEN	6 mm
	R/H Rear Tyre	235/45Z R17	FALKEN	5 mm
	L/H Rear Tyre	235/45Z R17	FALKEN	5 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR & FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	19/08/2019	Inspection Date	22/08/2019
	Survey held at	CHEW GOON MOTOR BLK 10 ANG MO KIO IND PARK 2A #01-15/16/17, AVE 5, AMK AUTOPOINT SINGAPORE 568047		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days	