

ASS. REC. BY:

REF:

CS3/PWD19014806/Ad3

Special Instruction:

Surveyor: Adnan

ASSIGNMENT (Office)

From (Person): Venessa Chan

of

FWD

Date/Time: 22/8/19 @ 11.48am

Estimated Cost:

Bill to:

OI / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLX 9962X

Insured:

SLT 4767Y

at Workshop m/s

N-SI Automotive

Tel:

68420051

or

2 Kaki Bukit Ave 2 # 01-18

Policy No:

PNV2018-0001952

Claim No:

1201900025125

Sum Insured:

Excess:

D.O.A. 21/8/2019

Make of Veh:

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 2:17pm @ 22/8/19

Person Contacted:

zi ting

Vehicle: IN/OUT

Date/Time	Action/Instruction	Vehicle? (X)
	SLX 9962X - NA / FWD 19014806 / h4	DOA: 21/8/2019
	SLT 4767Y - CCH / LCR 18010280 / K00392	DOA: 7/5/2018
	Dismantle: 23/8/2019	
	After repair: 27/8/2019	

ASS. REG. BY:

REF:

Adrian

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLX9962X Yr Regn: 2018 April

Type M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai Elantra C.C. 1591

Colour Gold Beige A/C: Insured / Std / NI / NA

Sp. Reading 8950 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KMH D84CMJU 665502

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15

R: 195/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Nexen

Front

Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. _____ D.O.I. 22/08/19

Survey held at Twinkl

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>TP FWD PRS</u>
	<u>\$5.5k - \$6.5k 06 Days</u>
	<u>He S.</u>
	<u>MV:</u>
	<u>PV:</u>
	<u>Nett:</u>

Date/Time, File Pass to?

Date/Time, File Return to?

1) PRS - 2 trips

2)

3)

4)

5)

6)

Prel. Report:

Final Report:

Part Prices Check:

IN

OUT

Survey Fee:

Date:

Basic & Add.

___ S + RS, ___ SI

Photos

Others

TOTAL

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	22 Aug 2019 Edit Reg		22 Aug 2019 00:00 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	Ong Herng Jiunn Pierre Jim, ID: S8207618B		
Main Claimant:	THNG SOW KENG WINNIE, ID: S7719839C		
Vehicle Reg. No.:	SLX9962C	Date of Loss:	21/08/2019 16:00 - :59
Claim Type:	TP / 1201900025125	Policy/Cover Note No.:	PNPV2018-00011952 (Comprehensive) Coverage: 30/10/2018 - 29/10/2019
Vehicle Reg. No. (Insured):	SLT4767Y	Policy No. (Claimant):	
		Excess:	
Repairer:	N-51 Automotive Pte Ltd (HQ) BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB, 417921 Kaki Bukit - Tel: 68420051		
Handling Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Josey Loh]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 02/09/2019]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date Priority Type Task Group Subject Handler Assigned By Completed On Created On Done?

No results.

Nivitha (LKK Auto)

From: venessa.chan@fwd.com
Sent: Thursday, 22 August 2019 11:48 AM
To: admin-d@lkkauto.com; admin-a@lkkauto.com
Cc: motorclaims.sg@fwd.com; josey.loh@fwd.com
Subject: SLX9962X & SLT4767Y - NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS
Attachments: SLX9962X PRI - TWINCAR AUTOMOTIVE PTE LTD & TP GIA.zip

Dear Nivitha,

Please refer to the email below and liaise with TP repairer for PRS.

Please create the case in Merimen & our insured has yet to report.

Thank you.


Best Regards,

Venessa Chan

Administrative Assistant, Claims



FWD Singapore Pte. Ltd.
6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986
E venessa.chan@fwd.com
W www.fwd.com.sg



From: Venessa Chan - SGUser
Sent: Thursday, August 22, 2019 11:44 AM
To: Chio Ziting
Cc: Motor Claims SG - SG Common; Josey Loh Kah Wai - SGUser
Subject: SLX9962X & SLT4767Y - NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS

Dear Zi Ting,

We regret that we are objecting to your proposed list of surveyors.

We will be appointing, M/s **LKK Auto Consultants Pte Ltd**, to conduct the pre-repair survey (PRS) on your client's vehicle, SLX9962X. We seek your cooperation to inform your client's workshop to arrange the vehicle readily for dismantling with repair estimates during the pre-repair survey.

If there is a change in your client's workshop, please inform us soon. We reserve our rights for re-inspection.

**Please note that we do not accept fax. Hence, please send in any correspondences related to Motor Claims via e-mail to motorclaims.sg@fwd.com.*

Thank you.

Best Regards,

Venessa Chan

Administrative Assistant, Claims




FWD Singapore Pte. Ltd.

6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

E venessa.chan@fwd.com

W www.fwd.com.sg



From: Chio Ziting [<mailto:ziting@n51.com.sg>]

Sent: Thursday, August 22, 2019 11:26 AM

To: Venessa Chan - SGUser

Subject: Re: SLX9962X & SLT4767Y - NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS

Dear Sir / Madam,

We refer to your list of motor surveyors proposed.

We do not agree to your list of motor surveyors.

Please see attached.

Thank you.

Regards,

Zi Ting

N-51 Automotive Pte Ltd

Office: 6842 0051

Fax: 6741 0510

www.n51.com.sg



bizSAFE₃

On Thu, Aug 22, 2019 at 11:01 AM <venessa.chan@fwd.com> wrote:

WITHOUT PREJUDICE

Dear Zi Ting,

We refer to your email dated on 22.08.2019 of the PRI Notice of your client's vehicle SLX9962X.

Please find our panel surveyors as follows: -

1. LKK AUTO CONSULTANTS PTE LTD
2. INFINITI APPRAISAL SERVICE
3. AJAX INSPECTION SERVICES PTE LTD
4. RT Appraisal Pte Ltd

If you are not agreeable to any of the above, we reserve our rights to request for pre-repair inspection of your client's vehicle.

We look forward to receiving your reply.

Thank you.

*Please note that contents of this email should not be construed as any admission of liability on the part of our insured and/ or insurers. We hereby maintain full reservation of rights and all defences available to us.

*Please note that we do not accept fax. Hence, please send in any correspondences related to Motor Claims via e-mail to motorclaims.sg@fwd.com.

Best Regards,

Venessa Chan

Administrative Assistant, Claims




FWD Singapore Pte. Ltd.

6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

E venessa.chan@fwd.com

W www.fwd.com.sg



From: Chio Ziting [mailto:ziting@n51.com.sg]

Sent: Thursday, August 22, 2019 10:31 AM

To: Motor Claims SG - SG Common

Subject: SLX9962X & SLT4767Y - NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS

Dear Sir/Madam,

As per above subject,

Please refer attachment and:-

Kindly propose / provide your 10 surveyors

Thank you.

Regards,

Zi Ting

N-51 Automotive Pte Ltd

Office: 6842 0051

Fax: 6741 0510

www.n51.com.sg



ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	22/08/2019 09:51
Date Of Accident	21/08/2019 16:30
Exact Location Of Accident	PIE TWDS CHANGI AFTER KIM KEAT LINK EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLX9962X
Insured/Policyholder	
Name Of Registered Owner	THNG SOW KENG WINNIE
NRIC No	S7719839C
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90604657
Alternative Phone No	OFFICE-90604657

Vehicle Particulars

Manufacturer	HYUNDAI
Model	ELANTRA
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	FWD SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	PNPV2019-00006865
Cover Note Number	-

Driver

Name of Driver	THNG KIM YONG
NRIC No	S0014657I
Date Of Birth	17/06/1952
Occupation	INDOOR
Date Of Driving Pass	01/03/2000
Driving Experience	19 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90088811
Fax Number	
Contact Number	
Email Address	NOEMAIL

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SHC8077R
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number	SJH4135H
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 4

Vehicle Registration Number	SFU1877Z
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	THNG KIM YONG
Approximate Age	
Injuries Sustain	BODY
Injured person in which vehicle?	SLX9962X
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

DETAILS OF INJURED PERSON 2

Name	MARICHU GUZON GUZMANA
Approximate Age	
Injuries Sustain	BODY
Injured person in which vehicle?	SLX9962X
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policy holder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer [collectively the "Personal Information"] and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims [collectively the "Purposes"]
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Accident Sketch Plan

SKETCH PLAN

A - SLX9962X
 B - SLT4702Y
 C - SHC2077R
 D - SJH4135H
 E - SFH1877Z

Pic towards CHANGE After Ken KEAT LINK



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving along Pic towards CHANGE on the most extreme right lane, 4-lane expressway. Somewhere after Ken KEAT LINK Exit, vehicle in front of me slowed down due to heavy traffic ahead. Therefore, I applied brake and stop fully out of sudden, I felt an impact from the rear. I alighted and realised vehicle (B) collided onto my vehicle rear portion. I was involved in a 5 vehicles chain collision. We exchange particulars and left the scene.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
 Date & Time:

Driver's Signature
 (if driver is not the policyholder)
 Date & Time:

Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	839C
Vehicle Details	
Vehicle No.:	SLX9962X
Vehicle to be Exported:	No
Intended Deregistration Date:	26 Aug 2019
Vehicle Make:	HYUNDAI
Vehicle Model:	ELANTRA AD 1.6 GLS AT (AMS)
Primary Colour:	Beige
Manufacturing Year:	2018
Engine No.:	G4FGJU167954
Chassis No.:	KMHD841CMJU665502
Maximum Power Output:	93.8 kW (125 bhp)
Open Market Value:	\$10,055.00
Original Registration Date:	20 Apr 2018
First Registration Date:	20 Apr 2018
Transfer Count:	0
Actual ARF Paid:	\$10,055.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	19 Apr 2028
PARF Rebate Amount:	\$7,541.00
Intended COE Rebate Details	
COE Expiry Date:	19 Apr 2028
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$37,000.00
COE Rebate Amount:	\$32,003.00
Total Rebate Amount:	\$39,544.00

The information contained herein is correct as at 26 Aug 2019

OK

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING						
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed
Main	22 Aug 2019 Edit Reg		22 Aug 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt	
						Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	Ong Herng Jiunn Pierre Jim, ID: S8207618B		
Main Claimant:	THNG SOW KENG WINNIE, ID: S7719839C		
Vehicle Reg. No.:	SLX9962C	Date of Loss:	21/08/2019 16:00 - :59 [16 Months and 1 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 1201900025125	Policy/Cover Note No.:	PNPV2018-00011952 (Comprehensive) Coverage: 30/10/2018 - 29/10/2019
Vehicle Reg. No. (Insured):	SLT4767Y	Policy No. (Claimant):	
		Excess:	
Repairer:	N-51 Automotive Pte Ltd (HQ) BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB, 417921 Kaki Bukit - Tel: 68420051		
Handling Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Josey Loh]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 02/09/2019]		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)









































Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



















































Claim Documents



***SLX9962C (1201900025125)**
[SLT4767Y]

TP

THNG SOW KENG WINNIE
Aug 21 2019 4:00PM
[Ong Herng Jiunn Pierre Jim]
N-51 Automotive Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	27/08/19 17:44	General View	 Load JPG	<input checked="" type="checkbox"/>
2	27/08/19 17:44	General View	 Load JPG	<input checked="" type="checkbox"/>
3	27/08/19 17:44	General View	 Load JPG	<input checked="" type="checkbox"/>
4	27/08/19 17:44	General View	 Load JPG	<input checked="" type="checkbox"/>
5	27/08/19 17:44	General View	 Load JPG	<input checked="" type="checkbox"/>
6	27/08/19 17:44	General View	 Load JPG	<input checked="" type="checkbox"/>
7	27/08/19 17:44	General View	 Load JPG	<input checked="" type="checkbox"/>
8	27/08/19 17:44	General View	 Load JPG	<input checked="" type="checkbox"/>
9	27/08/19 17:44	General View	 Load JPG	<input checked="" type="checkbox"/>
10	27/08/19 17:44	General View	 Load JPG	<input checked="" type="checkbox"/>
11	27/08/19 17:44	General View	 Load JPG	<input checked="" type="checkbox"/>
12	27/08/19 17:44	General View	 Load JPG	<input checked="" type="checkbox"/>
13	27/08/19 17:44	General View	 Load JPG	<input checked="" type="checkbox"/>
14	27/08/19 17:44	General View	 Load JPG	<input checked="" type="checkbox"/>
15	27/08/19 17:44	General View	 Load JPG	<input checked="" type="checkbox"/>
16	27/08/19 17:44	General View	 Load JPG	<input checked="" type="checkbox"/>
17	27/08/19 17:44	General View	 Load JPG	<input checked="" type="checkbox"/>
18	27/08/19 17:44	General View	 Load JPG	<input checked="" type="checkbox"/>
19	27/08/19 17:44	General View	 Load JPG	<input checked="" type="checkbox"/>
20	27/08/19 17:44	General View	 Load JPG	<input checked="" type="checkbox"/>
21	27/08/19 17:44	General View	 Load JPG	<input checked="" type="checkbox"/>
22	27/08/19 17:44	General View	 Load JPG	<input checked="" type="checkbox"/>
23	27/08/19 17:44	General View	 Load JPG	<input checked="" type="checkbox"/>
24	27/08/19 17:44	General View	 Load JPG	<input checked="" type="checkbox"/>
25	27/08/19 17:44	General View	 Load JPG	<input checked="" type="checkbox"/>
26	27/08/19 17:44	General View	 Load JPG	<input checked="" type="checkbox"/>
27	27/08/19 17:44	General View	 Load JPG	<input checked="" type="checkbox"/>
28	27/08/19 17:44	General View	 Load JPG	<input checked="" type="checkbox"/>
29	27/08/19 17:44	General View	 Load JPG	<input checked="" type="checkbox"/>
30	27/08/19 17:44	General View	 Load JPG	<input checked="" type="checkbox"/>
31	27/08/19 17:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
32	27/08/19 17:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
33	27/08/19 17:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
34	27/08/19 17:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
35	27/08/19 17:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
36	27/08/19 17:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
37	27/08/19 17:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
38	27/08/19 17:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	27/08/19 17:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	27/08/19 17:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
41	27/08/19 17:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	27/08/19 17:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	27/08/19 17:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	27/08/19 17:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	27/08/19 17:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	27/08/19 17:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	27/08/19 17:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	27/08/19 17:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	27/08/19 17:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	27/08/19 17:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	27/08/19 17:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	27/08/19 17:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	27/08/19 17:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	27/08/19 17:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	27/08/19 17:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	27/08/19 17:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	27/08/19 17:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	27/08/19 17:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	27/08/19 17:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	27/08/19 17:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	27/08/19 17:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	27/08/19 17:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	27/08/19 17:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	27/08/19 17:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	27/08/19 17:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	27/08/19 17:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	27/08/19 17:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	27/08/19 17:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	27/08/19 17:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	27/08/19 17:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	27/08/19 17:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	27/08/19 17:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
73	27/08/19 17:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
74	30/08/19 10:31	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
75	30/08/19 10:31	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
76	30/08/19 10:31	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
77	30/08/19 10:31	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
78	30/08/19 10:31	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
79	30/08/19 10:31	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
80	30/08/19 10:31	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
81	30/08/19 10:31	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
82	30/08/19 10:31	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
83	30/08/19 10:31	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
84	30/08/19 10:31	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
85	30/08/19 10:31	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
86	30/08/19 10:31	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
87	30/08/19 10:31	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
88	30/08/19 10:31	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
89	30/08/19 10:31	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
90	30/08/19 10:31	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
91	30/08/19 10:31	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
92	30/08/19 10:31	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
93	30/08/19 10:31	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
Documentation			1 per page ▼	✓
No	Finalized On	FWD Singapore Pte, Ltd. (HQ)	Thumbnail	Print
1	26/08/19 11:02	SLT4767Y OI GIA	 Load PDF	
2	26/08/19 11:02	EMAIL TO OI	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST			Reset	Save	Print
There are no document checklists configured.					

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/FWD19014806/ACD3S2

Date: 13/09/2019

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2018-00011952
 Claimant Vehicle No: SLX9962C Insured Vehicle No: SLT4767Y
 Date of Loss: 21/08/2019 Nature of Claim: TP Claim No: 1201900025125

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLX9962C**
 Make & Model: HYUNDAI ELANTRA, 1.6 (A) Engine No: G4FGJU167954
 Reg. Date: 20/04/2018 (Man. Year: 2018) Chassis No: KMHD841CMJU665502
 Colour: Beige Odometer: 89750 km
 Engine Capacity: 1591 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
 Front Left Side: Nexen 6 mm Rear Left Side: Nexen 6 mm
 Front Right Side: Nexen 6 mm Rear Right Side: Nexen 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 22/08/2019

Date Inspected: 22/08/2019 Inspected At:

N-51 Automotive Pte Ltd (HQ)
 BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT
 AUTOHUB
 Singapore 417921

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,500.00 - \$6,500.00

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 13 Sep 2019)
Parts:	143	HYUNDAI ELANTRA 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLX9962C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >