

ASS. REC. BY:

REF:

CS/FCI/90/4807/R290302

Special Instruction:

Assignee: Rasul

ASSIGNMENT (Office)

aws

From (Person): Jason Tea

of

FCI

Date/Time: 4:11pm @ 21/8/19

Estimated Cost:

Bill to:

OD - ~~FD~~ / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SMG 4664Y

Insured:

SHC 8338M

at Workshop m/s

MOVA

Tel:

6262 3377

of

15 Fan Yang Road

Policy No:

Claim No:

D19005395MPSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 19/08/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

3:19pm @ 22/8/19

Person Contacted:

Nabilah

Vehicle IN / OUT

Date/Time

Action/Instruction

Estimate (✓)

30/8/19 @ 11:58am revised to Jason Tea by email.

20/9/19 @ 12:00pm Items finalized US \$ 6300, 5 days (Red \$ 7701.90, 55%)

ASS. REC. BY:

REF: FCI

753B

COPY: 2022/SEP

ASSIGNMENT

From:

Date:

29/8/2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SMG 4564Y

at Workshop m/s

Mova Automotive

of BLK 1008 Bltmanh Lane 3 #01-04

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

, Morning

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 1up

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SMG 4564Y

Yr Regn:

2012/SEP

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

B.M.W 640I GRAN COUPE 402 c.c 2579

Colour:

Black

A/C: Insured / Std / NI / NA

Sp. Reading

148909

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WBA 6A020200210663

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rfm / STD A/Rim or

Tyre Size:

F: 245/40 R19

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6 mm

R/Bal.

6 mm

L/Bal.

6 mm

L/Bal.

6 mm

D.O.A.

19/08/19

D.O.I.

29/08/19

Survey held at

Mova (BM)

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S FR

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 23 SEP 2019

Date/Time, File Pass to?



: Preli. Report

1) 23/9/19 Mair



: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

5

Resurvey No. of Trip:

1

Add Fee:



: Site Insp (\$)



: Interview (\$)



: Tech. Invs (\$)



: Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format:

TP

Lump Sum / P.P. G

6300

4x15=60

170+60

90

50

62

342

MOTOR SURVEY ASSIGNMENT

Date	20-08-2019	Our Ref No. D19005395MFSH
Accident Date	19-08-2019	Claim Type. Third Party
Insured Vehicle	SHC8338M	Third Party Vehicle. SMG4564Y
Survey Location	15 FAN YOONG ROAD	
Contact Person.	NABILAH SENIN	
Contact No.	62623377/ 0	Fax No. 62643151
Survey Type	WITHOUT PREJUDICE: LIABILITY UNCLEAR: CONFLICTING VERSIONS OF REPORT, WAITING FOR INSURED VIDEO	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	MOVA AUTOMOTIVE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	JASON TEA CHEE KIAT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Shiau Chan (LKKAUTO)

From: Tan Yoong Wei <tanyw@mova.com.sg>
Sent: Friday, 20 September 2019 12:50 PM
To: Rasul (LKKAUTO)
Subject: RE: FINALISE SMG4564Y

CLOSE

Best Regards,
Tan Yoong Wei
Estimator
Mova Automotive Pte Ltd
Tel: 6272 3892 Fax: 6270 8314



This message is confidential and is for the use of the intended recipient only. If you have received this message in error, please do not copy, disclose or use its content. We would be grateful if you would notify us by email and delete the original transmission and any attachment from your system. Any attachment to this e-mail may contain software viruses that could damage your computer system. Although we will take reasonable precaution to minimize this risk, we do not accept any liability resulting from software viruses. Please carry out your own virus checks before opening any attachment.

From: Rasul (LKKAUTO) [mailto:Rasul@lkkauto.com]
Sent: Friday, 20 September 2019 12:18 PM
To: Tan Yoong Wei
Subject: RE: FINALISE SMG4564Y

Hi Yoong Wei,

Refer to attachment
Finalised amount is \$ 6,300 / 5 days of lump sum
Kindly confirm

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

From: Tan Yoong Wei [mailto:tanyw@mova.com.sg]
Sent: Friday, 20 September, 2019 9:08 AM
To: Rasul (LKKAUTO)
Cc: Hsiao Tong (LKKAUTO); Veron Chen (LKKAUTO); 'Nitha'; 'Suann'
Subject: FINALISE SMG4564Y

Hi
Good morning

Please advice whether we can finalise cost of repair lumpsum \$6900 with 5 working days ?
TQ

Best Regards,
Tan Yoong Wei
Estimator
Mova Automotive Pte Ltd
Tel: 6272 3892 Fax: 6270 8314



This message is confidential and is for the use of the intended recipient only. If you have received this message in error, please do not copy, disclose or use its content. We would be grateful if you would notify us by email and delete the original transmission and any attachment from your system. Any attachment to this e-mail may contain software viruses that could damage your computer system. Although we will take reasonable precaution to minimize this risk, we do not accept any liability resulting from software viruses. Please carry out your own virus checks before opening any attachment.

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Friday, 30 August 2019 11:58 AM
To: 'CWS Motor Claims'; assignments
Cc: 'Jason Tea'; SUR
Subject: RE: SURVEY ASSESSMENT - D19005395MFSH/1
Attachments: CSFCI19014807R1qd3.pdf

Dear Jason,

Enclosed herewith preliminary advice of SMG 4564Y.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Sent: Thursday, 22 August 2019 3:22 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Jason Tea' <JasonTea@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19005395MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed that vehicle is not in the workshop, repairer will arrange.

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Wednesday, 21 August 2019 4:11 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Jason Tea <JasonTea@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19005395MFSH/1

Dear Sir/Mdm,



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19005395MFSH

Date: 30 August 2019

Our Ref: CS/FCI19014807/R1qd3

The Motor Claims Department
MS First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SMG 4564Y .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 19/08/2019 at the premises of M/s MOVA, and have the following to report:-

Workshop Estimate Amount	: <u>S\$ 14,001.90 .</u>
Revised Estimate Amount	: <u>S\$ 6,800.01 .</u>
"Check" Items Amount	: <u>S\$ 2,975.42 .</u>
Market Value	: <u>S\$ - .</u>
LTA Reimbursement Value	: <u>S\$ - .</u>
Nett Value	: <u>S\$ - .</u>

Description of Damage:
The vehicle sustained damages
at the o/s front portion.



Yours faithfully

Rasul
Automotive Assessor

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	793B
Vehicle Details	
Vehicle No.:	SMG4564Y
Vehicle to be Exported:	No
Intended Deregistration Date:	30 Aug 2019
Vehicle Make:	B.M.W.
Vehicle Model:	640I GRAN COUPE 4DR SR LED DSC NAV HUD
Primary Colour:	Brown
Manufacturing Year:	2012
Engine No.:	05578245N55B30A
Chassis No.:	WBA6A02020DZ10663
Maximum Power Output:	235.0 kW (315 bhp)
Open Market Value:	\$80,078.00
Original Registration Date:	24 Sep 2012
First Registration Date:	24 Sep 2012
Transfer Count:	1
Actual ARF Paid:	\$80,078.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	23 Sep 2022
PARF Rebate Amount:	\$52,050.00
Intended COE Rebate Details	
COE Expiry Date:	23 Sep 2022
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$80,191.00
COE Rebate Amount:	\$24,591.00
Total Rebate Amount:	\$76,641.00

The information contained herein is correct as at 30 Aug 2019

OK

111,000
76,641

34,359

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	19/08/2019 11:32
Date Of Accident	19/08/2019 09:10
Exact Location Of Accident	IN FRONT OF CLIFFORD CENTRE (CLIFFORD RD)
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SMG4564Y
Insured/Policyholder	
Name Of Registered Owner	DENG LIN
NRIC No	S9280793B
Email Address	DENGLINLYNN@GMAIL.COM
Mobile Phone No	(LOCAL) +65-98414732
Alternative Phone No	OTHERS-NOPHONE
Vehicle Particulars	
Manufacturer	BMW
Model	640I GRAN COUPE 4DR SR LED DSC NAV HUD
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5106516728
Cover Note Number	
Driver	
Name of Driver	HE GUANGXU
NRIC No	S9278978J
Date Of Birth	06/11/1992
Occupation	INDOOR
Date Of Driving Pass	09/12/2017
Driving Experience	1 YEAR AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98414752
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	23 KEPPEL BAY VIEW #06-72
Postcode	098414
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

-

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHC8338M
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	LIM AH KAU
NRIC/Passport Number	S0689429A
Contact Number	93745903
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	


excess - 1600.00


SKETCH PLAN**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow Insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


 Policyholder's Signature
 Date & Time:


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:


 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

SKETCH PLAN




DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

LICENSE PLATE: SMG 4564Y	ACCIDENT DATE & TIME: 19/08/19 09:10am
CONTACT NUMBER: 98414752	E-MAIL ADDRESS: deaglinlyan@gmail.com
LOCATION: In front of Clifford Centre (Clifford Road)	
<p>I was slowly driving on the Fullerton Road, suddenly taxi (SHC 8338m) cut into my lane and hit on the front RH side. As there is a taxi stand to try to drop off passengers so that he changed lane. When I spoken to the taxi driver he mention he got video footage.</p>	
NOTE: PLEASE NOTE THAT YOUR INSURER MAY HAVE 14 DAYS TIME FRAME FOR YOU TO SUBMIT AN OWN DAMAGE CLAIM UNDER YOUR OWN POLICY. PLEASE CHECK YOUR POLICY FOR MORE INFORMATION	
Please state:	
<input type="checkbox"/> Claim Own Policy <input checked="" type="checkbox"/> Claim Third Party <input type="checkbox"/> Claim OD/TP at other workshop <input type="checkbox"/> Reporting Only	

DECLARATION

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722

Tel: (65) 6272 3892
Fax: (65) 6270 8314

Co. Reg. 198904033G
GST Reg. M2-008864-2

Estimate

21/08/2019

MS FIRST CAPITAL INSURANCE LIMITED
36 Robinson Road
#16-01 City House
Singapore 068877.

Attention :- XA026

Page # :- 1

Veh # :- SMG4564Y

Veh Model :- BMW 640i GRAN COUPE 4DR SR

Estimate# :- CK419576

Claim # :-

ACC. Date :- 19/08/19

Terms :- C.O.D Days

Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
LIST ITEMS :				
1.	FRONT FENDER RH <i>Cra /</i>	1	PC 1,920.75	1,920.75
2.	FRONT FENDER LAMP RH <i>X sul</i>	1	PC 325.45	325.45 <i>X</i>
3.	FRONT FENDER RIVET RH <i>nee /</i>	10	PCS 5.80	58.00
4.	FRONT WIPER TANK RH <i>? de /</i>	1	PC 193.40	193.40
5.	FRONT WIPER TANK HOSE RH <i>Cra /</i>	1	PC 68.30	68.30
6.	FRONT DOOR RH <i>bt</i>	1	PC 2,391.40	2,391.40
7.	FRONT DOOR HINGE RH <i>X sul</i>	2	PCS 113.05	226.10 <i>X</i>
8.	FRONT DOOR WEATHERSTRIP RH <i>nee /</i>	1	PC 290.55	290.55
9.	FRONT DOOR RIVET RH <i>nee /</i>	10	PCS 5.80	58.00
10.	FRONT DOOR STICKER <i>nee X an</i>	2	PCS 68.00	136.00 <i>X</i>
11.	VACUUM PUMP DOOR RH <i>? X sul</i>	1	PC 496.70	496.70 <i>X</i>
12.	FRONT SIDE MIRROR RH <i>X sul</i>	1	PC 1,222.85	1,222.85 <i>X</i>
13.	FRONT SIDE MIRROR COVER RH <i>X sul</i>	1	PC 195.45	195.45 <i>X</i>
14.	SIDE SKIRT RH <i>sul</i>	1	PC 657.20	657.20
15.	SIDE SKIRT CLIPS RH <i>nee /</i>	10	PCS 4.00	40.00
16.	FRONT WHEEL RIM RH <i>sul ? X sul</i>	1	PC 1,985.20	1,985.20 <i>500 spu</i>
17.	FRONT WHEEL BEARING RH	1	PC 494.55	494.55 <i>X</i>
18.	FRONT LOWER ARM RH - CHECK <i>X sul</i>	1	PC	
19.	FRONT UPPER ARM RH - CHECK <i>X sul</i>	1	PC	
LIST TOTAL S\$				10,759.90
5% DISCOUNT S\$				-538.00
				10,221.90
SPECIAL NET ITEMS :				
1.	FRONT FENDER MATTE BLACK (3M) RH <i>nee /</i>	1	PC 600.00	300 <i>500</i>
2.	FRONT DOOR MATTE BLACK (3M) RH <i>nee /</i>	1	PC 600.00	300 <i>500</i>
3.	FRONT SIDE SKIRT MATTE BLACK (3M) RH <i>nee /</i>	1	PC 400.00	200 <i>500</i>
4.	FRONT SIDE MIRROR MATTE BLACK (3M) RH <i>X an</i>	1	PC 150.00	150.00 <i>X</i>
SPECIAL NET TOTAL S\$				1,750.00

LABOUR :

TO REPAIR FRONT WHEELHOUSE RH, FRONT DOOR
INNER PILLAR. TO REMOVE & REPLACE ALL
ACCIDENT DAMAGED PARTS. TO STRAIGHTEN &
RE-ALIGN ON ACCIDENT DAMAGED PARTS

TO SPRAY PAINT ON ACCIDENT DAMAGED PARTS

TO CHECK FRONT WHEEL ALIGNMENT

TO REMOVE FRONT WHEEL RIM & CONDUCT BALANCING

TO REMOVE FRONT SUSPENSION *- photo*

TO REMOVE FRONT DOOR MECHANISM, DOOR LOCK &
OTHER ATTACHMENT PARTS

400 *600.00*

600 *750.00*

60 *80.00*

30 *50.00*

(no photo) X 80? *250.00*

60 *150.00*

5677.60
59
5393.72

1300

price?

Estimate

21/08/2019

MS FIRST CAPITAL INSURANCE LIMITED
36 Robinson Road
#16-01 City House
Singapore 068877.

Attention :- XA026

Page # :- 1 135853

Veh # :- SMG4564Y

Veh Model :- BMW 640I GRAN COUPE 4DR SR I

Estimate# :- CK419576

Claim # :-

ACC. Date :- 19/08/19

Terms :- C.O.D Days

Remarks :-

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722
Tel: (65) 6272 3892
Fax: (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

No.	Description	Qty	U.Price	Amounts S\$
	TO CHECK FRONT DOOR VACUUM DOOR & SETTING			60 150.00
	LABOUR TOTAL S\$	1210		2,030.00

E. & O.E

NON-TAX AMOUNT S

AMOUNT S\$ 14,001.90

GST @ 7 % 980.13

AMOUNT DUE S\$ 14,982.03

Customer's Signature/Co. Stamp MOVA AUTOMOTIVE PTE LTD

5393.72

1300.00

1210.00

7903.72

20%

6322.97

411 - 6,300

5 days

Rasul *[Signature]* 30/8/19
Hp 90010068

5 days

4/5

29/08/19 @ 1355

Resume after repair



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19014807/R1qd3e2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 24-09-2019		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 8338M	Veh. Inspected	SMG 4564Y	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19005395MFSH	Excess (\$)	0.00	
Assign From	JASON TEA	Assign Date	21/08/2019	
2. Vehicle Particulars & Condition				
Make & Model	B.M.W. 640I GRAN COUPE 4DR	c.c	2979	
Engine No.	HIDDEN	Year of Reg.	2012	
Chassis No.	WBA6A02020DZ10663	Colour	BLACK	
Odometer	148909	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	245/40 R19	GOODYEAR	6 mm	
L/H Front Tyre	245/40 R19	GOODYEAR	6 mm	
R/H Rear Tyre	245/40 R19	GOODYEAR	6 mm	
L/H Rear Tyre	245/40 R19	GOODYEAR	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	19/08/2019	Inspection Date	29/08/2019	
Survey held at	MOVA AUTOMOTIVE PTE LTD 15 FAN YONG ROAD SINGAPORE 629792			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMG 4564Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT FENDER RH	CRACKED	1,920.75	1,920.75
1	FRONT FENDER LAMP RH	SERVICEABLE	325.45	-
10	FRONT FENDER RIVET RH @\$5.80	NECESSARY	58.00	58.00
1	FRONT WIPER TANK RH	DEFORMED	193.40	193.40
1	FRONT WIPER TANK HOSE RH	CRACKED	68.30	68.30
1	FRONT DOOR RH	BENT	2,391.40	2,391.40
2	FRONT DOOR HINGE RH @\$113.05	SERVICEABLE	226.10	-
1	FRONT DOOR WEATHERSTRIP RH	NECESSARY	290.55	290.55
10	FRONT DOOR RIVET RH @\$5.80	NECESSARY	58.00	58.00
2	FRONT DOOR STICKER @\$68.00	NOT NECESSARY	136.00	-
1	VACUUM PUMP DOOR RH	SERVICEABLE	496.70	-
1	FRONT SIDE MIRROR RH	SERVICEABLE	1,222.85	-
1	FRONT SIDE MIRROR COVER RH	SERVICEABLE	195.45	-
1	SIDE SKIRT RH	SCRATCHED	657.20	657.20
10	SIDE SKIRT CLIPS RH @\$4.00	NECESSARY	40.00	40.00
1	FRONT WHEEL BEARING RH	SERVICEABLE	494.55	-
1	FRONT LOWER ARM RH (NPA)	SERVICEABLE	-	-
1	FRONT UPPER ARM RH (NPA)	SERVICEABLE	-	-
	LESS 5% DISCOUNT		-438.74	-283.88
			8,335.96	5,393.72
1	FRONT WHEEL RIM RH (SN)	SCRATCHED	1,985.20	500.00
	LESS 5% DISCOUNT		-99.26	-
			1,885.94	500.00
<u>SPECIAL NETT ITEMS</u>				
1	FRONT FENDER MATTE BLACK (3M) RH (SN)	NECESSARY	600.00	300.00
1	FRONT DOOR MATTE BLACK (3M) RH (SN)	NECESSARY	600.00	300.00
1	FRONT SIDE SKIRT MATTE BLACK (3M) RH (SN)	NECESSARY	400.00	200.00
1	FRONT SIDE MIRROR MATTE BLACK (3M) RH (SN)	NOT NECESSARY	150.00	-
			1,750.00	800.00

Report Ref No. CS/FCI19014807/R1qd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO REPAIR FRONT WHEELHOUSE RH, FRONT DOOR INNER PILLAR. TO REMOVE & REPLACE ALL ACCIDENT DAMAGED PARTS. TO STRAIGHTEN & RE-ALIGN ON ACCIDENT DAMAGED PARTS.		600.00	400.00
	TO SPRAY PAINT ON ACCIDENT DAMAGED PARTS.		750.00	600.00
	TO CHECK FRONT WHEEL ALIGNMENT.		80.00	60.00
	TO REMOVE FRONT WHEEL RIM & CONDUCT BALANCING.		50.00	30.00
	TO REMOVE FRONT SUSPENSION.	NOT NECESSARY	250.00	-
	TO REMOVE FRONT DOOR MECHANISM, DOOR LOCK & OTHER ATTACHMENT PARTS.		150.00	60.00
	TO CHECK FRONT DOOR VACUUM DOOR & SETTING.		150.00	60.00
			2,030.00	1,210.00
	GRAND TOTAL		14,001.90	7,903.72
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			6,300.00

Report Ref No. CS/FCI19014807/R1qd3e2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.