

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

MSIC/

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SKC9006D
 at Workshop m/s M.
 of _____
 Insured: _____
 Policy No. 29114756
 Claims No. 602998
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: £6
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GA / PR Seen: 2 Consistent? : Yes or No
 Est. Repairs: 4 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: Dep 7k Vehicle: IN / OUT

Veh No: SKC9006D Yr Regn: 10.07
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or GA
 Make: Lexus 15250 c.c. 2500
 Colour: Grey A/C: Insured / Std / NI / NA
 Sp. Reading: 94458 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: JTHBK26805053313
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 225/45-17
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front 6 mm Rear 6 mm
 R/Bal. _____ mm R/Bal. _____ mm
 L/Bal. _____ mm L/Bal. 6 mm
 D.O.A. 14/8/19 D.O.I. 22/8/19
 Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

0/s Rear
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction LTA 41123

23/8/19 @ 9.27am Email G1A report to MSIG
16/9/19 1/5 £4000 agreed with Mr. Red 10574.50, 73.1%

16/9/19 @ 2.54pm revised to Christina Wong via Meimien.

RECEIVED 18 SEP 2019

Date/Time, File Pass to?

☐ : Preli. Report1) 18/9/19 turn in☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 4

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

Add Fee:

☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Photos

Others

Report Format: MER-TLump Sum / I.P.I. (\$) 4000

TOTAL

200

11

211

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Christina Wong

Date: 16 Sep 2019

Preliminary Advice

Insured Vehicle No	: SLT4697R	Accident Date	: 14/08/2019
TP Vehicle No	: SKC9006D	Assignment Date	: 23/08/2019
Make	: TOYOTA LEXUS	Est. Duration of Repair	: 4.00
Date of Inspection	: 22/08/2019		
Inspection At	: FASTECH AUTO PTE LTD (HQ) 1 KAKI BUKIT AVE 6, #01-46/48/50 AUTOBAY SINGAPORE 417883		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	14,574.50
Revised Amount	:S\$	5,012.85
Check Items (Estimated)	:S\$	0.00
Total	:S\$	5,012.85
Lump Sum Repair	:S\$	4,000.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Friday, 23 August 2019 9:27 AM
To: motorsurvey@sg.msig-asia.com
Cc: SUR; KKLau; Accounts (LKKAuto)
Subject: DIRECT SURVEY INSPECTION ON WORKSHOP - FASTECH AUTO PTE LTD, DOA: 14/08/2019, SKC 9006D (TP VEHICLE), SLT 4697R (OI VEHICLE)
Attachments: SKC9006 GIA.pdf

Dear Sir/Madam,

Please be informed that we had inspected the vehicle SKC 9006D at M/s: FASTECH AUTO PTE LTD, 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883.

Enclosed herewith a copy of TP's GIA report. The estimated cost of repair will forward to you shortly.

Meanwhile, kindly provide us the claim reference number for our necessary action.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

[New Cars](#)[Used Cars](#)[Sell My Car](#)[Directory](#)[Products](#)[Insurance](#)[Articles](#)[Forum](#)[Resources](#)

Get Comprehensive Hospitalisation
Coverage With Our Affordable Plans.

IS250

Price Range

Depreciation

> 10 year(

Vehicle Type



Submit

[Advanced Search](#)[Home](#) » [Used Cars](#) » [Monster Motors Pte Ltd](#) » [Lexus IS250 \(COE till 10/2027\)](#)

Lexus IS250 (COE till 10/2027)

[Overview](#)[Financial](#)[Insurance](#)[Accessories](#)[Similar](#)[Research](#)[Photos](#)[Map](#)

PREMIUM AD



CONSIGNMENT / BUY / SELL / SCRAP / EXPORT

Price \$65,000**Depreciation** \$7,990 /yr**Reg Date** 11-Oct-2007
(8yrs 1mth 18days COE left)**Mileage** N.A.**Manufactured** 2007**Road Tax** \$2,160 /yr**Transmission** Auto**Dereg Value** \$41,066 as of today (change)**OMV** \$36,637**COE** \$50,451**ARF** \$40,301**Engine Cap** 2,500 cc**Power** 153.0 kW (205 bhp)**Curb Weight** 1,625 kg**No. of Owners** 4**Type of Vehicle** Luxury Sedan**Features**

2.5L V6 Dual VVT-I Engine, 6 Speed Auto, Paddle Shifters, Push Start, Keyless, Cruise Control, Rear Aircon, Electric Seats. View specs of the [Lexus IS250 \(2006-2013\)](#)

Accessories

New Audio Control Panel & Amp, Multi Function Steering, Reverse Sensor/Cam, 19" Vertini Rims, F-Sport BBK, V Vision Bodykit, Upgraded Head & Taillights

Description


100% Stock Unit With Over \$25K Worth Of Accessories! View To Believe! New Headlights! Brand New Gearbox Replaced With Ongoing Warranty! Car's Driven With Utmost Care And Maintained In Good Condition. Regular Servicing Done. Trade In And High Loans Available, Contact Us Now For Viewing Arrangement!

Category

COE Car, Premium Ad Car

Status

Available

Resources**Car Valuation - Free**Find out the market value of your existing car for free. [Get started](#)[Compare](#)

Location Map

[Shortlist](#)[Compare](#)[Add note](#)[Report Error](#)[More Actions](#)**Seller Information****Company****Monster Motors Pte Ltd**

» dealer's pricelist

» 78 vehs sold | 151 vehs available

Address

453 Tagore Industrial Avenue #01-02

[Search cars nearby this location](#)**Location**

Sindo Industrial Estate

Websitewww.monstermotors.com.sg**Contact Person (s)**Sindy
Daryl96777794
96804425

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC

Owner ID: 482F

Vehicle Details

Vehicle No.: SKC9006D

Vehicle to be Exported: No

Intended Deregistration Date: 22 Aug 2019

Vehicle Make: TOYOTA

Vehicle Model: LEXUS IS250 AUTO STD

Primary Colour: Grey

Manufacturing Year: 2007

Engine No.: 4GR0388040

Chassis No.: JTHBK262805053313

Maximum Power Output: 153.0 kW (205 bhp)

Open Market Value: \$36,637.00

Original Registration Date: 18 Oct 2007

First Registration Date: 18 Oct 2007

Transfer Count: 4

Actual ARF Paid: \$40,301.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 17 Oct 2027

COE Category: E - Open Category

COE Period(Years): 10

PQP Paid: \$50,451.00

COE Rebate Amount: \$41,123.00

Total Rebate Amount: \$41,123.00

The information contained herein is correct as at 22 Aug 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	15/08/2019 16:19
Date Of Accident	14/08/2019 20:00
Exact Location Of Accident	TOA PAYOH LOR 6
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKC9006D
Insured/Policyholder	
Name Of Registered Owner	LAM CHOON BENG
NRIC No	S7246482F
Email Address	LAMALAN.BV@GMAIL.COM
Mobile Phone No	(LOCAL) +65-96897996
Alternative Phone No	OFFICE-NOPHONE

Vehicle Particulars

Manufacturer	LEXUS
Model	IS250
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA457705
Cover Note Number	

Driver

Name of Driver	LAM CHOON BENG
NRIC No	S7246482F
Date Of Birth	12/12/1972
Occupation	INDOOR
Date Of Driving Pass	13/02/1993
Driving Experience	26 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96897996
Fax Number	
Contact Number	OFFICE-NOPHONE
EMail Address	LAMALAN.BV@GMAIL.COM

Address	BLK 3 QUEEN'S ROAD #12-171
Postcode	260003
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : TEO CHIN LING GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLT4697R
Vehicle Make/Model/Colour	MAZDA 3
Details Of Properties	FRONT BUMPER
Vehicle Category	PRIVATE HIRE
Name of Driver	KUMAR S/O SELVARAJ
NRIC/Passport Number	S1622741B
Contact Number	
Address	BLK 226B ANG MO KIO AVENUE 1 #02-643
Postcode	562226
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time:

15/1/2019
1506hrs

Driver's Signature

(If driver is not the policyholder)

Date & Time:

15/1/2019
1506hrs

Reporting Centre Personnel's Signature


Name: Anna

NRIC/FIN No.:

Sketch Plan #2

TOA PAYOH LCR 6

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 14 August 2019, at about 2000 hrs I was travelling along Toa Payoh Lor 6 approaching a traffic light front while slowing down as I was approaching a red traffic light. Suddenly a car MA2DA 3, SLT 4697R hit my right rear of my car while making an abrupt lane change.

We stopped our vehicle immediately and he decided to make a claim for from his insurance. Nobody was injured during the accident.

That is all.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time: 15/08/2019

GA/DMC SketchPlanForm_V3 1520hrs

Driver's Signature
(If driver is not the policyholder)
Date & Time: 15/08/2019

1520hrs

Reporting Centre Personnel's Signature
Name: Anna
NRIC/FIN No.:

FASTECH AUTO PTE LTD
BLK1 KAKI BUKIT AVE 6
#01-46,48,50 AUTOBAY
SINGAPORE 417883

Not Authorized
LKK
22/8/18 4dy.
4/s 4000

VEHICLE NO :SKC 9006D

QTY	PARTICULAR
1 PCS	REAR DOOR O/S 1255.10
1 PCS	REAR DOOR INNER LOCK O/S
1 PCS	REAR DOOR INNER RUBBER O/S 245.30
1 PCS	REAR DOOR INNER TRIM BOARD O/S
1 PCS	REAR DOOR GLASS REGULATOR
1 PCS	REAR FENDER O/S
1 PCS	REAR FENDER UNDER COVER O/S 299.20
1 PCS	REAR WINDSCREEN MOULDING
1 PCS	REAR BUMPER 855.10
1 PCS	REAR BUMPER SIDE REPAIR O/S
1 SET	REAR BUMPER CLIPS
1 PCS	REAR SHOCK ABSORBER O/S
1 PCS	REAR WHEEL HUB BEARING O/S
1 PCS	REAR KNUCKLE ARM O/S
1 PCS	ROCKER PANEL garnish o/s
1 PCS	REAR SPORT RIM O/S
1 PCS	REAR TYRE O/S

22/8/18	\$1,899.10	✓
11	\$350.00	X
11	\$266.00	✓
11	\$1,049.30	X
11	\$311.00	X
11	\$1,455.10	X
11	\$311.20	✓
11	\$122.50	X
11	\$1,066.10	✓
11	\$151.00	X
11	\$50.00	✓
11	\$392.50	X
11	\$566.50	X
11	\$1,265.10	X
11	\$899.10	✓
11	\$1,050.00	580 s.w
11	\$200.00	602 120 s.w
	\$11,404.50	

LABOUR CHARGES
TO CHECK WIRING
TO DISMANTLE & REFIX REVERSE SENSOR
TO DISMANTLE & REFIX REAR WINDSCREEN
TO TRANSFER REAR DOOR COMPONENTS
TO CONDUCT WHEEL ALIGNMENT
TO DISMANTLE & REFIX REAR UNDERCARRIAGE
TO SPRAY RUST PROOFING
LABOUR FOR PANEL BEATING & REPLACING PARTS
TO PUTTY & SPRAY PAINTING

	\$80.00	20
	\$80.00	50
11	\$150.00	X
	\$100.00	60
	\$150.00	60
11	\$150.00	X
	\$80.00	40
	\$880.00	580
	\$1,500.00	800
TOTAL	\$14,574.50	

LKK Auto Consultants hence notify
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

1-3603-80
257
2702-85
5012-85
4010.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/MSG19014815/UQD3N2

Date: 18/09/2019

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	29114756
Claimant Vehicle No :	SKC9006D	Insured Vehicle No :	SLT4697R
Date of Loss:	14/08/2019	Nature of Claim:	TP
		Claim No:	602998

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKC9006D	Engine No:	4GR0388040
Make & Model:	TOYOTA LEXUS, 2.5 IS250 (A)	Chassis No:	JTHBK262805053313
Reg. Date:	18/10/2007 (Man. Year: 2007)	Odometer:	94458 km
Colour:	Grey		
Engine Capacity:	2500 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	11,404.50	3,402.85	8,001.65	70.16
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,170.00	1,610.00	1,560.00	49.21
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	14,574.50	5,012.85	9,561.65	65.61
Approved Total (Overridden) (\$\$)		4,000.00		
(\$\$)	14,574.50	4,000.00	10,574.50	72.55
+ GST 7.00/7.00% (\$\$)	1,020.22	280.00	740.22	72.55
Nett Amount (\$\$)	15,594.72	4,280.00	11,314.72	72.55

INSPECTION

Date of Assignment:	23/08/2019	
Date Inspected:	22/08/2019	Inspected At:
		Fastech Auto Pte Ltd (HQ)
		1 Kaki Bukit Ave 6, #01-46/48/50
		Autobay
		Singapore 417883
Estimated Period of Repair:	4.0 days	

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 18 Sep 2019)
Parts:	143	TOYOTA LEXUS 2.5 IS250 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKC9006D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR O/S	Dented/Bent	1,899.10 F	*1,255.10 FL
2	1		*REAR DOOR INNER LOCK O/S	Not Necessary	350.00 F	*- FL
3	1		*REAR DOOR INNER RUBBER O/S	Necessary	266.00 F	*245.30 FL
4	1		*REAR DOOR INNER TRIM BOARD O/S	Not Necessary	1,049.30 F	*- FL
5	1		*REAR DOOR GLASS REGULATOR	Not Necessary	311.00 F	*- FL
6	1		*REAR FENDER O/S	Repair	1,455.10 F	*- FL
7	1		*REAR FENDER UNDER COVER O/S	Torn	311.20 F	*299.20 FL
8	1		*REAR WINDSCREEN MOULDING	Not Necessary	122.50 F	*- FL
9	1		*REAR BUMPER	Deep Cut/Torn	1,066.10 F	*855.10 FL
10	1		*REAR BUMPER SIDE RETAINER O/S	Not Necessary	151.00 F	*- FL
11	1		*SET REAR BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
12	1		*REAR SHOCK ABSORBER O/S	Not Necessary	392.50 F	*- FL
13	1		*REAR WHEEL HUB BEARING O/S	Not Necessary	566.50 F	*- FL
14	1		*REAR KNUCKLE ARM O/S	Not Necessary	1,265.10 F	*- FL
15	1		*ROCKER PANEL GARNISH O/S	Warped/Deformed	899.10 F	*899.10 FL
16	1		*REAR SPORT RIM O/S	Warped	1,050.00 FS	*580.00 FS
17	1		*REAR TYRE O/S (60%)	Cut	200.00 FS	*120.00 FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (\$\$)	11,404.50	4,303.80
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	900.95
Total Parts (\$\$)	11,404.50	3,402.85

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	80.00	20.00
2	TO DISMANTLE & REFIX REVERSE SENSOR	New	80.00	50.00
3	TO DISMANTLE & REFIX REAR WINDSCREEN	New	150.00	0.00
4	TO TRANSFER REAR DOOR COMPONENTS	New	100.00	60.00
5	TO CONDUCT WHEEL ALIGNMENT	New	150.00	60.00
6	TO DISMANTLE & REFIX REAR UNDERCARRIAGE	New	150.00	0.00
7	TO SPRAY RUST PROOFING	New	80.00	40.00
8	LABOUR FOR PANEL BEATING & REPLACING PARTS	New	880.00	580.00
9	TO PUTTY & SPRAY PAINTING	New	1,500.00	800.00
Gross Labour Cost (S\$)			3,170.00	1,610.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >