

108/11/13

Surveyor: Kelvin

REF:

NS/INC 19014817/K9sf3SV

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TPRES/ODRES/EVA/INV/MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: SJH 5186D

Policy No: 5102012658-01 (12/08/2019-11/08/2020)

Claims No: MT/1059829-001

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHD 3625L Yr Regn: 20 Sep, 2017

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Prius c.c. 1798

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 29143 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: J70KB3F4003564244

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / Rim or

Tyre Size: F: 195/65 R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Danti

Front Rear

R/Bal. 7 mm R/Bal. 7 mm

L/Bal. 7 mm L/Bal. 7 mm

D.O.A. 22/8/19 D.O.I. 22/8/19

Survey held at C/DGE (Loyang)

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear d/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	SJH 5186D : X INC
	SHD 3625L (53/1111801689/12463-2 D.O.A. 22/08/2019) P/P
28/8/19	Control P/P \$1266.93 / 2 P/P.
	(466.92 Red - 35%)

Date/Time, File Pass to?

29/08/19

1) Type

Date/Time, File Return to?

2) _____

☐ : Prel. Report☒ : Final Report

Days Of Repair: 2

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)

Survey Fee:

Transportation:

S + RS, SI

Photos

\$1,266.93 AP

TP Claims against NTUC Income: Follow-Through Survey

Date : 28/08/2019

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	Date of Accident	Estimate
1	MT/1058784-002	COMFORT TRANSPORTATION PTE LTD	SHC2223A	SJR9200S	21/08/2019	\$ 2,251.93
2	MT/1058925-002	CITYCAB PTE LTD	SHA233U	SKV8847A	21/08/2019	\$ 2,602.64
3	MT/1059829-001	COMFORT TRANSPORTATION PTE LTD	SHD3625L	SIH5186D	22/08/2019	\$ 1,933.85
4	MT/1059135-002	COMFORT TRANSPORTATION PTE LTD	SHA4719J	SJR7693R	22/08/2019	\$ 4,284.75
5	MT/1058712-002	COMFORT TRANSPORTATION PTE LTD	SH7169J	SHC6321Z	20/08/2019	\$ 9,545.63
6	MT/1059834-001	COMFORT TRANSPORTATION PTE LTD	SHC1574T	SLE3769C	23/08/2019	\$ 2,011.18

Claim received from LKK Auto

eBaoTech

General Claim

Hello, NAC_PAYA_UBI_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)

Policy Query

Policy No.	<input type="text"/>	Date of Accident	<input type="text" value="22/08/2019 08:29"/>
Vehicle No. (For Motor)	<input type="text" value="SJH5186D"/>	Certificate Number	<input type="text"/>
<input type="button" value="Search"/>			

Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input type="checkbox"/>	5102012658-01		A ESWARAN REDDIAR	S8330027B	GPC	drive CLASSIC	SJH5186D	SJH5186D	12/08/2019	11/08/2020
<input type="button" value="Continue"/>										

COMFORTDELGRO ENGINEERING

A member of COMFORTDELGRO

ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701

Mainline + 65 6383 8280 Facsimile + 65 6260 9756

Workshops

59 Loryang Drive Singapore 508969

383 Sin Ming Drive Singapore 575717

45 Pandan Road Singapore 609286

200 Loke Road 3 Singapore 639242

24 Senoko Loop Singapore 758156

7 Sungai Kadut Way Singapore 728791

501 Yishun Industrial Park A Singapore 7687

Date/Time: 22.08.2019 13:33

Page : 1

Team: ARC Repair TP(CLS0)1

JOB CARD

Sales Order:

JC NO.: 305326668

CUSTOMER

R/M/S COMFORT TRANSPORTATION PTE LTD

CUSTOMER NO. 7010045

ADDRESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717

TEL (R) 65508755

(O)

(P)

DISCOUNT CARD NO.

REGN NO.:

SHD3625L

MILEAGE

MAKE :

TOYOTA

FUEL

E.....1/2.....F

MODEL

PRIUS HYBRID(G4) 22.08.2019 07:55

DATE/TIME IN

YR OF MANU

20.09.2017

TARGET DATE

CHASSIS CODE

JTDKB3FU003564244

COMPLETION DATE/TIME:

JOB DESCRIPTION


Accident Date: 22.08.2019

NATURE: 3P 22.08.2019

S/NO

LABOR CODE

DESCRIPTION



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Signature

Vehicle No.:

Vehicle No.:

SHD3625L

LKE

Exit Pass

Vehicle No.:

SHD3625L

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	22/08/2019 11:19
Date Of Accident	22/08/2019 00:10
Exact Location Of Accident	BLK 260A PUNGGOL WAY SVC RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD3625L
-----------------------------	----------

Insured/Policyholder

Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFTY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	MCOM0015
Cover Note Number	

Driver

Name of Driver	LAW PICK YEW STEVEN
NRIC No	S8131450J
Date Of Birth	05/10/1981
Occupation	OUTDOOR
Date Of Driving Pass	21/03/2001
Driving Experience	18 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91257116
Fax Number	
Contact Number	
Email Address	TANABE97@HOTMAIL.COM

Address	289A 14-889 PUNGGOL PLACE
Postcode	821289
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
POLICE STATION NAME [OTHER]	PUNGGOL NPC
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

SEE POLICE REPORT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1


Vehicle Registration Number	SJH5186D
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	NOT SURE
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	LAW PICK YEW STEVEN
Approximate Age	38
Injuries Sustain	KNEES,LEFT ANKLE,NECK,SHOULDER
Injured person in which vehicle?	SHD3625L
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

Sketch Plan Pg. 1

SKETCH PLAN



RTK
260A
Ringgo Way
Sea Road

A) SHD 3625L
B) SJH 5186 D

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer Police Report - T/20190822/2011

DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE. LTD.
CO. REG. NO. T8801521K

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



**SINGAPORE
POLICE FORCE**



T/20190822/2011

Police Station Of Origin:
Punggol N.P.C
21A Tebing Lane SINGAPORE 828837
Tel No: 1800-6049999

1 of 4

Report No. T/20190822/2011

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 22/08/2019 05:46		Vide Report No.: F/20190822/0002		Station Diary No.: 21	
Informant's Particulars					
Name of Informant: LAW PICK YEW STEVEN			Address: APT BLK 289A PUNGGOL PLACE #14-889 SINGAPORE 821289		
ID Type / ID No.: NRIC NO / S8131450J			Contact No.: Home/Office: Mobile: 91257116		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 37	Date of Birth: 05/10/1981	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: Taxi driver			Driving Licence Information: Class: 2B,3 Date of Expiry:		

General Information of the Accident

Type of Accident:	Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 22/08/2019 00:10	Type of Location: Service Road
Location: Along Road 1 PUNGGOL WAY Blk 260A Punggol Way Service Road				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: Two Way		Traffic Control: Not Controlled		Traffic Volume:
Type of Collision: Moving Vehicle Against - Parked Vehicle				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SHD3625L	Taxi				Slightly Damaged	0
SJH5186D	Car					0

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20190822/2011

Police Station Of Origin:
Punggol N.P.C
21A Tebing Lane SINGAPORE 828837
Tel No: 1800-6049999

2 of 4

Report No. T/20190822/2011

CONTINUATION OF REPORT

Driver			
Name	LAW PICK YEW STEVEN	ID No.	S8131450J
Related Vehicle	SHD3625L (Taxi)	Contact No.	91257116
Hospital/Clinic	MOUNT ALVERNIA HOSPITAL	Class of Driving Licence & Expiry Date	Class: 2B,3 Date of Expiry: NIL
Date Treatment	22/08/2019	Date Discharge	22/08/2019
No. of Days granted Medical Leave	05	Degree of Injury	Slight

Brief Details.

On 22/08/2019 at 0000hrs, I was driving my taxi bearing registration number SHD3625L along Punggol Central towards Punggol East. As I reached the junction of Punggol Central and Punggol Place, I performed a U-Turn and after I completed the U-Turn I heard a horn and notice from my rear view mirror a vehicle bearing registration number SJH5186D approaching from the opposite direction at high speed. I was already travelling quite a distance after the U-turn. There was another vehicle behind me that managed to perform a U-Turn as well. Subsequently I stopped my vehicle at a signalised pedestrian crossing along Punggol Central towards Sumang Walk near to the bus interchange. The driver stopped his vehicle behind and subsequently moved to my left. He then gestured at me after winding down his window. I also wind down my windows to understand what he was talking about and asked if his horn was intended for me. The other driver informed that the horn was for me and asked me if I knew how to drive or not. He also gestured his hands towards me. He was then mumbling and I could not make it what he was talking about. Both of us then continued moving straight after the lights turned green.

Our vehicles came a stop at the next junction again and I requested for the driver to stop by the side to have further conversation as I suspected that he was drink driving due to his mumbling. The driver agreed and I was about to stop by the side when I realised the other driver did not stop. I then followed the other driver all the way to Blk 260A Punggol Way. The reason I followed the driver was that I suspected that he was drink driving from the way he was mumbling and also the way he drove off after agreeing to stop his vehicle by the side. I parked my vehicle parallel to the left side of the curb. I did not alight immediately as I noticed the driver talking to another male indian subject. At this point of time, I also started calling for assistance via 999. I then noticed the driver going back to his vehicle and wanting to perform a 3 point-turn. I then shifted my vehicle to park it horizontal to the left of the curb blocking the driver from leaving. The driver then exited his vehicle and approached me while I was still seated in my vehicle. I wind down my window and spoke to the driver. While speaking to the driver, I noticed the driver reeked strongly of alcohol was seen to mumble. The driver then returned to his vehicle and tried to squeeze in between my vehicle and the left curb. The driver reversed and I exited from my vehicle to make a check on my taxi and also to take a video footage using my mobile phone. I then observed the other vehicle's front left portion collided in to the right rear portion of my vehicle.

I then tried to stand in front of the said vehicle to block the driver from leaving however the driver accelerated and the front portion collided in to my knee area. I wish to state that the reason I stood in front of the said vehicle was due to my taxi being hit and I needed him to stay at scene first. I then jumped out of the driver's way to avoid getting hit any further. The driver drove away after I stepped out of the way. The driver appeared to be a male indian in his 30s. The incident where he hit me and my taxi was captured on my mobile phone camera. I was advised by the police officers to lodge a report. I have



**SINGAPORE
POLICE FORCE**



T/20190822/2011

Police Station Of Origin:
Punggol N.P.C
21A Tebing Lane SINGAPORE 828837
Tel No: 1800-6049999

3 of 4

Report No. T/20190822/2011

CONTINUATION OF REPORT

since seek treatment at Mount Alvernia Hospital as I was injured on both knees, left ankle, left neck and left shoulder. I was discharged on the same day. I was given 5 days of MC.



**SINGAPORE
POLICE FORCE**



T/20190822/2011

4 of 4

Police Station Of Origin:
Punggol N.P.C
21A Tebing Lane SINGAPORE 828837
Tel No: 1800-6049999



Report No. T/20190822/2011

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report: F / Staff Sgt MUHAMMAD AQIB BIN MOHAMMAD AKHTAR	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 22/08/2019 05:46
Officer In Charge Of Case: TP / HRT / Sr Staff Sgt IRMAN BIN MOHAMAD SAID Contact No.: 65476145	Classification Of Case:  5N 6c5
Authentication Stamp NP168	



**SINGAPORE
POLICE FORCE**



F/20190822/2012

1 of 3

POLICE REPORT (NP299)

Report No. F/20190822/2012

Police Station Of Origin
Punggol N.P.C
21A Tebing Lane SINGAPORE 828837
Tel No: 1800-6049999


Date/Time Report Made 22/08/2019 05:17		Vide Report No. F/20190822/0002		Station Diary No. 5	
Name Of Informant LAW PICK YEW STEVEN		Address APT BLK 289A PUNGGOL PLACE #14-889 SINGAPORE 821289			
ID Type / ID No. NRIC NO / S8131450J		Contact No. Home/Office Mobile 91257116			
Nationality SINGAPORE CITIZEN		Email Address			
Occupation Taxi driver		Sex Male	Age 37	Date of Birth 05/10/1981	Race Chinese
Institution/School Name		Language			
Date/Time Of Incident 22/08/2019 00:10		Location Of Incident APT BLK 260A PUNGGOL WAY PUNGGOL TOPAZ SINGAPORE 821260 Service Road			

Brief details.

On 22/08/2019 at 0000hrs, I was driving my taxi bearing registration number SHD3625L along Punggol Central towards Punggol East. As I reached the junction of Punggol Central and Punggol Place, I performed a U-Turn and after I completed the U-Turn I heard a horn and notice from my rear view mirror a vehicle bearing registration number SJH5186D approaching from the opposite direction at high speed. I was already travelling quite a distance after the U-turn. There was another vehicle behind me that

Signature Of Officer Recording The Report: F / Staff Sgt MUHAMMAD AQIB BIN MOHAMMAD AKHTAR	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 22/08/2019 05:17
Officer In-Charge Of Case: F / Ang Mo Kio Police Divisional Investigation Branch / Sgt 1 LEONG GHUM WAI Contact No.: 62180000	Classification Of Case:

Authentication Stamp





**SINGAPORE
POLICE FORCE**



F/20190822/2012

2 of 3

POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. F/20190822/2012

managed to perform a U-Turn as well. Subsequently I stopped my vehicle at a signalised pedestrian crossing along Punggol Central towards Sumang Walk near to the bus interchange. The driver stopped his vehicle behind and subsequently moved to my left. He then gestured at me after winding down his window. I also wind down my windows to understand what he was talking about and asked if his horn was intended for me. The other driver informed that the horn was for me and asked me if I knew how to drive or not. He also gestured his hands towards me. He was then mumbling and I could not make it what he was talking about. Both of us then continued moving straight after the lights turned green.

Our vehicles came a stop at the next junction again and I requested for the driver to stop by the side to have further conversation as I suspected that he was drink driving due to his mumbling. The driver agreed and I was about to stop by the side when I realised the other driver did not stop. I then followed the other driver all the way to Blk 260A Punggol Way. The reason I followed the driver was that I suspected that he was drink driving from the way he was mumbling and also the way he drove off after agreeing to stop his vehicle by the side. I parked my vehicle parallel to the left side of the curb. I did not alight immediately as I noticed the driver talking to another male indian subject. At this point of time, I also started calling for assistance via 999. I then noticed the driver going back to his vehicle and wanting to perform a 3 point-turn. I then shifted my vehicle to park it horizontal to the left of the curb blocking the driver from leaving. The driver then exited his vehicle and approached me while I was still seated in my vehicle. I wind down my window and spoke to the driver. While speaking to the driver, I noticed the driver reeked strongly of alcohol was seen to mumble. The driver then returned to his vehicle and tried to squeeze in between my vehicle and the left curb. The driver reversed and I exited from my vehicle to make a check on my taxi and also to take a video footage using my mobile phone. I then observed the other vehicle's front left portion collided in to the right rear portion of my vehicle.

Signature Of Officer Recording The Report:

F / Staff Sgt MUHAMMAD AQIB BIN MOHAMMAD AKHTAR

Signature Of Interpreter:
Not applicableOfficer In-Charge Of Case:
F / Ang Mo Kio Police Divisional Investigation Branch /
Sgt 1 LEONG GHUM WAI
Contact No.: 62180000

Signature Of Informant:

Date/Time:
22/08/2019 05:17

Classification Of Case:

Authentication Stamp



**SINGAPORE
POLICE FORCE**



F/20190822/2012

3 of 3

POLICE REPORT (NP299)


CONTINUATION OF REPORT


Report No. F/20190822/2012

I then tried to stand in front of the said vehicle to block the driver from leaving however the driver accelerated and the front portion collided in to my knee area. I wish to state that the reason I stood in front of the said vehicle was due to my taxi being hit and I needed him to stay at scene first. I then jumped out of the driver's way to avoid getting hit any further. The driver drove away after I stepped out of the way. The driver appeared to be a male indian in his 30s. The incident where he hit me and my taxi was captured on my mobile phone camera. I was advised by the police officers to lodge a report. I have since seek treatment at Mount Alvernia Hospital as I was injured on both knees, left ankle, left neck and left shoulder. I was discharged on the same day. I was given 5 days of MC.

Signature Of Officer Recording The Report: F / Staff Sgt MUHAMMAD AQIB BIN MOHAMMAD AKHTAR	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 22/08/2019 05:17
Officer In-Charge Of Case: F / Ang Mo Kio Police Divisional Investigation Branch / Sgt 1 LEONG GHUM WAI Contact No.: 62180000	Classification Of Case:

Authentication Stamp





COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

VEHICLE NO: SHD 3625L

22/8/2019 14:41

MAKE :

MODEL : TOYOTA PRIUS

Ukr/Kalvin phy P
 NTUC

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT
REAR BUMPER <i>Detail</i>			\$ 458.60
REAR BUMPER UNDER COVER <i>all</i>			\$ 552.60
REAR BUMPER SIDE RETAINER <i>all</i>			\$ 112.70
REAR BUMPER TOWING COVER <i>missing</i>			\$ 82.70
REAR BUMPER CLIPS <i>all</i>			\$ 22.00
RETAINER, REAR BUMPER, SIDE, RH <i>X replace</i>			\$ 94.80
SEAL, REAR BUMPER SIDE, RH <i>X repair</i>			\$ 148.40
SUB TOTAL			\$ 1,471.80
LESS 25%			\$ 367.95
DISCOUNTED TOTAL			\$ 1,103.85
LABOUR CHARGE			
Panel Beating			\$ 400.00 ²⁰⁰
Spray Painting Charge			\$ 300.00 ²⁰⁰
Wiring Charge			\$ 50.00 ^X
Remove/Refix Reverse Sensor			\$ 80.00 ²⁰
TOTAL LABOUR			\$ 830.00
ESTIMATE TOTAL			\$ 1,933.85

Kalvin (Ukr)

22/8/19 1505h

2 Pys.

P P

Before Part photo

the repairer is not responsible for any damage to the vehicle or its contents caused by the repairer or his employees or agents.

- To display on the repairer's premises a copy of this survey
- Parts prices are subject to change without notice
- Third party modification(s) is allowed
- No illegal modification(s) must be resurveyed on
- Supplementary item(s) must be resurveyed on
- is subject to final approval from insurance company

Acknowledged by Repairer
 Signature:
 Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Our Job Ref No 305326668

Date : 27.08.19

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : Mr KALVIN ANG

Vehicle Reg No. SHD3625L CTPL

22.08.19

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: NTUC SJH5186D
2. The finalized amount shall be:
 - (a) Spare Parts after List discount \$836.93
 - (b) Labour Charges \$430.00
 - Total for Part-By-Part Repair Cost** \$1266.93
 - (c) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: 20%
Final Lumpsum Repair cost

3. Estimated normal period for repairs: 2 working days.
4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Name : LIM KWOK ENG

Tel : 62148316

Fax : 65468156

Signature : 

Name : KALVIN

Date : 28/8/19

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
4. LTA Search Fee	\$7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 27.08.2019

Time: 10:50:06

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305326668
REGN NO : SHD3625L
MILEAGE : 0000000000
MAKE : TOYOTA
MODEL : PRIUS HYBRID(G4)
DATE OF REGN : 20.09.2017
DATE/TIME IN : 22.08.2019 07:55
ACCIDENT DATE : 22.08.2019

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0302-2282-G	PRIG4 COVER REAR BUMPER	1 L	458.60	25.00	343.95
0002 04-01-0302-2287-G	PRIG4 GUARD-REAR BUMPER C	1 L	552.60	25.00	414.45
0003 04-01-0302-1150-A	PRIG4 BUMPER PROTECTOR MA	1 N	50.00	2.50-	50.00 X
0004 04-01-0302-2286-G	PRIG4 COVER REAR BUMPER-T	1 L	82.70	25.00	62.02
0005 04-01-0302-2267-G	PRIVC BUMPER PIECE	10 L	22.00	25.00	16.50

SUB-TOTAL : 886.92

JOB NATURE

300 L	PANEL BEATING	200.00
0001 23-502	SPRAYPAINT ON AFFECTED AREA	200.00
0002 20-22	REMOVE/REFIX REVERSE SENSOR	30.00

SUB-TOTAL : 430.00

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 27.08.2019

Time: 10:50:06

Page: 2

COMPANY : THIRD PARTY'S CLAIMS (CAS)

CUSTOMER: 7010045

ADDRESS : COMFORT TRANSPORTATION PTE LTD

383 SIN MING DRIVE

SINGAPORE SINGAPORE 575717

65508755

JOB NO : 305326668

REGN NO : SHD3625L

MILEAGE : 0000000000

MAKE : TOYOTA

MODEL : PRIUS HYBRID

DATE OF REGN : 20.09.2017

DATE/TIME IN : 22.08.2019 07:5

ACCIDENT DATE : 22.08.2019

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

TOTAL : 1,316.92

MVA NAME & SIGNATURE

DATE :

AUTHORISED : YES / NO

SURVEYOR NAME & SIGNATURE

DATE :

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.: 1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 3625L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	DEFORMED	458.60	458.60
1	REAR BUMPER UNDER COVER	CRACKED	552.60	552.60
1	REAR BUMPER SIDE RETAINER	SERVICEABLE	112.70	-
1	REAR BUMPER TOWING COVER	MISSING	82.70	82.70
10	REAR BUMPER CLIPS	NECESSARY	22.00	22.00
1	RETAINER, REAR BUMPER SIDE, RH	SERVICEABLE	94.80	-
1	SEAL, REAR BUMPER SIDE, RH	TO REPAIR SEE LABOUR	148.40	-
	LESS 25% DISCOUNT		-367.95	-278.97
			1,103.85	836.93
	<u>LABOUR</u>			
	PANEL BEATING, INCLUSIVE OF THE REPAIR OF SEAL, REAR BUMPER SIDE, RH.		400.00	200.00
	SPRAY PAINTING CHARGE.		300.00	200.00
	WIRING CHARGE.	NOT NECESSARY	50.00	-
	REMOVE/REFIX REVERSE SENSOR.		80.00	30.00
			830.00	430.00
	GRAND TOTAL		1,933.85	1,266.93
RECOMMENDED COST OF REPAIRS (CONFIRMED)				1,266.93

Report Ref No. NS/INC19014817/K1sf3s2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

K.K. LAU CPT(RET)BEng(Hons), B.Bus, MBA, PEng, PE,
MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC19014817/K1sf3s2

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE Date: 03-09-2019

189556



Code: INC4

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJH 5186D	Veh. Inspected	SHD 3625L
Policy No.	5102012658-01	Coverage (\$)	0.00
Claim No.	MT/1059829-001	Excess (\$)	0.00
Assign From		Assign Date	22/08/2019

2. Vehicle Particulars & Condition

Make & Model	TOYOTA PRIUS	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JTDKB3FU003564244	Colour	BLUE
Odometer	291943	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	DAVANTI	7 mm
L/H Front Tyre	195/65 R15	DAVANTI	7 mm
R/H Rear Tyre	195/65 R15	DAVANTI	7 mm
L/H Rear Tyre	195/65 R15	DAVANTI	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	22/08/2019	Inspection Date	22/08/2019
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	2 Working Days
-------------------------------------	----------------