

22/03/2002

ASS. REC. BY:

REF:

CS/MSG19014832/Dgfsor

Special Instruction:

Surveyor: Bryan

ASSIGNMENT (Office)

From (Person): Ong Zi Hui

of

MSIG

Date/Time: 22.8.19 4.49p.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FU 3246G

Insured:

SKS 6749D

at Workshop m/s

SG 98 motor

Tel:

64524898

of

Blk 4001 #01-21

Policy No:

A29121094AV2

Claim No:

603343

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 18.8.2019

CA / REV / REP. / REV 24 HRS

my

H.O.D. Endorsement:

Date/Time:

23.8.19

11.30a.m

Person Contacted:

Leena

Vehicle: IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	FU 3246G : 447/AIG12012040/Cm1up1 D.O.A. 14/06/2012
	SKS 6749D : X
28/8/19 @ 5.16pm	revised to Ong Zi Hui via Merimen.

REF:

ASSIGNMENT

CDB 2021 Nov

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.: Yes or No

Lump Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

FU 3246G

Yr Regn:

Jan 2002

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Kawasaki KRRZX150 148

Colour:

Blue

A/C:

Insured / Std / NI / NA

Sp. Reading:

38220

T/Radio:

Insured / Std / NI / NA

Eng/No:

KR150EEA54381

C/No:

KR150KA54381

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / SRim / STD A/Rim or

Tyre Size:

F:

70/90 R17

R:

80/90 R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Maxxis

Front

Rear

R/Bal.

3

mm

R/Bal.

3

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

18/08/2019

D.O.I.

23/08/2019

Survey held at

SG 98

AMK

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Body y 8/8 Body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

MSG SKS 6749D

MV 4.5K

LIA 470.00

NL 4K

RECEIVED 22 NOV 2019

22/11/2019

Invoice 2/5 3000/- in 4 days 7ra
 (led @ 2487.50, 45%)

Date/Time, File Pass to?



Preli. Report

1) 24/11/2019



Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Report Format :

Lump Sum / I.P.I. (\$

MER-TP

3000

Survey Fee:

Transportation:

S + R5, 50

Photos:

Others:

TOTAL:

190

11

161

SG 98 MOTOR PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622

Tel: 6452 4898 Fax: 6452 4868

Email: sg_motor_enterprise@yahoo.com.sg

Date: 22 August 2019

To : LKK

By Fax: 6256-4315

Attn :

Tel :

VEHICLE NO : FU 3246G

Kawasaki KRRZX 150

ACCIDENT DATE: 18 August 2019

Description	Qty	Quotation \$
1 Front Mudguard <i>new</i>	1	190.00 X
2 Front Cowling <i>cut</i>	1	260.00 ✓
3 Visor <i>broken</i>	1	150.00 ✓
4 Handle Bar LH <i>new</i>	1	155.00 X
5 Clutch Lever <i>cut</i>	1	65.00 ✓
6 Fuel Tank <i>Detached</i>	1	320.00 550.00 ✓
7 Front LH Fairing - Centre <i>cut/broken</i>	1	190.00 ✓
8 Front Signal L/RH <i>o/s new m/s broken</i>	2	180.00 90.00 ✓
9 Cover Set Bolt <i>new/cut</i>	10	30.00 ✓
10 L/H Rear Tail Panel <i>broken/dislodged</i>	1	160.00 ✓
11 Rear Centre Panel <i>broken</i>	1	180.00 ✓
12 Fork Tube <i>2. distarter</i>	1 set	550.00 ✓
13 Fork Oil Seal <i>2 new</i>	2	90.00 ✓
14 Fork Under Bracket <i>2 distarter</i>	1	250.00 ✓
15 Front Centre Guard - Lower <i>crack</i>	1	250.00 ✓
16 Rear Tail Lamp <i>new</i>	1	155.00 X
17 Front Rim <i>new</i>	1	380.00 X

Sub-Total 3,555.00

Less 10% 355.50

Sub-Total 3,199.50

(18) Rear Exhaust Pipe *cut* 350.00 ✓

(19) Rear ~~left~~ tail Panel *crack* ~~180.00~~ 160.00 ✓
right

20) Front RH Fairing *crack* 190.00 ✓

21-) Front inner panel *crack* 150.00 ✓

3665.00

3298.50

VEHICLE NO : FU 3246G

Kawasaki KRRZX 150

Nett items

1	Rear number plate <i>BT</i>	18.00	✓
2	Towing fee <i>NH</i>	40.00	X
3	Remove & replace necessary parts, align & etc	280.00	200/-
4	Remove & replace fork assy, fork oil seal & top up fork oil	180.00	80/-
5	Putty & respray paint work	550.00	200/-
6	Check wiring connections	80.00	30/-
		528.00	

7. front Tyre - \$150.00 *nett*
X

Sub-Total *NH* 1,148.00

Nett Total 4,347.50 *3826.50*
4/s 3000/-

NB: This estimate was made from a visual inspection only, any other damage parts or labour require when repair commences, we will advise you and submit supplementary item to you accordingly.

Kindly revert upon completion
Thank you

SG 98 MOTOR PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

23/08/19 @ 1730h

HA Andri

2/sun 4 days

2KK Andri

5181.50

5247.50
5482.50

Nivitha (LKK Auto)

From: Ong Zi Hui <zihui_ong@sg.msig-asia.com>
Sent: Thursday, 22 August 2019 4:49 PM
To: assignments@lkkauto.com; admin-d@lkkauto.com
Cc: Crystal Lee
Subject: Survey Request - Manual Assigned

Please arrange PRI on bike FU3246G DOA: 18/08/19 SKS6749D (MSIG)

Manual Assigned

Dear LKK

Refer to the email below, please survey the vehicle.

We'll assign via Merimen once we receive the assignment from Motor Team.

Please contact us ASAP if you cannot attend this assignment

Thank you.

Ong Zi Hui
Admin Officer, Claims Services
D: +65 6643 1320 | F: +65 6225 7402 | zihui_ong@sg.msig-asia.com



MSIG

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: Helene Phua
Sent: Thursday, 22 August, 2019 4:11 PM
To: 'Sg Motor' <sgmotor2000@yahoo.com.sg>
Cc: Muhd Ashik B Madi <ashik_madi@sg.msig-asia.com>
Subject: RE: Please arrange PRI on bike FU3246G DOA: 18/08/19 SKS6749D (MSIG)

Hi Leena,

Thank you for your selection.

We will proceed to assign **LKK Auto Consultants Pte Ltd** via Merimen at our end and update you upon confirmation.

Please do not contact them directly to prevent confusion.

Please be informed that our surveyor will also be conducting a post repair inspection within the stipulated timeline under the protocol.

Have a great week ahead!

Helene Phua

Admin Assistant, Claims Services

D: +65 6594 2493 | F: +65 6225 7402 | helene_phua@sg.msig-asia.com



MSIG

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: Sg Motor [<mailto:sgmotor2000@yahoo.com.sg>]

Sent: Thursday, 22 August, 2019 2:05 PM

To: Helene Phua <helene_phua@sg.msig-asia.com>

Subject: Re: Please arrange PRI on bike FU3246G DOA: 18/08/19 SKS6749D (MSIG)

EXTERNAL EMAIL: Be careful when you click any links or open any attachment(s).

Please arrange for LKK Auto Consultants Pte Ltd to survey the bike.

Thank You

Regards
Leena

SG 98 Motor Pte Ltd

Blk 4001 #01-21

Ang Mo Kio Industrial Park 1

Singapore 569622

Tel: 64524898 Fax: 64526898

On Thursday, 22 August 2019, 11:51:48 am GMT+8, Helene Phua <helene_phua@sg.msig-asia.com> wrote:

Hi Leena,

We refer to your email dated 22/08/2019.

Please choose one surveyor from the list that you wish for us to appoint to conduct the pre-repair inspection:

- 1) LKK Auto Consultants Pte Ltd
- 2) Forinteam Consultancy Pte Ltd
- 3) Automobile Inspection Services Pte Ltd

4) STA Inspection Pte Ltd

5) MSIG In-House Surveyors

This Fast-Lane settlement option is for clear-cut liability which MSIG will expedite offer @ 100% with express payment. Priority will be given to those opted for our in-house surveyor

To facilitate an expeditious claim settlement, we hope you are agreeable for the above surveyor to be the SJE (Single Joint Expert).

If not, you may wish to nominate any of the 10 surveyors listed below as the SJE, depending on their availability:

1) Calvin Ang	6) Frankie Pang
2) Kenneth Kong	7) Ng You Han
3) Marcus Chua	8) Gary Soon
4) Henry Ng	9) Chow Bo Xiong
5) Lau Kwok Kwong	10) Axel Lee

NB:

(a) *Fast lane settlement is not applicable for cases that liability is in dispute*

(b) If both of us could not agree with each other's list of nominated SJE, we may still proceed to appoint a motor surveyor to conduct a pre repair survey & post repair inspection within the timeline stipulated under the NIMA protocol.

We have created a dedicated motor survey mailbox for your motor survey request and pre-repair inspection. Moving forward, please email your survey request to motorsurvey@sg.msiga-asia.com

Thank you.

Have a great week ahead!

Helene Phua

Admin Assistant, Claims Services

D: +65 6594 2493 | F: +65 6225 7402 | helene_phua@sg.msiga-asia.com



MSIG

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: Sg Motor <sgmotor2000@yahoo.com.sg>
Sent: Thursday, 22 August 2019 10:57 AM
To: Claims <claims@sg.msig-asia.com>
Cc: Sg Motor <sg_motor_enterprise@yahoo.com.sg>
Subject: Fw: Please arrange PRI on bike FU 3246G

EXTERNAL EMAIL: Be careful when you click any links or open any attachment(s).

Attn: Motor Claims Dept

Please arrange PRI as per attached

Thank You

Regards

Leena

SG 98 Motor Pte Ltd

Blk 4001 #01-21

Ang Mo Kio Industrial Park 1

Singapore 569622

Tel: 64524898 Fax: 64526898

Forwarded message -----

From: Sg Motor <sgmotor2000@yahoo.com.sg>
To: Motor Survey <motorsurvey@sg.msig-asia.com>
Cc: Sg Motor <sg_motor_enterprise@yahoo.com.sg>
Sent: Tuesday, 20 August 2019, 04:54:37 pm GMT+8
Subject: Please arrange PRI on bike FU 3246G

Attn: Claims Dept

Dear Sir/Madam

Please arrange PRI on bike FU 3246G.

Thank You

Regards

Linda

SG 98 Motor Pte Ltd

Blk 4001 #01-21

Ang Mo Kio Industrial Park 1

Singapore 569622

Tel: 64524898 Fax: 64526898

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Muhd Ashik B Madi

Date: 28 Aug 2019

Preliminary Advice

Insured Vehicle No	: SKS6749D	Accident Date	: 18/08/2019
TP Vehicle No	: FU3246G	Assignment Date	: 23/08/2019
Make	: KAWASAKI KRR ZX150 M	Est. Duration of Repair	: 4.00
Date of Inspection	: 23/08/2019		
Inspection At	: SG 98 MOTOR PTE LTD (HQ) BLK 4001 ANG MO KIO INDUSTRIAL PARK 1 #01-21 SINGAPORE 569622		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s & o/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,181.50
Revised Amount	:S\$	3,296.50
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,296.50

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	20/08/2019 19:36
Date Of Accident	18/08/2019 16:35
Exact Location Of Accident	EUNOS ROAD 8
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FU3246G
Insured/Policyholder	
Name Of Registered Owner	MUHAMMAD JUZAILI BIN JURIY
NRIC No	S9929039J
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-87498104
Alternative Phone No	OFFICE-87498104

Vehicle Particulars

Manufacturer	KAWASAKI
Model	KRR ZX150-148CC (M)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE

Insurance Company

Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	D19MTMC01005556
Cover Note Number	

Driver

Name of Driver	MUHAMMAD JUZAILI BIN JURIY
NRIC No	S9929039J
Date Of Birth	13/09/1999
Occupation	INDOOR
Date Of Driving Pass	21/06/2018
Driving Experience	1 YEAR AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-87498104
Fax Number	
Contact Number	OFFICE-87498104
Email Address	NOEMAIL

Address	BLK 23 BALAM ROAD #02-187
Postcode	370023
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CROSS JUNCTION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	MACPHERSON NEIGHBOURHOOD POLICE POST
Police Station Address	ROAD: BLK 54 PIPIT ROAD #01-82/84 , POSTCODE: 370054 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-7449999 - FAX NO: 65476366
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO THE POLICE REPORT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKS6749D
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	LINDA GUNARSO
NRIC/Passport Number	S7764307I
Contact Number	
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

Approximate Age

Injuries Sustain

Injured person in which vehicle? FU3246G

Were seat belts worn? NO

Was this injured conveyed to hospital by ambulance? NO

Address

Postcode

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 20/8/2019

6pm

Driver's Signature

(If driver is not the policyholder)

Date & Time:


Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to police report no: T/20190818/2163

✓

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time: 20/8/2019
6pm

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



SINGAPORE POLICE FORCE



T/20190818/2103

Police Station Of Origin:
MacPherson NPP
54 Pipit Road #01-82/84 SINGAPORE
370054
Tel No: 1800-7449999

1 of 4

Report No. T/20190818/2103

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 18/08/2019 20:21		Vide Report No.:		Station Diary No.: 42	
Informant's Particulars					
Name of Informant: MUHAMMAD JUZAILI BIN JURIY			Address: APT BLK 23 BALAM ROAD #02-187 SINGAPORE 370023		
ID Type / ID No.: NRIC NO / S9929039J			Contact No.: Home/Office: Mobile: 87498104		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 19	Date of Birth: 13/09/1999	Type of Informant: Rider		
Race: Malay			Language: English		Institution / School Name:
Occupation: PRODUCTION TEAM			Driving Licence Information: Class: 2B Date of Expiry:		

General Information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 18/08/2019 16:35	Type of Location: T-Junction
Location: Along Road 1 EUNOS ROAD 8				
Exact location Eunoss Rd 8 inside Yellow Box				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: Two Way		Traffic Control: Not Controlled		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FU3246G	Motorcycle	KAWASAKI	KRRZX150	Blue	Seriously Damaged	0
SKS6749D	Car	VOLKSWAGO N	"		Seriously Damaged	2

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
FU3246G	TENET SOMPO INSURANCE PTE. LTD.	D19MTMC0100555 6	09/07/2019	08/07/2020



SINGAPORE POLICE FORCE



T/20190818/2103

Police Station Of Origin:
MacPherson NPP
54 Pipit Road #01-82/84 SINGAPORE
370054
Tel No: 1800-7449999

2 of 4

Report No. T/20190818/2103

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Rider			
Name	MUHAMMAD JUZAILI BIN JURIY	ID No.	S9929039J
Related Vehicle	FU3246G (Motorcycle)	Contact No.	87498104
Hospital/Clinic	ACCESS MEDICAL (CIRCUIT ROAD)	Class of Driving Licence & Expiry Date	Class: 2B Date of Expiry: NIL
Date Treatment	18/08/2019	Date Discharge	18/08/2019
No. of Days granted Medical Leave	03	Degree of Injury	Slight
Driver			
Name	LINDA GUNARSO	ID No.	S7764307I
Related Vehicle	NIL	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 18/08/2019 at about 04:35PM, I was riding my bike FU3246G Kawasaki/Blue travelling along Eunos Rd 8 at the right lane. As I was maintaining at the said road, out of sudden one vehicle SKS6749D Volkswagen making a right turn towards Lifelong Centre Junction. The said driver stop the vehicle in the yellow box as the driver realized that the distance between me and the vehicle was very closed.

Immediately I applied my emergency break but could not stop in time and due to that accident happened as I hit onto her left front side bumper and I felt on the left side. A few passerby render assistance and I also realized that the driver did come out from the vehicle. I did seek assistance from a passerby to call for Traffic Police and ambulance which they did. Shortly after that the lady driver came out from the vehicle but she did approached about my condition. After which the lady driver husband came to the location and informed that to claim the matter through insurance.

Subsequently Traffic Police and ambulance attended to me. I wish to state that I did not conveyed to hospital but I did when to private clinic for further check up at B/88 Curcuit Road #01-965 (Access Medical). The doctor informed that I only suffered abrasion and swelled on my both legs. Doctor gave me 03 days Medical Leave from 19/08/2019 to 21/08/2019. Serial MC Chip: 2-529727



**SINGAPORE
POLICE FORCE**



T/20190818/2103

Police Station Of Origin:
MacPherson NPP
54 Pipit Road #01-82/84 SINGAPORE
370054
Tel No: 1800-7449999

3 of 4

Report No. T/20190818/2103

CONTINUATION OF REPORT



**SINGAPORE
POLICE FORCE**



T/20190818/2103

4 of 4

Report No. T/20190818/2103

Police Station Of Origin:
MacPherson NPP
54 Pipit Road #01-82/84 SINGAPORE
370054
Tel No: 1800-7449999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report: G / Sgt 3 MUHAMMAD DJAMADIL BIN SIDIK
Signature Of Interpreter: Not applicable
Officer In Charge Of Case: TP / AEIT / Sgt 2 SHARIFAH NOR FARIZAN BINTE SYED MOHD SAID Contact No.: 65476172

Authentication Stamp
NP168

Signature Of Informant:
Date/Time: 18/08/2019 20:21
Classification Of Case:

SINGAPORE
POLICE FORCE

SINGAPORE
POLICE FORCE

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	19 Aug 2019		23 Aug 2019 15:29 Edit Adj Rpt	S\$3,000.00 Edit Estimates	S\$3,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: LINDA GUNARSO , ID: S7764307I, Tel: +6598233080, Email: NOEMAIL									
Main Claimant: MUHAMMAD JUZAILI BIN JURIY , ID: S9929039J									
Vehicle Reg. No.: FU3246G		Date of Loss: 18/08/2019 16:00 - :59 [211 Months and 16 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 603343		Policy/Cover Note No.: A29121094AV2 (Comprehensive) Coverage: 29/04/2019 - 28/04/2021							
Vehicle Reg. No. (Insured): SKS6749D		Policy No. (Claimant):							
		Excess: S\$500.00							
Repairer: Sg 98 Motor Pte Ltd (HQ) BLK 4001 ANG MO KIO INDUSTRIAL PARK 1 #01-21, 569622 Ang Mo Kio - Tel: 64524898									
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Muhd Ashik B Madi - 6594 2548]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by BRYAN TANI] ... [Final Rpt due 22/09/2019]									
Driver/Custodian (Insured): LINDA GUNARSO (42 / Female), NRIC: S7764307I, Tel: +6598233080 Email: NOEMAIL									
Adj Asg. Remarks: on WP. (Manual Assign). Liab: 100%. Agree on SJE. Assign: LKK Auto Consultants Pte Ltd. Contact: Leena @ 6452 4898. Manual assigned to LKK via email on 22/08/19.									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									















































Claim Documents

*FU3246G (603343)
[SKS6749D]
TP
MUHAMMAD JUZAILI BIN JURIY
Aug 18 2019 4:00PM
[LINDA GUNARSO]
Sg 98 Motor Pte Ltd

Upload Documents | Upload Photos | Compose New Letter

View View In Browser

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	23/08/19 09:40	Accident Statement From:OD - Reg. No: SKS6749D, Claimant: LINDA GUNARSO		Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	28/08/19 17:27	Adjuster Immediate Advice		Load HTM	
Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	15/10/19 13:34	General View		Load JPG	<input checked="" type="checkbox"/>
2	15/10/19 13:34	General View		Load JPG	<input checked="" type="checkbox"/>
3	15/10/19 13:34	General View		Load JPG	<input checked="" type="checkbox"/>
4	15/10/19 13:34	General View		Load JPG	<input checked="" type="checkbox"/>
5	15/10/19 13:34	General View		Load JPG	<input checked="" type="checkbox"/>
6	15/10/19 13:34	General View		Load JPG	<input checked="" type="checkbox"/>
7	15/10/19 13:34	General View		Load JPG	<input checked="" type="checkbox"/>
8	15/10/19 13:34	General View		Load JPG	<input checked="" type="checkbox"/>
9	15/10/19 13:34	General View		Load JPG	<input checked="" type="checkbox"/>
10	15/10/19 13:34	General View		Load JPG	<input checked="" type="checkbox"/>
11	15/10/19 13:34	General View		Load JPG	<input checked="" type="checkbox"/>
12	15/10/19 13:34	General View		Load JPG	<input checked="" type="checkbox"/>
13	15/10/19 13:34	General View		Load JPG	<input checked="" type="checkbox"/>
14	15/10/19 13:34	General View		Load JPG	<input checked="" type="checkbox"/>
15	15/10/19 13:34	General View		Load JPG	<input checked="" type="checkbox"/>
16	15/10/19 13:34	General View		Load JPG	<input checked="" type="checkbox"/>
17	15/10/19 13:34	General View		Load JPG	<input checked="" type="checkbox"/>
18	15/10/19 13:34	General View		Load JPG	<input checked="" type="checkbox"/>
19	15/10/19 13:34	General View		Load JPG	<input checked="" type="checkbox"/>
20	15/10/19 13:34	General View		Load JPG	<input checked="" type="checkbox"/>
21	15/10/19 13:34	General View		Load JPG	<input checked="" type="checkbox"/>
22	15/10/19 13:34	General View		Load JPG	<input checked="" type="checkbox"/>
23	15/10/19 13:34	General View		Load JPG	<input checked="" type="checkbox"/>
24	15/10/19 13:34	General View		Load JPG	<input checked="" type="checkbox"/>
25	15/10/19 13:34	General View		Load JPG	<input checked="" type="checkbox"/>
26	15/10/19 13:34	General View		Load JPG	<input checked="" type="checkbox"/>
27	15/10/19 13:34	General View		Load JPG	<input checked="" type="checkbox"/>
28	15/10/19 13:34	General View		Load JPG	<input checked="" type="checkbox"/>
29	15/10/19 13:34	General View		Load JPG	<input checked="" type="checkbox"/>
30	15/10/19 13:34	General View		Load JPG	<input checked="" type="checkbox"/>
31	15/10/19 13:34	General View		Load JPG	<input checked="" type="checkbox"/>
32	15/10/19 13:34	General View		Load JPG	<input checked="" type="checkbox"/>
33	15/10/19 13:34	General View		Load JPG	<input checked="" type="checkbox"/>
34	15/10/19 13:34	General View		Load JPG	<input checked="" type="checkbox"/>
35	15/10/19 13:34	General View		Load JPG	<input checked="" type="checkbox"/>
36	15/10/19 13:34	General View		Load JPG	<input checked="" type="checkbox"/>
37	15/10/19 13:34	General View		Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
38	15/10/19 13:34	General View	 Load JPG	<input checked="" type="checkbox"/>
39	15/10/19 13:34	General View	 Load JPG	<input checked="" type="checkbox"/>
40	15/10/19 13:34	General View	 Load JPG	<input checked="" type="checkbox"/>
41	15/10/19 13:34	General View	 Load JPG	<input checked="" type="checkbox"/>
42	15/10/19 13:34	General View	 Load JPG	<input checked="" type="checkbox"/>
43	15/10/19 13:34	General View	 Load JPG	<input checked="" type="checkbox"/>
44	15/10/19 13:34	General View	 Load JPG	<input checked="" type="checkbox"/>
45	15/10/19 13:34	General View	 Load JPG	<input checked="" type="checkbox"/>
46	15/10/19 13:34	General View	 Load JPG	<input checked="" type="checkbox"/>
47	15/10/19 13:34	General View	 Load JPG	<input checked="" type="checkbox"/>
48	15/10/19 13:34	General View	 Load JPG	<input checked="" type="checkbox"/>
49	15/10/19 13:34	General View	 Load JPG	<input checked="" type="checkbox"/>
50	15/10/19 13:34	General View	 Load JPG	<input checked="" type="checkbox"/>
51	15/10/19 13:34	General View	 Load JPG	<input checked="" type="checkbox"/>
52	15/10/19 13:34	General View	 Load JPG	<input checked="" type="checkbox"/>
53	15/10/19 13:34	General View	 Load JPG	<input checked="" type="checkbox"/>
54	15/10/19 13:34	General View	 Load JPG	<input checked="" type="checkbox"/>
55	15/10/19 13:34	General View	 Load JPG	<input checked="" type="checkbox"/>
56	15/10/19 13:34	General View	 Load JPG	<input checked="" type="checkbox"/>
57	15/10/19 13:34	General View	 Load JPG	<input checked="" type="checkbox"/>
58	15/10/19 13:34	General View	 Load JPG	<input checked="" type="checkbox"/>
59	15/10/19 13:34	General View	 Load JPG	<input checked="" type="checkbox"/>
60	15/10/19 13:35	General View	 Load JPG	<input checked="" type="checkbox"/>
61	15/10/19 13:35	General View	 Load JPG	<input checked="" type="checkbox"/>
62	15/10/19 13:35	General View	 Load JPG	<input checked="" type="checkbox"/>
63	15/10/19 13:35	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
64	15/10/19 13:35	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
65	15/10/19 13:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	15/10/19 13:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	15/10/19 13:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	15/10/19 13:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	15/10/19 13:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	15/10/19 13:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	15/10/19 13:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	15/10/19 13:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	15/10/19 13:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	15/10/19 13:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	15/10/19 13:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	15/10/19 13:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	15/10/19 13:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	15/10/19 13:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	15/10/19 13:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	15/10/19 13:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
81	15/10/19 13:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
82	15/10/19 13:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
83	15/10/19 13:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
84	15/10/19 13:36	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
85	15/10/19 13:36	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
86	15/10/19 13:36	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
87	15/10/19 13:36	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
88	15/10/19 13:36	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
89	15/10/19 13:36	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
90	15/10/19 13:36	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
91	15/10/19 13:36	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
92	15/10/19 13:36	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
93	15/10/19 13:36	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
94	15/10/19 13:36	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
95	15/10/19 13:36	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
96	15/10/19 13:36	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
97	15/10/19 13:36	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
98	15/10/19 13:36	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
99	15/10/19 13:36	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
100	15/10/19 13:36	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
101	15/10/19 13:36	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
102	15/10/19 13:36	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
103	15/10/19 13:36	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
104	15/10/19 13:36	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
105	15/10/19 13:36	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
106	15/10/19 13:36	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
107	15/10/19 13:36	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
108	15/10/19 13:36	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
109	15/10/19 13:36	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
110	15/10/19 13:36	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
111	15/10/19 13:36	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
112	15/10/19 13:36	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
113	15/10/19 13:36	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
114	15/10/19 13:36	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
115	15/10/19 13:36	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
116	15/10/19 13:36	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
117	12/11/19 17:33	After Repair Photo		Load JPG	<input checked="" type="checkbox"/>
118	12/11/19 17:33	After Repair Photo		Load JPG	<input checked="" type="checkbox"/>
119	12/11/19 17:33	After Repair Photo		Load JPG	<input checked="" type="checkbox"/>
120	12/11/19 17:33	After Repair Photo		Load JPG	<input checked="" type="checkbox"/>
121	12/11/19 17:33	After Repair Photo		Load JPG	<input checked="" type="checkbox"/>
122	12/11/19 17:33	After Repair Photo		Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	23/08/19 09:40	TP GIA RPT (FU3246G) From:OD - Reg. No: SKS6749D, Claimant: LINDA GUNARSO		Load PDF	
2	23/08/19 09:41	PRI		Load PDF	
3	23/08/19 15:17	Agree on SJE		Load PDF	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor)		Thumbnail	Print
1	23/08/19 15:27	Survey Request - Manual Assigned		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 100px; width: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19014832/DQF3E2

Date: 25/11/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: A29121094AV2
Claimant
Vehicle No : FU3246G **Insured Vehicle No :** SKS6749D
Date of Loss: 18/08/2019 **Nature of Claim:** TP **Claim No:** 603343

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: FU3246G
Make & Model: KAWASAKI KRR ZX150 M, 149cc (M) **Engine No:** KR150EEA54381
Reg. Date: 02/01/2002 (Man. Year: 2001) **Chassis No:** KR150KA54381
Colour: Blue **Odometer:** 38220 km
Engine Capacity: 148 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes **Footbrake (Serviceable):** Yes
Handbrake (Serviceable): Yes **Engine Modification:** No **Pre-accident Condition:** Yes

CONDITION OF TYRES

Front Tyre Size: 70/90 R17 **Rear Tyre Size:** 80/90 R17
Front Left Side: Maxxis 3 mm **Rear Left Side:** Maxxis 3 mm
Front Right Side: 0 mm **Rear Right Side:** 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,357.50	3,316.50	1,041.00	23.89
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,130.00	510.00	620.00	54.87
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,487.50	3,826.50	1,661.00	30.27
Approved Total (Overridden) (S\$)		3,000.00		
Nett Amount (S\$)	5,487.50	3,000.00	2,487.50	45.33

INSPECTION

Date of Assignment: 23/08/2019
Date Inspected: 23/08/2019 Inspected At: Sg 98 Motor Pte Ltd (HQ)
 BLK 4001 ANG MO KIO INDUSTRIAL
 PARK 1 #01-21
 Singapore 569622

Estimated Period of Repair: 4.0 days**Adjuster:** BRYAN TANI**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 22 Nov 2019)	
Parts:	N/A	KAWASAKI KRR ZX150 M 149cc (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FU3246G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT MUDGUARD	Repair	190.00 FL	*- FL
2	1		*FRONT COWLING	Cut	260.00 FL	*260.00 FL
3	1		*VISOR	Broken	150.00 FL	*150.00 FL
4	1		*HANDLE BAR LH	Not Necessary	155.00 FL	*- FL
5	1		*CLUTCH LEVER	Cut	65.00 FL	*65.00 FL
6	1		*FUEL TANK	Dented	550.00 FL	*550.00 FL
7	1		*FRONT LH FAIRING - CENTRE	Cut / Broken	190.00 FL	*190.00 FL
8	1		*FRONT SIGNAL L/RH	O/S NotNecessary / N/S Broken	180.00 FL	*90.00 FL
9	10		*COVER SET BOLT	Necessary / Cut	30.00 FL	*30.00 FL
10	1		*L/H REAR TAIL PANEL	Broken / Dislodged	160.00 FL	*160.00 FL
11	1		*REAR CENTRE PANEL	Broken	180.00 FL	*180.00 FL
12	1		*SET FORK TUBE	Distorted	550.00 FL	*550.00 FL
13	2		*FORK OIL SEAL	Necessary	90.00 FL	*90.00 FL
14	1		*FORK UNDER BRACKET	Distorted	250.00 FL	*250.00 FL
15	1		*FRONT CENTRE GUARD - LOWER	Cracked	250.00 FL	*250.00 FL
16	1		*REAR TAIL LAMP	Not Necessary	155.00 FL	*- FL
17	1		*FRONT RIM	Not Necessary	380.00 FL	*- FL
18	1		*REAR EXHAUST PIPE	Cut	350.00 FL	*350.00 FL
19	1		*REAR RIGHT TAIL PANEL	Cracked	180.00 FL	*160.00 FL
20	1		*FRONT RH FAIRING	Cracked	190.00 FL	*190.00 FL
21	1		*FRONT INNER PANEL	Cracked	150.00 FL	*150.00 FL
22	1		*REAR NUMBER PLATE	Bent	18.00 FS	*18.00 FS
23	1		*FRONT TYRE	Not Necessary	150.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,823.00	3,683.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	465.50	366.50
Total Parts (\$\$)	4,357.50	3,316.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING FEE	New	40.00	0.00
2	REMOVE & REPLACE NECESSARY PARTS, ALIGN & ETC	New	280.00	200.00
3	PUTTY & RESPRAY PAINT WORK	New	550.00	200.00
4	CHECK WIRING CONNECTIONS	New	80.00	30.00
5	REMOVE & REPLACE FORK ASSY, FORK OIL SEAL & TOP UP FORK OIL	New	180.00	80.00
Gross Labour Cost (\$\$)			1,130.00	510.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >