

INS. CASE OWNER:

CC4/AIG19014834/ 4 da3

LKK:

IDAC:

Surveyor:

MARCUS

DOI:

ASSIGNMENT

23/8/19

Date / Time: 22/08/2019

Registered in Merimen: 23/08/2019

Pre-assign / CCU / FTE



Insured Vehicle No. : EY 54D

Claim No. :

Name of Insured : CHAY POH KEE

Policy No. :

Insured Tel No. : HP:

Make / Model :

Excess Sec II : S\$

D.O.A : 21/08/2019

Place of Accident :

Is driver the owner? (YES / NO)

Nature of Accident :

If NO, Driver Name / Age :

Driver Tel No. :

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability : % Final ? Yes / No

SLX 4580Y

INSRS:
WSP: ZOOM
Tel: AUTOWERKS
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time		STAGE	DATE / PIC
	SLX 4580Y	Non-Reporting ltr (1st):	
	EY 54D - NA/AIG19014758/z4; DOA: 21/08/19	Non-Reporting ltr (2nd):	
		Non-Reporting ltr (Final):	
5/9/19	- FILE PAS TO TYPE MANDATE	Notification ltr (if non-pickup):	
		Call OI:	
2/12/19	- FILE PAS TO MAIL TO CLOSURE	After call ltr to OI:	
		Documentation Check List:	Handler Typist
		Notification ltr (if non-pickup)	☐
		After call ltr to OI:	☒
		Authorisation To Act:	☒
		Release Voucher:	☒
		Final Repair Bill:	☒
		Car Rental Invoice:	☒
		Towing Invoice	☐
		LTA / GIA :	☒
		Medical Bill:	☐
		PIR:	☐
		Mandate/Reject Instruction:	☐
		LOD	☒
		Payment Breakdown Form:	☐
PRELIMINARY ADVICE	Date/Time:	Sent By:	Post-Repair Photos: ☐
			Others: ☐

FINALIZATION	Date/Time:	Confirm with:	Confirm by:
Repair Cost:	S\$ (days) Reduction:	%	Email ☐ Call ☐
FINAL SETTLEMENT	Date/Time: 1/12/19	Confirm with: E/M	Email ☒ Call ☐
Final Liability:	% 100 (Agreed / Assessed) BOLA S/N No. : 27		If NO or B 28, Ass. Lia :
Repair Cost:	S\$ 7000.00		
Loss of Rental (LOR):	S\$ 1680.00 (14 days) x \$120		
Loss of Use (LOU):	S\$ - (5 x days)		
Loss of Income (LOI):	S\$ - (5 x days)		
LOR only ☒ LOU only ☐ LOR + LOU ☐ LOR + LOI ☐ (Tick only one)			
GIA/LTA Search	S\$ 36.45		
Medical:	S\$ -		
Disbursement:	S\$ - (e.g. Tow/ Independent)		
Legal Cost	S\$ -		
Total:	S\$ 8716.45	Global Sum S\$: 8700.00	
FINAL PAYMENT	Date/Time:	Confirm with:	Email ☐ Call ☐
Payee 1:	S\$ 8700.00	Name 1: Zoom Autowerks Pte Ltd	
Payee 2: (Strike if N.A.)	S\$	Name 2:	
Payee 3: (Strike if N.A.)	S\$	Name 3:	

COPY SENT
11/12/191) Claim status: Normal/Reject/Private Settle
2) Report Format: TP
3) Survey fee: \$320

REF: A19

ASSIGNMENT

From:

Date:

23/8/19

Estimated Cost:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLX 4880Y

at Workshop m/s

ZOOM Autowerks

of 15 Kerli Bukit Rd 4 #01-53

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

65

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

6

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val:

Yes or No

CA / REV / REP. / 24 HRS

up

72/3

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLX 4880Y

Yr Regn:

3 / 8

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

(A)

Make:

KIA Cerato

cc

1591

Colour:

Blue

A/C:

Insured / Std / NI / NA

Sp. Reading

21000

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

KNAF2411M.J.57619F9

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/45-R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

nexen

Front

6

Rear

6

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

23/8/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

LTA 43067

L13 - \$7000 (Red \$ 7887.06 / 53%)

Date/Time, File Pass to?



Prel. Report

1)



Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

\$ + PS. 31

Folio

Claims

TOTAL

Add Fee:



Site Insp (\$



Interview (\$



Tech. Insp (\$



Weekend (\$

Report Format:

Lump Sum / L&M:



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road
#08-1339 Singapore 470130
Tel: 9450 7920
* zoomautowerks@gmail.com

Alb d Jie

Not Authorized

28 August 2019

ACCIDENT DATE: 21 Aug 2019
OWNER: YONG WEN GIN LEONARD
REG NO.: SLX 4580 Y
MAKE/MODEL: KIA CERATO

2/s \$7000/
6dy.

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(\$)
	<u>LIST ITEMS</u>	
1	Rear windscreen moulding	\$ 111 98.60 X
1	Rear boot lid	\$ 773.80
2	Rear boot lock sensor	\$ 250.00
2	Rear boot lamps	\$ 373.00
1	Rear boot inner lock	\$ 126.50
1	Rear boot rubber	\$ 128.60
1	Rear boot "KIA" emblem	\$ 52.50
1	Rear boot "CERATO" emblem	\$ 42.50
1	Rear boot "K3" emblem	\$ 45.00
1	Rear boot "C&C" emblem	\$ 45.60
2	Rear taillamps	\$ 975.20
1	Rear end panel	\$ 598.50
1	Rear end panel inner garnish	\$ 152.50
1	Rear bumper	\$ 658.00
1	Rear bumper lower garnish	\$ 145.50
2	Rear bumper reflectors	\$ 136.00
1	Rear bumper reinforcement	\$ 356.00
2	Rear bumper reinforcement stays	\$ 305.00 X
3	Rear bumper reinforcement brackets	\$ 68.70
2	Rear bumper side retainers	\$ 77.00 X
4	Rear bumper PDC sensors	\$ 746.00 2pc
1	Rear bumper lower tray garnish	\$ 198.50
2	Rear fenders	\$ 1,779.20 X
1	Rear fender inner trim	\$ 117.20
1	Rear floor board	\$ 280.50 X
1	Rear floor panel	\$ 885.00 X
1	Rear exhaust silencer	\$ 726.50
2	Rear exhaust mountings	\$ 87.00 X
1	Rear exhaust chrome tail pipe	\$ 115.00
		\$ 10,363.40
	Less 10%	\$ 1,036.34
		\$ 9,327.06

6475.1

1
1
1
1

\$	11	80.00	X
\$	12	50.00	40
\$	125	<u>750.00</u>	600
\$	11	50.00	X
\$		930.00	

LABOUR CHARGES

\$	80.00	30
\$	150.00	80
\$	150.00	50
\$	120.00	60
\$	180.00	X
\$	150.00	60
\$	200.00	60
\$	1,800.00	800
\$	1,800.00	1200
\$	<u>4,630.00</u>	

\$ 14,887.06

1. The Insured Consultants hence notify the Reproter in the following:

- To allow you (Insured) to "speak" passing
- To allow you (Insured) to bring resources
- To allow you (Insured) to be consulted
- To allow you (Insured) to be "Without Prejudice" basis
- To allow you (Insured) to be allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Reproter:

Signed:

Date:

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC
Owner ID: 726J

Vehicle Details

Vehicle No.: SLX4580Y
Vehicle to be Exported: No
Intended Deregistration Date: 23 Aug 2019
Vehicle Make: KIA
Vehicle Model: CERATO K3 1.6A SUNROOF
Primary Colour: Blue
Manufacturing Year: 2017
Engine No.: G4FGHH692006
Chassis No.: KNAFZ411MJ5761959
Maximum Power Output: 95.3 kW (127 bhp)
Open Market Value: \$15,245.00
Original Registration Date: 28 Mar 2018
First Registration Date: 28 Mar 2018
Transfer Count: 0
Actual ARF Paid: \$15,245.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 27 Mar 2028
PARF Rebate Amount: \$11,433.00

Intended COE Rebate Details

COE Expiry Date: 27 Mar 2028
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$36,810.00
COE Rebate Amount: \$31,634.00
Total Rebate Amount: \$43,067.00

The information contained herein is correct as at 23 Aug 2019

OK

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

F

Roadshow Exclusive
T&Cs apply

sgCarMart Carnival
31 Aug - 1 Sep 2019
 10am - 8pm
 Downtown East
 (next to Open Carpark B)
VISIT US!

Post an Advertisement
 Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Volkswagen Tiguan 2.0L TSI



2018 Volkswagen Tiguan 2.0L TSI
 Direct Owner

Think One Auto

NEW & COMMERCIAL

Post an Ad

Advertiser Login

Ways of Selling

Browse by Category

Sort by Date Posted

6 vehicles

kia cerato k3

Advanced Search

Search Selection	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	V
kia cerato k3		Any	Any	2018	Any	Any	

**Kia Cerato K3 1.6A****\$71,800****\$7,720 /yr****23-Feb-2018****1,591 cc****16,110 km**

Comes With Agent Warranty Till Feb 2023 For Peace Of Mind! Powerful Yet Economical For Daily Commute. Spacious Cabin For Small Families. Large Boot Provide You With Ample Luggage Space For Your Luggage And Golf Bags! Low Mileage Done! Call Us Now For A Test Drive.

Select By Performance Premium Selection

Posted: 22-Aug-2019 Tags: 2018 Kia Cerato, 2018 kia cerato, Kia Cerato, kia cerato, Kia, Cerato, cerato, Used Kia

**Kia Cerato K3 1.6A Sunroof (OPC)****\$53,900****\$5,430 /yr****28-Feb-2018****1,591 cc****25,000 km**

Look No Further! Best Value For Your Money. Direct Owner's Beautiful White, Feb '2018' Kia Cerato K3 1.6A Sunroof. Selling Due To Upgrading To New Car. Low Fuel Consumption, Low Maintenance. Original Paintwork Condition And Well Taken Care By 1 Owner. Trade In Offer Available.

Posted: 19-Aug-2019 Tags: 2018 Kia Cerato, 2018 kia cerato, Kia Cerato, kia cerato, Kia, Cerato, cerato, Used Kia

**Kia Cerato K3 1.6A****\$71,500****\$7,470 /yr****22-May-2018****1,591 cc****15,854 km**

1 Owner, Sports Rims, Leather Seats, Functions Steering, Cruise Control, Touch Screen LCD Audio System, Bluetooth, Reverse Camera And Sensors. Full Agent Maintained With Agent Warranty Till April 2023 For Peace Of Mind Plus 10 Years Engine Warranty. Clean And Neat Condition.

Posted: 17-Aug-2019 Tags: 2018 Kia Cerato, 2018 kia cerato, Kia Cerato, kia cerato, Kia, Cerato, cerato, Used Kia

**Kia Cerato K3 1.6A Sunroof****\$85,800****\$9,110 /yr****20-Mar-2018****1,591 cc****28,800 km**

Rare Sunroof Unit. 1 Careful Owner Relocating. Urgent Sale Required. Still Smells Like A New Car. High Trade In And Flexible Financing Schemes Available. Call Us Today For A Viewing Or Discussion.

Posted: 01-Aug-2019 Tags: 2018 Kia Cerato, 2018 kia cerato, Kia Cerato, kia cerato, Kia, Cerato, cerato, Used Kia

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

► Buy Tyres Online!
 ► Latest Special Offers R

**Kia Cerato K3 1.6A****\$68,800****\$7,410 /yr****29-Jan-2018****1,591 cc****19,641 km**

1 Owner, Full Agent Maintained With Agent Warranty Till April 2023 For Peace Of Mind + 10years Engine Warranty. Clean & Neat Condition. Flexible Loan Available. View Now!

Posted: 24-Jul-2019 Tags: 2018 Kia Cerato, 2018 kia cerato, Kia Cerato, kia cerato, Kia, Cerato, cerato, Used Kia

Compare

PRE-REPAIR INSPECTION REQUEST – SLX4850Y vs EY54D (OI) on D.O.A.: 21/08/2019

From: Hor Yinrul
To: assignments@lkkauts.com, Admin A (admin-a@lkkauts.com)
Cc: Fong, Andy-SY, Chin, Lee-Ying, Abu Kassim, Noor Mariesa, Azlan, Syazairdina, Chan, Yoke Shi, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur, Parthiban, Theerthan, Subramaniam, Divy
Sent: 8/22/2019 1:59:04 PM
Attachments: SLX4850 Y.PDF

Hi,

Please refer to the enclosed request from Zoom Autowerks Pte Ltd.
Kindly carry out Policy coverage verification first before conducting the pre-repair inspection within 48 hours

If you have any queries/concerns, please let us know.
Kindly assist to assign **Marcus Chua** as Single Joint Expert as requested.

Thanks & Regards,

Hor Yin Rul (Viviane)
AIG
FNOL Adjuster I
Singapore FNOL | Claims Operations – Auto

Yinrul.Hor@aig.com | www.aig.sg

Spm @ 22/8/19
vehicle in
person @ Elin
agreed by on 23/8/19

From: zoomautowerks@gmail.com [mailto:zoomautowerks@gmail.com]
Sent: Thursday, August 22, 2019 1:30 PM
To: Hor, Yinrul
Cc: Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Parthiban, Theerthan; Subramaniam, Divyashni; Tong, Wahxin
Subject: RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE EY54D AND SLX4850Y ON 21/08/2019

Dear Yinrul,

Kindly arrange LKK - Marcus Chua.

From: Hor, Yinrul
Sent: Thu, 22 Aug 2019 03:41:28 +0000
To: zoomautowerks@gmail.com
Cc: Fong, Andy-SY, Chin, Lee-Ying, Abu Kassim, Noor Mariesa, Azlan, Syazairdina, Chan, Yoke Shi, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur, Parthiban, Theerthan, Subramaniam, Divyashni, Tong, Wahxin
Subject: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE EY54D AND SLX4850Y ON 21/08/2019

Without Prejudice

Your Reference : SLX4850Y
Our Reference : EY54D

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Raoul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thank&& Regards,

Hor Yin Rul (Viviane)
AIG
FNOL Adjuster I
Singapore FNOL | Claims Operations – Auto

Yinru.Hor@aig.com | www.aig.sg

From: Zoom Autowerks [<mailto:zoomautowerks@gmail.com>]

Sent: Thursday, August 22, 2019 11:11 AM

To: AIG SGP, Claims-Survey; Hor, Yinrul

Subject: [EXTERNAL] Pre-Repair Inspection for SLX 4850 Y // Accident on 21/08/2019 @ 19:10HR at along Bukit Timah Road involving SLX 4850 Y & EY 54 D

This message is from an external sender; be cautious with links and attachments.

Dear Sir/Madam,

We are instructed by Yong Wei Gin, Leonard to notify you of a road traffic accident on 21/08/2019

at about 19:10HR at along Bukit Timah Road involving our client's vehicle registration number SLX 4850 Y and vehicle registration number EY 54 D driven by your insured at the material time.

A copy of the Singapore Accident Statement/Traffic Police Report filed is enclosed. As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated time, our client shall proceed to repair the vehicle without further reference to you.

Please contact me @ 9450 7920, should you require more information.

Kindly arrange survey at Blk 15 Kaki Bukit Road 4, Bartley Biz Centre, #01-53, Singapore 4178 08.

Warmest Regards,
Elin Cai

Zoom Autowerks Pte Ltd
130 Bedok Reservoir Road
#08-1339 Singapore 470130
☎9450 7920
✉zoomautowerks@gmail.com

- Please note our change in mailing/registered address with effect from 1st July 2018 -

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

View Received Message

This mail is associated with :

***SLX4580Y (0846651744SG)
[EY54D]**

TP
YONG WEN GIN, LEONARD
Aug 21 2019 7:00PM
[CHOY POH KEE]
Zoom Autowerks Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 14/10/2019 18:46 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$7996.45) - SLX4580Y - Claim Handler: Loh, Chee-Heng

Approved:7996.45.

DOCUMENTS SUMMARY

There are no documents.

Date	Day	Job Description	Number of day
22/8/2019	Thu	REQUEST FOR SURVEY	1
23/8/2019	Fri	DATE OF INSPECTION	2
24/8/2019	Sat	DURANTE / REPAIR DAY 1	3
25/8/2019	Sun		4
26/8/2019	Mon	REPAIR DAY 2	5
27/8/2019	Tue	REPAIR DAY 3	6
28/8/2019	Wed	PURCHASE DATE	7
29/8/2019	Thu	WAITING PARTS	8
30/8/2019	Fri		9
31/8/2019	Sat		10
1/9/2019	Sun		11
2/9/2019	Mon	WAITING PARTS	12
3/9/2019	Tue		13
4/9/2019	Wed	Delivery Date: PRICE AGREEMENT	14
5/9/2019	Thu	REPAIR DAY 4	15
6/9/2019	Fri	REPAIR DAY 5	16
7/9/2019	Sat	REPAIR DAY 6	17
8/9/2019	Sun		0
9/9/2019	Mon		0
10/9/2019	Tue		0
8/6/2016	Wed		0
9/6/2016	Thu		0
10/6/2016	Fri		0
11/6/2016	Sat		0

Surveyour Recommended 6
 NON WORKING DAYS 2
 PRI & ACCIDENT DAY 9
 Total 17

Days

Days

Days

Days



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710 TEL: 6745 3833 FAX: 6745 4442, 6745 0616 (Account)
WAREHOUSE: 48A SUNGEI KADUT AVE SINGAPORE 729672 TEL: 6365 1255 FAX: 6365 2580
Email: jaeauto@pacific.net.sg GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

ZOOM AUTOWERKS

BLK 15 Kaki Bukit Road4 #01-53 Bartley Biz Centre

TEL: 9450 7920

SINGAPORE 417808

28.08.2019

ATTN: ELIN CAI

LETTER OF CONFIRMATION – ETA
(PURCHASE ORDER NO. GN201909-000340)

We confirm receipt of your order for the Vehicle No. SLX4580Y mentioned in your Purchase Order dated 28th of Aug 2019. Indent Order from Malaysia Supplier
1 items :

*1. SKIRT.RR BUMPER- (Accessories)

The part(s) is/are at present out of stock. We are making every effort to supply the item(s). According by Accessories About EST ETA 5 to 7 Day if Malaysia Supplier have stock, if Malaysia Supplier No Stocks 7 to 14 Day 2019.

Yours sincerely

Signature : 

Name : Alan Leow



Company's stamp



各種各樣的汽車擋風鏡與配件

WINDSCREEN GLASS & ACCESSORIES FOR ALL TYPES OF CARS



日美汽車私人有限公司

JAE AUTO PTE LTD

BLK 3018 UBI ROAD 1 #01-121 SINGAPORE 408703
TEL: 67453033 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
66 JALAN LAM HUAT #B1-0506 CARIUS CENTRE
SINGAPORE 737869 TEL: 63622226 FAX: 63626977

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M



MyJae Dealer (2000) Program (Wipe Screen, Upgrade) Made in Japan
Japan (Made in Germany)
Sports plug Nissan Dealer, NISSAN (Made in Japan)

CASH SALES

CASH

TAX INVOICE : AR201909-4
DATE : 04/09
CUSTOMER ID : C/P
VEH REG. NO. : SLX4
TERMS :
PO NO. :
PAGE NO. : Page
CURR. :

IN : ZOOM AUTOWERKS BLDG 15 KAKI BUKIT RD 4 #01-53
RTLEY BIZ CENTRE S(417808) ATTN: ELIN 94507920

Q STOCKID	DESCRIPTION	SGL. no	QTY	UPPRICE	AM
KSLK-LI-930 FORTE	SKIRT RE BUMPER	111 SUPPLIER	1		

2LK
45807

prod. EL

2760

4/9/19

TO COLLECT : 299.60***

SUB-TOTAL :
ADD GST 7.00 %

E & O E TOTAL AMOUNT SGD

[E] 04/09/2019 12:

[P] 04/09/2019 12:36:17PM
Goods Sold are not refundable for Cash.
Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

Goods Received in Good Order

JAE Auto Pte. Ltd.
Sales Executive : ALAN



This is computer generated document.
No signature is required.

ORIGINAL

Signature / Co Stamp / Date

View Received Message

This mail is associated with :

***SLX4580Y (0846651744SG)
[EY54D]**

TP
YONG WEN GIN, LEONARD
Aug 21 2019 7:00PM
[CHOY POH KEE]
Zoom Autowerks Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 26/11/2019 14:52 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$8716.45) - SLX4580Y - Claim Handler: Loh, Chee-Heng

Approved:8716.45.

DOCUMENTS SUMMARY

There are no documents.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	23 Aug 2019 Edit Reg		22 Aug 2019 00:00 Edit Adj Rpt	\$57,000.00 Edit Estimates	\$57,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	CHOY POH KEE, ID: S2548682Z								
Main Claimant:	YONG WEN GIN, LEONARD, ID: S8919726J								
Vehicle Reg. No.:	SLX4580Y	Date of Loss:	21/08/2019 19:00 - :59 [16 Months and 24 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 08466517445G	Policy/Cover Note No.:	0100381061 (TP, Fire & Theft)						
Vehicle Reg. No. (Insured):	EY54D	Policy No. (Claimant):							
		Excess:							
Repairer:	Zoom Autowerks Pte Ltd () 832 SIMS AVENUE #12-884 EUNOSVILLE, 400832 Eunos - Tel:								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Loh, Chee-Heng] Chee-Heng.Loh@aig.com								
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 03/09/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG_EXPRESS (26/11/2019): Alert - Adj Mandate Approved (\$58716.45) - SLX4580Y - Claim Handler: Loh, Chee-H... - AIG_SG_EXPRESS (14/10/2019): Alert - Adj Mandate Approved (\$57996.45) - SLX4580Y - Claim Handler: Loh, Chee-H...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLX4580Y (0846651744SG)
[EY54D]

TP
YONG WEN GIN, LEONARD
Aug 21 2019 7:00PM
[CHOY POH KEE]
Zoom Autowerks Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	Upload Video	Upload Audio	View View in Browser
----------------------------------	--	-------------------------------	------------------------------------	------------------------------	------------------------------	--

Letters/Correspondences				1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	(Draft)	Third Party Express Settlement - Payment Breakdown		Edit	

Photos/Images				3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	19/09/19 08:47	Chassis Number		Load JPG	☒
2	19/09/19 08:47	Odometer Reading		Load JPG	☒
3	19/09/19 08:48	General View		Load JPG	☒
4	19/09/19 08:48	General View		Load JPG	☒
5	19/09/19 08:48	General View		Load JPG	☒
6	19/09/19 08:48	General View		Load JPG	☒
7	19/09/19 08:48	General View		Load JPG	☒
8	19/09/19 08:48	General View		Load JPG	☒
9	19/09/19 08:48	General View		Load JPG	☒
10	19/09/19 08:48	General View		Load JPG	☒
11	19/09/19 08:48	General View		Load JPG	☒
12	19/09/19 08:48	General View		Load JPG	☒
13	19/09/19 08:48	General View		Load JPG	☒
14	19/09/19 08:48	General View		Load JPG	☒
15	19/09/19 08:48	General View		Load JPG	☒
16	19/09/19 08:48	General View		Load JPG	☒
17	19/09/19 08:48	General View		Load JPG	☒
18	19/09/19 08:48	General View		Load JPG	☒
19	19/09/19 08:48	General View		Load JPG	☒
20	19/09/19 08:48	General View		Load JPG	☒
21	19/09/19 08:48	General View		Load JPG	☒
22	19/09/19 08:48	General View		Load JPG	☒
23	19/09/19 08:48	General View		Load JPG	☒
24	19/09/19 08:48	General View		Load JPG	☒
25	19/09/19 08:48	General View		Load JPG	☒
26	19/09/19 08:48	General View		Load JPG	☒
27	19/09/19 08:48	General View		Load JPG	☒
28	19/09/19 08:48	General View		Load JPG	☒
29	19/09/19 08:48	General View		Load JPG	☒
30	19/09/19 08:48	General View		Load JPG	☒
31	19/09/19 08:48	General View		Load JPG	☒
32	19/09/19 08:48	General View		Load JPG	☒
33	19/09/19 08:48	General View		Load JPG	☒
34	19/09/19 08:48	General View		Load JPG	☒
35	19/09/19 08:48	General View		Load JPG	☒
36	19/09/19 08:48	General View		Load JPG	☒
37	19/09/19 08:48	General View		Load JPG	☒
38	19/09/19 08:48	General View		Load JPG	☒
39	19/09/19 08:48	General View		Load JPG	☒
40	19/09/19 08:48	General View		Load JPG	

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				☒
41	19/09/19 08:48	General View		☒
42	19/09/19 08:48	General View		☒
43	19/09/19 08:48	General View		☒
44	19/09/19 08:48	General View		☒
45	19/09/19 08:48	General View		☒
46	19/09/19 08:48	General View		☒
47	19/09/19 08:48	General View		☒
48	19/09/19 08:48	General View		☒
49	19/09/19 08:48	General View		☒
50	19/09/19 08:48	General View		☒
51	19/09/19 08:48	General View		☒
52	19/09/19 08:48	General View		☒
53	19/09/19 08:48	General View		☒
54	19/09/19 08:48	General View		☒
55	19/09/19 08:48	General View		☒
56	19/09/19 08:48	Reinspection Photo		☒
57	19/09/19 08:48	Reinspection Photo		☒
58	19/09/19 08:48	Reinspection Photo		☒
59	19/09/19 08:48	Reinspection Photo		☒
60	19/09/19 08:48	Reinspection Photo		☒
61	19/09/19 08:48	Reinspection Photo		☒
62	19/09/19 08:48	Reinspection Photo		☒
63	19/09/19 08:48	Reinspection Photo		☒
64	19/09/19 08:48	Reinspection Photo		☒
65	19/09/19 08:48	Reinspection Photo		☒
66	19/09/19 08:48	Reinspection Photo		☒
67	19/09/19 08:48	Reinspection Photo		☒
68	19/09/19 08:48	Reinspection Photo		☒
69	19/09/19 08:48	Reinspection Photo		☒
70	19/09/19 08:48	Reinspection Photo		☒
71	19/09/19 08:48	Reinspection Photo		☒
72	19/09/19 08:48	Reinspection Photo		☒
73	19/09/19 08:48	Reinspection Photo		☒
74	19/09/19 08:48	Reinspection Photo		☒
75	19/09/19 08:48	Reinspection Photo		☒
76	19/09/19 08:48	Reinspection Photo		☒
77	19/09/19 08:48	Reinspection Photo		☒
78	19/09/19 08:48	Reinspection Photo		☒
79	19/09/19 08:48	Reinspection Photo		☒
80	19/09/19 08:48	Reinspection Photo		☒
81	19/09/19 08:48	Reinspection Photo		☒
82	19/09/19 08:48	Reinspection Photo		☒
83	19/09/19 08:48	Reinspection Photo		☒
84	19/09/19 08:48	Reinspection Photo		☒
85	19/09/19 08:48	Reinspection Photo		☒
86	19/09/19 08:48	Reinspection Photo		☒
87	19/09/19 08:48	Reinspection Photo		☒
88	19/09/19 08:48	Reinspection Photo		☒
89	19/09/19 08:48	Reinspection Photo		☒
90	19/09/19 08:48	Reinspection Photo		☒
91	19/09/19 08:48	Reinspection Photo		☒
92	19/09/19 08:48	Reinspection Photo		☒
93	19/09/19 08:48	Reinspection Photo		☒
94	19/09/19 08:48	Reinspection Photo		☒
95	19/09/19 08:48	Reinspection Photo		☒

Letters/Correspondences			1 per page	☐
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
96	19/09/19 08:48	Reinspection Photo		☒
97	19/09/19 08:48	Reinspection Photo		☒
98	19/09/19 08:48	Reinspection Photo		☒
99	19/09/19 08:48	Reinspection Photo		☒
100	19/09/19 08:48	Reinspection Photo		☒
101	19/09/19 08:48	Reinspection Photo		☒
102	19/09/19 08:48	Reinspection Photo		☒
103	19/09/19 08:48	Reinspection Photo		☒
104	19/09/19 08:48	Reinspection Photo		☒
105	19/09/19 08:48	Reinspection Photo		☒
106	19/09/19 08:48	Reinspection Photo		☒
107	19/09/19 08:48	Reinspection Photo		☒
108	19/09/19 08:48	Reinspection Photo		☒
109	19/09/19 08:48	Reinspection Photo		☒
110	19/09/19 08:48	Reinspection Photo		☒
111	19/09/19 08:48	Reinspection Photo		☒
112	19/09/19 08:48	Reinspection Photo		☒
113	19/09/19 08:48	Reinspection Photo		☒
114	19/09/19 08:48	Reinspection Photo		☒
115	19/09/19 08:48	Reinspection Photo		☒
116	19/09/19 08:48	Reinspection Photo		☒
117	19/09/19 08:48	Reinspection Photo		☒
118	19/09/19 08:48	Reinspection Photo		☒
119	19/09/19 08:48	Reinspection Photo		☒
120	19/09/19 08:48	Reinspection Photo		☒
121	19/09/19 08:48	Reinspection Photo		☒
122	19/09/19 08:48	Reinspection Photo		☒
123	19/09/19 08:48	Reinspection Photo		☒
124	19/09/19 08:48	Reinspection Photo		☒
125	19/09/19 08:48	Reinspection Photo		☒
126	19/09/19 08:48	Reinspection Photo		☒
127	19/09/19 08:48	Reinspection Photo		☒
128	19/09/19 08:48	After Repair Photo		☒
129	19/09/19 08:48	After Repair Photo		☒
130	19/09/19 08:48	After Repair Photo		☒
131	19/09/19 08:48	After Repair Photo		☒
Documentation			1 per page	☐
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	23/08/19 12:05	ACKNOWLEDGEMENT EMAIL TO AIG DD 22.08.2019		☐
2	23/08/19 12:05	EMAIL FROM AIG DD 22.08.2019		☐
3	23/08/19 12:05	TP GIA REPORT		☐
4	27/09/19 13:26	LETTER TO OI		☐
5	14/10/19 16:28	TP ESTIMATE - MARKED		☐
6	14/10/19 16:35	LOD		☐
7	14/10/19 16:35	RENTAL RECEIPT		☐
8	14/10/19 16:35	LTA/GIA Search Fee		☐
9	09/12/19 09:03	WORKSHOP INVOICE		☐
10	09/12/19 09:03	AUTHORISATION TO ACT FORM		☐
11	09/12/19 09:03	Release Voucher		☐
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	29/08/19 16:17	OI GIA REPORT		☐

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	EY54D (Insd veh)	Model:	KIA CERATO K3 1.6 (A)
	SLX4580Y (TP veh)		
Date of Accident:	21/08/2019		

Global Sum Settlement	:	☒ Yes	☐ No
Repair Estimate	:	\$	14,887.06
Final Repair Cost	:	\$	8,700.00
Loss of Use	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	14 days
LTA / GIA Search Fee	:	\$	
Others:	:	\$	
	:	\$	
Final Settlement Sum (Global Sum)	:	\$	8,700.00
Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)			
A) For <u>Non GIA Registered Workshop</u> :		Agreed Liability _____ 100 _____ (%)	
B) For <u>GIA Registered Workshop</u> :		BOLA Applicable: Yes/ No BOLA Scenario No: _____	
BOLA Liability: _____ (%)		Assessed Liability (*): _____ (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	Zoom Autowerks Pte Ltd	:	\$ 8,700.00
2)		:	\$
3)		:	\$
4)		:	\$

JOANNE LEE KHANG MIN

09 Dec
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;
Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19014834/UDA3Q2

Date: 09/12/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0100381061

Claimant
Vehicle No : SLX4580Y **Insured Vehicle No :** EY54D

Date of Loss: 21/08/2019 Nature of Claim: TP Claim No: 0846651744SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLX4580Y**
 Make & Model: KIA CERATO K3, 1.6 (A) Engine No: G4FGHH692006
 Reg. Date: 28/03/2018 (Man. Year: 2017) Chassis No: KNAFZ411MJ5761959
 Colour: Blue Odometer: 21000 km
 Engine Capacity: 1591 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/45 R17 Rear Tyre Size: 215/45 R17
 Front Left Side: Nexen 6 mm Rear Left Side: Nexen 6 mm
 Front Right Side: Nexen 6 mm Rear Right Side: Nexen 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,257.06	6,467.59	3,789.47	36.94
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,630.00	2,340.00	2,290.00	49.46
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,887.06	8,807.59	6,079.47	40.84
Approved Total (Overridden) (S\$)		7,000.00		
Nett Amount (S\$)	14,887.06	7,000.00	7,887.06	52.98
+ Car Rental (14.0 x S\$120.00/day) (S\$)		1,680.00		
+ Doc/Search Fee (S\$)		36.45		
Nett Liability (S\$)		8,716.45		
Global Sum Settlement (S\$)		8,700.00		

INSPECTION

Date of Assignment: 22/08/2019

Date Inspected: 23/08/2019 Inspected At: 15 KAKI BUKIT RD 4 #01-53
Repairer: Zoom Autowerks Pte Ltd

Estimated Period of Repair: 6.0 days

Adjuster: MARCUS CHUA

Manager: CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN MOULDING	Not Necessary	98.60 FL	*- FL
2	1		*REAR BOOT LID	Dented / Buckled	793.80 FL	*793.80 FL
3	2		*REAR BOOT LOCK SENSOR	Cracked	250.00 FL	*250.00 FL
4	2		*REAR BOOT LAMPS	Cracked	373.00 FL	*373.00 FL
5	1		*REAR BOOT INNER LOCK	Twisted	126.50 FL	*126.50 FL
6	1		*REAR BOOT RUBBER	Twisted	128.60 FL	*128.60 FL
7	1		*REAR BOOT KIA EMBLEM	Necessary	52.50 FL	*52.50 FL
8	1		*REAR BOOT CERATO EMBLEM	Necessary	42.50 FL	*42.50 FL
9	1		*REAR BOOT K3 EMBLEM	Necessary	45.00 FL	*45.00 FL
10	1		*REAR BOOT C&C EMBLEM	Necessary	45.60 FL	*45.60 FL
11	2		*REAR TAILLAMPS	Cracked	975.20 FL	*975.20 FL
12	1		*REAR END PANEL	Badly Dented	598.50 FL	*598.50 FL
13	1		*REAR END PANEL INNER GARNISH	Twisted	152.50 FL	*152.50 FL
14	1		*REAR BUMPER	Distorted	658.00 FL	*658.00 FL
15	1		*REAR BUMPER LOWER GARNISH	Distorted	145.50 FL	*145.50 FL
16	2		*REAR BUMPER REFLECTORS	Scratched / Cracked	136.00 FL	*136.00 FL
17	1		*REAR BUMPER REINFORCEMENT	Cracked	356.00 FL	*356.00 FL
18	2		*REAR BUMPER REINFORCEMENT STAYS	Not Necessary	305.00 FL	*- FL
19	3		*REAR BUMPER REINFORCEMENT BRACKETS	Twisted	68.70 FL	*68.70 FL
20	2		*REAR BUMPER SIDE RETAINERS	Not Necessary	77.00 FL	*- FL
21	4		*REAR BUMPER PDC SENSORS	Shorted (2 PCS ONLY)	746.00 FL	*370.00 FL
22	1		*REAR BUMPER LOWER TRAY GARNISH	Distorted	198.50 FL	*198.50 FL
23	2		*REAR FENDERS	Repair	1,779.20 FL	*- FL
24	1		*REAR FENDER INNER TRIM	Torn	117.20 FL	*117.20 FL
25	1		*REAR FLOOR BOARD	Not Necessary	280.50 FL	*- FL
26	1		*REAR FLOOR PANEL	Repair	885.00 FL	*- FL
27	1		*REAR EXHAUST SILENCER	Bent	726.50 FL	*726.50 FL
28	2		*REAR EXHAUST MOUNTING	Not Necessary	87.00 FL	*- FL
29	1		*REAR EXHAUST CHROME TAIL PIPE	Bent	115.00 FL	*115.00 FL
30	1		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
31	1		*SET REAR BUMPER CLIP	Necessary	50.00 FS	*40.00 FS
32	1		*REAR BUMPER LOWER SPOILER	Distorted	750.00 FS	*600.00 FS
33	1		*REAR NUMBER PLATE WITH HOLDER	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	11,293.40	7,115.10
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,036.34	647.51
Total Parts (\$\$)	10,257.06	6,467.59

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,REPLACED DAMAGED LAMPS AND CHECK UP REAR WIRING	New	80.00	30.00
2	TO REMOVE AND REFIT INNER GARNISHES	New	150.00	80.00
3	TO REMOVE AND REFIT REAR REVERSE SENSOR	New	150.00	50.00
4	TO TRANSFER BOOT LID MECHANISM AND WIRING ASSEMBLY	New	120.00	60.00
5	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	180.00	0.00
6	TO REMOVE,REFIT AND REPLACE EXHAUST SILENCER AND MOUNTINGS	New	150.00	60.00
7	TO APPLY UNDERCOATING	New	200.00	60.00
8	PANEL BEATING	New	1,800.00	800.00
9	TO RE-SPRAY PAINTING ON THE AFFECTED AREAS	New	1,800.00	1,200.00
Gross Labour Cost (\$\$)			4,630.00	2,340.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >