

ASS. REC. BY:

REF: CS/CTI 19614845/uvf3 n2

Special Instruction:

Surveyor: Marcus

ASSIGNMENT (Office)

From (Person): Irre Tay Hui Ping of CTI Date/Time: 23.8.19 10.03 am

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SMJ 9798R Insured: SLP 5846Sat Workshop m/s Euro Success Tel: 9689277of 1 Kati Bukit Ave 6 #02-03Policy No: DMPCSA18163819011 Claim No: SNM19D203911102

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 20/08/2019
(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 23.8.19 10.27 a.m Person Contacted: Ally Huat H.O.D. Endorsement: _____Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SMJ 9798R - X
	SLP 5846S - X

(08/11/13) - wef

ASS. REC. BY: *Marcus*

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: *SMJ 978R*at Workshop m/s *Euro Scan*

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
N/S	O/S
<input type="checkbox"/>	<input type="checkbox"/>

Bal. or Market Value: *14500*

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: *4*

days

Res.: Yes or No

Lum Sum: *20*

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

LTA/OIS3

Vehicle: IN / OUT

Date: _____

Person Contacted: *Nett 4347*Veh No: *SMJ 978R* Yr Regn: *10, 10*Type: *M. Car* / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or *CA1*Make: *chevrolet cruze*C.C. *1598*Colour: *Grey*

A/C: Insured / Std / NI / NA

Sp. Reading: *140162*

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: *KL1JA6961AK717450*Gen. Cond: *Good* / Fair / Poor / BurntSteering: *In order* / Jammed / Leaked / Burnt orBrake: *In order* / Jammed / Leaked / Burnt orModi: *Nil* / S/Rim / STD A/Rim orTyre Size: F: *205/60 R16*

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front *6*Rear *6*R/Bal. *6* mmR/Bal. *6* mmL/Bal. *6* mmL/Bal. *6* mmD.O.A. *20/8/19*D.O.L. *23/8/19*

Survey held at _____

Des. of Damages: *Frt* / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

*con 4-10-2020 1yrs. 1ml.**29/8/19 L/S = 4000 confirmed with AM huaf. (Red 8001-06, 6790)*

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2) *30/8 - typist*Days Of Repair: *4*Resurvey No. of Trip: *1*

Survey Fee: _____

Transportation: _____

Add Fee: ☐

: Site Insp (\$ _____)

) \$ + RS, \$ SI

☐

: Interview (\$ _____)

) Photos

☐

: Tech. Invs (\$ _____)

) Others

☐

: Weekend (\$ _____)

)

Report Format: *Merimen*Lump Sum / I.B.I: (\$ *4000/2*)

TOTAL

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	23 Aug 2019		23 Aug 2019 10:03 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

Show All

CLAIM SUBFOLDER DETAILS

Insured:	[Created by insurer]		
Main Claimant:	GO-RENT PTE LTD		
Vehicle Reg. No.:	SMJ9798R		
Claim Type:	TP / SNM19D203911C02	Date of Loss:	20/08/2019 15:00 - :59
Vehicle Reg. No. (Insured):	SLP5846S	Policy/Cover Note No.:	DMPCSN18163819011
Insurer:	Euro Success Services Pte Ltd (HQ) 1 KAKI BUKIT AVENUE 6 #02-03 AUTOBAY, 417883 Kaki Bukit - Tel: S\$0.00		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 03/09/2019]		
Adj. Remarks:	PLEASE SURVEY AND REVERT		

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

View All

Compose Case Mail

ASSOCIATED TASKS

Date	Priority	Type	Task Group	Subject	Handler	View All	Search Tasks	Create New Task	Complete
Results.						Assigned By	Completed On	Created On	Done?

Catherine Chong (LKK Auto)

From: Ruby Ong <ruby@htapartners.com.sg>
Sent: Thursday, 22 August, 2019 5:42 PM
To: assignments; Asher Sng (LKK Auto)
Cc: Irene Tan
Subject: RE: SNM19D203911 - FW: REQUEST FOR PRE-REPAIR SURVEY PROTOCOL FOR SMJ 9798R [OUR REF. TCL.GCN.RO.50522.19.ESS]

Importance: High

WITHOUT PREJUDICE
SAS TO COSTS

Dear Sirs

We refer to the above.

Please make the necessary arrangements with the contact person. The details are as follows :

Vendor : **EURO SUCCESS SERVICES PTE LTD**
1 Kaki Bukit Avenue 6
#02-03 Autobay
Singapore 417883

Contact Person : Ah Huat (Tel. 9828 9277 / 6742 6231)

If you fail to conduct the pre-repair survey within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference.

Best regards,

Ruby Ong

Secretary

M. Tan Tat Augustine & Partners

20 Upper Circular Road

#02-10/12 The Riverwalk

Singapore 058416

Tel : 6533 0212 ext 278

Fax : 6338 3536 / 6533 0313

www.htapartners.com.sg

Privileged/Confidential information is contained in this message. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email.

From: Irene Tay <irene.tay@sg.cntaiping.com>

Sent: Thursday, 22 August 2019 5:38 PM

To: Ruby Ong <ruby@htapartners.com.sg>

Cc: assignments <assignments@lkkauto.com>; Asher Sng (LKK Auto) <AsherSng@lkkauto.com>

Subject: SNM19D203911 - FW: REQUEST FOR PRE-REPAIR SURVEY PROTOCOL FOR SMJ 9798R [OUR REF. TCL.GCN.RO.50522.19.ESS]

Importance: High

WITHOUT PREJUDICES

Dear Sir (LKK),

We refer to the above matter.

Please liaise with **Hin Tat Augustine** to conduct PRS.

Thank you.

Regards,

Irene Tay

Executive

Claims Department (Motor Division)



This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please inform the sender immediately.

From: Claims Dept of CTI

Sent: Thursday, 22 August, 2019 1:17 PM

To: 'Irene Tay' <irene.tay@sg.cntaiping.com>

Subject: 11SD203911 - FW: REQUEST FOR PRE-REPAIR SURVEY PROTOCOL FOR SMJ 9798R [OUR REF. 50522.19.ESS]

Importance: High

From:

Ruby Ong <ruby@htapartners.com.sg>

Sent: Thursday, August 22, 2019 11:38 AM

To: Claims Dept of CTI

Subject: REQUEST FOR PRE-REPAIR SURVEY PROTOCOL FOR SMJ 9798R [OUR REF. TCL.GCN.RO.50522.19.ESS]

Importance: High

View: HTML | PDF

Send: 22/08/2019

From:

Your mail dated 21 August 2019 refers.

Please find our client's Accident Statement for your kind attention.

Regards,

Respects,
In Tat Augustine & Partners
2100 Springleaf Tower
#12/12 Riverwalk
Singapore 1116
Tel: 65 6382 278
Fax: 65 6382 35 / 6533 0313
Email: info@htapartners.com.sg

Confidential information is contained in this message. If you are not the addressee indicated in this message (or delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you must delete the message and kindly notify the sender by reply email.

From: Department of CTI <claimsdept@sg.cntaiping.com>
Sent: Friday, 21 August 2019 2:54 PM
To: ruby@htapartners.com.sg
Subject: REQUEST FOR PRE-REPAIR SURVEY PROTOCOL FOR SMJ 9798R [OUR REF. TCL.GCN.RO.50522.19.ESS]

Please find the GIA report in order to proceed.

Chin Insurance (Singapore) Pte. Ltd.
1100 Springleaf Tower Singapore 079909
Tel: (65) 62247175

sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平獅城 Taiping SG

This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please delete the e-mail and any copies of it thereafter.

From: Ruby <ruby@htapartners.com.sg>
Sent: Friday, 21 August, 2019 11:33 AM
To: Department of CTI <claimsdept@sg.cntaiping.com>
Subject: REQUEST FOR PRE-REPAIR SURVEY PROTOCOL FOR SMJ 9798R [OUR REF. TCL.GCN.RO.50522.19.ESS]

Ref: SLP 5846S
TCL.GCN.ro.50522.19.ess

WITHOUT PREJUDICE

Chin Insurance Co (Singapore) Pte Ltd
Claims Department
1100 Springleaf Tower
Singapore 079909

By Email Only

VERY URGENT

GO-RENT PTE LTD

IDENT AND PRE-REPAIR SURVEY - ACCIDENT INVOLVING SMJ 9798R & SLP 5846S ALONG GEYLANG
AUGUST 2019 @ 1503 HRS

I am instructed by Go-Rent Pte Ltd to notify you of a road traffic accident on 20 August 2019 at about 1503hrs
on Road involving our clients' vehicle registration number SMJ 9798R and vehicle registration number
by your insured/insured's driver at the material time.

Following the accident, our clients' vehicle has been damaged. Before our clients proceed to repair the damaged
vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurers would
like to have a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated
time, we shall proceed to repair the vehicle without reference to you.

To: Mr. Lim & Partners
100, Marine Parade
Singapore 119074
Tel: 65 6333 1616
Fax: 65 6333 278
Email: lim@limandpartners.com.sg
Mobile: 9753 0313

If the information is contained in this message. If you are not the addressee indicated in this message (or
any of the message to such person), you may not copy or deliver this message to anyone. In such case, you
must delete the message and kindly notify the sender by reply email.

Scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

Scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

Das WeltAuto.
Used cars you can trust. Guaranteed.

Only at the sgCarMart Carnival @ Downtown East.
From 31 Aug to 1 Sep 2019



Chevrolet Cruze

Price Range

Depreciation

2010

Vehicle Type

Submit

Advanced Search

Home » Used Cars » LZY Motoring Pte Ltd » Chevrolet Cruze 1.6A

Chevrolet Cruze 1.6A

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

PREMIUM AD

Price \$13,600

Depreciation \$6,740 /yr
View models with similar depre

Reg Date 29-Sep-2010
(1yr 1mth COE left)

Mileage 110,000 km (12.3k /yr)

Manufactured 2010

Road Tax \$742 /yr

Transmission Auto

Dereg Value \$10,154 as of today (change)

OMV \$12,529

COE \$30,001

ARF \$12,529

Engine Cap 1,598 cc

Power 80.0 kW (107 bhp)

Curb Weight 1,388 kg

No. of Owners 4

Type of Vehicle Mid-Sized Sedan

Features

1.6L DOHC Engine, 6 Speed Auto Transmission, SRS Airbags, Digital Climatic Aircon, Multi-Function Steering Control, ABS, Auto Rain Sensors. View specs of the Chevrolet Cruze (2009-2018)

Accessories

Original Factory Fitted Audio, Sports Rims, Original Leather Seats, Reverse Sensors, Fog Lights Etc.

Description

Look No Further! Well Maintained Unit By Previous Owner. Stock Condition. Low Depreciation! Wears And Tears Replaced. View In Person To Believe The Condition. Appointment After Office Hours For Viewing Can Be Arranged. Trades In Are Welcome. Bank Loan/In House/High Loan And Insurance Will Be Arrange Accordingly To Your Needs. "Your Wheel's, Our Responsibility".

Category

PARF Car, Premium Ad Car

Status

Available

Resources



Car Valuation - Free

Find out the market value of your existing car for free. Get started



Vehicle Evaluation


Afraid of lemons? Request to have this car evaluated professionally. Find out more

Posted on: 26-Aug-2019 | Last Updated on: 26-Aug-2019

Compare



Price Chart



Click on the point to view the vehicle

Shortlist

Compare

Add note

Report Error

More Actions

Seller Information

Company

LZY Motoring Pte Ltd

* dealer's pricelist

* 15 vehs sold | 7 vehs available

Address

60 Jalan Lam Huat #03-01

Search cars nearby this location

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	747D

Vehicle Details

Vehicle No.:	SMJ9798R
Vehicle to be Exported:	No
Intended Deregistration Date:	28 Aug 2019
Vehicle Make:	CHEVROLET
Vehicle Model:	CRUZE 1.6L AUTO ABS D/AB 2WD 4DR
Primary Colour:	Grey
Manufacturing Year:	2010
Engine No.:	F16D36644041
Chassis No.:	KL1JA6961AK717450
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$12,463.00
Original Registration Date:	05 Oct 2010
First Registration Date:	05 Oct 2010
Transfer Count:	1
Actual ARF Paid:	\$12,463.00 6231

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	04 Oct 2020
PARF Rebate Amount:	\$6,854.00

Intended COE Rebate Details

COE Expiry Date:	04 Oct 2020
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$30,001.00
COE Rebate Amount:	\$3,299.00
Total Rebate Amount:	\$10,153.00

The information contained herein is correct as at 28 Aug 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	21/08/2019 17:06
Date Of Accident	20/08/2019 15:05
Exact Location Of Accident	191 GEYLANG ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMJ9798R
Insured/Policyholder	
Name Of Registered Owner	GO-RENT PTE LTD
Co Reg No	201824747D
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-92223331

Vehicle Particulars

Manufacturer	CHEVROLET
Model	CRUZE 1.6L AUTO ABS D/AB 2WD 4DR

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	5107335101
Cover Note Number	

Driver

Name of Driver	TEO JUN JIE
NRIC No	S9138645C
Date Of Birth	23/10/1991
Occupation	OUTDOOR
Date Of Driving Pass	12/02/2016
Driving Experience	3 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-83829474
Fax Number	
Contact Number	
EMail Address	JUNJI3_@HOTMAIL.COM

Address	BLK 662 HOUGANG AVENUE 4 #06-413
Postcode	530662
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TRAFFIC POLICE DIVISION HQ
Police Station Address	ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 65470000 - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

AS PER POLICE REPORT No.T/20190821/7026;

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLP5846S
Vehicle Make/Model/Colour	TOYOTA / COROLLA ALTIS 1.6 CVT
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	


DOI: 10.1002/for

1

-

IDAC KAKI BUKIT (VAC)
23 KAKI BUKIT AVE 4
Singapore 415931
Reporting Contact: Mr. Peter S. Sistrunk
Tel: 67446697
Fax: 67492305
NRIC/FIN No.:
E-mail: vac@idacsingnet.com.sg

Accident Sketch Plan



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the above above stated date and time I was traveling along 191 Geylang Road I was traveling straight when suddenly vehicle B turn into my lane without ~~signalling~~ signalling and collided on to my vehicle front left portion.

DECLARATION

I/We declare that the foregoing particulars are true to the best of my/our knowledge.



Policyholder's Signature
Date & Time:

4-1-1997 (Signature) 01/01/97

Driver's Signature
(If driver is not the policyholder)
Date & Time:

IDAC KAKI BUKIT (VAC)
23 KAKI BUKIT AVE 4

Singapore 415023
Reporting Centre (Policyholder's Signature)
Name: Tel: 67416699
Fax: 67492305
Email: vackb@singnet.com.sg

EURO SUCCESS SERV PTE. LTD

Blk 1 Kaki Bukit 6, #02-03 Singapore 417883

TEL: 67426231

FAX: 67411019

H/P: 98289277 (AH HUAT)

Vehicle No: SMJ9798R

Model: CHEVROLET CRUZE

not Authorized
LH
1/2 4000
Take photo After repair
Hong
23/8/19

QTY	List Items	Price \$
1	FRONT BUMPER	1100.00 De/waged ✓
1	FRONT BUMPER CENTRE GRILLE	105.00 n1 X
2	FRONT BUMPER SIDE	65.00 one ✓
1	FRONT BUMPER REINFORCEMENT	659.00 sel ✓
1	FRONT L/H BUMPER REINFORCEMENT STAYS	60.00 n1 X
1	FRONT BUMPERSponge	178.00 Torn ✓
10	FRONT BUMPER CLIPS @4.5	45.00 n1 ✓
1	FRONT GRILLE ASSY	218.00 n1 X
1	FRONT GRILLE LOGO	105.00 n1 X
1	FRONT L/H HEAD LAMPS	831.00 sel ✓
1	FRONT L/H HEAD LAMPS lower retainer	60.00 one ✓
1	FRONT SUPPORT PANEL ASSY	859.00 n1 X
1	FRONT L/H FOG LAMP	261.60 one ✓
1	FRONT L/H FOG LAMP COVER	105.00 sel ✓
1	FRONT L/H KNUCKLE ARM	484.00 n1 X
1	FRONT L/H SHOCK ABSORBER	391.00 n1 X
1	FRONT L/H LOWER ARM	455.00 n1 X
1	FRONT L/H WHEEL BEARING	250.00 n1 X
1	FRONT L/H FENDER	850.00 100/300 ✓
1	FRONT L/H FENDER INNER SHIELD	121.00 n1 X
1	STEERING RACK	1720.80 n1 X

4154.6
10%
3739.14
5009.14

TOTAL
LESS
TOTAL

Special Nett Items

1	FRONT L/H SPORT RIM	450.00	n1 X
1	FRONT L/H TYRE	200.00	sel X
1	FRONT NO. PLATE	50.00	sel X

Insurance Company's hence notify
the following:
To ensure the quality of the spray painting
The repairer must subject to confirmation
The repairer must survey on a "Without Prejudice" basis
The repairer must allow modification(s) is allowed
The repairer must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Labour Charges

TO RESPRAY UNDERCOATING	350.00	30
TO CHECK FRONT AND REAR ELECTRICAL WIRING	250.00	20
TO RESPRAY PAINTING AND ETC	1500.00	550
PANEL BEATING, CUT, WELD, REMOVE AND REPLACING ABOVE PARTS	1000.00	600
To conduct wheel alignment	100.00	70

12,021.06

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT19014845/UVF3N2

Date: 20/09/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN18163819011	
Claimant Vehicle No :	SMJ9798R	Insured Vehicle No :	SLP5846S	
Date of Loss:	20/08/2019	Nature of Claim:	TP	Claim No: SNM19D203911C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMJ9798R	Engine No:	F16D36644041
Make & Model:	CHEVROLET CRUZE, 1.6 2WD (A)	Chassis No:	KL1JA6961AK717450
Reg. Date:	05/10/2010 (Man. Year: 2010)	Odometer:	140162 km
Colour:	Grey		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth.

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,821.06	3,739.14	5,081.92	57.61
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,200.00	1,270.00	1,930.00	60.31
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	12,021.06	5,009.14	7,011.92	58.33
Approved Total (Overridden) (\$\$)		4,000.00		
Nett Amount (\$\$)	12,021.06	4,000.00	8,021.06	66.73

INSPECTION

Date of Assignment:	23/08/2019	
Date Inspected:	23/08/2019	Inspected At:
		Euro Success Services Pte Ltd (HQ)
		1 KAKI BUKIT AVENUE 6 #02-03
		AUTOBAY
		Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 19 Sep 2019)
Parts:	143	CHEVROLET CRUZE 1.6 2WD (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMJ9798R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER	Deformed / Warped	1,100.00 FL	*1,100.00 FL
2	1	*FRONT BUMPER CENTRE GRILLE	Not Necessary	105.00 FL	*- FL
3	2	*FRONT BUMPER SIDE RETAINER N/S	Cracked	65.00 FL	*65.00 FL
4	1	*FRONT BUMPER REINFORCEMENT	Bent	659.00 FL	*659.00 FL
5	1	*FRONT L/H BUMPER REINFORCEMENT STAYS	No such part	60.00 FL	*- FL
6	1	*FRONT BUMPER SPONGE	Torn	178.00 FL	*178.00 FL
7	10	*FRONT BUMPER CLIPS	Necessary	45.00 FL	*45.00 FL
8	1	*FRONT GRILLE ASSY	Not Necessary	318.00 FL	*- FL
9	1	*FRONT GRILLE LOGO	Not Necessary	105.00 FL	*- FL
10	1	*FRONT L/H HEAD LAMPS	Scratched	831.00 FL	*831.00 FL
11	1	*FRONT L/H HEAD LAMPS LOWER RETAINER	Necessary	60.00 FL	*60.00 FL
12	1	*FRONT SUPPORT PANEL ASSY	Not Necessary	859.00 FL	*- FL
13	1	*FRONT L/H FOG LAMP	Cracked	261.60 FL	*261.60 FL
14	1	*FRONT L/H FOG LAMP COVER	Scratched	105.00 FL	*105.00 FL
15	1	*FRONT L/H KNUCKLE ARM	Not Necessary	484.00 FL	*- FL
16	1	*FRONT L/H SHOCK ABSORBER	Not Necessary	391.00 FL	*- FL
17	1	*FRONT L/H LOWER ARM	Not Necessary	455.00 FL	*- FL
18	1	*FRONT L/H WHEEL BEARING	Not Necessary	250.00 FL	*- FL
19	1	*FRONT L/H FENDER	Dented / Bent	850.00 FL	*850.00 FL
20	1	*FRONT L/H FENDER INNER SHIELD	Not Necessary	121.00 FL	*- FL
21	1	*STEERING RACK	Not Necessary	1,720.80 FL	*- FL
22	1	*FRONT L/H SPORT RIM	Repair	450.00 FS	*- FS
23	1	*FRONT L/H TYRE	Serviceable	200.00 FS	*- FS
24	1	*FRONT NO PLATE	Serviceable	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,723.40	4,154.60
- List Item Discount on L Items 10.00/10.00% (\$\$)	902.34	415.46
Total Parts (\$\$)	8,821.06	3,739.14

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RESPRAY UNDERCOATING	New	350.00	30.00
2	TO CHECK FRONT AND REAR ELECTRICAL WIRING	New	250.00	20.00
3	TO RESPRAY PAINTING AND ETC	New	1,500.00	550.00
4	PANEL BEATING ,CUT ,WELD ,REMOVE AND REPLACING ABOVE PARTS	New	1,000.00	600.00
5	TO CONDUCT WHEEL ALIGNMENT	New	100.00	70.00
Gross Labour Cost (\$\$)			3,200.00	1,270.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >