

22/03/2002

ASS. REC. BY:

REF: CS 3/CT1 19014855 / GCF302

Special Instruction:

Surveyor: GA

ASSIGNMENT (Office)

From (Person): Elaine Cheong

of CT1

Date/Time: 23.8.19 14.07p.m

Estimated Cost: Bill to:

OD TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: FBF 1986T

Insured: PC 60 T

at Workshop m/s Speedy Motor Cycle

Tel: 64815567

of 10 Amic Ind Park 2A #05-21

Policy No: DMBISA16912618022

Claim No: SNM190203750C02

Sum Insured:

Excess:

Make of Veh:

D.O.A. 8.2.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 23.8.19 2.17p.m

Person Contacted: Lim

Vehicle IN / OUT

Date/Time	Action/Instruction (X) Estimate
	FBF 1986T -X
	PC 603T -X
	Demantle: 29/8/2019

Verimon

mp"

You are returning to a previous page. This page may be outdated.
Please click 'Refresh' to refresh the page.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	21 Aug 2019		23 Aug 2019 14:07 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS				[Created by insurer]					
Insured:									
Main Claimant:	WAN JURAIMI BIN WAN ANDALLY , ID: S9403697F								
Vehicle Reg. No.:	FBF1986T	Date of Loss:	08/08/2019 06:00 - :59						
Claim Type:	TP / SNM19D203750C02	Policy/Cover Note No.:	DMB1SN16912618022						
Vehicle Reg. No. (Insured):	PC6030T	Policy No. (Claimant):	5086357801-02						
		Excess:	S\$2,000.00						
Repairer:	Speedy Motor Cycle Service Centre (HQ) 10 ANG MO KIO IND PARK 2A #05-21, 568047 Ang Mo Kio - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 03/09/2019]								
ASSOCIATED MAIL RECEIVED				View All	Compose Case Mail				
There are no mail for this case.									
ALL ASSOCIATED TASKS									
View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Catherine Chong (LKK Auto)

From: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>
Sent: Friday, 23 August, 2019 2:01 PM
To: Tan Mei Ling; assignments
Subject: RE: FW: FW: OUR RWEF: SNM19D203750-PC6030T-CML - FW: Fax Message NO.2055

WITHOUT PREJUDICE
SAVE AS TO COSTS

Dear Mei Ling,

We refer to your letter dated 23.08.2019.

We regret to inform that we are not agreeable to your list of proposed surveyors and will be assigning our panel surveyor, M/s LKK Auto Consultants to conduct the Pre-repair survey.

Please contact our surveyor to conduct the post repair inspection before returning the repaired vehicle to the claimant.

Aside to LKK,

Please refer to the email below and liaise with third party workshop accordingly.

Thank you.

Regards

Tan Kah Leong

Assistant Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6193 | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Tan Mei Ling [mailto:ml_tan@juseq.com.sg]
Sent: Friday, 23 August, 2019 12:36 PM
To: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>; Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Subject: Fwd: FW: FW: OUR RWEF: SNM19D203750-PC6030T-CML - FW: Fax Message NO.2055

Dear Sirs

We refer to your email of even date.

We are instructed that our client is not agreeable to all the surveyors proposed by you.

Pursuant to Appendix C, pre-action protocol for NIMA cases, we are also instructed to furnish you our client's list of motor surveyors for your selection:-

- 1) UNITED Appraisal And Management Pte Ltd
- 2) SK Auto Consultants
- 3) Chartered Auto Assessors
- 4) LCW APPRAISER PTE LTD
- 5) Sincere Appraisal Services
- 6) Pal's Appraisal Pte Ltd
- 7) Mc-Coy Appraiser Pte Ltd
- 8) CM Automotive Consultancy

Please be informed that if the above is not agreeable by you, our client's motor vehicle is available for pre-repair inspection at the under-stated workshop:-

Speedy Motor Cycle Service Centre

Blk 10 Ang Mo Kio Industrial Park 2A

#05-21 Singapore 568047

Person In-Charge: Mr Lim Sam Hee at Tel: 6481 5567 / 9388 6867

Fax No. 6482 5567

*Further, please remind your appointed surveyor to request for post repair inspection if you wish to do so under NIMA Protocol Appendix C paragraph 2.11.

From: Tan Kah Leong [mailto:KahLeong.Tan@sg.cntaiping.com]

Sent: Friday, August 23, 2019 10:25 AM

To: CLAIMS@JUSEQ.COM.SG

Subject: RE: FW: OUR RWEF: SNM19D203750-PC6030T-CML - FW: Fax Message NO.2055

Without Prejudice

Dear Mei Ling,

We refer to your email dated 21 August 2019.

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
LOW SAR HUEI
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
HONG FOOK CHOY
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Thank you.

Regards

Tan Kah Leong

Assistant Executive

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

DID: (65) 6389 6193 | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Claims Dept of CTI

Sent: Friday, 23 August, 2019 10:15 AM

To: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>; Alfred Toh <alfred.toh@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>

Subject: FW: FW: OUR RWEF: SNM19D203750-PC6030T-CML - FW: Fax Message NO.2055

Dear Kah Leong,

Please assist.

Regards,

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

T: (65) 63896116 | F: (65) 62247175

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Tan Mei Ling [mailto:ml_tan@juseq.com.sg]

Sent: Friday, 23 August, 2019 9:58 AM

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>; Elaine Cheong <elaine.cheong@sg.cntaiping.com>; Alfred Toh <alfred.toh@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>

Subject: Fwd: FW: OUR RWEF: SNM19D203750-PC6030T-CML - FW: Fax Message NO.2055

Dear Sirs

Our Notice of Accident dated 21/8/19 sent on the same day.

We have yet to hear from you. Please revert urgently.

-----Original Message-----

From: Claims Dept of CTI [<mailto:claimsdept@sg.cntaiping.com>]

Sent: Wednesday, August 21, 2019 4:39 PM

To: Elaine Cheong <elaine.cheong@sg.cntaiping.com>; Alfred Toh <alfred.toh@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>; CLAIMS@JUSEQ.COM.SG

Subject: OUR RWEF: SNM19D203750-PC6030T-CML - FW: Fax Message NO.2055

Dear Elaine,

Please conduct PRS for FBF1986T.

Note : officer in charge - Elaine Cheong 63896530.

Regards,

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
T: (65) 63896116 | F: (65) 62247175

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

-----Original Message-----

From: FA-X5575C-16A-CL
Sent: Wednesday, 21 August, 2019 4:19 PM
To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Subject: FW: Fax Message NO.2055

-----Original Message-----

From: RC6004F-15A-CL@sg.cntaiping.com [mailto:RC6004F-15A-CL@sg.cntaiping.com]
Sent: Wednesday, 21 August, 2019 3:31 PM
To: FA-X5575C-16A-CL <FA-X5575C-16A-CL@sg.cntaiping.com>
Subject: Fax Message NO.2055

This E-mail was sent from "RC6004F-15A-CL" (MP C6004ex).

Queries to: RC6004F-15A-CL@sg.cntaiping.com

--

Regards

Tan Mei Ling

Sent for and on behalf of

JusEquity Law Corporation
Advocates & Solicitors

Commissioner For Oaths

171 Chin Swee Road #02-06 CES Centre Singapore 169877

☎ : (65) 6536 9339 | DID : (65) 6506 6063

📠 : (65) 6536 5368

✉ : ml_tan@juseq.com.sg

CONFIDENTIALITY CAUTION

This message is intended only for the use of the individual or entity to whom it is addressed and contains information that is privileged and confidential. If you, the reader of this message, are not the intended recipient, you should not disseminate, distribute or copy this communication. If you have received this communication in error, please notify us immediately by telephone and return the original message to us at the above address at our expense. Thank you.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

--

Regards

Tan Mei Ling

Sent for and on behalf of

JusEquity Law Corporation

Advocates & Solicitors

Commissioner For Oaths

171 Chin Swee Road #02-06 CES Centre Singapore 169877

☎ : (65) 6536 9339 | DID : (65) 6506 6063

📠 : (65) 6536 5368

✉ : ml_tan@juseq.com.sg

CONFIDENTIALITY CAUTION

This message is intended only for the use of the individual or entity to whom it is addressed and contains information that is privileged and confidential. If you, the reader of this message, are not the intended recipient, you should not

disseminate, distribute or copy this communication. If you have received this communication in error, please notify us immediately by telephone and return the original message to us at the above address at our expense. Thank you.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>



**SINGAPORE
POLICE FORCE**



T/20190809/2132

Police Station Of Origin:
Serangoon North NPP
108 Serangoon North Ave 1 #01-709
SINGAPORE 550108
Tel No: 1800-2849999

1 of 3

Report No. T/20190809/2132

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 09/08/2019 21:40		Vide Report No.: L/20190808/0035	Station/Diary No.: 12
Informant's Particulars			
Name of Informant: WAN JURAIMI BIN WAN ANDALLY		Address: APT BLK 589D MONTREAL DRIVE #09-128 SINGAPORE 754589	
ID Type / ID No.: NRIC NO / S9403697F		Contact No.: Home/Office: Mobile: 98582047	
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 25	Date of Birth: 23/01/1994	Type of Informant: Rider
Race: Malay		Language:	Institution / School Name:
Occupation: CISCO OFFICER		Driving Licence Information: Class: 2B,2A,2,3 Date of Expiry:	

General Information of the Accident				
Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 08/08/2019 06:30	Type of Location:
Location: SEMBAWANG ROAD sembawang Road Towards Sembawang Park direction near to Sembawang CC Straight Junction				
Weather:		Road Surface:	Road Speed Limit:	
Traffic Flow:		Traffic Control:	Traffic Volume:	
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance: No	

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No. of Passenger
FBF1986T	Motorcycle	YAMAHA	YZF-R1	White		0
PC6030T	Bus/Coach/Minibus					0

Details of Vehicle Insurance					
Vehicle No.	Insurance Company	Insurance No.	Effective	Expiry Date	
FBF1986T	NTUC Income Insurance Co-Operative Limited	5086357801-02	18/11/2018	17/11/2019	



**SINGAPORE
POLICE FORCE**



T/20190809/2132

Police Station Of Origin:
Serangoon North NPP
108 Serangoon North Ave 1 #01-709
SINGAPORE 550108
Tel No: 1800-2849999

2 of 3
Report No. T/20190809/2132

CONTINUATION OF REPORT

Brief Details.

On the 08/08/2019 at about 0630hrs, I was riding my bike FBF1986T along Sembawang Road Towards Sembawang Park direction near to Sembawang CC Straight Junction. It is a 2 lane road, I was stationary at the said junction at the stop line, on the right lane and there was a big Passenger Bus hide of me and there was a SBS bus on the yellow box right beside me. As the traffic light indicated green letter "B", the SES bus moved and I was still stationary. But the Said bus behind me hit onto my rear, I itched forward and fell. I Felt pain on my right leg and there was some abrasion on my left wrist area. I was still able to stand up and I took pictures of the scene and the said bus that hit onto me was PC6030T and the driver provided me his particulars: Wang Mohai G5266996R. After taking pictures I continued to feel pain in my right leg and therefore I called for Ambulance. Shortly Ambulance and traffic police came and Tp gave me a case card (L/20190808/0035) and I was conveyed to KTPH. After the doctor made a check on me, I was informed that my right leg shin area was fractured and some abrasion on the left wrist and was given 2 weeks of hospital leave. After the medical examination, I was discharged. I then was informed to lodge an accident report about the said accident.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	697F
Vehicle No.:	FBF1986T
Vehicle to be Exported:	No
Intended Deregistration Date:	25 Aug 2019
Vehicle Make:	YAMAHA
Vehicle Model:	YZF-R1
Primary Colour:	White
Manufacturing Year:	2011
Engine No.:	N519E014714
Chassis No.:	JYARN221000010383
Maximum Power Output:	-
Open Market Value:	\$15,679.00
Original Registration Date:	14 Mar 2011
First Registration Date:	14 Mar 2011
Transfer Count:	2
Actual ARF Paid:	\$2,352.00
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
COE Expiry Date:	13 Mar 2021
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$2,604.00
COE Rebate Amount:	\$448.00
Total Rebate Amount:	\$448.00

The information contained herein is correct as at 25 Aug 2019

OK

Bike model
Yamaha YZF-R1

Type
Any

Price From
Any

Price To
Any

Class
2

MORE SEARCH OPTIONS

SEARCH VIEW ALL (/LISTING/USEDBIKES/LISTING/)

SEARCH

Yamaha YZF-R1 (/listing/usedbike/yamaha-yamaha-yzf-r1/13438/)



(/listing/usedbike/yamaha-yamaha-yzf-r1/13438/)

SGD\$34800

Reg : 04/09/2015

Type: Sport Bikes

998cc

YZF R1 With Many Accessories. Trade in/Loan available. Visit 2 Yishun Industrial Street 1, Northpoint bizhub #01-23 Singapore 768159

Posted on : 16/08/2019

★ PAID AD ★ DEALER AD

COMPARE DETAILS (/LISTING/USEDBIKE/YAMAHA-YAMAHA-YZF-R1/13438/)

Yamaha YZF-R1 (/listing/usedbike/yamaha-yamaha-yzf-r1/13800/)



(/listing/usedbike/yamaha-yamaha-yzf-r1/13800/)

SGD\$12000

Reg : 10/07/2009

Type: Sport Bikes

998cc

85000km

Urgent Sales. Interested Parties Can Contact Me.

Posted on : 14/08/2019

★ DIRECT SELLER

COMPARE DETAILS (/LISTING/USEDBIKE/YAMAHA-YAMAHA-YZF-R1/13800/)

Yamaha YZF-R1 (/listing/usedbike/yamaha-yamaha-yzf-r1/13690/)



(/listing/usedbike/yamaha-yamaha-yzf-r1/13690/)

SGD\$49000

Reg : 28/02/2017

Type: Sport Bikes

998cc

25000km

Excellent Condition. Accident Free. Massive Load Of Accessories, Full Carbon Parts, 1 And Only In Sg. 1 Owner. Fully Serviced At Hong Leong Yamaha Only. From Day One Eo Change At 50Km, 150Km...

Posted on : 04/08/2019

★ DIRECT SELLER

■ COMPARE DETAILS > (/LISTING/USEDBIKE/YAMAHA-YAMAHA-YZF-R1/13690/)

Yamaha YZF-R1 (/listing/usedbike/yamaha-yamaha-yzf-r1/9106/)



(/listing/usedbike/yamaha-yamaha-yzf-r1/9106/)

Reg : 11/03/2009

Type: Sport Bikes

998cc

73034km

Well maintain. Trade in/Loan of vehicle available. Interested buyers are welcome to neg. Come visit Albert Motor Supply.

Never Track.

Posted on : 19/03/2019

★ PAID AD ★ DEALER AD

■ COMPARE DETAILS > (/LISTING/USEDBIKE/YAMAHA-YAMAHA-YZF-R1/9106/)

Yamaha YZF-R1M (/listing/usedbike/yamaha-yamaha-yzf-r1/8829/)



(/listing/usedbike/yamaha-yamaha-yzf-r1/8829/)

Reg : 22/07/2015

Type: Sport Bikes

998cc

17700km

Showroom condition Yamaha R1M for sale with lot of accessories. 100% accident free Loan and trade in avail at attractive rate. Call us now for more info. 1 Expat Owner With Low Mileage Of 17,700km Only.

Posted on : 14/03/2019

★ PAID AD ★ DEALER AD

■ COMPARE DETAILS > (/LISTING/USEDBIKE/YAMAHA-YAMAHA-YZF-R1/8829/)

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	21 Aug 2019		23 Aug 2019 14:07 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	-, Co. Reg. No.: -								
Main Claimant:	WAN JURAIMI BIN WAN ANDALLY , ID: S9403697F								
Vehicle Reg. No.:	FBF1986T	Date of Loss:	08/08/2019 06:00 - :59 [100 Months and 25 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D203750C02	Policy/Cover Note No.:	DMB1SN16912618022						
Vehicle Reg. No. (Insured):	PC6030T	Policy No. (Claimant):	5086357801-02						
		Excess:	S\$2,000.00						
Repairer:	Speedy Motor Cycle Service Centre (HQ) 10 ANG MO KIO IND PARK 2A #05-21, 568047 Ang Mo Kio - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 03/09/2019]								
ASSOCIATED MAIL RECEIVED			View All	Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS			View All	Search Tasks					
			Create New Task	Complete					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*FBF1986T (SNM19D203750C02)

[PC6030T]

TP

WAN JURAIMI BIN WAN ANDALLY

Aug 8 2019 6:00AM

[-]

Speedy Motor Cycle Service Centre

Upload Documents Upload Photos Compose New Letter			View	View in Browser <input type="button" value="v"/>
Photos/Images			3 per page <input type="button" value="v"/>	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	27/08/19 18:16	General View		Load JPG <input checked="" type="checkbox"/>
2	27/08/19 18:16	General View		Load JPG <input checked="" type="checkbox"/>
3	27/08/19 18:16	General View		Load JPG <input checked="" type="checkbox"/>
4	27/08/19 18:16	General View		Load JPG <input checked="" type="checkbox"/>
5	27/08/19 18:16	General View		Load JPG <input checked="" type="checkbox"/>
6	27/08/19 18:16	General View		Load JPG <input checked="" type="checkbox"/>
7	27/08/19 18:16	General View		Load JPG <input checked="" type="checkbox"/>
8	27/08/19 18:16	General View		Load JPG <input checked="" type="checkbox"/>
9	27/08/19 18:16	General View		Load JPG <input checked="" type="checkbox"/>
10	27/08/19 18:16	General View		Load JPG <input checked="" type="checkbox"/>
11	27/08/19 18:16	General View		Load JPG <input checked="" type="checkbox"/>
12	27/08/19 18:16	General View		Load JPG <input checked="" type="checkbox"/>
13	27/08/19 18:16	General View		Load JPG <input checked="" type="checkbox"/>
14	27/08/19 18:16	General View		Load JPG <input checked="" type="checkbox"/>
15	27/08/19 18:16	General View		Load JPG <input checked="" type="checkbox"/>
16	27/08/19 18:16	General View		Load JPG <input checked="" type="checkbox"/>
17	27/08/19 18:16	General View		Load JPG <input checked="" type="checkbox"/>
18	27/08/19 18:16	General View		Load JPG <input checked="" type="checkbox"/>
19	27/08/19 18:16	General View		Load JPG <input checked="" type="checkbox"/>
20	27/08/19 18:16	General View		Load JPG <input checked="" type="checkbox"/>
21	27/08/19 18:16	General View		Load JPG <input checked="" type="checkbox"/>
22	27/08/19 18:17	General View		Load JPG <input checked="" type="checkbox"/>
23	27/08/19 18:17	General View		Load JPG <input checked="" type="checkbox"/>
24	27/08/19 18:17	General View		Load JPG <input checked="" type="checkbox"/>
25	27/08/19 18:17	General View		Load JPG <input checked="" type="checkbox"/>
26	27/08/19 18:17	General View		Load JPG <input checked="" type="checkbox"/>
27	27/08/19 18:17	General View		Load JPG <input checked="" type="checkbox"/>
28	27/08/19 18:17	General View		Load JPG <input checked="" type="checkbox"/>
29	27/08/19 18:17	General View		Load JPG <input checked="" type="checkbox"/>
30	27/08/19 18:17	General View		Load JPG <input checked="" type="checkbox"/>
31	27/08/19 18:17	General View		Load JPG <input checked="" type="checkbox"/>
32	27/08/19 18:17	General View		Load JPG <input checked="" type="checkbox"/>
33	27/08/19 18:17	General View		Load JPG <input checked="" type="checkbox"/>
34	27/08/19 18:17	General View		Load JPG <input checked="" type="checkbox"/>
35	27/08/19 18:17	General View		Load JPG <input checked="" type="checkbox"/>
36	27/08/19 18:17	General View		Load JPG <input checked="" type="checkbox"/>
37	27/08/19 18:17	General View		Load JPG <input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	27/08/19 18:17	General View	 Load JPG	<input checked="" type="checkbox"/>
39	27/08/19 18:17	General View	 Load JPG	<input checked="" type="checkbox"/>
40	27/08/19 18:17	General View	 Load JPG	<input checked="" type="checkbox"/>
41	27/08/19 18:17	General View	 Load JPG	<input checked="" type="checkbox"/>
42	27/08/19 18:17	General View	 Load JPG	<input checked="" type="checkbox"/>
43	27/08/19 18:17	General View	 Load JPG	<input checked="" type="checkbox"/>
44	27/08/19 18:17	General View	 Load JPG	<input checked="" type="checkbox"/>
45	27/08/19 18:17	General View	 Load JPG	<input checked="" type="checkbox"/>
46	27/08/19 18:17	General View	 Load JPG	<input checked="" type="checkbox"/>
47	27/08/19 18:17	General View	 Load JPG	<input checked="" type="checkbox"/>
48	27/08/19 18:17	General View	 Load JPG	<input checked="" type="checkbox"/>
49	27/08/19 18:17	General View	 Load JPG	<input checked="" type="checkbox"/>
50	27/08/19 18:17	General View	 Load JPG	<input checked="" type="checkbox"/>
51	27/08/19 18:17	General View	 Load JPG	<input checked="" type="checkbox"/>
52	27/08/19 18:17	General View	 Load JPG	<input checked="" type="checkbox"/>
53	27/08/19 18:17	General View	 Load JPG	<input checked="" type="checkbox"/>
54	27/08/19 18:17	General View	 Load JPG	<input checked="" type="checkbox"/>
55	27/08/19 18:17	General View	 Load JPG	<input checked="" type="checkbox"/>
56	27/08/19 18:17	General View	 Load JPG	<input checked="" type="checkbox"/>
57	27/08/19 18:17	General View	 Load JPG	<input checked="" type="checkbox"/>
58	27/08/19 18:17	General View	 Load JPG	<input checked="" type="checkbox"/>
59	27/08/19 18:17	General View	 Load JPG	<input checked="" type="checkbox"/>
60	27/08/19 18:17	General View	 Load JPG	<input checked="" type="checkbox"/>
61	27/08/19 18:17	General View	 Load JPG	<input checked="" type="checkbox"/>
62	27/08/19 18:17	General View	 Load JPG	<input checked="" type="checkbox"/>
63	27/08/19 18:17	General View	 Load JPG	<input checked="" type="checkbox"/>
64	27/08/19 18:17	General View	 Load JPG	<input checked="" type="checkbox"/>
65	27/08/19 18:17	General View	 Load JPG	<input checked="" type="checkbox"/>
66	27/08/19 18:17	General View	 Load JPG	<input checked="" type="checkbox"/>
67	27/08/19 18:17	General View	 Load JPG	<input checked="" type="checkbox"/>
68	27/08/19 18:17	General View	 Load JPG	<input checked="" type="checkbox"/>
69	27/08/19 18:17	General View	 Load JPG	<input checked="" type="checkbox"/>
70	27/08/19 18:17	General View	 Load JPG	<input checked="" type="checkbox"/>
71	27/08/19 18:17	General View	 Load JPG	<input checked="" type="checkbox"/>
72	27/08/19 18:17	General View	 Load JPG	<input checked="" type="checkbox"/>
73	27/08/19 18:17	General View	 Load JPG	<input checked="" type="checkbox"/>
74	27/08/19 18:17	General View	 Load JPG	<input checked="" type="checkbox"/>
75	27/08/19 18:17	General View	 Load JPG	<input checked="" type="checkbox"/>
76	27/08/19 18:17	General View	 Load JPG	<input checked="" type="checkbox"/>
77	27/08/19 18:17	General View	 Load JPG	<input checked="" type="checkbox"/>
78	27/08/19 18:17	General View	 Load JPG	<input checked="" type="checkbox"/>
79	27/08/19 18:17	General View	 Load JPG	<input checked="" type="checkbox"/>
80	27/08/19 18:17	General View	 Load JPG	<input checked="" type="checkbox"/>
81	30/08/19 12:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
82	30/08/19 12:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
83	30/08/19 12:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
84	30/08/19 12:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
85	30/08/19 12:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
86	30/08/19 12:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
87	30/08/19 12:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
88	30/08/19 12:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
89	30/08/19 12:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
90	30/08/19 12:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
91	30/08/19 12:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
92	30/08/19 12:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
93	30/08/19 12:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
94	30/08/19 12:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
95	30/08/19 12:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
96	30/08/19 12:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
97	30/08/19 12:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
98	30/08/19 12:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
99	30/08/19 12:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
100	30/08/19 12:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
101	30/08/19 12:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
102	30/08/19 12:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
103	30/08/19 12:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
104	30/08/19 12:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
105	30/08/19 12:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
106	30/08/19 12:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
107	30/08/19 12:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
108	30/08/19 12:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
109	30/08/19 12:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
110	30/08/19 12:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
111	30/08/19 12:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
112	30/08/19 12:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
113	30/08/19 12:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
114	30/08/19 12:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
115	30/08/19 12:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
116	30/08/19 12:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
117	30/08/19 12:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
118	30/08/19 12:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
119	30/08/19 12:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
120	30/08/19 12:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
121	30/08/19 12:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
122	30/08/19 12:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
123	30/08/19 12:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
124	30/08/19 12:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
125	30/08/19 12:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
126	30/08/19 12:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
127	30/08/19 12:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
128	30/08/19 12:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
129	30/08/19 12:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
130	30/08/19 12:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
131	30/08/19 12:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
132	30/08/19 12:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
133	30/08/19 12:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
134	30/08/19 12:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
135	30/08/19 12:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
136	30/08/19 12:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
137	30/08/19 12:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
138	30/08/19 12:32	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
139	30/08/19 12:32	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
140	30/08/19 12:32	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
141	30/08/19 12:32	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
142	30/08/19 12:32	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
143	30/08/19 12:32	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
144	30/08/19 12:32	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
145	30/08/19 12:32	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
146	30/08/19 12:32	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
147	30/08/19 12:32	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
148	30/08/19 12:32	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
149	30/08/19 12:32	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
150	30/08/19 12:32	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
151	30/08/19 12:32	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
152	30/08/19 12:32	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
153	30/08/19 12:32	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
154	30/08/19 12:32	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
155	30/08/19 12:32	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
156	30/08/19 12:32	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
157	30/08/19 12:32	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
158	30/08/19 12:32	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
159	30/08/19 12:32	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
160	30/08/19 12:32	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
161	30/08/19 12:32	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
162	30/08/19 12:32	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
163	30/08/19 12:32	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
164	30/08/19 12:32	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
165	30/08/19 12:32	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
166	30/08/19 12:32	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
167	30/08/19 12:32	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
168	30/08/19 12:32	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
169	30/08/19 12:32	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
170	30/08/19 12:32	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
171	30/08/19 12:32	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
172	30/08/19 12:32	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
173	30/08/19 12:32	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
174	30/08/19 12:32	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
175	30/08/19 12:32	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
176	30/08/19 12:32	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
177	30/08/19 12:32	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
178	30/08/19 12:32	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
179	30/08/19 12:32	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
180	30/08/19 12:32	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
181	30/08/19 12:32	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
182	30/08/19 12:32	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
183	30/08/19 12:32	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
184	30/08/19 12:32	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>

Linked Accident Report Documents

			View	View in Browser
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Hua Hong Pte Ltd (Sungei Kadut)	Thumbnail	Print
1	21/08/19 14:58	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
2	21/08/19 14:58	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
3	21/08/19 14:58	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
4	21/08/19 14:58	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Hua Hong Pte Ltd (Sungei Kadut)	Thumbnail	Print
1	21/08/19 14:57	Accident Sketch Plan	Load TIF	
2	21/08/19 14:57	Accident Sketch Plan	Load TIF	
3	21/08/19 14:57	POLICE REPORT	Load TIF	
4	21/08/19 14:57	POLICE REPORT	Load TIF	
5	21/08/19 14:57	POLICE REPORT	Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div style="border: 1px solid black; width: 100%; height: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/CTI19014855/GCF3E2**Date:** 03/09/2019REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMB1SN16912618022

Claimant Vehicle No : FBF1986T **Insured Vehicle No :** PC6030T

Date of Loss: 08/08/2019 Nature of Claim: TP Claim No: SNM19D203750C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBF1986T**

Make & Model: YAMAHA YZF-R1, 998cc (M) Engine No: N519E014714

Reg. Date: 14/03/2011 (Man. Year: 2011) Chassis No: JYARN221000010383

Colour: Black Odometer: 0 km

Engine Capacity: 998 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 120/70Z R17 Rear Tyre Size: 190/50Z R17

Front Left Side: Bridgestone 4 mm Rear Left Side: Bridgestone 4 mm

Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 23/08/2019

Date Inspected: 23/08/2019 Inspected At: Speedy Motor Cycle Service Centre (HQ)
10 ANG MO KIO IND PARK 2A #05-21
Singapore 568047

Estimated Period of Repair: 5.0 days

Adjuster: XING GUO QIANG**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$7,000.00 -\$8,000.00

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 03 Sep 2019)	
Parts:	N/A	YAMAHA YZF-R1 998cc (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBF1986T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >