



DAVANTI
Proven Performance Tyre



31 Aug & 1 Sep | 10am - 8pm
Downtown East Carpark B
SEE YOU @ BOOTH 2!

SPARKO Kallias @ \$356 includes GST
FREE 1 Essential Servicing & 1 Grooming (worth \$236 total)
Plus Many Other Benefits!



Follow us:  

Nissan Sylphy

Price Range

Depreciation

2015

Vehicle Type

Advanced Search

Home » Used Cars » GOwheeler Pte Ltd » Nissan Sylphy 1.6A

Nissan Sylphy 1.6A

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

PREMIUM AD



Our Accreditations



Singapore Vehicle Traders Association



Price \$58,800

Depreciation ⑦ \$8,120 /yr
View models with similar depreReg Date 18-Nov-2015
(6yrs 2mths 22days COE left)

Mileage 75,333 km (20k /yr)

Manufactured ⑦ 2015

Road Tax ⑦ \$742 /yr

Transmission Auto

Dereg Value ⑦ \$47,234 as of today (change)

OMV ⑦ \$16,439

COE ⑦ \$56,001

ARF ⑦ \$16,439

Engine Cap 1,598 cc

Power 85.0 kW (113 bhp)

Curb Weight ⑦ 1,205 kg

No. of Owners ⑦ 1

Type of Vehicle Mid-Sized Sedan

Features

114bhp DOHC Engine, 154Nm Torque, Advanced Xtronic CVT Gearbox, 0-100km/h 11.7s, Navigation, Bluetooth, Auto Retractable Side Mirrors. View specs of the Nissan Sylphy (2013-2016)

Accessories

16" Rims, Keyless Entry/Start, Dual Climatic Aircon With Rear Aircon, Reverse Camera, Reverse Sensors.

Description

Low Interest Rate. 1 Year Warranty. Balloon Scheme, In-house Financing Options Available. Just Replaced Car Battery. Buy With A Peace Of Mind. 1 Owner, 100% Genuine Mileage. Well Maintained. No Chassis/Structural Damage. Immaculate Condition. All Trade In Welcome.

Category

PARF Car, Premium Ad Car

Status

Available

Resources



Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. Find out more



Car Valuation - Free


Find out the market value of your existing car for free. Get started

Posted on: 10-Aug-2019 | Last Updated on: 18-Aug-2019

Up: Compare

More Financial Info

Price Chart



Click on the point to view the vehicle

Shortlist

Compare

Add note

Report Error

More Actions

Seller Information

Company

GOwheeler Pte Ltd




» dealer's pricelist

» 50 vehs sold | 70 vehs available

Address

60 Jalan Lam Huat #01-03/04/05/39

Search cars nearby this location



Nissan Sylphy

Price Range ▾

Depreciation ▾

2016 ▾

Vehicle Type ▾

Advanced Search

Home » Used Cars » Cosmo Automobiles » Nissan Sylphy 1.6A

Nissan Sylphy 1.6A

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map



Price \$63,800

Depreciation \$7,680 /yr
View models with similar depreReg Date 10-Nov-2016
(7yrs 2mths 14days COE left)

Mileage 84,339 km (30.2k /yr)

Manufactured 2016

Road Tax \$742 /yr

Transmission Auto

Dereg Value \$49,452 as of today (change)

OMV \$16,910

COE \$50,991

ARF \$16,910

Engine Cap 1,598 cc

Power 85.0 kW (113 bhp)

Curb Weight 1,205 kg

No. of Owners 1

Type of Vehicle Mid-Sized Sedan

Features

Powerful 1.6L DOHC Engine, Automatic Transmission, Airbags, ABS, DRL, Immobilizer, Keyless Entry/Start/Stop, Digital Climate Aircon Controls. View specs of the Nissan Sylphy (2013-2016)

Accessories

Sports Rims, Leather Seats, Built-In Audio, GPS, Steering Controls, Solar Film, Reverse Sensors/Camera, Retractable Side Mirrors, Front/Back Camera.

Description

Promo 1.98% Interest Rate! Purchase From An Award Winning Dealership! 1 Owner! STA Certified Accident Free Quality Pre Owned With Low Mileage Done And Agent Warranty For Peace Of Mind. 100% Loan Approval With Our Flexible In House Financing Available. View Today!

Category

PARF Car, STA Evaluated Car

Status

Available

Resources



Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. Find out more



Car Valuation - Free

Find out the market value of your existing car for free. Get started

Posted on: 26-Aug-2019
Compare

Updated on: 26-Aug-2019

STA Evaluation


This vehicle has undergone a 120-point check by STA, and has received a Graded B for its overall condition.

View more STA vehicles | Learn More on STA



Location Map

Price Chart



Click on the point to view the vehicle

Shortlist

Compare

Add note

Report Error

More Actions

Seller Information

Company

Cosmo Automobiles

* dealer's pricelist

* 69 vehs sold | 75 vehs available

[> Back to OneMotoring](#)

Enquire Road Tax Expiry Date

Review Details

Vehicle No.
SE2018K

Vehicle Make/Model
NISSAN / SYLPHY 1.6 CVT ABS D/AIRBAG 2WD 4DR

Road Tax Expiry Date :
07 Oct 2019

The information contained herein is correct as at 23 Aug 2019 / 14:44.

Save as PDF

OK →

Print

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est. Submitted	Adj. Assigned	Adj. Rpt	Adj. Submitted	Ins. Auth'd	Status
Main	28 Aug 2019		28 Aug 2019 09:03 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	-, Co. Reg. No.: -			
Main Claimant:	CONNECT4CAR PTE LTD , Co. Reg. No.: 201411459M			
Vehicle Reg. No.:	SE2018K	Date of Loss:	10/08/2019 04:00 - :59 [46 Months and 2 Days From LTA Reg Date (Man Yr)]	
Claim Type:	TP / SNM19D203763C02	Policy/Cover Note No.:	DMB1SN19315419000	
Vehicle Reg. No. (Insured):	PC8194R	Policy No. (Claimant):	999994343	
		Excess:	S\$0.00	
Repairer:	Teamwork Garage Pte Ltd (HQ) 53 Ubi Ave 1 #01-24, Paya Ubi Industrial Park, 408934 Ubi - Tel: 6844 2475			
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]			
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by LEE HOCK ANN] ... [Final Rpt due 06/09/2019]			

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SE2018K (SNM19D203763C02)**
[PC8194R]

TP
CONNECT4CAR PTE LTD
Aug 10 2019 4:00AM

[-]
Teamwork Garage Pte Ltd

Upload Documents Upload Photos Compose New Letter

View View in Browser ▼

Assessment Reports			1 per page ▼	✓
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)	Thumbnail	Print
1	13/08/19 16:00	Accident Statement	1 Load HTM	
2	15/08/19 14:51	Addendum Sheet	1 Load TIFF	
3	15/08/19 14:53	Accident Statement Addm. #1	1 Load HTM	
Photos/Images			3 per page ▼	✓
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)	Thumbnail	Print
1	15/08/19 14:53	Accident Photo [Linked Accident Report Documents]	1 Load JPG	✓
2	15/08/19 14:53	Accident Photo [Linked Accident Report Documents]	1 Load JPG	✓
3	15/08/19 14:53	Accident Photo [Linked Accident Report Documents]	1 Load JPG	✓
4	15/08/19 14:53	Accident Photo [Linked Accident Report Documents]	1 Load JPG	✓
5	15/08/19 14:53	Accident Photo [Linked Accident Report Documents]	1 Load JPG	✓
6	15/08/19 14:53	Accident Photo [Linked Accident Report Documents]	1 Load JPG	✓
7	15/08/19 14:53	Accident Photo [Linked Accident Report Documents]	1 Load JPG	✓
8	15/08/19 14:53	Accident Photo [Linked Accident Report Documents]	1 Load JPG	✓
9	15/08/19 14:53	Accident Photo [Linked Accident Report Documents]	1 Load JPG	✓
10	15/08/19 14:53	Accident Photo [Linked Accident Report Documents]	1 Load JPG	✓
11	15/08/19 14:53	Accident Photo [Linked Accident Report Documents]	1 Load JPG	✓
12	15/08/19 14:53	Accident Photo [Linked Accident Report Documents]	1 Load JPG	✓
13	15/08/19 14:53	Accident Photo [Linked Accident Report Documents]	1 Load JPG	✓
14	15/08/19 14:53	Accident Photo [Linked Accident Report Documents]	1 Load JPG	✓
15	15/08/19 14:53	Accident Photo [Linked Accident Report Documents]	1 Load JPG	✓
16	15/08/19 14:53	Accident Photo [Linked Accident Report Documents]	1 Load JPG	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	30/08/19 10:14	General View	1 Load JPG	✓
2	30/08/19 10:14	General View	1 Load JPG	✓
3	30/08/19 10:14	General View	1 Load JPG	✓
4	30/08/19 10:14	General View	1 Load JPG	✓
5	30/08/19 10:14	General View	1 Load JPG	✓
6	30/08/19 10:14	General View	1 Load JPG	✓
7	30/08/19 10:14	General View	1 Load JPG	✓
8	30/08/19 10:14	General View	1 Load JPG	✓
9	30/08/19 10:14	General View	1 Load JPG	✓
10	30/08/19 10:14	General View	1 Load JPG	✓
11	30/08/19 10:14	General View	1 Load JPG	✓
12	30/08/19 10:14	General View	1 Load JPG	✓
13	30/08/19 10:14	General View	1 Load JPG	✓

Assessment Reports			1 per page ▾	☒
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)	Thumbnail	Print
14	30/08/19 10:14	General View	 Load JPG	☒
15	30/08/19 10:14	General View	 Load JPG	☒
16	30/08/19 10:14	General View	 Load JPG	☒
17	30/08/19 10:14	General View	 Load JPG	☒
18	30/08/19 10:14	General View	 Load JPG	☒
19	30/08/19 10:14	General View	 Load JPG	☒
20	30/08/19 10:14	General View	 Load JPG	☒
21	30/08/19 10:14	General View	 Load JPG	☒
22	30/08/19 10:14	General View	 Load JPG	☒
23	30/08/19 10:14	General View	 Load JPG	☒
24	30/08/19 10:14	General View	 Load JPG	☒
25	30/08/19 10:14	General View	 Load JPG	☒
26	30/08/19 10:14	General View	 Load JPG	☒
27	30/08/19 10:14	General View	 Load JPG	☒
28	30/08/19 10:14	General View	 Load JPG	☒
29	30/08/19 10:14	General View	 Load JPG	☒
30	30/08/19 10:14	General View	 Load JPG	☒
31	30/08/19 10:14	General View	 Load JPG	☒
32	30/08/19 10:14	General View	 Load JPG	☒
33	30/08/19 10:14	General View	 Load JPG	☒
34	30/08/19 10:14	General View	 Load JPG	☒
35	30/08/19 10:14	General View	 Load JPG	☒
36	30/08/19 10:14	General View	 Load JPG	☒
37	30/08/19 10:14	General View	 Load JPG	☒
38	30/08/19 10:14	General View	 Load JPG	☒
39	30/08/19 10:14	General View	 Load JPG	☒
40	30/08/19 10:14	General View	 Load JPG	☒
41	30/08/19 10:14	General View	 Load JPG	☒
42	30/08/19 10:14	General View	 Load JPG	☒
43	30/08/19 10:14	General View	 Load JPG	☒
44	30/08/19 10:14	General View	 Load JPG	☒
45	30/08/19 10:14	General View	 Load JPG	☒
46	30/08/19 10:14	General View	 Load JPG	☒
47	30/08/19 10:14	General View	 Load JPG	☒
48	30/08/19 10:14	General View	 Load JPG	☒
49	30/08/19 10:14	General View	 Load JPG	☒
50	30/08/19 10:14	General View	 Load JPG	☒
51	30/08/19 10:14	General View	 Load JPG	☒
52	30/08/19 10:14	General View	 Load JPG	☒
53	30/08/19 10:14	General View	 Load JPG	☒
54	30/08/19 10:14	General View	 Load JPG	☒
55	30/08/19 10:14	General View	 Load JPG	☒
56	30/08/19 10:14	General View	 Load JPG	☒
57	30/08/19 10:14	General View	 Load JPG	☒
58	30/08/19 10:14	General View	 Load JPG	☒
59	30/08/19 10:14	General View	 Load JPG	☒
60	30/08/19 10:14	General View	 Load JPG	☒
61	30/08/19 10:14	General View	 Load JPG	☒
62	30/08/19 10:14	General View	 Load JPG	☒
63	30/08/19 10:14	General View	 Load JPG	☒
64	30/08/19 10:14	General View	 Load JPG	☒
65	30/08/19 10:14	General View	 Load JPG	☒
66	30/08/19 10:14	General View	Load JPG	☒

Assessment Reports			1 per page ▼	✓
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)	Thumbnail	Print
67	30/08/19 10:14	General View	 Load JPG	✓
68	30/08/19 10:14	General View	 Load JPG	✓
69	30/08/19 10:14	General View	 Load JPG	✓
70	30/08/19 10:14	General View	 Load JPG	✓
71	30/08/19 10:14	General View	 Load JPG	✓
72	30/08/19 10:14	General View	 Load JPG	✓
73	30/08/19 10:14	General View	 Load JPG	✓
74	30/08/19 10:14	General View	 Load JPG	✓
75	30/08/19 10:14	General View	 Load JPG	✓
76	30/08/19 10:14	General View	 Load JPG	✓
77	30/08/19 10:14	General View	 Load JPG	✓
78	30/08/19 10:14	General View	 Load JPG	✓
79	30/08/19 10:14	General View	 Load JPG	✓
80	30/08/19 10:14	General View	 Load JPG	✓
81	30/08/19 10:14	General View	 Load JPG	✓
82	30/08/19 10:14	General View	 Load JPG	✓
83	30/08/19 10:14	General View	 Load JPG	✓
84	30/08/19 10:14	General View	 Load JPG	✓
85	30/08/19 10:14	General View	 Load JPG	✓
86	30/08/19 10:14	General View	 Load JPG	✓
87	30/08/19 10:14	General View	 Load JPG	✓
88	30/08/19 10:14	General View	 Load JPG	✓
89	30/08/19 10:14	General View	 Load JPG	✓
90	30/08/19 10:14	General View	 Load JPG	✓
91	30/08/19 10:14	General View	 Load JPG	✓
92	30/08/19 10:14	General View	 Load JPG	✓
93	30/08/19 10:14	General View	 Load JPG	✓
94	30/08/19 10:14	General View	 Load JPG	✓
95	30/08/19 10:14	General View	 Load JPG	✓
96	30/08/19 10:14	General View	 Load JPG	✓
97	30/08/19 10:14	General View	 Load JPG	✓
98	30/08/19 10:14	General View	 Load JPG	✓
99	30/08/19 10:14	General View	 Load JPG	✓
100	30/08/19 10:14	General View	 Load JPG	✓
101	30/08/19 10:14	General View	 Load JPG	✓
102	30/08/19 10:14	General View	 Load JPG	✓
103	30/08/19 10:14	General View	 Load JPG	✓
104	30/08/19 10:14	General View	 Load JPG	✓
105	30/08/19 10:14	General View	 Load JPG	✓
106	30/08/19 10:14	General View	 Load JPG	✓
107	30/08/19 10:14	General View	 Load JPG	✓
108	30/08/19 10:14	General View	 Load JPG	✓
109	30/08/19 10:14	General View	 Load JPG	✓
110	30/08/19 10:14	General View	 Load JPG	✓
111	30/08/19 10:14	General View	 Load JPG	✓
112	30/08/19 10:14	General View	 Load JPG	✓
113	30/08/19 10:14	General View	 Load JPG	✓
114	30/08/19 10:14	General View	Load JPG	✓
115	30/08/19 10:14	General View	Load JPG	✓
Documentation			1 per page ▼	✓
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)	Thumbnail	Print
1	13/08/19 16:00	Accident Sketch Plan [Linked Accident Report Documents]	 Load TIF	

Assessment Reports			1 per page ▼	☒
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)	Thumbnail	Print
2	13/08/19 16:00	Accident Sketch Plan [Linked Accident Report Documents]	 Load TIF	
3	13/08/19 16:00	aig interview form [Linked Accident Report Documents]	 Load TIF	
4	13/08/19 16:00	police report [Linked Accident Report Documents]	 Load TIF	
5	13/08/19 16:00	police report [Linked Accident Report Documents]	 Load TIF	
6	13/08/19 16:00	police report [Linked Accident Report Documents]	 Load TIF	
7	13/08/19 16:00	driver's nric & license [Linked Accident Report Documents]	 Load TIF	
8	13/08/19 16:00	certificate of insurance [Linked Accident Report Documents]	 Load TIF	

Linked Accident Report Documents

Assessment Reports			1 per page ▼	☒
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)	Thumbnail	Print
1	13/08/19 16:00	Accident Statement	 Load HTM	
2	15/08/19 14:51	Addendum Sheet	 Load TIFF	
3	15/08/19 14:53	Accident Statement Addm. #1	 Load HTM	
Photos/Images			3 per page ▼	☒
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)	Thumbnail	Print
1	15/08/19 14:53	Accident Photo	 Load JPG ☒	☒
2	15/08/19 14:53	Accident Photo	 Load JPG ☒	☒
3	15/08/19 14:53	Accident Photo	 Load JPG ☒	☒
4	15/08/19 14:53	Accident Photo	 Load JPG ☒	☒
5	15/08/19 14:53	Accident Photo	 Load JPG ☒	☒
6	15/08/19 14:53	Accident Photo	 Load JPG ☒	☒
7	15/08/19 14:53	Accident Photo	 Load JPG ☒	☒
8	15/08/19 14:53	Accident Photo	 Load JPG ☒	☒
9	15/08/19 14:53	Accident Photo	 Load JPG ☒	☒
10	15/08/19 14:53	Accident Photo	 Load JPG ☒	☒
11	15/08/19 14:53	Accident Photo	 Load JPG ☒	☒
12	15/08/19 14:53	Accident Photo	 Load JPG ☒	☒
13	15/08/19 14:53	Accident Photo	 Load JPG ☒	☒
14	15/08/19 14:53	Accident Photo	 Load JPG ☒	☒
15	15/08/19 14:53	Accident Photo	 Load JPG ☒	☒
16	15/08/19 14:53	Accident Photo	 Load JPG ☒	☒
Documentation			1 per page ▼	☒
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)	Thumbnail	Print
1	13/08/19 16:00	Accident Sketch Plan	 Load TIF	
2	13/08/19 16:00	Accident Sketch Plan	 Load TIF	
3	13/08/19 16:00	aig interview form	 Load TIF	
4	13/08/19 16:00	police report	 Load TIF	
5	13/08/19 16:00	police report	 Load TIF	
6	13/08/19 16:00	police report	 Load TIF	
7	13/08/19 16:00	driver's nric & license	 Load TIF	
8	13/08/19 16:00	certificate of insurance	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI19014860/HCD3S2

Date: 12/09/2019

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMB1SN19315419000

Claimant Vehicle No: SE2018K Insured Vehicle No: PC8194R

Date of Loss: 10/08/2019 Nature of Claim: TP Claim No: SNM19D203763C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SE2018K

Make & Model: NISSAN SYLPHY, 1.6 CVT ABS D/AIRBAG 2WD 4DR (A) Engine No: HR16974043B

Reg. Date: 08/10/2015 (Man. Year: 2015) Chassis No: MNTBBAB17Z0024781

Colour: Grey Odometer: 337693 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16

Front Left Side: Achilles 3 mm Rear Left Side: Toyo 4 mm

Front Right Side: Achilles 3 mm Rear Right Side: Achilles 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 28/08/2019

Date Inspected: 23/08/2019 Inspected At: Teamwork Garage Pte Ltd (HQ)
53 Ubi Ave 1 #01-24, Paya Ubi Industrial Park
Singapore 408934

Estimated Period of Repair: 20.0 days

Adjuster: LEE HOCK ANN

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$23,000.00 - \$27,000.00

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 12 Sep 2019)

Parts: 143 NISSAN SYLPHY 1.6 CVT ABS D/AIRBAG 2WD 4DR (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SE2018K)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >