

22/8/2009

ASS. REC. BY:

REF:

CS/MA/19014879/Gcd327

Special Instruction:

ok

Sumur: Ano Ding
mentenASSIGNMENT (Office)From (Person): chin lu ying

of

Alu

Date/Time:

23/8/19 @ 10.20am

Estimated Cost:

Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.:

SJJ 9522E

Insured:

SQT 7937M

at Workshop m/s

Motor Intel

Tel:

82810087/

of

13 Kuli Bukit Road 4 #01-20

Policy No:

2100016039

Claim No:

285278185286

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

20/08/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

11.36am 23/8/19

Person Contacted:

lyVehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction
	<u>Tolmng (x)</u>
	<u>SJJ 9522E - MA/Alu 18011022/14</u>
	<u>SQT 7937M - x</u>
	<u>Dismantle: 26/8/2019</u>
	<u>After repair: 30/8/2019</u>

DOA: 17/6/2018

Surveyor: PKS

REF: A19

ASSIGNMENT

(-2028)

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s Meter Intel

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \$50k

IDAC Accident Rpt.: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SJ9522E Yr Regn: 14 Jun 2008

Type: MCar / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or SD 2.0

Make: Subaru Impreza c.c. 1994

Colour: Silver A/C: Insured / Std / NI / NA

Sp.Reading: 128088 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: GH 8004902

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225 / 48 R17

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIG / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. _____ D.O.I. 23-08-19

Survey held at w/s 1pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

coe : 33365

RECEIVED 13 NOV 2019

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 6

Resurvey No. of Trip: 3

Survey Fee:

Transportation:

120 S + RS. SI

Photos

Others

TOTAL

Add Fee: ☐ : Site Insp* (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

Report Format : DAR

Lump Sum / I.B.I. (\$) _____

191

...CLAIM SUBFOLDER...(Pending for Survey Report)


PRI

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	23 Aug 2019 Edit Reg		23 Aug 2019 00:00 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: Tan Keng Hoon , ID: S1084660I									
Main Claimant: NA									
Vehicle Reg. No.: SJJ9522E		Date of Loss: 21/08/2019 16:00 - :59							
Claim Type: TP / 2852781852SG		Policy/Cover Note No.: (Comprehensive)							
Vehicle Reg. No. (Insured): SGT7937M		Policy No. (Claimant):							
		Excess:							
Repairer: Motor Intelligence Automo Pte Ltd (HQ) 13 KAKI BUKIT ROAD 4, #01-20 BARTLEY BIZ CENTRE, 417807 Kaki Bukit - Tel:									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Ler, Bernard-JQ] BernardJiQian.Ler@aig.com									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 03/09/2019]									
Claimant's Solicitor: ALLISTER LIM & THRUMURGAN - Tel: 64222187									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG (26/08/2019): No OI GIA Report AIG_SG (26/08/2019): Request To Upload TP GIA Report 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHIC...

From: Chin, Lee-Ying
To: assignments, Admin A
Cc: Fong, Andy-SY
Sent: 8/23/2019 10:21:34 AM
Attachments:  PRS letter.pdf

Hi LKK,

Kindly assist to survey, vehicle in workshop.

Thanks.

Best Regards

Lee Ying, Chin

AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1947

Lee-Ying.Chin@aig.com | www.aig.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Your Ref: SGT 7937 M

Our Ref: AL.INS.2019.SJJ9522E(PDPI)KC

21st August 2019

AIG ASIA PACIFIC INSURANCE PTE LTD
78 Shenton Way
#07-16, AIG Building
Singapore 079120
Attn: Motor Claims Dept.

BY PDX & EMAIL ONLY

PDX Intercompany Exchange Pte Ltd



010808787919
FROM Allister Lim & Thrumurgan
PDX Box No. 8144

Dear Sirs,

**ACCIDENT INVOLVING SJJ 9522 E / SGT 7937 M ON 21st AUGUST 2019 ALONG
SERANGOON CENTRE TOWARDS CTE AT ABOUT 14:30**

We act for the owner of vehicle no. SJJ 9522 E.

We are instructed to claim damages against you in connection with the above accident.

Pursuant to NIMA protocol, we hereby give you notice to conduct a pre-repair survey of our client's motor vehicle at the under-stated workshop: -

MOTOR INTELLIGENCE AUTOMO PTE LTD
13 Kaki Bukit Road 4
#01-20, Bartley Biz Centre
Singapore 417807
Person In-Charge: Wilson / Ivy
Mobile Number: 8838 3318 / 6281 0087

TAKE NOTICE that you are required to respond to us within 2 working days (excluding Saturday, Sunday and Public Holiday) of receipt of this notice as to whether you wish to carry out or waive a pre-repair inspection. If we do not hear from you in this regard by the stipulated time, we shall construe your silence as waiver of the requirement for a pre-repair survey and our client's repairers shall proceed to repair our client's vehicle without further reference.

Please contact our staff, Kelly / Jeremy / Cho at 6438 3303 / 6422 2185 or email us at Kelly.cheng@alt.sg / Jeremy.peh@alt.sg / Cho.tsui@alt.sg for future correspondences.

Yours faithfully


P. ALLISTER LIM

ALLISTER LIM & THRUMURGAN

[➤ Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Owner ID Type:	Singapore NRIC
Owner ID:	857C
Vehicle No.:	SJJ9522E
Vehicle to be Exported:	No
Intended Deregistration Date:	25 Aug 2019
Vehicle Make:	SUBARU
Vehicle Model:	IMPREZA 5D 2.0 S-GT-S AWD 4AT
Primary Colour:	Silver
Manufacturing Year:	2008
Engine No.:	EJ20D311020
Chassis No.:	GH8004902
Maximum Power Output:	184.0 kW (246 bhp)
Open Market Value:	\$25,958.00
Original Registration Date:	14 Jun 2008
First Registration Date:	14 Jun 2008
Transfer Count:	4
Actual ARF Paid:	\$25,958.00
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
COE Expiry Date:	13 Jun 2028
COE Category:	E - Open Category
COE Period(Years):	10
PQP Paid:	\$37,906.00
COE Rebate Amount:	\$33,365.00
Total Rebate Amount:	\$33,365.00

The information contained herein is correct as at 25 Aug 2019

OK

► Impreza Used Vehicle List (5 vehicles)

Car Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Company	Availabi
Subaru Impreza 5D 2.0A S-GT (COE till 04/2029)	\$56,800	\$5,860 /yr	02-Jun-2009	1,994 cc	174,681 km	GOWheeler Pte Ltd	Availabl

Low Interest Rate. COE Till April 2029. In-house Financing Options Available. Buy With A Peace Of Mind. Low Mileage. 100% Genuine Mileage. Well Maintained. No Chassis/Structural Damage. Immaculate Con...

Office No. - 69311212

Ivan Gan - 81813725 | Gwen Chen - 86138585 | Lawrence Loh - 88083507 | Marissa Yang - 98185238

Subaru Impreza 5D 2.0M R-S (COE till 01/2024)	\$26,800	\$6,110 /yr	15-Jan-2009	1,994 cc	225,000 km		Availabl
--	-----------------	--------------------	--------------------	-----------------	-------------------	--	-----------------

Drives Perfectly, No Repairs Needed. New Road Tax. Test Drive It Today!

Office No. - -

Andrew - 90079338

Subaru Impreza WRX 2.0A (COE till 07/2026)	\$49,800	\$7,180 /yr	25-Jan-2007	1,994 cc	165,000 km	Tely Auto Trading	Availabl
---	-----------------	--------------------	--------------------	-----------------	-------------------	--------------------------	-----------------

1 Owner Low Mileage Original Grey 100% -Stock, No Modify Very Good Condition. Don't Miss! For Viewing Please Call.

Office No. - -

Mr Toh - 96656068

Subaru Impreza WRX 2.0M (COE till 01/2026)	\$65,000	\$10,130 /yr	25-Jan-2006	1,994 cc	225,000 km	A Star Motors Pte Ltd	Availabl
---	-----------------	---------------------	--------------------	-----------------	-------------------	------------------------------	-----------------

Very Clean Interior And Untouched Exterior. Only 1 In Market. And It Has Had Only 2 Owners. Very Stable Car, With No Issues. Clear Headlight. Readily Ceramic Coated Paintwork! 2 Owners Only, Accident ...

Office No. - 63397788

Aloy - 82227296 | Kree - 81686947

Subaru Impreza WRX 2.0M (COE till 02/2026)	\$56,500	\$8,750 /yr	08-Feb-2006	1,994 cc	-		Availabl
---	-----------------	--------------------	--------------------	-----------------	----------	--	-----------------

Car Is In Stock Condition. Right Fender And Side Skirt Might Need A Change Due To A Small Bump. Come View To Believe It! Not Many On The Road Left. Price Still Negotiable! Open To Trade! Call Or Whats...

Office No. - -

Raxton - 96403820

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale even for COE cars, OPC cars, vans, trucks, hybrid cars, sports cars or station wagons. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. We have new car dealers comprising parallel importers, authorized car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions, and also motoring advice, car reviews & car news on the latest models. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

© 2004-2019 sgCarMart. All rights reserved.

META MECHANIC
25 KAKI BUKIT ROAD 4#01-36
SYNERGY @ KAKI BUKIT
SINGAPORE 417800
TEL: 98250505


Work Order: R000067
 VIN: SJJ9522E
 Date: 21.8.19 11:29




SJJ9522E

Subaru : Impreza (Including WRX/STI, XV) : 2007-11 (GE/GH) : 1.5L, 2.0L Gasoline : 17" Wheel
4-Wheel Total Alignment


Left Front



Before Measurements




Right Front




Front





Left Rear



Right Rear



Rear



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	21/08/2019 18:02
Date Of Accident	20/08/2019 14:30
Exact Location Of Accident	SERANGOON CENTRE TOWARDS CTE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJJ9522E
Insured/Policyholder	
Name Of Registered Owner	TAY TECK LYE PETER
NRIC No	S1732857C
Email Address	SALES@MIA.COM.SG
Mobile Phone No	(LOCAL) +65-96664095
Alternative Phone No	OFFICE-96664095

Vehicle Particulars

Manufacturer	SUBARU
Model	IMPREZA 5D
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA472175/1
Cover Note Number	

Driver

Name of Driver	TAY TECK LYE PETER
NRIC No	S1732857C
Date Of Birth	16/08/1965
Occupation	INDOOR
Date Of Driving Pass	06/10/1993
Driving Experience	25 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96664095
Fax Number	
Contact Number	OFFICE-96664095
Email Address	SALES@MIA.COM.SG

Address	APT BLK 205 SERANGOON CENTRAL #05-132
Postcode	550205
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	WITH OWNER
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGT7937M
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	


SKETCH PLAN


IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for Investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

Serangoon Centre Toward CTE

A SJS 9522E

B SGT 7937M



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving along at the Serangoon Centre Toward CTE at the 2 lane traffic and I was driving at the extreme right lane suddenly vehicle B from my left cut into my lane and collided onto my car due to the straight impact my car go onto the kerb after the accident.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Front Portion

NAC	INC	Item	CON	AC	Qty
1001	991886	Frt Number Plate			
1002	991887	Frt Number Plate Base			
1004	991300	Frt Bumper	BR		
2001	991477	Frt Bumper Upper			
2002	991387	Frt Bumper Lower clips	MC		
2003	991449	Frt Bumper Side Cover			
2004	991443	Frt Bumper Side Retainer LH	DE		
1006	991325	Frt Bumper Bracket			
1008	991433	Frt Bumper Reinforcement			
2005	991466	Frt Bumper Signal Lamp			
1017	995100	Frt LH Bumper Fog Lamp Cover			
1018	991355	Frt RH Bumper Fog Lamp Cover			
1019	995079	Frt LH Bumper Fog Lamp			
1020	995080	Frt RH Bumper Fog Lamp			
1021	991793	Frt Grille			
1022	991328	Frt Grille Emblem			
2006	990247	Frt Grille Sticker			
1023	991799	Frt Grille Chrome Moulding			
2007	991891	Frt Panel			
2008	991874	Frt Lower Panel			
2009	991328	Frt Panel Emblem			
2010	990247	Frt Panel Sticker			
2011	991893	Frt Panel Garnish			
1024	991222	Frt Apron Panel			
2012	991527	Frt Corner Panel			
2013	991532	Frt Corner Panel Signal Lamp			
2014	995245	Frt Signal Lamp LH			
2015	995246	Frt Signal Lamp RH			
1029	995153	Frt LH Headlamp Assy	cut		
1030	991821	Frt RH Headlamp Assy			
1031	995088	Frt LH Side Lamp			
1032	995089	Frt RH Side Lamp			
2016	992149	Frt Wiper Panel			
2017	995043	Frt Wiper Nozzle			
1120	992140	Frt Wiper Arm			
1121	992142	Frt Wiper Blade			
2018	992145	Frt Wiper Link			
2019	992148	Frt Wiper Motor			
1122	995045	Wiper Panel Garnish			
1114	992093	Frt Windscreen			
1115	992097	Frt Windscreen Rubber			
1117	992098	Frt Windscreen Sealant			
2020	992114	Frt Windscreen Outer Pillar			
2021	992113	Frt Windscreen Inner Pillar			
1118	991019	ERP Bracket			
1119	991020	ERP Unit			
2022	991958	Frt Side Mirror (Big)			
2023	991959	Frt Side Mirror (Small)			
2024	991962	Frt Side Mirror (Round)			
2025	995015	Frt Wing Mirror Stay			
1025	992013	Frt Support Panel			
1033	990248	Bonnet			
1035	990287	Bonnet Lock			
1037	990273	Bonnet Hinge			
1039	990305	Bonnet Rubber			
1042	990119	Air Con Condenser			
1043	990122	Air Con Fan Assy			
1048	990149	Air Con Liquid Pipe			
1049	995066	Air Con Receiver Drier			
1052	995074	Radiator			
1053	992738	Radiator Cowling			
1054	992742	Radiator Fan Assy			
1056	992758	Radiator Hose Top			
1058	992741	Radiator Expansion Tank			
2026	992596	Oil Cooler			
1079	994431	Power Steering Cooler Pipe			
1059	990151	Air Duct			
1060	990070	Air Cleaner Assy			
1067	990219	Battery			
1069	990223	Battery Bracket			

Vehicle No:

SJS 9522E

NAC	INC	Item	CON	AC	Qty
1085	991011	Engine Under Cover			
1086	990946	Engine Mounting			
2027	991500	Frt Cabin Assy			
2028	991501	Frt Cabin Mounting			
2029	991502	Frt Cabin Rear Panel			
1092	991520	Frt LH Chassis Member			
1093	991520	Frt RH Chassis Member			
1094	990728	Frt Vertical Cross Member			
1095	991863	Frt Lower Cross Member			
2030	990143	Air Con Evaporator Assy			
2031	990106	Air Con Blower			
1082	990427	Brake Master Pump Assy			
1083	990403	Brake Booster Pump Assy			
2032	990431	Brake Pedal			
2033	990021	Accelerator Pedal			
2034	990627	Clutch Pedal			
1127	994483	Steering Wheel Airbag			
1128	994485	Steering Wheel Airbag Sensor			
1131	990029	Airbag Control Unit			
1133	991922	Frt RH Seat Belt Assy			
1135	995182	Frt LH Seat Belt Assy			
1124	990753	Dashboard Assy			
1125	992282	Glove Box Cover			
1126	992281	Glove Box Compartment			
1096	995070	Frt LH Fender	Buc		
1097	995072	Frt LH Fender Inner Panel			
1100	991740	Frt LH Fender Inner Shield	TV		
1101	995179	Frt LH Mudflap			
2035	994966	Frt LH Wheel Guard			
1102	995170	Frt LH Wheel Rim	Cut		
1104	995065	Frt LH Tyre	Scr		
1105	995071	Frt RH Fender			
1106	991739	Frt RH Fender Inner Panel			
1109	991740	Frt RH Fender Inner Shield			
1110	991884	Frt RH Mudflap			
2036	994966	Frt RH Wheel Guard			
1111	992087	Frt RH Wheel Rim	OT		
1113	995065	Frt RH Tyre	Scr		
1255	995326	Frt LH Door			
1256	995140	Frt LH Door Protector			
1257	995104	Frt LH Door Hinge			
1258	995142	Frt LH Door Wing Mirror			
1262	995103	Frt LH Door Glass			
1263	991595	Frt LH Door Glass Regulator			
1264	991596	Frt LH Door Glass Regulator Motor			
1265	991662	Frt LH Door Rubber			
1266	991636	Frt LH Door Outer Handle			
1272	991617	Frt LH Door Inner Trim Board			
1316	995327	Frt RH Door			
1317	991654	Frt RH Door Protector			
1318	991601	Frt RH Door Hinge			
1319	991685	Frt RH Door Wing Mirror			
1323	991584	Frt RH Door Glass			
1324	991595	Frt RH Door Glass Regulator			
1325	991596	Frt RH Door Glass Regulator Motor			
1326	991662	Frt RH Door Rubber			
1327	991636	Frt RH Door Outer Handle			
1333	991617	Frt RH Door Inner Trim Board			
2037	991644	Frt Door Frt Pillar			
2038	991657	Frt Door Rear Pillar			
2039	992072	Frt Wheel Arch Panel			
2040	992069	Frt Wheel Arch Panel Garnish			
2041	991996	Frt Step Panel			
2042	994498	Frt Step Panel Top Garnish			
2043	994495	Frt Step Panel Inner Garnish			
1073	995053	Wiper Washer Tank			
1136	990247	Sticker			
		LH Rocker panel Garnish repair			
		RH Rocker panel Garnish de			

No of Items: Assessor:

(01)Bent (2)Dented (3)Distorted (4)Cracked (5)Cut (6)Scratched
(07)Deformed (08)Shifted (09)Buckled (10)Broken (11)Necessary
(12)Missing (13)Torn (14)Unconfirmed (15)Not Working

MOTORCAR (Rear)

(1)Replace (✓) (2)Repair(X) (3)Check (P)
(4)Not Consistent (NC)

Rear Portion

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	PR	/	
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips	NC	/	
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer	PR	DR	/
1149	993045	Rear Bumper Reinforcement			
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector			
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor			
1159	993327	Rear End Panel			
1160	993339	Rear End Panel Top Garnish			
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp			
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp			
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid			
1171	991328	Bootlid Emblem			
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock			
1178	990377	Bootlid Rubber			
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate			
1182	991328	Tailgate Emblem			
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board			

Vehicle No: GS 9522E

NAC	INC	Item	CON	AC	Qty
1202	993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel			
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe			
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim			
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993401	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1136	990247	Sticker			
		Wing mirror LH repair			

No of Items: _____ Assessor: _____

Undercarriage

NAC	INC	Item	CON	AC	Qty
1372	995163	Frt LH Shock Absorber			
1373	991944	Frt LH Shock Absorber Mounting			
1374	990632	Frt LH Coil Spring			
1375	995198	Frt LH Knuckle Arm	BT	/	
1376	995199	Frt LH Knuckle Arm Bearing	MC	/	
1377	995178	Frt LH Lower Arm	BT	/	
1378	995169	Frt LH Upper Arm			
1379	995183	Frt LH Tie Rod			
1380	995143	Frt LH Drive Shaft			
1381	990661	Frt LH Control Arm			
1382	992062	Frt LH Trailing Arm			
1383	991848	Frt LH Leaf Spring			
1384	991293	Frt LH Brake Disc Rotor			
1385	991281	Frt LH Brake Caliper			
1386	991292	Frt LH Brake Pipe			
1387	991287	Frt LH Brake Hose			
1388	991295	Frt LH Brake Sensor Wire			
1389	991989	Frt Stay Bar Bracket			
1390	994455	Steering Rack & Pinion			
1391	994435	Steering Cross Member			
1392	994519	Frt Sub Frame			
1393	992003	Frt Sub Frame Mounting			
1394	991217	Frt Anti Roll Bar			
1395	991219	Frt Anti Roll Bar Linkage			
1396	990887	Engine Block			
1397	990890	Engine Block Gasket			
1398	990972	Engine Oil Sump			
1399	990960	Engine Oil			
1400	992224	Gear Box Assy			
1401	992229	Gear Box Gasket			
1402	992241	Gear Box Oil Sump			
1403	992257	Gear Oil			
1404	990534	Centre Exhaust Pipe Assy			
1405	990532	Centre Exhaust Mounting			
1406	991134	Floor Panel			
1407	993719	Rear LH Shock Absorber			
1408	993723	Rear LH Shock Absorber Mounting			
1409	993170	Rear LH Coil Spring			
1410	993550	Rear LH Knuckle Arm			
1411	993551	Rear LH Knuckle Arm Bearing			
1412	993597	Rear LH Lower Arm			
1413	993884	Rear LH Upper Arm			
1414	995161	Rear LH Drive Shaft			
1415	995216	Rear LH Control Arm			
1416	993881	Rear LH Trailing Arm			
1417	993573	Rear LH Leaf Spring			
1418	992941	Rear LH Brake Disc Rotor			
1419	992937	Rear LH Brake Caliper Assy			
1420	990434	Rear LH Brake Pipe			
1421	992946	Rear LH Brake Hose			
1422	993819	Rear Sub Frame			
1423	993820	Rear Sub Frame Mounting			
1424	992813	Rear Anti Roll Bar			
1425	990168	Rear Anti Roll Bar Linkage			
1426	990202	Axle Beam			
1427	990170	Rear Axle Panhard Rod			
1428	990810	Differential Assy			
1429	992706	Propeller Shaft			

Vehicle No:

553 9822E

[illegible]

No of Items: _____ Assessor: _____

Original copy

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	23 Aug 2019 Edit Reg		23 Aug 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by adjuster]							
Insured:	Tan Keng Hoon, ID: S1084660I								
Main Claimant:	NA								
Vehicle Reg. No.:	SJJ9522E	Date of Loss:	20/08/2019 16:00 - :59 [134 Months and 6 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 2852781852SG	Policy/Cover Note No.:	2100016039 (Comprehensive)						
Vehicle Reg. No. (Insured):	SGT7937M	Policy No. (Claimant):							
		Excess:							
Repairer:	Motor Intelligence Automo Pte Ltd (HQ) 13 KAKI BUKIT ROAD 4, #01-20 BARTLEY BIZ CENTRE, 417807 Kaki Bukit - Tel:								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Ler, Bernard-JQ] BernardJiQian.Ler@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 03/09/2019]								
Claimant's Solicitor:	ALLISTER LIM & THRUMURGAN - Tel: 64222187								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG (26/08/2019): No OI GIA Report AIG_SG (26/08/2019): Request To Upload TP GIA Report 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SJJ9522E (2852781852SG)
[SGT7937M]**












































TP















































NA
















































Aug 20 2019 4:00PM

[Tan Keng Hoon]

Motor Intelligence Automo Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View		View in Browser	
Photos/Images															3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)														Thumbnail	Print	
1	30/08/19 14:01	General View														Load JPG	<input checked="" type="checkbox"/>	
2	30/08/19 14:01	General View														Load JPG	<input checked="" type="checkbox"/>	
3	30/08/19 14:01	General View														Load JPG	<input checked="" type="checkbox"/>	
4	30/08/19 14:01	General View														Load JPG	<input checked="" type="checkbox"/>	
5	30/08/19 14:01	General View														Load JPG	<input checked="" type="checkbox"/>	
6	30/08/19 14:01	General View														Load JPG	<input checked="" type="checkbox"/>	
7	30/08/19 14:01	General View														Load JPG	<input checked="" type="checkbox"/>	
8	30/08/19 14:01	General View														Load JPG	<input checked="" type="checkbox"/>	
9	30/08/19 14:01	General View														Load JPG	<input checked="" type="checkbox"/>	
10	30/08/19 14:01	General View														Load JPG	<input checked="" type="checkbox"/>	
11	30/08/19 14:01	General View														Load JPG	<input checked="" type="checkbox"/>	
12	30/08/19 14:01	General View														Load JPG	<input checked="" type="checkbox"/>	
13	30/08/19 14:01	General View														Load JPG	<input checked="" type="checkbox"/>	
14	30/08/19 14:01	General View														Load JPG	<input checked="" type="checkbox"/>	
15	30/08/19 14:01	General View														Load JPG	<input checked="" type="checkbox"/>	
16	30/08/19 14:01	General View														Load JPG	<input checked="" type="checkbox"/>	
17	30/08/19 14:01	General View														Load JPG	<input checked="" type="checkbox"/>	
18	30/08/19 14:01	General View														Load JPG	<input checked="" type="checkbox"/>	
19	30/08/19 14:01	General View														Load JPG	<input checked="" type="checkbox"/>	
20	30/08/19 14:01	General View														Load JPG	<input checked="" type="checkbox"/>	
21	30/08/19 14:01	General View														Load JPG	<input checked="" type="checkbox"/>	
22	30/08/19 14:01	General View														Load JPG	<input checked="" type="checkbox"/>	
23	30/08/19 14:01	General View														Load JPG	<input checked="" type="checkbox"/>	
24	30/08/19 14:01	General View														Load JPG	<input checked="" type="checkbox"/>	
25	30/08/19 14:01	General View														Load JPG	<input checked="" type="checkbox"/>	
26	30/08/19 14:01	General View														Load JPG	<input checked="" type="checkbox"/>	
27	30/08/19 14:01	General View														Load JPG	<input checked="" type="checkbox"/>	
28	30/08/19 14:01	General View														Load JPG	<input checked="" type="checkbox"/>	
29	30/08/19 14:01	General View														Load JPG	<input checked="" type="checkbox"/>	
30	30/08/19 14:01	General View														Load JPG	<input checked="" type="checkbox"/>	
31	30/08/19 14:01	General View														Load JPG	<input checked="" type="checkbox"/>	
32	30/08/19 14:01	General View														Load JPG	<input checked="" type="checkbox"/>	
33	30/08/19 14:01	General View														Load JPG	<input checked="" type="checkbox"/>	
34	30/08/19 14:01	General View														Load JPG	<input checked="" type="checkbox"/>	
35	30/08/19 14:01	General View														Load JPG	<input checked="" type="checkbox"/>	
36	30/08/19 14:01	General View														Load JPG	<input checked="" type="checkbox"/>	
37	30/08/19 14:01	General View														Load JPG	<input checked="" type="checkbox"/>	
38	30/08/19 14:01	General View														Load JPG	<input checked="" type="checkbox"/>	
39	30/08/19 14:01	General View														Load JPG	<input checked="" type="checkbox"/>	
40	30/08/19 14:01	General View														Load JPG	<input checked="" type="checkbox"/>	
41	30/08/19 14:01	General View														Load JPG	<input checked="" type="checkbox"/>	
42	30/08/19 14:01	General View														Load JPG	<input checked="" type="checkbox"/>	
43	30/08/19 14:01	General View														Load JPG	<input checked="" type="checkbox"/>	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
44	30/08/19 14:02	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
45	30/08/19 14:02	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
46	30/08/19 14:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
47	30/08/19 14:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
48	30/08/19 14:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
49	30/08/19 14:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
50	30/08/19 14:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
51	30/08/19 14:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
52	30/08/19 14:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
53	30/08/19 14:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
54	30/08/19 14:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
55	30/08/19 14:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
56	30/08/19 14:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
57	30/08/19 14:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
58	30/08/19 14:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
59	30/08/19 14:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
60	30/08/19 14:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
61	30/08/19 14:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
62	30/08/19 14:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
63	30/08/19 14:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
64	30/08/19 14:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
65	30/08/19 14:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
66	30/08/19 14:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
67	30/08/19 14:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
68	30/08/19 14:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
69	30/08/19 14:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
70	30/08/19 14:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
71	30/08/19 14:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
72	30/08/19 14:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
73	30/08/19 14:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
74	30/08/19 14:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
75	30/08/19 14:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
76	30/08/19 14:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
77	30/08/19 14:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
78	30/08/19 14:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
79	30/08/19 14:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
80	30/08/19 14:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
81	30/08/19 14:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
82	30/08/19 14:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
83	30/08/19 14:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
84	30/08/19 14:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
85	30/08/19 14:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
86	30/08/19 14:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
87	30/08/19 14:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
88	30/08/19 14:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
89	30/08/19 14:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
90	30/08/19 14:02	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
91	30/08/19 14:02	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
92	30/08/19 14:02	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
93	30/08/19 14:02	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
94	30/08/19 14:02	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
95	30/08/19 14:02	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
96	30/08/19 14:02	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
97	30/08/19 14:02	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
98	30/08/19 14:02	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
99	30/08/19 14:02	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
100	30/08/19 14:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
101	30/08/19 14:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
102	30/08/19 14:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
103	30/08/19 14:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
104	30/08/19 14:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
105	30/08/19 14:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
106	30/08/19 14:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
107	30/08/19 14:03	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
108	30/08/19 14:03	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
109	30/08/19 14:03	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
110	30/08/19 14:03	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
111	30/08/19 14:03	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
112	30/08/19 14:03	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
113	30/08/19 14:03	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
114	30/08/19 14:03	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
115	30/08/19 14:03	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
116	30/08/19 14:03	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
117	30/08/19 14:03	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
118	30/08/19 14:03	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
119	30/08/19 14:03	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
120	30/08/19 14:03	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
121	30/08/19 14:03	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
122	30/08/19 14:03	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
123	30/08/19 14:03	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
124	30/08/19 14:03	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
125	30/08/19 14:03	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
126	30/08/19 14:03	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
127	30/08/19 14:03	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
128	30/08/19 14:03	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
129	30/08/19 14:03	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
130	30/08/19 14:03	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
131	30/08/19 14:03	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
132	30/08/19 14:03	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
133	30/08/19 14:03	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
134	30/08/19 14:03	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
135	30/08/19 14:03	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
136	30/08/19 14:03	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
137	30/08/19 14:03	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
138	30/08/19 14:03	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
139	30/08/19 14:03	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
140	30/08/19 14:03	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
141	30/08/19 14:03	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
142	30/08/19 14:03	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
143	30/08/19 14:03	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
144	30/08/19 14:03	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	28/11/19 12:33	Singapore Accident Statement	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	19/12/19 09:04	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19014879/GCD3E2

Date: 26/12/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100016039

Claimant Vehicle No : SJJ9522E Insured Vehicle No : SGT7937M

Date of Loss: 20/08/2019 Nature of Claim: TP Claim No: 2852781852SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJJ9522E
 Make & Model: SUBARU IMPREZA 5D, 2.0 I-S EYESIGHT (A) Engine No: EJ20D311020
 Reg. Date: 14/06/2008 (Man. Year: 2008) Chassis No: GH8004902
 Colour: Silver Odometer: 128088 km
 Engine Capacity: 1994 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45Z R17 Rear Tyre Size: 225/45Z R17
 Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
 Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 23/08/2019

Date Inspected: 23/08/2019 Inspected At:

Motor Intelligence Automo Pte Ltd
 (HQ)
 13 KAKI BUKIT ROAD 4, #01-20
 BARTLEY BIZ CENTRE
 Singapore 417807

Estimated Period of Repair: 6.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Broken	0.00 F	*- F
2	1		*FRT BUMPER CLIPS	Necessary	0.00 F	*- F
3	1		*FRT BUMPER SIDE RETAINER LH	Deformed	0.00 F	*- F
4	1		*FRT LH HEADLAMP ASSY	Cut	0.00 F	*- F
5	1		*FRT LH FENDER	Buckled	0.00 F	*- F
6	1		*FRT LH FENDER INNER SHIELD	Torn	0.00 F	*- F
7	1		*FRT LH WHEEL RIM	Cut	0.00 F	*- F
8	1		*FRT LH TYRE	Scratched	0.00 F	*- F
9	1		*FRT RH WHEEL RIM	Bent	0.00 F	*- F
10	1		*FRT RH TYRE	Scratched	0.00 F	*- F
11	1		*LH ROCKER PANEL GARNISH	Repair	0.00 F	*- F
12	1		*RH ROCKER PANEL GARNISH	Deformed	0.00 F	*- F
13	1		*REAR BUMPER	Broken	0.00 F	*- F
14	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
15	1		*REAR BUMPER SIDE RETAINER RH	Deformed	0.00 F	*- F
16	1		*REAR RH WHEEL RIM	Cut	0.00 F	*- F
17	1		*REAR RH TYRE	Scratched	0.00 F	*- F
18	1		*WING MIRROR LH	Repair	0.00 F	*- F
19	1		*FRT LH KNUCKLE ARM	Bent	0.00 F	*- F
20	1		*FRT LH KNUCKLE ARM BEARING	Necessary	0.00 F	*- F
21	1		*FRT LH LOWER ARM	Bent	0.00 F	*- F
22	1		*FRT RH KNUCKLE ARM	Bent	0.00 F	*- F
23	1		*FRT RH KNUCKLE ARM BEARING	Necessary	0.00 F	*- F
24	1		*FRT RH LOWER ARM	Bent	0.00 F	*- F
25	1		*REAR RH KNUCKLE ARM	Bent	0.00 F	*- F
26	1		*REAR RH KNUCKLE ARM BEARING	Necessary	0.00 F	*- F
27	1		*REAR RH LOWER ARM	Bent	0.00 F	*- F
F=Franchise part.						
Total Parts (\$\$)					0.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >