

ASS. REC. BY:

REF:

083/PWD19014888/Fsd302

Special Instruction:

Surveyor: Ram

ASSIGNMENT (Office)

merimen

From (Person):

Eileen bay

of

PWD

Date/Time:

23/8/1900 11:32am

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SCX 9595D

Insured:

SLG 83724

at Workshop m/s

Thian choon Auto

Tel:

9755 3077

of

Blk 176 8m Piney Drive # 05-02

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

22/8/19

26/8/19 @ after 9am

H.O.D. Endorsement:

CA / REV / REP. / REV 24 HRS

Date/Time:

12:20pm 23/8/19

Person Contacted:

james

Vehicle IN/OUT

OUT

Date/Time	Action/Instruction
	Initials (✓)
	SCX 9595D - CS/AXA/4016380/Mlgpk3
	SLG 83724 - X

DOA 23/08/2014

ASS. REC. BY:

REF: PWD

ASSIGNMENT

From:

Date: 26/8/19

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SCX 9595D

at Workshop m/s

Thian Choon

of

Blk 176 Sin Ming Drive

Insured:

05-02

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

James @ 9755 3077

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.

<input checked="" type="checkbox"/>	<input type="checkbox"/>
N/S	O/S
<input type="checkbox"/>	<input type="checkbox"/>

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS / up

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SCX 9595D

Yr Regn: MAY / 2018

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda HR-V

C.C 1496

Colour

Red

A/C:

Insured / Std / NI / NA

Sp. Reading

21137

T/Radio:

Insured / Std / NI / NA

Eng/No:

-

C/No:

J H M R V 181057 X 204 097

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi:

Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 215/60 R16

R: 215/60 R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

22/08/2019

D.O.I.

26/08/2019

Survey held at

Thian Choon

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

L/S: \$850 / 3 repair days confirmed with Sam's
 (\$ 2,055 /- Red - 71%)

RECEIVED 02 SEP 2019

Date/Time, File Pass to?

02/09/19

1)

Type

Date/Time, File Return to?

2)

☐

: Preli. Report

☒

: Final Report

Days Of Repair:

3

Resurvey No. of Trip:

2

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech. Invs (\$)

☐

: Weekend (\$)

Survey Fee:

200

Transportation:

50

S + RS: \$

50 + 50

Photos

Others

11

TOTAL

361

Report Format:

Lump Sum / L/S: (\$)

850/- L/S

Nivitha (LKK Auto)

From: eileen.bay@fwd.com
Sent: Friday, 23 August 2019 11:32 AM
To: assignments@lkkauto.com; sur@lkkauto.com; admin-a@lkkauto.com; admin-d@lkkauto.com
Cc: motorclaims.sg@fwd.com
Subject: RE: PRI G 479 - 19 TC =====scx 9595 d | FWD insured: SLG8372U
Attachments: PRI g 479tc.jpg; SLG8372U.zip

Hi LKK,

Please refer to the email below and liaise with TP repairer for survey arrangement.
Liability is clear, please explore direct settlement.
Kindly create the case in Merimen.

Kind regards,

Eileen Bay

Executive, Claims


FWD Singapore Pte. Ltd.

6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

T (65) 69217411

E eileen.bay@fwd.com

W www.fwd.com.sg



From: Motor Claims SG - SG Common
Sent: Friday, 23 August 2019 10:14 AM
To: Eileen Bay - SGUser
Subject: FW: PRI G 479 - 19 TC =====scx 9595 d

PNPV2018-00012176

From: tonygn tonygn [<mailto:tonygn18@hotmail.com>]
Sent: Thursday, 22 August, 2019 10:39 PM
To: Motor Claims SG - SG Common; james540@gmail.com
Subject: PRI G 479 - 19 TC =====scx 9595 d

Sent from Outlook

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the

use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

Thian Choon Auto

Blk. 176, Sin Ming Drive, #05 - 02, Sin Ming Autocare, Singapore 575721
Fax: 6458 - 8913 | Email: jamestay540@gmail.com

Date :- 22 / 8 / 2019

BY HAND

Motor Claims Department

BY FAX :-

FWD Singapore Pte. Ltd

Dear Sir,

EMAIL

COPY

**NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION
WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 6.2 OF
PRE-ACTION PROTOCOL FOR NIMA CASES**

We have been appointed by the Owner to repair his/her motor vehicle

No. *SCX 959SD* on *22-8-19* with another vehicle

No. *SLG 83724* at *Honda Service Centre*

Please be informed that the said vehicle can be inspected at:-

Contact

Workshop : Thian Choon Auto

Blk. 176, #05 - 02, Sin Ming Autocare

Sin Ming Drive, Singapore 575721

Contact

Fax : 6458 - 8913

Person : Mr. James / 9755 - 3077

Email : jamestay540@gmail.com

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Holiday. We will commence repairs thereafter without further reference to you.

Yours faithfully,

Wu LLC - Law Firm - Tony Gn

Our Ref : 19

- 479

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Singapore NRIC
Owner ID:	063C

Vehicle Details

Vehicle No.:	SCX9595D
Vehicle to be Exported:	No
Intended Deregistration Date:	27 Aug 2019
Vehicle Make:	HONDA
Vehicle Model:	HRV 1.5 DX CVT
Primary Colour:	Red
Manufacturing Year:	2018
Engine No.:	L15B4534096
Chassis No.:	JHMRU1810GX204097
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$19,096.00
Original Registration Date:	10 May 2018
First Registration Date:	10 May 2018
Transfer Count:	0
Actual ARF Paid:	\$19,096.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	09 May 2028
PARF Rebate Amount:	\$14,322.00

Intended COE Rebate Details

COE Expiry Date:	09 May 2028
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$38,000.00
COE Rebate Amount:	\$33,056.00
Total Rebate Amount:	\$47,378.00

The information contained herein is correct as at 27 Aug 2019

OK

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

Bmw 320i 2.0A Convertible.

19" M3 Sports Run, M-
Performance Exhaust, Carbon
Fibre Air Intake, High OMV,
Direct Owner - Star Ad

Auto Inn
An Inspiration For Car Buyers

click here to view
our **PRISTINE USED CARS**
at **GREAT PRICES**

Browse by Category







Sort by Date Posted

20 results/

6 vehicles

Honda HR-V

Advanced Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Stat
Search Selection	Honda HR-V		Any	Any	2018	Any	Any	Any	Av
	Honda HR-V 1.5A DX		\$84,800	\$8,670 /yr	30-Apr-2018	1,496 cc	27,160 km	SUV	Av
KAH Motor Unit! 1 Owner Only! Most Reliable And Well Known SUV! Very Low Fuel Consumption And Low On Maintenance! Trade In Welcome! Flexible Bank/In House Financing Available With Fast And Easy Loan Approval! 100% Loan Can Be Arranged As Well! Guarant...									
Benefit Auto Enterprise Pte Ltd									
Posted: 24-Aug-2019 Tags: 2018 Honda HR-V, 2018 honda HRV, Honda HR-V, honda HRV, Honda, HR-V, HRV, Used Honda									
	Honda HR-V 1.5A LX (OPC)		\$71,800	\$7,050 /yr	23-Apr-2018	1,496 cc	10,765 km	SUV	Av
Special Promotion 1.5% Interest Rate! Limited Time Only! Agent Warranty Till April 2023. Low Mileage And Low Depreciation! High Specs LX Model! 1 Owner Unit. Fully Agent Serviced And Maintained. Pristine Condition! A Peace Of Mind And Hassle Free Experience! Call/SM...									
Republic Auto									
Posted: 21-Aug-2019 Tags: 2018 Honda HR-V, 2018 honda HRV, Honda HR-V, honda HRV, Honda, HR-V, HRV, Used Honda									
	Honda HR-V 1.5A LX		\$105,800	\$10,810 /yr	06-Jun-2018	1,496 cc	28,000 km	SUV	Av
Loan Available! Sporty Suv White Unit. Highest Specs! 5 Years Agent Warranty, Best Selling Suv. Maintained At Kah Motors. Lowest Mileage In The Market. Please Call/Sms/Whatsapp Now For Enquiries And Viewing Appointment. (Consignment Unit).									
Autotruster Traders Pte Ltd									
Posted: 20-Aug-2019 Tags: 2018 Honda HR-V, 2018 honda HRV, Honda HR-V, honda HRV, Honda, HR-V, HRV, Used Honda									
	Honda HR-V 1.5A DX		\$84,500	\$8,630 /yr	03-May-2018	1,496 cc	23,000 km	SUV	Av
Superb Condition With 3 Years Agent Warranty (Until 2021), Best Selling SUV. Maintained At Kah Motors Since Day 1. High Loans Up To 90% Of The Car Price With Interest Rates Starting From 2.28%. Call Now To Book An Appointment To View This Beauty. Strictly By App...									
Posted: 19-Aug-2019 Tags: 2018 Honda HR-V, 2018 honda HRV, Honda HR-V, honda HRV, Honda, HR-V, HRV, Used Honda									
Car Buying	Car Selling		Car Ownership		Buying a pre-owned car Unsure of its Condi Get, STA Car Eval				
Car Aftermarket	On The Move		Lifestyle						
	Honda HR-V 1.5A LX		\$86,800	\$8,680 /yr	28-May-2018	1,496 cc	13,386 km	SUV	Av
Special Promotion At 1.5% Interest Rate! Limited Time Only! Low Mileage And Low Depreciation! High Specs LX Model! 1 Owner Only! Full Agent Servicing And Warranty Till May 2023! Pristine Condition! A Peace Of Mind And Hassle Free Experience! Call/Sms/Whatsapp F...									
Republic Auto									
Posted: 16-Aug-2019 Tags: 2018 Honda HR-V, 2018 honda HRV, Honda HR-V, honda HRV, Honda, HR-V, HRV, Used Honda									
	Honda HR-V 1.5A DX (OPC)		\$68,800	\$6,520 /yr	10-Sep-2018	1,496 cc	11,940 km	SUV	Av
Facelift Model! Low Interest, In House Loan Available, Choice Of Leather Colour Selection, Well Maintained SUV That Is As Good As Brand New And Smell Like Brand New! Fully Agent (Kah Motor) Maintained With On-going Warranty! 1 Owner! STA Evaluation Provided! Buy It...									
Dickson Automobile									
Posted: 23-Jul-2019 Tags: 2018 Honda HR-V, 2018 honda HRV, Honda HR-V, honda HRV, Honda, HR-V, HRV, Used Honda									

Compare

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	22/08/2019 17:48
Date Of Accident	22/08/2019 10:10
Exact Location Of Accident	255 ALEXANDRA ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SCX9595D
Insured/Policyholder	
Name Of Registered Owner	GN WENYI CHARLENE
NRIC No	S8811063C
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-92217272
Alternative Phone No	OFFICE-92217272

Vehicle Particulars

Manufacturer	HONDA
Model	HR-V-1.5 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	AVIVA LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	10835801
Cover Note Number	

Driver

Name of Driver	GN CHIANG HERN TONY
NRIC No	S1296823Z
Date Of Birth	03/02/1958
Occupation	INDOOR
Date Of Driving Pass	07/07/2003
Driving Experience	16 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-92217272
Fax Number	
Contact Number	
Email Address	TONGGN18@HOTMAIL.COM

212.8

Address	S
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	PARENT
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLG8372U
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan


Ref: _____
Date & Time: _____

SKETCH PLAN

IMPORTANT NOTICE


1. The report must **correctly** state the details of the accident to speed up the claims process.
2. The report must be **completed by the Policyholder and/or the Authorised Driver**.
3. If the report is provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting **may be referred to the Police for investigation**.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the signing of this report to the insurers, you hereby consent to the archiving of this report at the centre, and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)** I understand, acknowledge, agree and consent that:
 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, store and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) assessing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes");
 - (b) All insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, store and/or process my Personal Information for one or more of the above Purposes, and
 - (c) My Personal Information may/also be disclosed by any of the Insurers and/or GIA to their third party service providers or subcontractors (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
 - (d) My Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
 - (e) The information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders;

Policyholder's Signature
Date & Time: _____


Driver's Signature
(If driver is not the policyholder)
Date & Time: _____


Reporting Centre Personnel's Signature
Name: _____
NRIC/FIN No: _____

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

My car was stationary parked in the parking lot in 255 Alexandra Road. After awhile, the driver of vehicle B come up to me and say that he hit onto my vehicle A. My vehicle A front portion was damaged due to this accident.

DECLARATION

I/We declare the foregoing particulars are true in every respect

Reporting Centre's Signature
(Reporting Centre)

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NARC/HIN No:

THIAN CHOON AUTO

176 Sin Ming Drive #05-02 Sin Ming AutoCare

Singapore 575721

Tel: 6458 8913

Co. Reg. No. 53091973K

Agreed Settlement Estimated cost of repair

Vehicle No SCX9595D

- 1 Front Bumper \$ 650 / BUC ✓
- 2 Front LH head Lamp \$ 1,250 xnn
- 3 Front LH Bumper Sport Lamp cover \$ 75 / Br \$55
List Item: \$105
20% = \$564
- 4 Spray painting on affected area \$ 450 \$250
- 5 Knocking Adjust FR7 on affected area \$ 480 \$250

Labour \$500

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tot = \$2,905

28/8/19 RAM (LKK)
88622778
PARASURAM@lkkc-auto.com
L/S Repair days

Total \$1064

24 + 20% L/S: \$850.00

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	22 Aug 2019 Edit Reg		23 Aug 2019 00:00 Edit Adj Rpt	S\$850.00 Edit Estimates	S\$850.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	Tan Hock Hwa, ID: S1709877B								
Main Claimant:	GN WENYI CHARLENE, ID: S8811063C								
Vehicle Reg. No.:	SCX9595D	Date of Loss:	22/08/2019 00:00 - :59 [15 Months and 12 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 1201900025130	Policy/Cover Note No.:	PNPV2018-00012176 (Comprehensive) Coverage: 17/10/2018 - 16/10/2019						
Vehicle Reg. No. (Insured):	SLG8372U	Policy No. (Claimant):							
		Excess:							
Repairer:	Thian Choon Auto () Blk176 Sin Ming Drive, #05-02 Sin Ming Autocare, S75721 Sin Ming - Tel:								
Handling Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Eileen Bay]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by PARASURAM SHANMUGAM] ... [Final Rpt due 03/09/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> FWD_SG (30/08/2019): SURVEY REPORT 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SCX9595D (1201900025130)**

[SLG8372U]

TP



GN WENYI CHARLENE

Aug 22 2019 12:00AM

[Tan Hock Hwa]

Thian Choon Auto

Upload Documents		Upload Photos	Compose New Letter	View View in Browser	
Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	29/08/19 17:54	General View		Load JPG	<input checked="" type="checkbox"/>
2	29/08/19 17:54	General View		Load JPG	<input checked="" type="checkbox"/>
3	29/08/19 17:54	General View		Load JPG	<input checked="" type="checkbox"/>
4	29/08/19 17:54	General View		Load JPG	<input checked="" type="checkbox"/>
5	29/08/19 17:54	General View		Load JPG	<input checked="" type="checkbox"/>
6	29/08/19 17:54	General View		Load JPG	<input checked="" type="checkbox"/>
7	29/08/19 17:54	General View		Load JPG	<input checked="" type="checkbox"/>
8	29/08/19 17:54	General View		Load JPG	<input checked="" type="checkbox"/>
9	29/08/19 17:54	General View		Load JPG	<input checked="" type="checkbox"/>
10	29/08/19 17:54	General View		Load JPG	<input checked="" type="checkbox"/>
11	29/08/19 17:54	General View		Load JPG	<input checked="" type="checkbox"/>
12	29/08/19 17:54	General View		Load JPG	<input checked="" type="checkbox"/>
13	29/08/19 17:54	General View		Load JPG	<input checked="" type="checkbox"/>
14	29/08/19 17:54	General View		Load JPG	<input checked="" type="checkbox"/>
15	29/08/19 17:54	General View		Load JPG	<input checked="" type="checkbox"/>
16	29/08/19 17:54	General View		Load JPG	<input checked="" type="checkbox"/>
17	29/08/19 17:54	General View		Load JPG	<input checked="" type="checkbox"/>
18	29/08/19 17:54	General View		Load JPG	<input checked="" type="checkbox"/>
19	29/08/19 17:54	General View		Load JPG	<input checked="" type="checkbox"/>
20	29/08/19 17:54	General View		Load JPG	<input checked="" type="checkbox"/>
21	29/08/19 17:54	General View		Load JPG	<input checked="" type="checkbox"/>
22	29/08/19 17:54	General View		Load JPG	<input checked="" type="checkbox"/>
23	29/08/19 17:54	General View		Load JPG	<input checked="" type="checkbox"/>
24	29/08/19 17:54	General View		Load JPG	<input checked="" type="checkbox"/>
25	29/08/19 17:54	General View		Load JPG	<input checked="" type="checkbox"/>
26	29/08/19 17:54	General View		Load JPG	<input checked="" type="checkbox"/>
27	02/09/19 09:08	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
28	02/09/19 09:08	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
29	02/09/19 09:08	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
30	02/09/19 09:08	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
31	02/09/19 09:08	After Repair Photo		Load JPG	<input checked="" type="checkbox"/>
32	02/09/19 09:08	After Repair Photo		Load JPG	<input checked="" type="checkbox"/>
33	02/09/19 09:08	After Repair Photo		Load JPG	<input checked="" type="checkbox"/>
34	02/09/19 09:08	After Repair Photo		Load JPG	<input checked="" type="checkbox"/>
35	02/09/19 09:08	After Repair Photo		Load JPG	<input checked="" type="checkbox"/>
36	02/09/19 09:08	After Repair Photo		Load JPG	<input checked="" type="checkbox"/>
37	02/09/19 09:08	After Repair Photo		Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	FWD Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	26/08/19 15:49	SCX9595D TP GIA	 Load PDF	
2	26/08/19 15:49	SLG8372U OI GIA.	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer			
Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/FWD19014888/FSD3E2

Date: 02/09/2019

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2018-00012176
Claimant Vehicle No : SCX9595D **Insured Vehicle No :** SLG8372U
 Date of Loss: 22/08/2019 Nature of Claim: TP Claim No: 1201900025130

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SCX9595D**
 Make & Model: HONDA HR-V, 1.5 DX CVT (A) Engine No: L15B4534096
 Reg. Date: 10/05/2018 (Man. Year: 2018) Chassis No: JHMRU1810GX204097
 Colour: Red Odometer: 21137 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16
 Front Left Side: Dunlop 5 mm Rear Left Side: Dunlop 5 mm
 Front Right Side: Dunlop 5 mm Rear Right Side: Dunlop 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,975.00	564.00	1,411.00	71.44
Miscellaneous Items	0.00	0.00	0.00	
Labour	930.00	500.00	430.00	46.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,905.00	1,064.00	1,841.00	63.37
Approved Total (Overridden) (S\$)		850.00		
Nett Amount (S\$)	2,905.00	850.00	2,055.00	70.74

INSPECTION

Date of Assignment: 23/08/2019
 Date Inspected: 26/08/2019 Inspected At: Thian Choon Auto
 Blk176 Sin Ming Drive, #05-02 Sin Ming
 Autocare
 Singapore 575721
 Estimated Period of Repair: 3.0 days

Adjuster: PARASURAM SHANMUGAM

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 02 Sep 2019)	
Parts:	N/A	HONDA HR-V 1.5 DX CVT (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SCX9595D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Buckled	650.00 F	*650.00 FL
2	1		*FRONT LH HEAD LAMP	Not Necessary	1,250.00 F	*- FL
3	1		*FRONT LH BUMPER SPORT LAMP COVER	Broken	75.00 F	*55.00 FL
					Sub Total (S\$)	1,975.00 705.00
					- List Item Discount on L Items 0.00/20.00% (S\$)	0.00 141.00
					Total Parts (S\$)	1,975.00 564.00

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	SPRAY PAINTING ON AFFECTED AREA	New	450.00	250.00
2	KNOCKING ADJUST FRT ON AFFECTED AREA	New	480.00	250.00
Gross Labour Cost (\$\$)			930.00	500.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >