

2/02/2012

ASS. REC. BY

REF

CS3/A1919014891/Dcd30

Special Instruction:

Inspector

Byn

ASSIGNMENT (Office)

From (Person)

Murnen chin lee ying

of

AIG

Date/Time:

23/8/19 @ 11:16am

Estimated Cost:

Bill to:

OD (TP) WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLG 6235X

Insured:

SLA 7999

at Workshop m/s

R.S. Automotive

Tel:

9182 6089

of

Blk 3006 ubi Road 1 #01-394

Policy No:

0999994449

Claim No:

840470441386

Sum Insured:

Excess:

Make of Veh:

D.O.A. 21/8/19

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

11:23am @ 23/8/19

Person Contacted:

Richard

Vehicle IN/OUT

Date/Time

Action/Instruction

13/11/19 (X)

SLG 6235X - WA/MSG19014716/24

DOA: 21/8/2019

SLA 7999 - NA/MSG19014716/24

DOA: 21/8/2019

LHF door - rep

LHF door chrome moulding x1 cut

LHR door - rep

LHR " " x1 cut.

LHR fender - rep

LH rocker panel germ - rep

Labour - 800/-

3 dgs.

spray - 800/-

ASS. REC. BY:

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLG 6235X Yr Regn: 2016 Oct 1Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Crystal Harrow C.C. 1986Colour: Black A/C: Insured / Std / NI / NASp. Reading: 89102 T/Radio: Insured / Std / NI / NAEng/No: 3ZRFAE 1986C/No: Z8U600070699

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or _____

Brake: In order / Jammed / Leaked / Burnt or _____

Modi: Nil / S/Rim / STD A/Rim or _____

Tyre Size: F: 235/55 R18R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Dunlop

Front

Rear

R/Bal. S mm R/Bal. S mmL/Bal. S mm L/Bal. S mmD.O.A. 21/08/2019 D.O.I. 23/08/2019Survey held at IDAC Page Ubi

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

n/s body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

ALG PRSDisassemble: 27/8/2019After repair: 28/8/2019

RECEIVED 11 OCT 2019

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 3Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S + RS: 180

Photos

Others

TOTAL

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)Report Format: DAR

Lump Sum / B/L: _____

191

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	22 Aug 2019 Edit Reg		23 Aug 2019 00:00 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	BLUE STAR CONCIERGE PTE LTD, Co. Reg. No.: 201506692D		
Main Claimant:	NA		
Vehicle Reg. No.:	SLG6235X	Date of Loss:	21/08/2019 00:00 - :59
Claim Type:	TP / 8404704413SG	Policy/Cover Note No.:	0999994449 (Comprehensive)
Vehicle Reg. No. (Insured):	SLA799G	Policy No. (Claimant):	
		Excess:	
Repairer:	RS Automotive Workshop (HQ) 3066 Ubi Road 1, #01-394/384, 408700 Ubi - Tel: 67483032		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Syed-Yusoff, Saliha] Saliha.Syed-Yusoff@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by BRYAN TANI] ... [Final Rpt due 03/09/2019]		
Claimant's Solicitor:	KURU & CO - Tel: 65322009		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)


- AIG_SG (26/08/2019): Request To Upload TP GIA Report

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHIC...

From: Chin, Lee-Ying
To: assignments, Admin A
Cc: Feng, Andy-SY
Sent: 8/23/2019 11:16:59 AM
Attachments:  19.1100 SAS.PDF

Hi LKK,

Kindly contact Richard to arrange for survey, he requested survey btw 2pm-4pm today.

Thanks.

Best Regards

Lee Ying, Chin

AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1947

Lee-Ying.Chin@aig.com | www.aig.sg

From: Kuru & Co [mailto:kurulegal@yahoo.com.sg]

Sent: Thursday, August 22, 2019 2:54 PM

To: Hor, Yinrul

Cc: Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Parthiban, Theerthan; Subramaniam, Divyashni; Tong, Wahxin

Subject: [EXTERNAL] Re: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLA799G AND SLG6235X ON 21/08/2019 // Our ref: L.19.1100.lt

This message is from an external sender; be cautious with links and attachments.

Dear Sirs,

We confirm that you have **objected** to our client's list of surveyors. Our client's vehicle is at the following address:

R S Automotive Pte Ltd

Blk 3006 Ubi Road

#01-394

Singapore 408700

Tel: 91826089 - Richard

Please inform your surveyor to conduct the pre-repair survey within 2 working days, failing which our client will have no alternative but to proceed with the repair of his vehicle.

Regards,

Lena

Kuru & Co

150 South Bridge Road

#04-06 Fook Hai Building

Singapore 058727

Tel: 6532 2009

Fax: 6532 2007

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	21/08/2019 16:31
Date Of Accident	21/08/2019 14:45
Exact Location Of Accident	10 UBI CRESCENT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLG6235X
Insured/Policyholder	
Name Of Registered Owner	TEE CHEE SIONG
NRIC No	S7176923B
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-88090637
Alternative Phone No	OFFICE-88090637

Vehicle Particulars

Manufacturer	TOYOTA
Model	HARRIER PREMIUM 2.0 A
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	A29034026QMY
Cover Note Number	

Driver

Name of Driver	TEE CHEE SIONG
NRIC No	S7176923B
Date Of Birth	03/10/1971
Occupation	INDOOR
Date Of Driving Pass	23/10/2008
Driving Experience	10 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-88090637
Fax Number	
Contact Number	OFFICE-88090637

Address	BLK 130 LORONG AH SOO #05-388
Postcode	530130
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : - GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON STATED DATE AND TIME, I WAS TRAVELLING ALONG THE STATED VENUE. SUDDENLY VEHICLE B CAME OUT FROM LOBBY C CUT ONTO MY LANE WITHOUT STOPPED BEFORE THE STOPPING LINE TO CHECK ONCOMING VEHICLES BEFORE HE CAN PROCEED. AS A RESULT, VEHICLE B HIT ONTO MY VEHICLE LEFT PORTION.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	VIDEO FOOTAGE WITH DRIVER
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLA799G
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE HIRE
Name of Driver	SEET SIEW KIAM, VICTOR
NRIC/Passport Number	S1252390D
Contact Number	
Address	

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

2

Passenger 1

NAME: :

GENDER: :

Accident Sketch Plan

SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

B. Consent under the Personal Data Protection Act (PDPA)


I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:




Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to statement.



I/We declare the foregoing particulars are true in every respect.

Reporting Centre Personnel's Signature
Name: _____
NRIC/FIN No.: _____

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	22 Aug 2019 Edit Reg		23 Aug 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS				[Created by adjuster]		
Insured:	BLUE STAR CONCIERGE PTE LTD, Co. Reg. No.: 201506692D					
Main Claimant:	NA					
Vehicle Reg. No.:	SLG6235X	Date of Loss:	21/08/2019 00:00 - :59 [34 Months and 20 Days From LTA Reg Date (Man Yr)]			
Claim Type:	TP / 8404704413SG	Policy/Cover Note No.:	0999994449 (Comprehensive)			
Vehicle Reg. No. (Insured):	SLA799G	Policy No. (Claimant):				
		Excess:				
Repairer:	RS Automotive Workshop (HQ) 3066 Ubi Road 1, #01-394/384, 408700 Ubi - Tel: 67483032					
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Syed-Yusoff, Saliha] Saliha.Syed-Yusoff@aig.com					
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by BRYAN TANI] ... [Final Rpt due 03/09/2019]					
Claimant's Solicitor:	KURU & CO - Tel: 65322009					




















ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
<ul style="list-style-type: none"> AIG_SG (26/08/2019): Request To Upload TP GIA Report 		

ALL ASSOCIATED TASKS	View All	Search Tasks	Create New Task	Complete					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLG6235X (8404704413SG)
[SLA799G]
TP
NA
Aug 21 2019 12:00AM
[BLUE STAR CONCIERGE PTE LTD]
RS Automotive Workshop

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View View in Browser		
Video														1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)											Thumbnail		Print		
1	29/08/19 08:42	Video - Accident from insured												Load MP4			
Photos/Images														3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)											Thumbnail		Print		
1	10/10/19 15:43	Rear View Left												Load JPG	<input checked="" type="checkbox"/>		
2	10/10/19 15:43	Rear View Right												Load JPG	<input checked="" type="checkbox"/>		
3	10/10/19 15:44	General View												Load JPG	<input checked="" type="checkbox"/>		
4	10/10/19 15:44	General View												Load JPG	<input checked="" type="checkbox"/>		
5	10/10/19 15:44	General View												Load JPG	<input checked="" type="checkbox"/>		
6	10/10/19 15:44	General View												Load JPG	<input checked="" type="checkbox"/>		
7	10/10/19 15:44	General View												Load JPG	<input checked="" type="checkbox"/>		
8	10/10/19 15:44	General View												Load JPG	<input checked="" type="checkbox"/>		
9	10/10/19 15:44	General View												Load JPG	<input checked="" type="checkbox"/>		
10	10/10/19 15:44	General View												Load JPG	<input checked="" type="checkbox"/>		
11	10/10/19 15:44	General View												Load JPG	<input checked="" type="checkbox"/>		
12	10/10/19 15:44	General View												Load JPG	<input checked="" type="checkbox"/>		
13	10/10/19 15:44	General View												Load JPG	<input checked="" type="checkbox"/>		
14	10/10/19 15:44	General View												Load JPG	<input checked="" type="checkbox"/>		
15	10/10/19 15:44	General View												Load JPG	<input checked="" type="checkbox"/>		
16	10/10/19 15:44	General View												Load JPG	<input checked="" type="checkbox"/>		
17	10/10/19 15:44	General View												Load JPG	<input checked="" type="checkbox"/>		
18	10/10/19 15:44	General View												Load JPG	<input checked="" type="checkbox"/>		
19	10/10/19 15:44	General View												Load JPG	<input checked="" type="checkbox"/>		
20	10/10/19 15:44	General View												Load JPG	<input checked="" type="checkbox"/>		
21	10/10/19 15:44	General View												Load JPG	<input checked="" type="checkbox"/>		
22	10/10/19 15:44	General View												Load JPG	<input checked="" type="checkbox"/>		
23	10/10/19 15:44	General View												Load JPG	<input checked="" type="checkbox"/>		
24	10/10/19 15:44	General View												Load JPG	<input checked="" type="checkbox"/>		
25	10/10/19 15:44	General View												Load JPG	<input checked="" type="checkbox"/>		
26	10/10/19 15:44	General View												Load JPG	<input checked="" type="checkbox"/>		
27	10/10/19 15:44	General View												Load JPG	<input checked="" type="checkbox"/>		
28	10/10/19 15:44	General View												Load JPG	<input checked="" type="checkbox"/>		
29	10/10/19 15:44	Odometer Reading												Load JPG	<input checked="" type="checkbox"/>		
30	10/10/19 15:44	Chassis Number												Load JPG	<input checked="" type="checkbox"/>		
31	10/10/19 15:45	Reinspection Photo												Load JPG	<input checked="" type="checkbox"/>		
32	10/10/19 15:45	Reinspection Photo												Load JPG	<input checked="" type="checkbox"/>		
33	10/10/19 15:45	Reinspection Photo												Load JPG	<input checked="" type="checkbox"/>		
34	10/10/19 15:45	Reinspection Photo												Load JPG	<input checked="" type="checkbox"/>		
35	10/10/19 15:45	Reinspection Photo												Load JPG	<input checked="" type="checkbox"/>		
36	10/10/19 15:45	Reinspection Photo												Load JPG	<input checked="" type="checkbox"/>		
37	10/10/19 15:45	Reinspection Photo												Load JPG	<input checked="" type="checkbox"/>		
38	10/10/19 15:45	Reinspection Photo												Load JPG	<input checked="" type="checkbox"/>		
39	10/10/19 15:45	Reinspection Photo												Load JPG	<input checked="" type="checkbox"/>		
40	10/10/19 15:45	Reinspection Photo												Load JPG			

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
				<input checked="" type="checkbox"/>
41	10/10/19 15:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
42	10/10/19 15:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
43	10/10/19 15:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	10/10/19 15:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	10/10/19 15:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	10/10/19 15:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	10/10/19 15:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	10/10/19 15:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	10/10/19 15:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	10/10/19 15:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	10/10/19 15:45	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
52	10/10/19 15:45	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
53	10/10/19 15:45	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
54	10/10/19 15:45	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
55	10/10/19 15:45	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
56	10/10/19 15:45	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
57	10/10/19 15:45	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
58	10/10/19 15:45	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	29/08/19 08:43	E-filed GIA report	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 100px; width: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19014891/DCD3E2

Date: 14/10/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994449
Claimant
Vehicle No : SLG6235X **Insured Vehicle No :** SLA799G
Date of Loss: 21/08/2019 **Nature of Claim:** TP **Claim No:** 8404704413SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLG6235X
Make & Model: TOYOTA HARRIER, 2.0 Premium (A) **Engine No:** 3ZRFAE1986
Reg. Date: 01/10/2016 (Man. Year: 2016) **Chassis No:** ZSU600070699
Colour: Black **Odometer:** 89102 km
Engine Capacity: 1986 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes **Footbrake (Serviceable):** Yes
Handbrake (Serviceable): Yes **Engine Modification:** No **Pre-accident Condition:** Yes

CONDITION OF TYRES

Front Tyre Size: 235/55 R18 **Rear Tyre Size:** 235/55 R18
Front Left Side: Dunlop 5 mm **Rear Left Side:** Dunlop 5 mm
Front Right Side: Dunlop 5 mm **Rear Right Side:** Dunlop 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 23/08/2019
Date Inspected: 23/08/2019 **Inspected At:** RS Automotive Workshop (HQ)
3066 Ubi Road 1, #01-394/384
Singapore 408700
Estimated Period of Repair: 3.0 days

Adjuster: BRYAN TANI

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LHF DOOR	Repair	0.00 F	*- F
2	1		*LHR DOOR	Repair	0.00 F	*- F
3	1		*LHR FENDER	Repair	0.00 F	*- F
4	1		*LH ROCKER PANEL GARNISH	Repair	0.00 F	*- F
5	1		*LHF DOOR CHROME MOULDING	Cut	0.00 F	*- F
6	1		*LHR DOOR CHROME MOULDING	Cut	0.00 F	*- F
F=Franchise part.				Total Parts (\$\$)	0.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >