

21/11/2002

ASS. REC. BY:

REF:

C83/1191904895/Act3et

Special Instruction:

Surveyor: Adnan

ASSIGNMENT (Office)

From (Person):

Nurmer

Chin Lee Ying

of

119

Date/Time:

23/8/19 @ 10.23am

Estimated Cost:

Bill to:

OD / ~~TP~~ / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJH 7612C

Insured:

SDG 6718P

at Workshop in/s

Lynston Motor

Tel:

9727 7987

of

25 Kelki Bukit Road 4 #05-66/68

Policy No:

2100408344

Claim No:

2868921872SG

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

17/8/19

CA / REV / REP. / REV 24 HRS

I.O.D. Endorsement:

Date/Time:

11:40am 23/8/19

Person Contacted:

Henry

Vehicle:

IN / OUT

| Date/Time | Action/Instruction                    | Johny | X              |
|-----------|---------------------------------------|-------|----------------|
|           | SJH 7612C - C83/11911011812 / Ka2a3g2 |       | DOA: 7/6/2011  |
|           | SDG 6718P - C8/MSG100/6141 / Rvr      |       | DOA: 15/8/2010 |
|           | Dismantle: 23/8/2019                  |       |                |
|           | After repair: 27/8/2019               |       |                |

ASS. REF. BY:

REF:

Adrian

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_


Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SJH7612C Yr Regn: 2008 Augst.Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Stream c.c. 1799Colour: Black A/C: Insured / Std / NI / NASp. Reading 340557 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: RN61060246Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / SR / STD A/Rim orTyre Size: F: 215/50R17R: 215/50R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Kumho

Front

Rear

R/Bal. ob mm R/Bal. ob mmL/Bal. ob mm L/Bal. ob mmD.O.A. \_\_\_\_\_ D.O.I. 23/08/19Survey held at hystariDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP A16 PRS.COE Expiry: 21/08/23MV: 21KPV: 14KNett: 13K

Date/Time, File Pass to?

Date/Time, File Return to?

1) DAR - 2drips

2)

3)

4)

5)

6)

Prel. Report:

Final Report:

Part Prices Check:

IN

OUT

Survey Fee:

Date:

Basic &amp; Add.

S + RS, SI

Photos

Others

TOTAL

18011191

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

| CLAIM SUBFOLDER TRACKING |   |               |   |         |               |            |   |
|--------------------------|---|---------------|---|---------|---------------|------------|---|
| Case                     | Notified                                | Est Submitted | Adj Assigned                                      | Adj Rpt | Adj Submitted | Ins Auth'd | Status  |
| Main                     | 19 Aug 2019<br><a href="#">Edit Reg</a> |               | 23 Aug 2019 00:00<br><a href="#">Edit Adj Rpt</a> |         |               |            | <b>Pending for Survey Report</b><br><a href="#">Cancel Case</a> |

| Main | Reference | Claim Details | Documents | <a href="#">Show All</a> |
|------|-----------|---------------|-----------|--------------------------|
|------|-----------|---------------|-----------|--------------------------|

| CLAIM SUBFOLDER DETAILS     |  | [Created by adjuster]  |
|-----------------------------|--|--|
| Insured:                    |  |  |
| Main Claimant:              | E-CUBE VEHICLE RENTAL PTE LTD, Co. Reg. No.: 201607761H  |  |
| Vehicle Reg. No.:           | SJH7612C   | Date of Loss: 17/08/2019 10:00 - :59   |
| Claim Type:                 | TP / 2868921872SG  | Policy/Cover Note No.: 2100408344 (Comprehensive)<br>Coverage: 08/04/2019 - 07/04/2020 |
| Vehicle Reg. No. (Insured): | SDG6718P   | Policy No. (Claimant):   |
|                             |  | Excess:  |
| Repairer:                   | Lsm Lynston Motor & Spray Works (HQ) 25 KAKI BUKIT ROAD 4 #05-66/68 SYNERGY@KB, 417800 Kaki Bukit - Tel:       |  |
| Handling Insurer:           | AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000   |  |
| Adjuster:                   | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 03/09/2019] |  |

[View All](#)
[Compose Case Mail](#)

**ASSOCIATED MAIL RECEIVED**



- AIG\_SG (26/08/2019): Request To Upload TP GIA Report

**ALL ASSOCIATED TASKS** 
[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

| Due Date    | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
|-------------|----------|------|------------|---------|---------|-------------|--------------|------------|-------|
| No results. |          |      |            |         |         |             |              |            |       |

**PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHIC...**

From: Chin, Lee-Ying  
To: assignments, Admin A  
Cc: Fong, Andy-SY  
Sent: 8/23/2019 10:23:47 AM

Attachments:  letter to 3p and AIG.PDF  GIA REPORT SJH7612C.PDF

Hi LKK,

Kindly assist to survey, vehicle in workshop.

Thanks.

Best Regards

Lee Ying, Chin

AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1947

[Lee-Ying.Chin@aig.com](mailto:Lee-Ying.Chin@aig.com) | [www.aig.sg](http://www.aig.sg)

**From:** sengtat@aplp.com.sg [mailto:sengtat@aplp.com.sg]  
**Sent:** Thursday, August 22, 2019 3:43 PM

**To:** Hor, Yinrul

**Cc:** Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Parthiban, Theerthan; Subramaniam, Divyashni; Tong, Wahxin; sengtat@aplp.com.sg

**Subject:** RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SDG6718P AND SJH7612C ON 17/08/2019

**WITHOUT PREJUDICE**

Dear Sir/ Mdm,

We refer to your email of even date.

Our clients do not agree to your list of surveyors.

We are instructed to propose the use of one of the motor surveyors named below to conduct the joint pre-repair survey as a single joint expert:

- a. Alan Cheong
- b. TT Rajan
- c. Oh Han Cheong
- d. Andrew How
- e. Dave Ho Joo Koong
- f. Sincere Appraiser
- g. Seah Kwang Boon

h. L H Teo

i. Mr Willy Goh

j. Nicky Seah

k. Jayson Liaw

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors.

In the event you are not agreeable to our list of surveyor, please note that our client's vehicle can be inspected at:

**LSM Lynston Motor & Spray Works**

25 Kaki Bukit Road 4

#05-66/68 Synergy@KB

Singapore 417800

**Contact Person: Mr Henry (9727 7987)**

Please note that our clients' vehicle will only be available for pre-repair survey within the next two (2) working days. Our clients shall proceed to repair their vehicle thereafter without further notice or reference to you.

All our clients' rights are reserved.

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

| Vehicle Owner Particulars |         |
|---------------------------|---------|
| Owner ID Type:            | Company |
| Owner ID:                 | 761H    |

| Vehicle Details               |                    |
|-------------------------------|--------------------|
| Vehicle No.:                  | SJH7612C           |
| Vehicle to be Exported:       | Yes                |
| Intended Deregistration Date: | 23 Aug 2019        |
| Vehicle Make:                 | HONDA              |
| Vehicle Model:                | STREAM 1.8 A       |
| Primary Colour:               | Black              |
| Manufacturing Year:           | 2008               |
| Engine No.:                   | R18A1767327        |
| Chassis No.:                  | RN61060246         |
| Maximum Power Output:         | 103.0 kW (138 bhp) |
| Open Market Value:            | \$18,941.00        |
| Original Registration Date:   | 22 Aug 2008        |
| First Registration Date:      | 22 Aug 2008        |
| Transfer Count:               | 4                  |
| Actual ARF Paid:              | \$12,107.00        |

| Intended PARF Rebate Details  |           |
|-------------------------------|-----------|
| PARF Eligibility:             | Forfeited |
| PARF Eligibility Expiry Date: | -         |
| PARF Rebate Amount:           | \$0.00    |

| Intended COE Rebate Details |                          |
|-----------------------------|--------------------------|
| COE Expiry Date:            | 21 Aug 2023              |
| COE Category:               | B - Car (1601cc & above) |
| COE Period(Years):          | 5                        |
| PQP Paid:                   | \$17,496.00              |
| COE Rebate Amount:          | \$13,977.00              |
| <b>Total Rebate Amount:</b> | <b>\$13,977.00</b>       |

| Message   |  |
|---|--|
| Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier. |  |

The information contained herein is correct as at 23 Aug 2019

OK



## VGLOBAL CAR SALON @ SGCM CARNIVAL 2019

31 Aug - 1 Sept 2019 • 10am - 8pm • BOOTH 1  
Downtown East, Tentage next to Carpark B



Post an Advertisement  
Sell it yourself! Advertise it at just  
**\$58 until it's SOLD!**

[Post an Ad](#) [Advertiser Login](#) [Ways of Selling](#)

## New Facelift 520 For Sale. Price Nego.



Agent Car, Flexi Loan With High  
Trade In Available. Call Now Or  
Visit Our Showroom  
Car1 Pte Ltd. StarAd



## PRIME MOTOR &amp; LEASING

(CHENG YONG CREDIT ENTERPRISES PTE LTD. GROUP OF COMPANIES)

With over 200 units of vehicles  
to choose from, ranging from  
all European to Japanese Makes.



Browse by Category

Save Search

Print

« Back ( 1 2 3 4 ) Next »

Sort by Date Posted

20 results/page

76 vehicles

Search Honda Stream

Advanced Search

Search

View All

Make

Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

Veh Type

Status

Search Selection

Honda Stream

Any

Any

> 10 year(s)  
old

Any

Any

Any

Available



☐ Honda Stream 1.8A RSZ (COE  
till 07/2028)

\$49,988

\$5,600 /yr

28-Jul-2008

1,799 cc

210,000 km

MPV

Available

Drive With Assurance! Genuine And Transparent Deal! Bank/In House Up To 100% No Gimmick! All Our Quality Consignment Cars Are  
Selling At The Most Reasonable Price With A Peace Of Mind! STA Inspection Welcome! No Repair Needed! 100% Impressive! Best Price...

CONSIGNMENT

Posted: 15-Aug-2019 Tags: 2008 Honda Stream, 2008 honda stream, Honda Stream, honda stream, Honda, Stream, stream, Used  
Honda



☐ Honda Stream 1.8A X (COE till  
08/2023)

\$29,668

\$7,490 /yr

08-Aug-2008

1,799 cc

174,500 km

MPV

Available

Practical And Good Fuel Efficiency, Family Car Ideal For Daily Drives. Car Is In Good Condition. Strictly Call For Viewing Appointment Only  
As We Will Need To Make Arrangement With Owner. Flexible Bank/In House Loan And Trade In Available.

Posted: 29-Jul-2019 Tags: 2008 Honda Stream, 2008 honda stream, Honda Stream, honda stream, Honda, Stream, stream, Used  
Honda



☐ Honda Stream 1.8A X (COE till  
08/2028)

\$49,888

\$5,550 /yr

15-Aug-2008

1,799 cc

159,000 km

MPV

Available

New Road Tax, Servicing, Repairs Done.

DIRECT OWNER

Posted: 06-Aug-2019 Tags: 2008 Honda Stream, 2008 honda stream, Honda Stream, honda stream, Honda, Stream, stream, Used  
Honda



☐ Honda Stream 1.8A (COE till  
09/2028)

\$52,000

\$5,730 /yr

20-Sep-2008

1,799 cc

157,000 km

MPV

Available

Own A Superbly Maintained Stream, New Steering Rack, Tyres, Aircon Compressor, Shiny \$2K Paint, 4 Original Shock Absorbers, Battery,  
All Done Within 1 Month Plus, ATF And Engine Serviced And Replaced, No Worries For New Owner, Just Drive And Enjoy The Car, No M...

DIRECT OWNER

Posted: 15-Aug-2019 Tags: 2008 Honda Stream, 2008 honda stream, Honda Stream, honda stream, Honda, Stream, stream, Used  
Honda

GET YOUR  
COE  
RENEWAL  
LOAN

Is your COE expiring? Let us help you renew it!

Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town and an  
approval in 2 days without effort! Enquire today.



☐ Honda Stream 1.8A X (COE till  
10/2023)

\$28,800

\$6,920 /yr

22-Oct-2008

1,799 cc

-

MPV

Available

Excellent And Original Condition, Well Maintained Interior And Exterior, Powerful Engine, Call Now For Viewing.

DIRECT OWNER

Posted: 02-Aug-2019 Tags: 2008 Honda Stream, 2008 honda stream, Honda Stream, honda stream, Honda, Stream, stream, Used  
Honda



☐ Honda Stream 1.8A RSZ (COE  
till 10/2023)

\$28,800

\$6,910 /yr

24-Oct-2008

1,799 cc

-

MPV

Available

Full Loan Available At \$800 Plus, We Can Help To Convert To Z10 Usage If Needed. In House Loan Or Bank Loan Available! Fast, Easy  
And Flexible Loan Approval! We Are sgCarMart Premium Dealer! Buy With Confidence! Viewing And Test Drive Available Daily Including...

PREMIUM AD

88 Motor Trading

Posted: 28-Aug-2019 Tags: 2008 Honda Stream, 2008 honda stream, Honda Stream, honda stream, Honda, Stream, stream, Used  
Honda

SHORTLISTED HISTORY

Compare

☐ Honda Stream 1.8A (COE till  
10/2023)

\$31,800

\$7,630 /yr

24-Oct-2008

1,799 cc

146,212 km

MPV

Available

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report 19/08/2019 19:04  
Date Of Accident 17/08/2019 10:00  
Exact Location Of Accident DUNEARN ROAD  
Country/State of Loss SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number SJH7612C  
**Insured/Policyholder**  
Name Of Registered Owner E-CUBE VEHICLE RENTAL PTE LTD  
Co Reg No 201607761H  
Email Address ENQUIRIES@ECUBEAUTO.COM  
Mobile Phone No (LOCAL) +65-91718165  
Alternative Phone No OFFICE-91718165

### Vehicle Particulars

Manufacturer HONDA  
Model STREAM  
Exact Purpose for which vehicle was being used at time of accident PRIVATE HIRER USE

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY  
Vehicle Category PRIVATE HIRE

### Insurance Company

Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD  
Type Of Coverage COMPREHENSIVE  
Fleet Policy NO  
Policy Number 5093829349-01  
Cover Note Number

### Driver

Name of Driver MOHAMAD IBRAHIM BIN AHMAT  
NRIC No S1401126I  
Date Of Birth 22/03/1960  
Occupation OUTDOOR  
Date Of Driving Pass 19/06/1995  
Driving Experience 24 YEARS AND 1 MONTH  
Gender MALE  
Mobile Number (LOCAL) +65-91718165  
Fax Number  
Contact Number  
Email Address

ENQUIRIES@ECUBEAUTO.COM



Address

Postcode

BLK 576 HOUGANG AVE 4 #07-602

530576

Was driver an employee of the Insured's Company

NO

If No, Relationship of the Driver with the Insured

OTHER - HIRER

Vehicle Registration Number of Driver's Own Vehicle

-

-

-

-

-

Insurance Company of Driver's Own Vehicle

### General Information of the Accident

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

RAINING

Road Surface

WET

### Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles (including own vehicle) involved in the accident

2

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by ambulance?

NO

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

3

Passenger 1

NAME: : UNKNOWN

GENDER: : FEMALE

Passenger 2

NAME: : UNKNOWN

GENDER: : FEMALE

### Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

### Circumstances of Accident

REFER TO ATTACHED

### Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SDG6718P

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

**8. Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:


Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/IN No.:

# Sketch Plan #2

## SKETCH PLAN

Vehicle A: 5JH76126  
Vehicle B: 5D67678P



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 17/08/2019 @ 10:00hrs, I was travelling along Dunearn Road towards city when I stop at the traffic (Red light) light junction of Kearns Road. & Vehicle 'B' 5D67678P collided with my rear.

I got down of my vehicle and ask her why she bang me and she says "I cannot stop in time". After that we both exchange particulars, contact number & we left the scene.

## DECLARATION

I declare the foregoing particulars are true in every respect.



Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name  
NRIC/IN NO:

## Rear Portion

5TH 7612C

| NAC  | INC    | Item                             | CON | AC | Qty |
|------|--------|----------------------------------|-----|----|-----|
| 1137 | 993626 | Rear Number Plate                |     |    |     |
| 1138 | 993627 | Rear Number Plate Base           |     |    |     |
| 1139 | 993630 | Rear Number Plate Garnish        |     |    |     |
| 1140 | 993632 | Rear Number Plate Lamp           |     |    |     |
| 1141 | 992958 | Rear Bumper                      | De  | ✓  |     |
| 1142 | 993085 | Rear Bumper Upper                |     |    |     |
| 1143 | 993017 | Rear Bumper Lower                |     |    |     |
| 1144 | 993054 | Rear Bumper Side                 |     |    |     |
| 1145 | 993103 | Rear Bumper Tow Cover            |     |    |     |
| 1146 | 992341 | Rear Bumper Clips                | Nec | ✓  |     |
| 1147 | 992976 | Rear Bumper Bracket              |     |    |     |
| 1148 | 993068 | Rear Bumper Side Retainer        | Nec | ✓  | 02  |
| 1149 | 993045 | Rear Bumper Reinforcement        |     |    |     |
| 1150 | 992970 | Rear Bumper Beam                 |     |    |     |
| 1151 | 993077 | Rear Bumper Sponge               |     |    |     |
| 1152 | 992999 | Rear Bumper Damper               |     |    |     |
| 1153 | 993040 | Rear Bumper Protector            |     |    |     |
| 1154 | 993036 | Rear Bumper Pad                  |     |    |     |
| 1155 | 993026 | Rear Bumper Moulding             |     |    |     |
| 1156 | 993044 | Rear Bumper Reflector            |     |    |     |
| 1157 | 993023 | Rear Bumper Lower Spoiler        |     |    |     |
| 1158 | 994023 | Reverse Sensor                   | Dm  | ✓  |     |
| 1159 | 993327 | Rear End Panel                   | DD  | ✓  |     |
| 1160 | 993339 | Rear End Panel Top Garnish       | De  | ✓  |     |
| 1161 | 993333 | Rear End Panel Inner Trim Member | RE  | X  |     |
| 1162 | 990333 | Boot Compartment Inner Trim      |     |    |     |
| 1163 | 993851 | Rear LH Taillamp                 | cm  | ✓  |     |
| 1164 | 993853 | Rear LH Taillamp Garnish         |     |    |     |
| 1165 | 993859 | Rear LH Taillamp Panel           |     |    |     |
| 1166 | 995116 | Rear RH Taillamp                 | ht  | ✓  |     |
| 1167 | 993853 | Rear RH Taillamp Garnish         |     |    |     |
| 1168 | 993859 | Rear RH Taillamp Panel           |     |    |     |
| 1169 | 993554 | Rear Apron Panel                 |     |    |     |
| 1170 | 992895 | Bootlid                          |     |    |     |
| 1171 | 991328 | Bootlid Emblem                   |     |    |     |
| 1172 | 990356 | Bootlid Handle                   |     |    |     |
| 1173 | 995250 | Bootlid Moulding                 |     |    |     |
| 1174 | 990376 | Bootlid Reflector                |     |    |     |
| 1175 | 995222 | Bootlid Lamp LH                  |     |    |     |
| 1176 | 992899 | Bootlid Lamp RH                  |     |    |     |
| 1177 | 995243 | Bootlid Lock                     |     |    |     |
| 1178 | 990377 | Bootlid Rubber                   |     |    |     |
| 1179 | 990382 | Bootlid Hinge                    |     |    |     |
| 1180 | 993877 | Bootlid Spoiler                  |     |    |     |
| 1181 | 994543 | Tailgate                         | DD  | ✓  |     |
| 1182 | 991328 | Tailgate Emblem                  | Nec | ✓  | 02  |
| 1183 | 994643 | Tailgate Outer Handle            |     |    |     |
| 1184 | 994640 | Tailgate Moulding                |     |    |     |
| 1185 | 994545 | Tailgate Garnish Outer           | cm  | ✓  |     |
| 1186 | 994648 | Tailgate Reflector               |     |    |     |
| 1187 | 994549 | Tailgate Lamp                    |     |    |     |
| 1188 | 994646 | Tailgate Protector Pull Pocket   | De  | ✓  |     |
| 1189 | 994676 | Tailgate Wiper Arm               |     |    |     |
| 1190 | 994677 | Tailgate Wiper Blade             |     |    |     |
| 1191 | 994679 | Tailgate Wiper Nozzle            |     |    |     |
| 1192 | 994555 | Tailgate Wiper Motor             |     |    |     |
| 1193 | 994602 | Tailgate Glass                   |     |    |     |
| 1194 | 994606 | Tailgate Glass Rubber            |     |    |     |
| 1195 | 994604 | Tailgate Glass Moulding          | Nec | ✓  |     |
| 1196 | 994607 | Tailgate Glass Sealant           | Nec | ✓  |     |
| 1197 | 994629 | Tailgate Lock                    | De  | ✓  |     |
| 1198 | 994651 | Tailgate Rubber                  | ht  | ✓  |     |
| 1199 | 994611 | Tailgate Hinge                   |     |    |     |
| 1200 | 994594 | Tailgate Damper                  |     |    |     |
| 1201 | 994613 | Tailgate Inner Board             | De  | ✓  |     |

## Vehicle No:

| NAC  | INC    | Item                           | CON | AC | Qty |
|------|--------|--------------------------------|-----|----|-----|
| 1202 | 993784 | Spare Tyre Board               |     |    |     |
| 1203 | 994328 | Spare Tyre Panel               |     |    |     |
| 1204 | 995065 | Spare Tyre                     |     |    |     |
| 1205 | 994326 | Spare Tyre Lock Screw          |     |    |     |
| 1206 | 993787 | Spare Tyre Cover               |     |    |     |
| 1207 | 995323 | Triangle Breakdown Sign        |     |    |     |
| 1208 | 990507 | CD Changer Assy                |     |    |     |
| 1209 | 990164 | Antenna                        |     |    |     |
| 1210 | 990534 | Centre Exhaust Pipe Assy       |     |    |     |
| 1211 | 990532 | Centre Exhaust Mounting        |     |    |     |
| 1212 | 993364 | Rear Exhaust Pipe              |     |    |     |
| 1213 | 993357 | Rear Exhaust Chrome Pipe       |     |    |     |
| 1214 | 993361 | Rear Exhaust Mounting          |     |    |     |
| 1215 | 993358 | Rear Exhaust Heat Shield       |     |    |     |
| 1216 | 995223 | Rear LH Chassis Member         |     |    |     |
| 1217 | 993165 | Rear RH Chassis Member         |     |    |     |
| 1218 | 993436 | Rear LH Fender                 |     |    |     |
| 1219 | 993449 | Rear LH Fender Protector       |     |    |     |
| 1220 | 993420 | Rear LH Fender Inner Panel     |     |    |     |
| 1221 | 993431 | Rear LH Fender Inner Trim      |     |    |     |
| 1222 | 993415 | Rear LH Fender Inner Garnish   |     |    |     |
| 1223 | 993425 | Rear LH Fender Inner Shield    |     |    |     |
| 1224 | 993621 | Rear LH Mudflap                |     |    |     |
| 1225 | 993933 | Rear LH Wheel Rim              |     |    |     |
| 1226 | 994025 | Rear LH Rim Cover              |     |    |     |
| 1227 | 995065 | Rear LH Tyre                   |     |    |     |
| 1228 | 993456 | Rear RH Fender                 |     |    |     |
| 1229 | 993450 | Rear RH Fender Protector       |     |    |     |
| 1230 | 993420 | Rear RH Fender Inner Panel     |     |    |     |
| 1231 | 993431 | Rear RH Fender Inner Trim      |     |    |     |
| 1232 | 993415 | Rear RH Fender Inner Garnish   |     |    |     |
| 1233 | 993425 | Rear RH Fender Inner Shield    |     |    |     |
| 1234 | 993622 | Rear RH Mudflap                |     |    |     |
| 1235 | 993934 | Rear RH Wheel Rim              |     |    |     |
| 1236 | 994025 | Rear RH Rim Cover              |     |    |     |
| 1237 | 995065 | Rear RH Tyre                   |     |    |     |
| 1238 | 995162 | Rear Fender Extension Panel LH |     |    |     |
| 1239 | 993401 | Rear Fender Extension Panel RH |     |    |     |
| 1240 | 993430 | Rear Fender Inner Top Garnish  |     |    |     |
| 1241 | 993673 | Rear Fender 1/4 Glass          |     |    |     |
| 1242 | 993452 | Rear Fender 1/4 Glass Rubber   |     |    |     |
| 1243 | 993453 | Rear Fender 1/4 Glass Sealant  |     |    |     |
| 1244 | 993949 | Rear Windscreen Glass          |     |    |     |
| 1245 | 993976 | Rear Windscreen Rubber         |     |    |     |
| 1246 | 993961 | Rear Windscreen Moulding       |     |    |     |
| 1247 | 993955 | Rear Windscreen Sealant        |     |    |     |
| 1248 | 994729 | Third Brake Light              |     |    |     |
| 1249 | 993385 | Rear Fender Air Grille         |     |    |     |
| 1250 | 992167 | Fuel Lid                       |     |    |     |
| 1251 | 992168 | Fuel Neck                      |     |    |     |
| 1252 | 992179 | Fuel Tank                      |     |    |     |
| 1253 | 992184 | Fuel Tank Bracket              |     |    |     |
| 1254 | 992191 | Fuel Tank Float                |     |    |     |
| 1255 | 990247 | Sticker                        |     |    |     |

06 Days.

No of Items: \_\_\_\_\_

Assessor: \_\_\_\_\_

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

| CLAIM SUBFOLDER TRACKING |   |               |  |  |  |             |   |
|--------------------------|---|---------------|--|--|--|-------------|---|
| Case                     | Notified                                | Est Submitted | Adj Assigned   | Adj Rpt  | Adj Submitted                              | Ins Auth'ed | Status  |
| Main                     | 19 Aug 2019<br><a href="#">Edit Reg</a> |               | 23 Aug 2019<br>00:00<br><a href="#">Edit Adj Rpt</a> | <b>S\$0.00</b><br><a href="#">Edit Estimates</a> | <b>S\$0.00</b><br><a href="#">View Rpt</a> |             | <b>Pending for Survey Report</b><br><a href="#">Cancel Case</a> |

|             |                  |                      |                  |                          |
|-------------|------------------|----------------------|------------------|--------------------------|
| <b>Main</b> | <b>Reference</b> | <b>Claim Details</b> | <b>Documents</b> | <a href="#">Show All</a> |
|-------------|------------------|----------------------|------------------|--------------------------|












































|                                |  |                              |   |  |  |
|--------------------------------|--|------------------------------|---|--|--|
| <b>CLAIM SUBFOLDER DETAILS</b> |  | <b>[Created by adjuster]</b> |   |  |  |
| Insured:                       | ANG LAY PENG, SUSAN (HONG LIPING), ID: S7312677J   |                              |   |  |  |
| Main Claimant:                 | E-CUBE VEHICLE RENTAL PTE LTD, Co. Reg. No.: 201607761H  |                              |   |  |  |
| Vehicle Reg. No.:              | SIH7612C   | Date of Loss:                | 17/08/2019 10:00 - :59<br>[131 Months and 26 Days From LTA Reg Date (Man Yr)] |  |  |
| Claim Type:                    | TP / 2868921872SG  | Policy/Cover Note No.:       | 2100408344 (Comprehensive)<br>Coverage: 08/04/2019 - 07/04/2020               |  |  |
| Vehicle Reg. No. (Insured):    | SDG6718P   | Policy No. (Claimant):       |   |  |  |
|                                |  | Excess:                      |   |  |  |
| Repairer:                      | Lsm Lynston Motor & Spray Works (HQ) 25 KAKI BUKIT ROAD 4 #05-66/68 SYNERGY@KB, 417800 Kaki Bukit - Tel:                         |                              |   |  |  |
| Handling Insurer:              | AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Ler, Bernard-JQ]<br>BernardJlQian.Ler@aig.com |                              |   |  |  |
| Adjuster:                      | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 03/09/2019]                   |                              |   |  |  |
| Claimant's Solicitor:          | A P LAW PRACTICE - Tel: 6955 8899/9171 4767  |                              |   |  |  |

|  |                          |                                   |
|--|--------------------------|-----------------------------------|
| <b>ASSOCIATED MAIL RECEIVED</b>  | <a href="#">View All</a> | <a href="#">Compose Case Mail</a> |
| <ul style="list-style-type: none"> <li>AIG_SG (26/08/2019): Request To Upload TP GIA Report</li> </ul> |                          |                                   |





























|                             |                          |                              |                                 |                          |         |             |              |            |       |
|-----------------------------|--------------------------|------------------------------|---------------------------------|--------------------------|---------|-------------|--------------|------------|-------|
| <b>ALL ASSOCIATED TASKS</b> | <a href="#">View All</a> | <a href="#">Search Tasks</a> | <a href="#">Create New Task</a> | <a href="#">Complete</a> |         |             |              |            |       |
| Due Date                    | Priority                 | Type                         | Task Group                      | Subject                  | Handler | Assigned By | Completed On | Created On | Done? |
| No results.                 |                          |                              |                                 |                          |         |             |              |            |       |

## Claim Documents

\*SJH7612C (2868921872SG)  
[SDG6718P]  
TP  
E-CUBE VEHICLE RENTAL PTE LTD  
Aug 17 2019 10:00AM  
[ANG LAY PENG, SUSAN (HONG LIPING)]  
Lsm Lynston Motor & Spray Works

| <a href="#">Upload Documents</a> |                 | <a href="#">Upload Photos</a>     | <a href="#">Compose New Letter</a>  | <a href="#">Upload Video</a> | <a href="#">Upload Audio</a>        | <b>View</b> <a href="#">View in Browser</a> <input type="button" value="v"/> |                                     |
|----------------------------------|-----------------|-----------------------------------|---|------------------------------|-------------------------------------|--|-------------------------------------|
| <b>Photos/Images</b>             |                 |                                   |   |                              |                                     | 3 per page <input type="button" value="v"/>                                  | <input checked="" type="checkbox"/> |
| No                               | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) |   | Thumbnail                    | Print                               |  |                                     |
| 1                                | 27/08/19 17:41  | General View                      |    | Load JPG                     | <input checked="" type="checkbox"/> |  |                                     |
| 2                                | 27/08/19 17:41  | General View                      |    | Load JPG                     | <input checked="" type="checkbox"/> |  |                                     |
| 3                                | 27/08/19 17:41  | General View                      |    | Load JPG                     | <input checked="" type="checkbox"/> |  |                                     |
| 4                                | 27/08/19 17:41  | General View                      |    | Load JPG                     | <input checked="" type="checkbox"/> |  |                                     |
| 5                                | 27/08/19 17:41  | General View                      |    | Load JPG                     | <input checked="" type="checkbox"/> |  |                                     |
| 6                                | 27/08/19 17:41  | General View                      |    | Load JPG                     | <input checked="" type="checkbox"/> |  |                                     |
| 7                                | 27/08/19 17:41  | General View                      |    | Load JPG                     | <input checked="" type="checkbox"/> |  |                                     |
| 8                                | 27/08/19 17:41  | General View                      |    | Load JPG                     | <input checked="" type="checkbox"/> |  |                                     |
| 9                                | 27/08/19 17:41  | General View                      |    | Load JPG                     | <input checked="" type="checkbox"/> |  |                                     |
| 10                               | 27/08/19 17:41  | General View                      |    | Load JPG                     | <input checked="" type="checkbox"/> |  |                                     |
| 11                               | 27/08/19 17:41  | General View                      |   | Load JPG                     | <input checked="" type="checkbox"/> |  |                                     |
| 12                               | 27/08/19 17:41  | General View                      |  | Load JPG                     | <input checked="" type="checkbox"/> |  |                                     |
| 13                               | 27/08/19 17:41  | General View                      |  | Load JPG                     | <input checked="" type="checkbox"/> |  |                                     |
| 14                               | 27/08/19 17:41  | General View                      |  | Load JPG                     | <input checked="" type="checkbox"/> |  |                                     |
| 15                               | 27/08/19 17:41  | General View                      |  | Load JPG                     | <input checked="" type="checkbox"/> |  |                                     |
| 16                               | 27/08/19 17:41  | General View                      |  | Load JPG                     | <input checked="" type="checkbox"/> |  |                                     |
| 17                               | 27/08/19 17:41  | General View                      |  | Load JPG                     | <input checked="" type="checkbox"/> |  |                                     |
| 18                               | 27/08/19 17:41  | General View                      |  | Load JPG                     | <input checked="" type="checkbox"/> |  |                                     |
| 19                               | 27/08/19 17:41  | General View                      |  | Load JPG                     | <input checked="" type="checkbox"/> |  |                                     |
| 20                               | 27/08/19 17:41  | General View                      |  | Load JPG                     | <input checked="" type="checkbox"/> |  |                                     |
| 21                               | 27/08/19 17:41  | General View                      |  | Load JPG                     | <input checked="" type="checkbox"/> |  |                                     |
| 22                               | 27/08/19 17:41  | General View                      |  | Load JPG                     | <input checked="" type="checkbox"/> |  |                                     |
| 23                               | 27/08/19 17:41  | General View                      |  | Load JPG                     | <input checked="" type="checkbox"/> |  |                                     |
| 24                               | 27/08/19 17:41  | General View                      |  | Load JPG                     | <input checked="" type="checkbox"/> |  |                                     |
| 25                               | 27/08/19 17:41  | General View                      |  | Load JPG                     | <input checked="" type="checkbox"/> |  |                                     |
| 26                               | 27/08/19 17:41  | General View                      |  | Load JPG                     | <input checked="" type="checkbox"/> |  |                                     |
| 27                               | 27/08/19 17:41  | General View                      |  | Load JPG                     | <input checked="" type="checkbox"/> |  |                                     |
| 28                               | 27/08/19 17:41  | General View                      |  | Load JPG                     | <input checked="" type="checkbox"/> |  |                                     |
| 29                               | 27/08/19 17:41  | General View                      |  | Load JPG                     | <input checked="" type="checkbox"/> |  |                                     |
| 30                               | 27/08/19 17:41  | General View                      |  | Load JPG                     | <input checked="" type="checkbox"/> |  |                                     |
| 31                               | 27/08/19 17:41  | General View                      |  | Load JPG                     | <input checked="" type="checkbox"/> |  |                                     |
| 32                               | 27/08/19 17:41  | General View                      |  | Load JPG                     | <input checked="" type="checkbox"/> |  |                                     |
| 33                               | 27/08/19 17:41  | General View                      |  | Load JPG                     | <input checked="" type="checkbox"/> |  |                                     |
| 34                               | 27/08/19 17:41  | General View                      |  | Load JPG                     | <input checked="" type="checkbox"/> |  |                                     |
| 35                               | 27/08/19 17:41  | General View                      |  | Load JPG                     | <input checked="" type="checkbox"/> |  |                                     |
| 36                               | 27/08/19 17:41  | Photographs of Damaged Parts      |  | Load JPG                     | <input checked="" type="checkbox"/> |  |                                     |
| 37                               | 27/08/19 17:41  | Photographs of Damaged Parts      |  | Load JPG                     | <input checked="" type="checkbox"/> |  |                                     |
| 38                               | 27/08/19 17:41  | Photographs of Damaged Parts      |  | Load JPG                     | <input checked="" type="checkbox"/> |  |                                     |
| 39                               | 27/08/19 17:41  | Photographs of Damaged Parts      |  | Load JPG                     | <input checked="" type="checkbox"/> |  |                                     |
| 40                               | 27/08/19 17:41  | Photographs of Damaged Parts      |  | Load JPG                     | <input checked="" type="checkbox"/> |  |                                     |
| 41                               | 27/08/19 17:41  | Photographs of Damaged Parts      |  | Load JPG                     | <input checked="" type="checkbox"/> |  |                                     |
| 42                               | 27/08/19 17:41  | Photographs of Damaged Parts      |  | Load JPG                     | <input checked="" type="checkbox"/> |  |                                     |
| 43                               | 27/08/19 17:41  | Photographs of Damaged Parts      |  | Load JPG                     | <input checked="" type="checkbox"/> |  |                                     |



| Photos/Images |                 |   | 3 per page   | <input checked="" type="checkbox"/> |
|---------------|-----------------|---|--|-------------------------------------|
| No            | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ)         | Thumbnail  | Print                               |
| 44            | 27/08/19 17:41  | Photographs of Damaged Parts              |  Load JPG   | <input checked="" type="checkbox"/> |
| 45            | 27/08/19 17:41  | Photographs of Damaged Parts              |  Load JPG   | <input checked="" type="checkbox"/> |
| 46            | 27/08/19 17:41  | Photographs of Damaged Parts              |  Load JPG   | <input checked="" type="checkbox"/> |
| 47            | 27/08/19 17:41  | Photographs of Damaged Parts              |  Load JPG   | <input checked="" type="checkbox"/> |
| 48            | 27/08/19 17:41  | Photographs of Damaged Parts              |  Load JPG   | <input checked="" type="checkbox"/> |
| 49            | 27/08/19 17:41  | Photographs of Damaged Parts              |  Load JPG   | <input checked="" type="checkbox"/> |
| 50            | 27/08/19 17:41  | Photographs of Damaged Parts              |  Load JPG   | <input checked="" type="checkbox"/> |
| 51            | 27/08/19 17:41  | Photographs of Damaged Parts              |  Load JPG   | <input checked="" type="checkbox"/> |
| 52            | 27/08/19 17:41  | Photographs of Damaged Parts              |  Load JPG   | <input checked="" type="checkbox"/> |
| 53            | 27/08/19 17:41  | Photographs of Damaged Parts              |  Load JPG   | <input checked="" type="checkbox"/> |
| 54            | 27/08/19 17:41  | Photographs of Damaged Parts              |  Load JPG   | <input checked="" type="checkbox"/> |
| 55            | 27/08/19 17:41  | Photographs of Damaged Parts              |  Load JPG   | <input checked="" type="checkbox"/> |
| 56            | 27/08/19 17:41  | Photographs of Damaged Parts              |  Load JPG   | <input checked="" type="checkbox"/> |
| 57            | 27/08/19 17:41  | Photographs of Damaged Parts              |  Load JPG   | <input checked="" type="checkbox"/> |
| 58            | 27/08/19 17:41  | Photographs of Damaged Parts              |  Load JPG   | <input checked="" type="checkbox"/> |
| 59            | 27/08/19 17:41  | Photographs of Damaged Parts              |  Load JPG   | <input checked="" type="checkbox"/> |
| 60            | 27/08/19 17:42  | Photographs of Damaged Parts              |  Load JPG   | <input checked="" type="checkbox"/> |
| 61            | 27/08/19 17:42  | Photographs of Damaged Parts              |  Load JPG   | <input checked="" type="checkbox"/> |
| 62            | 27/08/19 17:42  | Photographs of Damaged Parts              |  Load JPG   | <input checked="" type="checkbox"/> |
| 63            | 27/08/19 17:42  | Photographs of Damaged Parts              |  Load JPG   | <input checked="" type="checkbox"/> |
| 64            | 27/08/19 17:42  | Photographs of Damaged Parts              |  Load JPG   | <input checked="" type="checkbox"/> |
| 65            | 27/08/19 17:42  | Photographs of Damaged Parts              |  Load JPG  | <input checked="" type="checkbox"/> |
| 66            | 27/08/19 17:42  | Photographs of Damaged Parts              |  Load JPG | <input checked="" type="checkbox"/> |
| 67            | 27/08/19 17:42  | Photographs of Damaged Parts              |  Load JPG | <input checked="" type="checkbox"/> |
| 68            | 27/08/19 17:42  | Photographs of Damaged Parts              |  Load JPG | <input checked="" type="checkbox"/> |
| 69            | 27/08/19 17:42  | Photographs of Damaged Parts              |  Load JPG | <input checked="" type="checkbox"/> |
| 70            | 27/08/19 17:42  | Photographs of Damaged Parts              |  Load JPG | <input checked="" type="checkbox"/> |
| 71            | 27/08/19 17:42  | Photographs of Damaged Parts              |  Load JPG | <input checked="" type="checkbox"/> |
| 72            | 27/08/19 17:42  | Photographs of Damaged Parts              |  Load JPG | <input checked="" type="checkbox"/> |
| 73            | 27/08/19 17:42  | Photographs of Damaged Parts              |  Load JPG | <input checked="" type="checkbox"/> |
| 74            | 30/08/19 10:27  | Photo After Spray                         |  Load JPG | <input checked="" type="checkbox"/> |
| 75            | 30/08/19 10:27  | Photo After Spray                         |  Load JPG | <input checked="" type="checkbox"/> |
| 76            | 30/08/19 10:27  | Photo After Spray                         |  Load JPG | <input checked="" type="checkbox"/> |
| 77            | 30/08/19 10:27  | Photo After Spray                         |  Load JPG | <input checked="" type="checkbox"/> |
| 78            | 30/08/19 10:27  | Photo After Spray                         |  Load JPG | <input checked="" type="checkbox"/> |
| 79            | 30/08/19 10:27  | Photo After Spray                         |  Load JPG | <input checked="" type="checkbox"/> |
| 80            | 30/08/19 10:27  | Photo After Spray                         |  Load JPG | <input checked="" type="checkbox"/> |
| 81            | 30/08/19 10:27  | Photo After Spray                         |  Load JPG | <input checked="" type="checkbox"/> |
| 82            | 30/08/19 10:27  | Photo After Spray                         |  Load JPG | <input checked="" type="checkbox"/> |
| 83            | 30/08/19 10:27  | Photo After Spray                         |  Load JPG | <input checked="" type="checkbox"/> |
| 84            | 30/08/19 10:27  | Photo After Spray                         |  Load JPG | <input checked="" type="checkbox"/> |
| 85            | 30/08/19 10:27  | Photo After Spray                         |  Load JPG | <input checked="" type="checkbox"/> |
| 86            | 30/08/19 10:27  | Photo After Spray                         |  Load JPG | <input checked="" type="checkbox"/> |
| 87            | 30/08/19 10:27  | Photo After Spray                         |  Load JPG | <input checked="" type="checkbox"/> |
| Documentation |                 |   | 1 per page   | <input checked="" type="checkbox"/> |
| No            | Finalized On    | AIG Asia Pacific Insurance Pte. Ltd. (SG) | Thumbnail  | Print                               |
| 1             | 26/08/19 11:07  | OI GIA REPORT                             |  Load PDF |                                     |

## Documents Checklist

| DOCUMENTS CHECKLIST                          | Reset | Save | Print |
|--|-------|------|-------|
| There are no document checklists configured. |       |      |       |



**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)****Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19014895/ACD3E2

Date: 17/09/2019

## REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100408344

Claimant Vehicle No : SJH7612C Insured Vehicle No : SDG6718P

Date of Loss: 17/08/2019 Nature of Claim: TP Claim No: 2868921872SG

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: **SJH7612C**  
 Make & Model: HONDA STREAM, 1.8 (A) Engine No: R18A1767327  
 Reg. Date: 22/08/2008 (Man. Year: 2008) Chassis No: RN61060246  
 Colour: Black Odometer: 340557 km  
 Engine Capacity: 1799 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

## CONDITION OF TYRES

Front Tyre Size: 215/50 R17 Rear Tyre Size: 215/50 R17  
 Front Left Side: Kumho 6 mm Rear Left Side: Kumho 6 mm  
 Front Right Side: Kumho 6 mm Rear Right Side: Kumho 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS           | Repairer's  | Adjuster's  | Difference  | Diff % |
|--------------------------|-------------|-------------|-------------|--------|
| Parts                    | 0.00        | 0.00        | 0.00        |        |
| Miscellaneous Items      | 0.00        | 0.00        | 0.00        |        |
| Labour                   | 0.00        | 0.00        | 0.00        |        |
| Paintwork Labour         | 0.00        | 0.00        | 0.00        |        |
| Towing                   | 0.00        | 0.00        | 0.00        |        |
| <b>Nett Amount (S\$)</b> | <b>0.00</b> | <b>0.00</b> | <b>0.00</b> |        |

## INSPECTION

Date of Assignment: 23/08/2019

Date Inspected: 23/08/2019 Inspected At: Lsm Lynston Motor & Spray Works (HQ)  
 25 KAKI BUKIT ROAD 4 #05-66/68  
 SYNERGY@KB  
 Singapore 417800

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

### Recommended Parts

| No.               | Qty | Part No. | Particulars                  | Condition                 | Repairer's  | Amount      |
|-------------------|-----|----------|------------------------------|---------------------------|-------------|-------------|
| 1                 | 1   |          | *REAR BUMPER                 | Deformed                  | 0.00 F      | *- F        |
| 2                 | 1   |          | *REAR BUMPER CLIPS           | Necessary                 | 0.00 F      | *- F        |
| 3                 | 2   |          | *REAR BUMPER SIDE RETAINER   | Necessary                 | 0.00 F      | *- F        |
| 4                 | 1   |          | *REVERSE SENSOR              | Damaged                   | 0.00 F      | *- F        |
| 5                 | 1   |          | *REAR END PANEL              | Dented                    | 0.00 F      | *- F        |
| 6                 | 1   |          | *REAR END PANEL TOP GARNISH  | Deformed                  | 0.00 F      | *- F        |
| 7                 | 1   |          | *REAR END PANEL INNER MEMBER | Repair                    | 0.00 F      | *- F        |
| 8                 | 1   |          | *REAR LH TAILLAMP            | Cracked                   | 0.00 F      | *- F        |
| 9                 | 1   |          | *REAR RH TAILLAMP            | Cut                       | 0.00 F      | *- F        |
| 10                | 1   |          | *TAILGATE                    | Dented                    | 0.00 F      | *- F        |
| 11                | 2   |          | *TAILGATE EMBLEM             | Necessary                 | 0.00 F      | *- F        |
| 12                | 1   |          | *TAILGATE GARNISH OUTER      | Cracked                   | 0.00 F      | *- F        |
| 13                | 1   |          | *TAILGATE PULL POCKET        | Deformed                  | 0.00 F      | *- F        |
| 14                | 1   |          | *TAILGATE GLASS MOULDING     | Necessary                 | 0.00 F      | *- F        |
| 15                | 1   |          | *TAILGATE GLASS SEALANT      | Necessary                 | 0.00 F      | *- F        |
| 16                | 1   |          | *TAILGATE LOCK               | Damaged                   | 0.00 F      | *- F        |
| 17                | 1   |          | *TAILGATE RUBBER             | Cut                       | 0.00 F      | *- F        |
| 18                | 1   |          | *TAILGATE INNER BOARD        | Deformed                  | 0.00 F      | *- F        |
| F=Franchise part. |     |          |                              |                           |             |             |
|                   |     |          |                              | <b>Total Parts (\$\$)</b> | <b>0.00</b> | <b>0.00</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

|   |
|---|
| Report was unsubmitted during this print-out. |
|---|

< END OF ESTIMATES >