ASS REC. BY:	P	ASSIGNMEN		Opecial Interection:
unsta.	N 111 W 1	Carried and a state of the stat		Date/Time: 32/2/2019
100 (Period)	Kanallah Kamis		STREET, STREET	Date Tube.
Estimated Cost			Bill to:	
		EVA / INV / MY / CS	1 2 2	No. of the Contract of the Con
To Inspect Vel	hicle No: GBF	SAOH D		_ Insured:
ы Workshop п	n/s			Tel:
ofi				
Policy No. MHRSPF06000038365 1			Claim No:	TP 11 50679 2019.
Sum lastared:			Excess:	
Make of Vetic				PIOC 18/21 A.O.D
(Client's Rocard		3,		
CA / REV / REP. / REV 24 HRS			77.0	H.O.D. Padorrement
Date/Time_		_ Person Contacted;	-	
Date/Time	Action/Instruction (). Estimate	HET ST	20
	BBF FROH D - NE	SA A1619014471 Y	DOA : 15/8	2009
	City City City	all near series and	100	
			SEE LA	
			2011	
			2015	
			0.00	
	1			D
				

d) Case IAFP-IB-20190820 - Mechanical Inspection of Motor Car, SMK3217K (TP/IP/46503/2019)

On the 31 July 2019 (Wednesday) sometime around 6.08 p.m., the motor car was travelling on lane 2 of 2 lanes along Serangoon North Ave 5. While proceeding across the T-junction of Serangoon North Ave 5 by Serangoon North Ave 6, the motor car collided into a pedestrian who was crossing from his left to right at the pedestrian crossing on red man. The pedestrian was conveyed unconscious and subsequently died due to his injuries on 13 August 2019.

Vehicles to be inspected: SMK3217K - Driver (Potential Defendant)

IO In-Charge: SIO Saleha

e) Case IAFP-IB-20190820 - Mechanical Inspection of Motor Van - GBF5904D (TP/IP/50679/2019)

On 15 August 2019 (Thursday) sometime before 3.27 pm a.m., the Accused was driving a motor van, GBF 5904D, along a single traffic along Tao Ching Road towards Corporation Drive. Approaching a non-signalised T-junction of Tao Ching Road by Corporation Road, the Accused made a left turn into the left lane of 2-lanes of Corporation Drive towards Yung Ho Road. While the Accused was in the midst of turning left into Corporation Drive, the Deceased was crossing from the Accused's left to right view. The Accused front portion of the motor van hit onto Deceased's left side and subsequently ran over the Deceased. As a result of the accident, the Deceased sustained injuries on the upper and lower abdomen. She succumbed to her injuries and was pronounced dead at scene at paramedic 5gt Helmi at 3.45 p.m.

Vehicles to be inspected: GBF5904D - Driver (Potential Defendant)

IO In-Charge: SIO Dzul Hairie

Case IAFP-IB-20190820 - Mechanical Inspection of Motorcycle - FBD4157K (TP/IP/39375/2019)

On 22 June 2019 (Sunday) sometime before 3.14 p.m., the Deceased was riding his motorcycle on lane 2 of 4-lanes along BKE towards Woodlands Checkpoint Somewhere before the viaduct into Woodlands Checkpoint, suddenly lost control and self-skidded. Deceased landed on the road on lane 2 and was conveyed by the ambulance to KTPH for multiple injuries. He was admitted in the Intensive Care Unit (ICU). On 23 July 2019, the deceased was pronounced dead at 3.02 a.m. in KTPH.

Vehicles to be inspected: FBD4157K - Rider (Deceased)

10 In-Charge: S10 Adrian Lim

g) Case IAFP-IB-20190820 - Mechanical Inspection of Motorcycle - FN17H (TP/IP/39375/2019)

On 29 July 2019 (Monday) sometime before 8.35 p.m., the accused was riding his motorcycle on lane 2 of 2-lanes along Sungei Kadut Street 1 when he noticed a road sweeper ahead. Rider informed he tried to swerve his motorcycle to the right however in the process of doing so, lost control and skidded to the right and collided onto the centre divider and the road signage. Rider and his pillion(Deceased) landed on the road on lane 1. Both of them were conveyed by the ambulance to KTPH for multiple injuries. The Deceased was admitted in the Intensive Care Unit (ICU) and on 13 August 2019, the deceased was pronounced dead at 12.03pm.

Vehicles to be inspected: FN17H - Rider (Potential Defendant)