

ASS. REC. BY: Surveys | REF: CS3/MSG190103A/Gsd^{or}-1

From (Person) Katherine Wong of MSG Date/Time: 22/08/2019

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SCU 6245K Insured: SKB 173T

at Workshop n/s: Apex Motoring Tel: 91690825

Policy No: 29071096MX Claim No: _____

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A: 7/6/19

CA / REV / REP. / REV 24 HRS "up" H.O.D. Endorsement _____

Date/Time: 11/6/19 11:04am Person Contacted: Rei Jie Vehicle: IN / OUT

Date/Time | Action/Instruction (X) Estimate

_____ | SCU 6245K - X

_____ | SKB 173T - X

_____ | Dismantle: 12/6/2019

_____ | After repair: 13/6/2019

\$650, 2 Days.
(of 700/- Red - 52%)
[Signature]
4/10/2019

Do Not Finalise

RECEIVED 09 OCT 2019

bl.

PRS

ASSIGNMENT

From: Date: 11.6.2019

Veh No: SKU6295K Regn: Aug 15

Estimated Cost:

Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No: SKU6295K

Make: Honda Jazz 1.5 cc 1498

at Workshop m/s: MREX motorms
of 25 Kaji Bukit Road 4 #01-65

Colour: Red A/C Insured / Std / NI / NA

Tp Reading: 113119 T/Facto: Insured / Std / NI / NA

Insured:

Eng/No:

Policy No:

C/No:

Claims No:

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: In order / Jammed / Leaked / Burnt or

(Client's Record)

Brake: In order / Jammed / Leaked / Burnt or

Make of Veh:

Modi: Nil / S/Rim / STD A/Rim or

(Policy Condition)

Tyre Size: F: 185/55R16

R: "

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Est. or Market Value:

Front

Rear

IDAC Accident Rpt: Consistent? Yes or No

R/Bal 6 mm

R/Bal 6 mm

GIA / PR Seen: Consistent? Yes or No

L/Bal 6 mm

L/Bal 6 mm

Est. Repairs: 4 days Res: Yes or No

D.O.A.

D.O.I. 11-06-19

Lump Sum: % 3 Val. Yes or No

Survey held at

w/s 11-06-19 5pm

CA / REV / REP. / 24 HRS

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Date: Person Contacted:

Vehicle: IN / OUT

O/S Rear

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

\$2000 - \$3000

12/6/2019

Date/Time, File Pass to?

: Proli. Report
 : Final Report

Days Of Repair: 4

Resurvey No. of Trip: 2

Survey Fee:

120

1)

Date/Time, File Return to?

Transportation:

2)

Add Fee: Site Insp (\$)

Interview (\$)

Tech Invs (\$)

Weekend (\$)

S + FCL SA

Photos

Others

11

TOTAL

131

Report Format: PRS

Lump Sum / I.B.I.: (\$)

Nivitha (LKK Auto)

From: Accounts (LKKAuto) <account@lkkauto.com>
Sent: Friday, 23 August 2019 11:33 AM
To: Admin-D (LKKAuto)
Cc: Accounts (LKKAuto)
Subject: RE: Report Send Back Alerts - SKU6295K (TP)

Dear Nivitha,

FYNA Please...

Pending for Survey Report-CS3/MSG19010317/GCD3E2

22 Aug 2019 09:45	Ins Send Back Adj Rpt	For paper survey	[1] Katherine Wong
22 Aug 2019 09:45	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/08/26	[1] Merimen Administrator
22 Aug 2019 09:45	Adj Mandate Set	Maintained.	[1] Merimen Administrator

Thank You

Best Regards,

SuthaShelia (Shelia) | Accounts Dept.

LKK Auto Consultants Pte Ltd

Phone: 6841 1891 | email: account@lkkauto.com | fax: 6844-8805

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Do-Not-Reply <do-not-reply@merimen.com>

Sent: Thursday, 22 August 2019 10:00 AM

To: account@lkkauto.com

Subject: Report Send Back Alerts - SKU6295K (TP)

Dear Sir / Madam,

Please login to Merimen Online at www.merimen.com.sg for more information.

Thanks,
The Merimen Team



This email has been checked for viruses by AVG antivirus software.
www.avg.com



6 tampines st 73, #01-03, singapore 528825
tel: 6746 2118 fax: 6746 1148
reg no: 53058468m

Claim Reference : -
Insured Vehicle No. : -
Thirty Party Veh No. : -
Officer-In-Charge : -

Our Reference : KAAS/TA/5545/6295/TP/06.19
Date : 30 June 2019

To: Asia Express Car Rental Pte Ltd
c/o 25 Kaki Bukit Road 4
#01-55, Synergy @ Kaki Bukit
Singapore 417800

VEHICLE APPRAISAL REPORT

Name of Workshop : Apex Motoring
Place of inspection : 25 Kaki Bukit Road 4 #01-55, Synergy @ Kaki Bukit, Singapore 417800
Date of Assignment : 10 June 2019
Date of Accident : 07 June 2019
Date of Inspection : 10 June 2019

PARTICULARS OF INSPECTED VEHICLE

Registration No.	: SKU 6295K	Chassis Frame No.	: JHMGK5850GX200050
Make / Model	: Honda Jazz 1.5 VTIR CVT ABS	Engine No. (Logcard)	: L15B31020005
Year of Manufacture/Reg	: 2015	Odometer Reading	: 113,119 KM
Colour	: Red		
Class / Type	: Hatchback		

CONDITION OF VEHICLE DURING SURVEY (Visual & Static Check Only)

General Condition : Excellent
Paintwork : Excellent
Market Value : -
Scrap Value : -

CONDITION OF TYRES ON VEHICLE

	<u>Make/Size</u>	<u>Thread Balance</u>
Front L	YOKOHAMA 185 / 55 R16	7 mm
Front R	YOKOHAMA 185 / 55 R16	7 mm
Rear L	YOKOHAMA 185 / 55 R16	7 mm
Rear R	YOKOHAMA 185 / 55 R16	7 mm

*The above is an estimate of the remaining life of the tyre thread in millimeters

The information contained in these documents may be privileged and confidential, and is intended for the exclusive use of the addressee designation. If you are not the addressee, any enclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this survey report in error, please contact us immediately by phone so that we can arrange for its return.



6 tampines st 73, #01-03, singapore 528825
 tel: 6746 2118 fax: 6746 1148
 reg no: 53058468m

Our Reference : K A A S / T A / 5545 / 6295 / T P / 06.19
 Vehicle Number : SKU 6295K

APPRAISEMENT SCHEDULE

S/N	Qty	Descriptions	Conditions	Repairer's Estimate	Revised Amount
		LIST ITEMS:-			
1	1 pc	Rear bumper	Deformed	\$ 447.00	\$ 447.00
2	1 pc	Rear bumper rh side retainer	Necessary	\$ 37.00	\$ 37.00
3	1 set	Rear bumper fasteners	Necessary	\$ 35.00	\$ 35.00
4	1 pc	RH taillamp	Cracked	\$ 216.40	\$ 216.40 X
5	1 pc	RH rear fender	Dented	Repair	Repair
6	1 pc	RH rear fender air vent	Not Affected	\$ 79.40	Reuse
				\$ 814.80	\$ 735.40
		Less 20%			\$ 147.08
				\$ 814.80	\$ 588.32
		519 20%: 415.2			
Sub - Total				\$ 814.80	\$ 588.32



Our Reference : KAAS/TA/5545/6295/TP/06.19
 Vehicle Number : SKU 6295K




6 tampines st 73, #01-03, singapore 528825
 tel: 6746 2118 fax: 6746 1148
 reg no: 53058468m

APPRAISEMENT SCHEDULE

S/N	Qty	Descriptions	Conditions	Repairer's Estimate	Revised Amount
		B/F		\$ 814.80	\$ 588.32
		LABOUR & OTHER CHARGES:-			
1		To panel beat and renewal of all necessary damaged body parts		\$ 800.00	\$ 600.00 200
2		To check wiring and rewire		\$ 60.00	\$ 50.00 X
3		To apply anti-rust		\$ 100.00	\$ 80.00 X
4		To putty and spray-paint of affected areas		\$ 600.00	\$ 400.00 200
				\$ 1,560.00	\$ 1,110.00
		815.2 20%: 650 2 Days			
Sub - Total				\$ 2,374.80	\$ 1,698.32

ASSESSMENT SUMMARY

Damages sustained were consistent with the subject vehicle being involved in a collision with another vehicle and the impact was delivered **Squarely to the RH Rear** portion of the vehicle.



The general area of damages is at the **RH Rear portion**
(Please refer to the parts list and photographs as attached for more information)

ASSESSOR'S RECOMMENDATIONS

The estimated repair costs submitted by Messrs **Apex Motoring** is \$ **2,374.80**
We have adjusted the cost to \$ **1,698.32** and the repairer has agreed to undertake the repairs at a
Contract Lump Sum of \$ 1,350.00 to a acceptable quality and standards.
However, we have not given authorization and instruction to the repairer to proceed with the repairs.

The repairs should be completed within a reasonable period of **2** working days.

26 photographs were taken at the time of static inspection.

This report is strictly done in a **Without Prejudice Basis**.

We are reverting the matter to you a decision.

We enclose herewith our Invoice No. **5545** for our services rendered and
we thank you for engaging our services.

Conducted By :



TERRENCE HONG
SENIOR SURVEYOR
Dip Engineering (SP) DECC
Certs Automotive Technology (NP)
Cert. Crash Investigation & Reconstruction
Cert SCI (General Insurance)
AMSAAA, AM SAE-A

Approved By :



KELVIN TEO
PRINCIPAL SURVEYOR
Licensed Automotive Appraiser
Nitec in Automotive Technology
Cert. Crash Investigation & Reconstruction
Dip MS
MSAAA, AM SAE-A

NOTE : This revised estimate was from a visual inspection. Should there be any discrepancy or unseen items not listed in this survey, kindly notify the company within Seven (7) days from the date hereof. Otherwise this revised amount shall be treated as valid.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	07/06/2019 18:39
Date Of Accident	07/06/2019 08:30
Exact Location Of Accident	KJE EXPRESSWAY TOWARDS TUAS
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKU6295K
Insured/Policyholder	
Name Of Registered Owner	MOHAMMAD FARHAN BIN JASMIN
NRIC No	S8741413B
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98006133
Alternative Phone No	OFFICE-98006133

Vehicle Particulars

Manufacturer	HONDA
Model	JAZZ
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA226208/1
Cover Note Number	

Driver

Name of Driver	MOHAMMAD FARHAN BIN JASMIN
NRIC No	S8741413B
Date Of Birth	24/12/1987
Occupation	INDOOR
Date Of Driving Pass	30/07/2007
Driving Experience	11 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98006133
Fax Number	
Contact Number	OFFICE-98006133

Address	APT BLK 506B YISHUN AVENUE 4 #05-132
Postcode	762506
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : NURIRSYIDAH BINTE MD RAZALI GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	KAKI BUKIT NEIGHBOURHOOD POLICE POST
Police Station Address	ROAD: BLK 526 BEDOK NORTH STREET 3 #01-448 , POSTCODE: 460526 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-4429999 - FAX NO: 62444377
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	WITH OWNER
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKB173T
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	CHEN QIANG
NRIC/Passport Number	S9076260E

Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name MOHAMMAD FARHAN BIN JASMIN
Approximate Age
Injuries Sustain
Injured person in which vehicle? SKU6295K
Were seat belts worn? YES
Was this injured conveyed to hospital by ambulance? NO
Address APT BLK 506B YISHUN AVENUE 4 #05-132
Postcode 762506

DETAILS OF INJURED PERSON 2

Name NURIRSYIDAH BINTE MD RAZALI
Approximate Age
Injuries Sustain
Injured person in which vehicle? SKU6295K
Were seat belts worn? YES
Was this injured conveyed to hospital by ambulance? NO
Address APT BLK 506B YISHUN AVENUE 4 #05-132
Postcode 762506

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to reputate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) Investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time: 7/6/19, 1653HAS


Driver's Signature
(If driver is not the policyholder)
Date & Time: 7/6/19, 1653HAS


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the 07/06/2019 at about 0830HRS, I was driving my vehicle SKU6295K along KJE towards TIAS on the right most lane. My wife was my passenger at that time. The weather was clear however the road surface was wet and the traffic volume was heavy. All of a sudden, I felt an impact from the rear of my vehicle hence I got down to make a check. I discovered that the front of vehicle, SKB173T has collided onto the rear of my vehicle. We exchanged particulars and no one was injured at that time. We decided to go for insurance settlement and left the scene. After a few hours, both my wife and I felt pain at our back, neck and foot (wife) area, therefore we want to seek medical treatment at Tan Tock Seng Hospital. Both of us were given 5 days of outpatient sick leave. Hence, I am lodging this injury traffic accident report. I wish to state that I have a rear in car camera which captured the whole incident.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time: 7/6/19, 1653HRS

Driver's Signature
(If driver is not the policyholder)
Date & Time: 7/6/19, 1653HRS.

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



**SINGAPORE
POLICE FORCE**



T/20190607/2119

Police Station Of Origin:
Kaki Bukit NPP
526 Bedok North Street 3 #01-448
SINGAPORE 460526
Tel No: 1800-4429999

1 of 4

Report No. T/20190607/2119

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 07/06/2019 16:11		Vide Report No.:		Station Diary No.: 12	
Informant's Particulars					
Name of Informant: MOHAMMAD FARHAN BIN JASMIN			Address: APT BLK 506B YISHUN AVENUE 4 #05-132 SINGAPORE 782506		
ID Type / ID No.: NRIC NO / S8741413B			Contact No.: Home/Office: Mobile: 98006133		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 31	Date of Birth: 24/12/1987	Type of Informant: Driver		
Race: Malay		Language: English		Institution / School Name:	
Occupation: SENIOR SUPPLY CHAIN OFFICER			Driving Licence Information: Class: 2B,3 Date of Expiry:		

Details of the Accident					
Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 07/06/2019 08:30	Type of Location: Straight Road	
Location: Along Road 1 KRANJI EXPRESSWAY <u>ALONG KJE TOWARDS TUAS</u>					
Weather: Clear		Road Surface: Wet		Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Heavy	
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No	

Details of Vehicle Involved						
Plate No.	Type	Make	Model	Colour	Condition	No of Passengers
SKB173T	Car	TOYOTA	CAMRY 2.0 AUTO ABS AIRBAG	White		0
SKU6295K	Car	HONDA	JAZZ 1.5 VTIR CVT ABS D/AIRBAG 2WD	Red	Slightly Damaged	1



**SINGAPORE
POLICE FORCE**



T/20190807/2119

Police Station Of Origin:
Kaki Bukit NPP
526 Bedok North Street 3 #01-448
SINGAPORE 460526
Tel No: 1800-4429999

2 of 4
Report No. T/20190807/2119

CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No. / Insurance Company				
SKU6295K	AXA INSURANCE SINGAPORE PTE LTD	GA226208	05/08/2018	04/08/2019

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	CHEN QIANG	ID No.	S9076260E
Related Vehicle	SKB173T (Car)	Contact No.	98511959
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Name	MOHAMMAD FARHAN BIN JASMIN	ID No.	S8741413B
Related Vehicle	SKU6295K (Car)	Contact No.	98006133
Hospital/Clinic	TAN TOCK SENG HOSPITAL	Class of Driving Licence & Expiry Date	Class: 2B,3 Date of Expiry: NIL
Date Treatment	07/06/2019	Date Discharge	07/06/2019
No. of Days granted Medical Leave	05	Degree of Injury	Slight

Name	NURIRSYIDAH BINTE MD RAZALI	ID No.	S9128754D
Related Vehicle	SKU6295K (Car)	Contact No.	83211737
Hospital/Clinic	TAN TOCK SENG HOSPITAL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	07/06/2019	Date Discharge	07/06/2019
No. of Days granted Medical Leave	05	Degree of Injury	Slight



**SINGAPORE
POLICE FORCE**



T/20190607/2119

Police Station Of Origin:
Kaki Bukit NPP
526 Bedok North Street 3 #01-448
SINGAPORE 480526
Tel No: 1800-4429999

3 of 4

Report No. T/20190607/2119

CONTINUATION OF REPORT

Brief Details.

On the 07/06/2019 at about 0830hrs, I was driving my vehicle SKU6295K, along KJE towards Tuas on the right most lane. My wife was my passenger at that time. The weather was clear however the road surface was wet and the traffic volume was heavy. All of a sudden, I felt an impact from the rear of my vehicle hence I got down to make a check. I discovered that the front of vehicle, SKB173T has collided onto the rear of my vehicle. We exchanged particulars and no one was injured at that time. We decided to go for insurance settlement and left the scene. After a few hours, both my wife and I felt pain at our back and neck area, therefore we went to seek medical treatment at Tan Tock Seng Hospital. Both of us were given 5 days of outpatient sick leave. Hence, I am lodging this injury traffic accident report. I wish to state that I have a rear in car camera which captured the whole incident.



**SINGAPORE
POLICE FORCE**



T/20190807/2119

Police Station Of Origin:
Kaki Bukit NPP
526 Bedok North Street 3 #01-448
SINGAPORE 460526
Tel No: 1800-4429999

4 of 4


Report No. T/20190807/2119

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report: G / Sgt 2 KOH WEN RUI 	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 07/08/2019 16:11
Officer In Charge Of Case: TP / AEIT / SI ANG YI TING Contact No. 6414 	Classification Of Case:
Authentication Stamp NP168  SIGNATURE	

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	08/06/2019 10:34
Date Of Accident	07/06/2019 08:30
Exact Location Of Accident	ALONG PIE TOWARDS TUAS
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKB173T
Insured/Policyholder	
Name Of Registered Owner	LI AIFENG
NRIC No	S2760272Z
Email Address	INFO.LCCQ@GMAIL.COM
Mobile Phone No	(LOCAL) +65-98511959
Alternative Phone No	OFFICE-98511959

Vehicle Particulars

Manufacturer	TOYOTA
Model	CAMRY
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	REPORTING ONLY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	A29099095QMX
Cover Note Number	

Driver

Name of Driver	CHEN QIANG
NRIC No	S9076260E
Date Of Birth	13/10/1990
Occupation	INDOOR
Date Of Driving Pass	13/04/2013
Driving Experience	6 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-98511959
Fax Number	
Contact Number	OFFICE-98511959

Address	BLK 783D WOODLANDS RISE #03-23
Postcode	734783
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of Intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER ATTACHED , REMARK: TYPE OF ACCIDENT REFER STATEMENT AND SKETCH

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	VIDEO WITH DRIVER
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKU6295K
Vehicle Make/Model/Colour	HONDA - RED COLOR
Details Of Properties	RIGHT REAR PORTION
Vehicle Category	PRIVATE CAR
Name of Driver	MOHAMMAD FARHAN BIN JASMIN
NRIC/Passport Number	
Contact Number	98006133
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Vehicle Registration Number

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

ROAD CENTRE DIVIDER

NA

GOVERNMENT

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:


Driver's Signature
(if driver is not the policyholder)
Date & Time:

8/6/2019

Reporting Centre Personnel's Signature
Name:
NIC/FIN No.:

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer Police Report
7/20/19 0607/2100

DECLARATION

(/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Control Personnel's Signature
Name:
NRIC/IN No.:

Refer
8/6/2019

Common Statement



**SINGAPORE
POLICE FORCE**



T/20190607/2100

Police Station Of Origin:
Jurong West N P C
700 Corporation Road SINGAPORE 649818
Tel No: 1800-2689999

1 of 3

Report No. T/20190607/2100

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 07/06/2019 15:23	Vide Report No.:	Station Diary No. 98
--	------------------	-------------------------

Informant's Particulars

Name of Informant: CHEN QIANG		Address: APT BLK 783D WOODLANDS RISE #03-23 SINGAPORE 734763	
ID Type / ID No.: NRIC NO / S9076260E		Contact No.: Home/Office: Mobile: 98511959	
Nationality: SINGAPORE CITIZEN		Email:	
Sex Male	Age 28	Date of Birth: 13/10/1990	Type of Informant: Driver
Race: Chinese		Language: English	Institution / School Name:
Occupation: CONSTRUCTION		Driving Licence Information: Class: 3 Date of Expiry:	

General information of the Accident

Type of Accident:	Non-Injury Government Vehicle	Drink Drive: No	Date/Time of Accident: 07/06/2019 08:30	Type of Location: Straight Road
Location: Along Road 1 BUKIT TIMAH EXPRESSWAY				
BKE before the exit towards KJE				
Weather: Drizzling		Road Surface: Wet		Road Speed Limit:
Traffic Flow:		Traffic Control:		Traffic Volume: Heavy
Type of Collision: Between Moving Vehicles - Side Swipe - Same Direction				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	Np of Passenger
SKP173T	Car	TOYOTA	Camry	Black	Slightly Damaged	0
SKU6295K	Car	HONDA	JAZZ	Red	Slightly Damaged	1

Common Statement



SINGAPORE
POLICE FORCE



T/20190607/2100

Police Station Of Origin:
Jurong West N.P.C
700 Corporation Road SINGAPORE 649618
Tel No: 1800-2689999

2 of 3

Report No: T/20190607/2100

CONTINUATION OF REPORT

Brief Details.

On 07/08/2019 at about 8.30am, I was driving my vehicle V1) SKP173T along BKE towards KJE on the most right lane. I was cruising my vehicle and suddenly, I noticed that all vehicle in front of me started to slow down thus I applied brake. At this point in time, the distance between my vehicle and the vehicle in front of me was about 2 car length.

As I applied my brake throughout however I noticed that my vehicle did not slow down enough and in order to avoid collision, I turned my steering wheel to the right. The left front portion of my vehicle side swipe against the rear right portion of V2) SKU6295K. The front right portion of my vehicle ended up into the bushes.

The driver of V2 was not seen to be injured and he alright from the vehicle and started to take picture of the vehicle. I am not injured. Both of us exchange particulars and left the scene.

Common Statement



SINGAPORE
POLICE FORCE



Tel: 1999 9999

Police Station Of Origin
Jurong West N.P.C
700 Corporation Road SINGAPORE 649816
Tel No: 1800-2689999

Report No: T101906070100

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan.

IMPORTANT Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report

Sgt 3 TEO KIAN HUI

Signature Of Informant

Signature Of Interpreter:
Not applicable

Date/Time:
07/05/2019 15:23

Officer in Charge Of Case
TP / GA /
Staff Sgt WONG SIEU LUI
Contact No: 65475151

Classification Of Case:

Authorisation Stamp



SN 126

Singapore Police Force

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo




Accident Photo



Accident Photo



Identification Card



Accident Photo



Accident Photo



...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	07 Jun 2019		11 Jun 2019 09:35 Edit Adj Rpt	S\$650.00 Edit Estimates	S\$650.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	LI AIFENG, ID: S27602722								
Main Claimant:	MOHAMMAD FARHAN BIN JASMIN, ID: S8741413B								
Vehicle Reg. No.:	SKU6295K	Date of Loss:	07/06/2019 08:00 - :59 [46 Months and 2 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 600599	Policy/Cover Note No.:	A29099095QMX (Comprehensive) Coverage: 16/10/2018 - 20/10/2019						
Vehicle Reg. No. (Insured):	SKB173T	Policy No. (Claimant):							
Repairer:	Apex Motoring () 25 Kaki Bukit Road 4, #01-55 Synergy @ KB, 417800 Kaki Bukit - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong - 6594 2544]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 26/08/2019]								
Driver/Custodian (Insured):	CHEN QIANG (28 / Male) , NRIC: S9076260E Email:								
Adj Asg. Remarks:	on WP. Liab: cleared. Disagreed on SJE, Assign to LKK. Peijie 91690825								
ASSOCIATED MAIL RECEIVED				View All	Compose Case Mail				
<ul style="list-style-type: none"> MSIG_SG (22/08/2019): Report Send Back Alerts - SKU6295K (TP) 									
ALL ASSOCIATED TASKS									
View All									
Search Tasks									
Create New Task									
Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKU6295K (600599)

[SKB173T]

TP

MOHAMMAD FARHAN BIN JASMIN

Jun 7 2019 8:00AM

[LI AIFENG]

Apex Motoring

Upload Documents			Upload Photos		Compose New Letter		View	View in Browser
Photos/Images							3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print			
1	20/06/19 18:39	General View		Load JPG	<input checked="" type="checkbox"/>			
2	20/06/19 18:39	General View		Load JPG	<input checked="" type="checkbox"/>			
3	20/06/19 18:39	General View		Load JPG	<input checked="" type="checkbox"/>			
4	20/06/19 18:39	General View		Load JPG	<input checked="" type="checkbox"/>			
5	20/06/19 18:39	General View		Load JPG	<input checked="" type="checkbox"/>			
6	20/06/19 18:39	General View		Load JPG	<input checked="" type="checkbox"/>			
7	20/06/19 18:39	General View		Load JPG	<input checked="" type="checkbox"/>			
8	20/06/19 18:39	General View		Load JPG	<input checked="" type="checkbox"/>			
9	20/06/19 18:39	General View		Load JPG	<input checked="" type="checkbox"/>			
10	20/06/19 18:39	General View		Load JPG	<input checked="" type="checkbox"/>			
11	20/06/19 18:39	General View		Load JPG	<input checked="" type="checkbox"/>			
12	20/06/19 18:39	General View		Load JPG	<input checked="" type="checkbox"/>			
13	20/06/19 18:39	General View		Load JPG	<input checked="" type="checkbox"/>			
14	20/06/19 18:39	General View		Load JPG	<input checked="" type="checkbox"/>			
15	20/06/19 18:39	General View		Load JPG	<input checked="" type="checkbox"/>			
16	20/06/19 18:39	General View		Load JPG	<input checked="" type="checkbox"/>			
17	20/06/19 18:39	General View		Load JPG	<input checked="" type="checkbox"/>			
18	20/06/19 18:39	General View		Load JPG	<input checked="" type="checkbox"/>			
19	20/06/19 18:39	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>			
20	20/06/19 18:39	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>			
21	20/06/19 18:39	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>			
22	20/06/19 18:39	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>			
23	20/06/19 18:39	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>			
24	20/06/19 18:39	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>			
25	20/06/19 18:39	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>			
26	20/06/19 18:39	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>			
27	20/06/19 18:39	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>			
28	20/06/19 18:39	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>			
29	20/06/19 18:39	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>			
30	20/06/19 18:40	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>			
31	20/06/19 18:40	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>			
32	20/06/19 18:40	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>			
33	20/06/19 18:40	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>			
Documentation							1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print			
1	10/06/19 15:38	PRI		Load PDF				
2	10/06/19 15:38	OI Accident Report		Load PDF				
3	10/06/19 15:38	TP SKU6295K E-REPORT		Load PDF				
4	10/06/19 17:49	EMAIL LIABILITY CLEAR		Load PDF				
5	21/08/19 19:08	Survey Report		Load PDF				
6	21/08/19 19:08	Survey Photos		Load PDF				
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print			
1	09/10/19 16:21	PRS Invoice		Load PDF				
2	09/10/19 16:21	Colour Photo		Load PDF				

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div style="border: 1px solid black; height: 40px; width: 100%;"></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG19010317/GSD3E2-1

Date: 09/10/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	A29099095QMX
Claimant	Insured Vehicle No :	SKB173T
Vehicle No : SKU6295K	Nature of Claim:	TP
Date of Loss: 07/06/2019		Claim No: 600599

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKU6295K	Engine No:	L15B31020005
Make & Model:	HONDA JAZZ, 1.3 (A)	Chassis No:	JHMGK5850GX200050
Reg. Date:	05/08/2015 (Man. Year: 2015)	Odometer:	113119 km
Colour:	Red		
Engine Capacity:	1498 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/55 R16	Rear Tyre Size:	185/55 R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	814.80	415.20	399.60	49.04
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,560.00	400.00	1,160.00	74.36
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,374.80	815.20	1,559.60	65.67
Approved Total (Overridden) (S\$)		650.00		
Nett Amount (S\$)	2,374.80	650.00	1,724.80	72.63

INSPECTION

Date of Assignment:	11/06/2019	
Date Inspected:	11/06/2019 Inspected At:	Apex Motoring 25 Kaki Bukit Road 4, #01-55 Synergy @ KB Singapore 417800
Estimated Period of Repair:	2.0 days	

Adjuster: XING GUO QIANG

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 09 Oct 2019)
Parts: 144	HONDA JAZZ 1.3 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SKU6295K)	
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	447.00 F	*447.00 FL
2	1		*REAR BUMPER RH SIDE RETAINER	Necessary	37.00 F	*37.00 FL
3	1		*SET REAR BUMPER FASTENERS	Necessary	35.00 F	*35.00 FL
4	1		*RH TAILLAMP	Serviceable	216.40 F	*- FL
5	1		*RH REAR FENDER (NPA)	Repair	0.00 F	*- FL
6	1		*RH REAR FENDER AIR VENT	Reuse	79.40 F	*- FL
Sub Total (S\$)					814.80	519.00
- List Item Discount on L Items 0.00/20.00% (S\$)					0.00	103.80
Total Parts (S\$)					814.80	415.20

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEAT AND RENEWAL OF ALL NECESSARY DAMAGED BODY PARTS	New	800.00	200.00
2	TO CHECK WIRING AND REWIRE	New	60.00	0.00
3	TO APPLY ANTI-RUST	New	100.00	0.00
4	TO PUTTY AND SPRAY-PAINT OF AFFECTED AREAS	New	600.00	200.00
Gross Labour Cost (S\$)			1,560.00	400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >