

INS CASE OWNER: YAMAHA | CC 6/AIG1701 7/10/19, U/6/6/92-1 LRR DAC

Surveyor: WATKINS DOI: 2/2/19 Date/Time: 2/2/19
 Registered in Missouri: 2/2/19

Pre-assign / CCU / FTE: _____
 Insured Vehicle No: SAC 8761P Claim No: _____
 Name of Insured: WEN WEN WEN Policy No: _____
 Insured Tel No: _____ HP: _____ Make / Model: _____
 Excess Sec II :SS _____ D.O.A. 2/2/19 Place of Accident: _____
 Is driver the owner? (YES / NO) _____ Nature of Accident: _____
 If NO: Driver Name / Age: _____ OI GLA REPORT: YES / NO : TP GLA REPORT: YES / NO
 Driver Tel No: _____ (VL: YES / NO) Insured Liability: _____ Final? Yes / No



INSRS WSP Tel Liability RMKS



INSRS WSP Tel Liability RMKS



INSRS WSP Tel Liability RMKS



INSRS WSP Tel Liability RMKS

Date/Time	STAGE	DATE / PIC
<u>2/2/19</u>	Non-Reporting In (1st)	
<u>2/2/19</u>	Non-Reporting In (2nd)	
<u>2/2/19</u>	Non-Reporting In (Final)	
<u>2/2/19</u>	Notification In (if non-pickup)	
<u>2/2/19</u>	Call Out: <u>2010.117-5111</u>	
<u>2/2/19</u>	After call In to OI: <u>29/09/19-OTC</u>	
<u>2/2/19</u>	Documentation Check List: Handler Typist	
<u>2/2/19</u>	Notification In (if non-pickup)	
<u>2/2/19</u>	After call In to OI	
<u>2/2/19</u>	Authorization To Act	
<u>2/2/19</u>	Release Voucher	
<u>2/2/19</u>	Final Repair Bill	
<u>2/2/19</u>	Car Rental Invoice	
<u>2/2/19</u>	Towing Invoice	
<u>2/2/19</u>	LIA / GLA	
<u>2/2/19</u>	Medical Bill	
<u>2/2/19</u>	PIR	
<u>2/2/19</u>	Mandate/Reject Instruction	
<u>2/2/19</u>	LOD	
<u>2/2/19</u>	Payment Breakdown Form	
<u>2/2/19</u>	Post-Repair Photos	
<u>2/2/19</u>	Others	

PRELIMINARY 20/08/19 - TP ACCEPTED OFFER.

FINALIZATION Date/Time: _____ Confirm with: _____ Confirm by: _____
 your Cost: LTD \$5 2,500.00 (5 days) Reduction: 46 %

FINAL SETTLEMENT	Date/Time	Confirm with	Confirm by
Global Policy No: <u>50</u>		(A-Record / Assented) BOLA SIN No. <u>NW-26</u>	
Repair Cost: <u>\$2,354.00</u>	<u>1,174</u>		
Loss of Rental (LOR):			
Loss of Use (LOU): <u>\$500</u>	<u>250.00</u> (100 days) <u>5</u> days	<u>406.95</u> (LOU+LOE) <u>466.95+480</u>	<u>2/2/19</u>
Loss of Income (LOI):			
LOR only: <input type="checkbox"/> LOU only: <input type="checkbox"/>	LOR + LOU: <input type="checkbox"/> LOR + LOI: <input type="checkbox"/>	(Tick only one)	
CATA Search: <u>\$5.35</u>	<u>5.35</u>		
Medical:			
Disbursement:		(e.g. Tow/Independent)	
Legal Cost:			
Total: <u>\$2,859.35</u>	<u>1,432.35</u>	Global Sum \$5: <u>1,430.00</u>	

FINAL PAYMENT Date/Time: _____ Confirm with: _____ Confirm by: _____
 Name 1: PEGASUS ENGINEERING & TRADING PTB LTD
 Name 2: _____
 Name 3: _____

REF

A141

ASSIGNMENT

File: _____ Date: _____
 Estimated Cost: _____
 OD (TP) / WS / TP RES / OD RES / EVA / INV / MY
 % Insured Vehicle Val: SL66187A
 Workshop Name: Pojasus
 Insured: SAC 8769P
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

NS	OS

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

Gen. or Market Value: _____
 IDAC Accident Report Consistent? Yes or No
 GIA / PR Seen Consistent? Yes or No
 Est. Repairs: 3 days Res: Yes or No
 Lump Sum: 20 % 3 Val: Yes or No

CA / REV / REP / 24 HRS 7200G
 Date: _____ Person Contacted: _____ Vehicle IN / OUT

Veh No: SL66187A Reg: 3 17
 Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover
 Truck / Trailer or CA1
 Make: Mercedes 3 CC 1496
 Colour: Grey A/C: Insured / Std / NI / NA
 Sp. Reading: 31953 T.Ratio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: JM6BN22A8H0144869
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Harder / Jammed / Leaked / Burnt or
 Brakes: Harder / Jammed / Leaked / Burnt or
 Mod: NR / SRim / STD A/Rim or
 Tyre Size: F: _____ R: 205/60R16
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / DHTSU / PIR / SUMI /
 TOYO / YOKO or Kumho
 Front: 6 mm Rear: 6 mm
 R/Se: 6 mm L/Se: 6 mm
 D.O.A: 7/7/17 D.O.I: 7/7/17
 Survey held at: _____
 Des. of Damages: Ft / Rear / OS / NS / UIC / Rooftop or
OS Body
 The UIC / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction
10/7/17 confirmed d/s to 2200 miles with.
 (KUMHO: # 1,807-00 / 46%)

Date/Time File Pass ()
 Prel. Report
 Final Report

Date/Time File Return ()

Days Of Repair

Resurvey No. of Trip:

Survey Fee:

Transporter:

Add Fee: Site Insp \$

Interview \$

Tech Invs \$

Weekend \$

Report Format:

Lump Sum / I.B. ()

TOTAL



Messrs Grab Rentals Pte Ltd

Estimate To Repair: Mazda 3 4-Door Sedan 1.5L
 Vehicle No: SLL6187A
 Chassis No: JM6BN22A8HD144869

*Not filled
 date
 2/5/2000
 1/7/17
 Take photo Attorney
 3 day.*

Insurer: AIG
 Insured's Veh No: SGC8769P
 Date of accident: 07.07.2017

Date: 07.07.2017

Pages: 1 of 1

S/No	Quantity	Description	Amount
LIST ITEMS			
1	1 pc	o/s front door	\$ 1,062.00
2	1 pc	front door inner lock	\$ 240.00
3	1 pc	front door inner lock striker	\$ 26.00
4	1 pc	front door power window motor	\$ 142.00
5	1 pc	front door regulator	\$ 120.00
6	1 pc	front door window glass channel weatherstrip	\$ 165.00
7	1 pc	front door outer weatherstrip moulding	\$ 77.00
8	1 pc	front door hinge top	\$ 42.00
9	1 pc	front door hinge bottom	\$ 40.00
10	1 pc	front door checker/arrestor	\$ 37.00
11	1 pc	front door weatherstrip	\$ 107.00
12	1 pc	front door inner trimboard	\$ 320.00
13	1 pc	o/s front fender	\$ 334.00
14	1 pc	front fender inner cowling	\$ 130.00
15	6 ps	front fender inner cowling clips @\$5.00	\$ 30.00
			\$ 2,872.00
Less 20%			\$ 574.40
			\$ 2,297.60
LABOUR & MISC. CHARGES			
1		To check steering geometry and computer wheel alignment.	\$ 11 100.00
2		To rust-proofing of the affected areas.	\$ 60 120.00
3		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 400 800.00
4		Putty and spray painting of the affected portion.	\$ 600 750.00
			\$ 1,770.00
Grand Total			\$ 4,067.60

*S. J. D
 11
 11
 11
 11
 To 1
 24
 24
 24
 To 1
 20
 20/24
 11
 11*

LET Auto Collision Centre notify
 the Insurer of the following:
 • To ensure follow-up repair work
 • To ensure damaged parts being repaired
 • Parts prices are subject to confirmation
 • This job is subject to "Workshop Repaired" status
 • No deep metalwork is allowed
 • Supplementary items must be reviewed and
 approved by your estimator from Insurance Company
 Acknowledged by Repairer
 Signature:
 Date:

Please conduct the survey at
 Pegasus Engineering @ Tan Lim Motor Pte Ltd c/o 51 Defu Lane 10 Singapore 539216

*2184
 1747.2
 2807.2*



GREAT AMERICAN INSURANCE COMPANY
UEN: T15FC0029B GST REG. NO.: M90370081T
3 TEMASEK AVENUE, #16-01 CENTENNIAL TOWER
SINGAPORE 039190
TEL: +65 6804 6000
FAX: +65 6235 2616

MOTOR COVER NOTE: MTGRAB20170341

The Insured mentioned in this Covernote, having proposed for insurance in respect of the Motor Vehicle described, is hereby HELD COVERED under the terms of the Insurer's usual form of Motor Policy applicable thereto for the period mentioned unless the cover be terminated by the Insurer by notice in writing in which case the insurance will thereupon cease and a proportionate part of the annual premium payable for such insurance will be charged for the time the Company has been on risk.

The Insurer	: GREAT AMERICAN INSURANCE COMPANY
The Insured	: Grab Rentals Pte. Ltd.
Insured Nric/Passport No/ Roc	: 201617200G
Policy Coverage	: Comprehensive
Make And Description Of Vehicle	: Mazda 3 1.5 Sedan Standard
Vehicle Registration No.	
Year Of Manufacture	: 2017
Engine No.	: P520432222
Chassis No.	: JM6BN22A8HD144859
Engine Capacity/ Tonnage/ Seater	: 1495cc
Hire Purchase	: Malayan Banking Berhad
Value (S\$)	: Market Value of Insured Vehicle at Time of Loss
Period Of Insurance	: From 02/03/2017 to 01/03/2018
Excess (S\$)	: All Claims Excess – S\$2,000.00 Windscreen Excess – S\$100.00
Great American Authorised Workshop	: Authorised Workshop

I/WE HEREBY CERTIFY THAT POLICY TO WHICH THIS CERTIFICATE RELATES IS ISSUED IN ACCORDANCE WITH THE PROVISIONS OF THE MOTOR VEHICLES (THIRD-PARTY RISK AND COMPENSATION) ACT (CHAPTER 189) AND PART IV OF THE ROAD TRANSPORT ACT 1987 (MALAYSIA)

Note: This Cover Note is only valid for 60 days from the date of issuance unless replaced by the Certificate of Insurance issued by the Company.

For and on behalf of Great American Insurance Company

Great American Insurance Company
Authorised Signatory

Date of Issue : 28/02/2017
Intermediary : Citrine Systems (S) Pte Ltd (Grab Leasing)

MTR/COVERNOTE/V02/16



9A Lok Yang Singapore 628628
c/o 51 Defu Lane 10 Singapore 539216

Tel: 6858 1846 / HP 9628 6508
Fax: 6858 0877

Our Ref SLL 6187A
Your Ref SGC 8769P

Date 30/1/2018

Claims Department - ALG
Executive in Charge

WITHOUT PREJUDICE

Dear Sir/Madam,

ACCIDENT INVOLVING SLL 6187A / SGC 8769P ON 07.07.2017
(PR Hire)

Refer to the above accident and please acknowledge receipt of this letter within 14 days.

It appears that the accident was caused by your insured. Enclosed documents to substantiate our client's property damaged claim as our client had authorized us to quantify, to act and to reach settlement within 6 weeks on their behalf: -

- Original survey report/ _____ copies of photographs _____
- Original Tax-invoice number IV 18/01-1194 police report / police result
- Certificate Of Insurance _____ Vehicle search result
- Authorization To Act - Owned/Hirer _____

*Survey under insurance instruction / Independent surveyor / No survey.
LKK

a) Cost of repair (inclusive GST)	\$ <u>2354.00</u>
b) Survey fees / Photographs as per request	\$ _____
c) Vehicle Search fees / GIA fees / Police Report fees / Reporting fees	\$ <u>5.25</u>
d) Loss of rental @ <u>4</u> days @ \$66.95	\$ <u>267.80</u>
e) Loss of <u>earnings</u> / rental fees @ <u>4</u> days @ \$100.00	\$ <u>400.00</u>
f) Administrative charges to negotiate settlement (Waive if 100% offer made within acknowledge timeframe)	\$ <u>235.00</u>
g) _____	\$ _____
Total	\$ <u>3262.15</u>

* Driver's injury and other losses exclude in this claim.

If you are agreeable to the above, please forward discharge voucher for our client's signature and payment issued directly to "Pegasus Engineering & Trading Pte Ltd" within 28 days.

Yours faithfully,

Sharon Ow

Email: claims@pegasusengrg.com.sg



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

29 SEPTEMBER 2017

LAW NGAI MOH
26 JALAN SAPPAN
SINGAPORE 576929

By Post and By Email

Dear Sir/Madam,

OUR REF : CC6/AIG17013199/Uhb3

YOUR REF : SGC 8769P

ACCIDENT INVOLVING SGC 8769P AND SLL 6187A ALONG JALAN CHENGAM ON
07.07.2017

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AIG Asia Pacific Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from Body Repairer/Workshop acting on behalf of the owner of SLL 6187A against your motor insurance policy.

Based on the accident report and accident scenario and all available information at hand, it was reported that your vehicle had collided to the Third-Party vehicle SLL 6187A. As such, liability may not be on your favour unless proven otherwise.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defense, please reply to us within 10 days from the date of this letter.

Your full co-operation in the handling of the claim is required and kindly submit the following to vicalpeh@lkkauto.com within 10 days from the date of this letter **if not provided at AIG's reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (if any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AIG's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AIG of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AIG shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6256 3561 or email us at vicalpeh@lkkauto.com.

Please quote the claim reference when you contact us that we can assist you more effectively.

Yours sincerely,

Vic Alpeh
Case Handler
DID: 6841 2096
FAX: 6741 4108
Email: vicalpeh@lkkauto.com

c.c. *AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)*

c.c. *gimlnm2@yahoo.com
(email)*

AUTHORIZATION TO ACT

TO: PEGASUS ENGINEERING & TRADING PTE LTD

FROM: OWNER OF VEHICLE NUMBER SLL 6187A

ACCIDENT INVOLVING SGC 8769P

ALONG/AT 14 Jalan Chengam (In front of our House)

We hereby authorize you to act on our behalf in pursuance of our claim for all damages during the repair arising out of the above accident.

This letter serve as the 'AUTHORITY TO ACT'.

We also hereby authorize all agreed settlement payment be made in favour to PEGASUS ENGINEERING & TRADING PTE LTD.

Name : Grab Rentals Pte Ltd

Co Reg No : 201617200G

Address : 18 Sin Ming Lane #01-08 Midview City Singapore 573960

Contact : 6655 0005

Date : 07/07/2017

Signature



Owner

RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, **PEGASUS ENGINEERING & TRADING PTE LTD** ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd **LKK AUTO CONSULTANTS PTE LTD** (name of surveyor) with respect to the amount claimed for **S\$1,430.00** (Global Sum – all in) for vehicle no. **SLL 6187A** that was damaged pursuant to the accident which occurred on **07/07/2017** (date) along **JALAN CHENGAM** (location) involving vehicle no/s **SGC 8769P**. This is pursuant to the inspection conducted on **07/07/2017** (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner **GRAB RENTALS PTE LTD** ("the third-party claimant") of vehicle no. **SLL 6187A** make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to **SLL 6187A** (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 20 (day) of Aug (month) ²⁰¹⁷~~2018~~ (year)



Signed by appointed surveyor



Signed by "the workshop" (with chop)

"The contents of this document apply to vehicle damages only. All personal injuries and damages arising therefrom are excluded from the ambit and application of this document."



PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Tax Invoice

From :
PEGASUS ENGINEERING & TRADING PTE LTD C/O 51 DEFU LANE 10 539218
Officer in Charge : WEE TZE FAH Tel : Email :

Customer :
GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960
Attn : Tel : Fax :


Inv No : IV18/01-1194	Inv Date : 30/01/2018	Term : 30 DAYS
Vehicle No : SLL6187A	Chassis No : JM6BN22A8H0144869	
Model : MAZDA 3		
Remarks : TP INSURER: AIG, INSURED'S VEH NO: SGC8769P, DATE OF ACCIDENT: 07.07.2017		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
1	TO LUMP SUM REPAIR AS RECOMMENDED BY SURVEYOR	1	2,200.0000	2,200.00

Cheques should be made payable to PEGASUS ENGINEERING & TRADING PTE LTD

Sub Total	2,200.00
GST(7.00%)	154.00
Total (SGD)	2,354.00

PEGASUS ENGINEERING & TRADING PTE LTD




Authorised Signature

Enquire Vehicle & Owner Information (Vehicle No. SGC8769P As At 07 Jul 2017 / 07:30:00)**Law Firm Search Details**

Search Reason: Insurance claim in relation to traffic accident

Law Firm Case No.: SLL6187A

Current Owner Details

Owner ID Type: Singapore NRIC

Owner ID: S1496308A

Owner Name: LAW NGAI MOH

Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes

Registered Block/House No.: 26

Registered Street Name: JALAN SAPPAN

Registered Unit No.: -

Registered Building Name: -

Registered Postal Code: 576929

Current Vehicle Details

Vehicle No.: SGC8769P

Make Description/Model: LAND ROVER / DISCOVERY SPORT 2.0 SI4 HSE 7STR S/R

Insurance Company Name: AIG ASIA PACIFIC INSURANCE PTE. LTD.


Land Transport  AuthorityPlease read through the [Privacy Statement](#), [Terms of Use](#) and [Disclaimer](#).Please do not use the **Back** or **Forward** buttons on your browser as this may alter the results of the transactions.

Best viewed with IE 6.0 SP3 and above, 1024 X 768 resolution

Copyright © 2017 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#)

Last updated on 01 Jul 2017 at 12:50 AM


 ONE MOTORING
 Your Fast Track To Complete Motoring


 Thank you


Lee Ming Hui Kelvin has successfully logged out.
 Your last login date and time was 07 Jul 2017, 13:04:50.

To return to ONE.MOTORING, please click [here](#).

For security reasons, please **CLEAR YOUR CACHE** after each session.

Session Transaction History

<u>No.</u>	<u>Asset Type</u>	<u>Asset ID</u>	<u>Asset Owner ID</u>	<u>Transaction Type</u>	<u>Transaction Amount(S\$)</u>	<u>Log Date/Time</u>
1	Vehicle	SGC8769P -		18.19 Enquire Veh Owner Info (Others) by Law Firm	5.35	07 Jul 2017 / 13:05:41

Land Transport Authority

Please read through the [Privacy Statement](#), [Terms of Use](#) and [Disclaimer](#).
 Please do not use the **Back** or **Forward** buttons on your browser as this may alter the results of the transactions.

Best viewed with IE 6.0 SP3 and above. 1024 X 768 resolution
 Copyright © 2017 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#)
 Last updated on 01 Jul 2017 at 12:50 AM

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	07 Jul 2017 Edit Reg		07 Jul 2017 00:00 Edit Adj Rpt	S\$2,200.00 Edit Estimates	S\$2,200.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by adjuster]							
Insured:	LAW NGAI MOH, ID: S1496308A								
Main Claimant:	GRAB RENTALS PTE LTD, Co. Reg. No.: 201617200G								
Vehicle Reg. No.:	SLL6187A	Date of Loss:	07/07/2017 07:00 - :59 [4 Months and 5 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 6458416785SG	Policy/Cover Note No.:	2100434274 (Comprehensive)						
Vehicle Reg. No. (Insured):	SGCB769P	Policy No. (Claimant):							
		Excess:							
Repairer:	Pegasus Engineering & Trading Pte Ltd (HQ) 51 DEFU LANE 10, 539216 Defu Lane - Tel: 68581846								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Syed-Yusoff, Saliha] Saliha.Syed-Yusoff@aig.com								
Claimant's Insurer:	Great American Insurance Company (HQ) - Tel: 6804 6047								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 27/08/2019]								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
<ul style="list-style-type: none"> • AIG_SG_EXPRESS (25/08/2019): Report Send Back Alerts - SLL6187A (TP) • AIG_SG (10/07/2017): No OI GIA Report • AIG_SG (10/07/2017): Request To Upload TP GIA Report 									
ALL ASSOCIATED TASKS		View All Search Tasks Create New Task Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLL6187A (6458416785SG)
 [SGC8769P]
 TP
 GRAB RENTALS PTE LTD
 Jul 7 2017 7:40AM
 [LAW NGAI MOH]
 Pegasus Engineering & Trading Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View View in Browser <input type="button" value="v"/>	
Letters/Correspondences										1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	(Draft)	Third Party Express Settlement - Payment Breakdown							Edit		
Photos/Images										3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	07/07/17 15:55	Chassis Number							Load JPG	<input checked="" type="checkbox"/>	
2	07/07/17 15:55	Odometer Reading							Load JPG	<input checked="" type="checkbox"/>	
3	07/07/17 15:55	General View							Load JPG	<input checked="" type="checkbox"/>	
4	07/07/17 15:55	General View							Load JPG	<input checked="" type="checkbox"/>	
5	07/07/17 15:55	General View							Load JPG	<input checked="" type="checkbox"/>	
6	07/07/17 15:55	General View							Load JPG	<input checked="" type="checkbox"/>	
7	07/07/17 15:55	General View							Load JPG	<input checked="" type="checkbox"/>	
8	07/07/17 15:55	General View							Load JPG	<input checked="" type="checkbox"/>	
9	07/07/17 15:55	General View							Load JPG	<input checked="" type="checkbox"/>	
10	07/07/17 15:55	General View							Load JPG	<input checked="" type="checkbox"/>	
11	07/07/17 15:55	General View							Load JPG	<input checked="" type="checkbox"/>	
12	07/07/17 15:55	General View							Load JPG	<input checked="" type="checkbox"/>	
13	07/07/17 15:55	General View							Load JPG	<input checked="" type="checkbox"/>	
14	07/07/17 15:55	General View							Load JPG	<input checked="" type="checkbox"/>	
15	07/07/17 15:55	General View							Load JPG	<input checked="" type="checkbox"/>	
16	07/07/17 15:55	General View							Load JPG	<input checked="" type="checkbox"/>	
17	07/07/17 15:55	General View							Load JPG	<input checked="" type="checkbox"/>	
18	07/07/17 15:55	General View							Load JPG	<input checked="" type="checkbox"/>	
19	07/07/17 15:55	General View							Load JPG	<input checked="" type="checkbox"/>	
20	07/07/17 15:55	General View							Load JPG	<input checked="" type="checkbox"/>	
21	07/07/17 15:55	General View							Load JPG	<input checked="" type="checkbox"/>	
22	07/07/17 15:55	General View							Load JPG	<input checked="" type="checkbox"/>	
23	07/07/17 15:55	General View							Load JPG	<input checked="" type="checkbox"/>	
24	07/07/17 15:55	General View							Load JPG	<input checked="" type="checkbox"/>	
25	07/07/17 15:55	General View							Load JPG	<input checked="" type="checkbox"/>	
26	07/07/17 15:55	General View							Load JPG	<input checked="" type="checkbox"/>	
27	07/07/17 15:55	General View							Load JPG	<input checked="" type="checkbox"/>	
28	07/07/17 15:55	General View							Load JPG	<input checked="" type="checkbox"/>	
29	07/07/17 15:55	General View							Load JPG	<input checked="" type="checkbox"/>	
30	07/07/17 15:55	General View							Load JPG	<input checked="" type="checkbox"/>	
31	07/07/17 15:55	General View							Load JPG	<input checked="" type="checkbox"/>	
32	07/07/17 15:55	General View							Load JPG	<input checked="" type="checkbox"/>	
33	07/07/17 15:55	General View							Load JPG	<input checked="" type="checkbox"/>	
34	07/07/17 15:55	General View							Load JPG	<input checked="" type="checkbox"/>	

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	07/07/17 15:55	General View	 Load JPG	<input checked="" type="checkbox"/>
36	07/07/17 15:55	General View	 Load JPG	<input checked="" type="checkbox"/>
37	07/07/17 15:55	General View	 Load JPG	<input checked="" type="checkbox"/>
38	07/07/17 15:55	General View	 Load JPG	<input checked="" type="checkbox"/>
39	07/07/17 15:55	General View	 Load JPG	<input checked="" type="checkbox"/>
40	07/07/17 15:55	General View	 Load JPG	<input checked="" type="checkbox"/>
41	07/07/17 15:55	General View	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	11/07/17 08:52	TP ESTIMATE- MARKED	 Load PDF	
2	11/07/17 08:52	TP GIA REPORT	 Load PDF	
3	11/07/17 10:43	Non reporting letter	 Load PDF	
4	29/09/17 11:47	LETTER TO OI	 Load PDF	
5	29/09/17 11:47	EMAIL TO OI	 Load PDF	
6	29/01/18 08:48	EMAIL TO AIG	 Load PDF	
7	02/02/18 16:17	EMAIL FROM AIG	 Load PDF	
8	18/01/19 15:14	EMAIL TO TP	 Load PDF	
9	18/01/19 15:14	EMAIL TO AIG	 Load PDF	
10	08/02/19 08:53	TP LOD	 Load PDF	
11	05/09/19 16:31	WORKSHOP INVOICE	 Load PDF	
12	05/09/19 16:31	AUTHORISATION TO ACT FORM	 Load PDF	
13	05/09/19 16:31	Release Voucher	 Load PDF	
14	05/09/19 16:31	LTA SEARCH	 Load PDF	
15	05/09/19 16:31	LOD	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	SGC8769P (Insd veh)	Model:	MAZDA 3 1.5 SEDAN L SP.6EAT (A)
	SLL6187A (TP veh)		
Date of Accident:	07/07/2017		

Global Sum Settlement	:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Repair Estimate	:\$	4,352.33	
Final Repair Cost	:\$	1,430.00	
Loss of Use	:\$	5.00 days at \$100.00 per day	
Rental (if any)	:\$	days	
LTA / GIA Search Fee	:\$		
Others:	:\$		
	:\$		
Final Settlement Sum (Global Sum)	:\$	1,430.00	
Is Third Party Workshop GIA Registered? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO (Kindly indicate below)			
A) For <u>Non GIA Registered Workshop</u> :		Agreed Liability <u>50</u> (%)	
B) For <u>GIA Registered Workshop</u> :		BOLA Applicable: Yes/ No BOLA Scenario No:	
BOLA Liability: _____ (%)		Assessed Liability (*): _____ (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	Pegasus Engineering & Trading Pte Ltd	:\$	1,430.00
2)		:\$	
3)		:\$	
4)		:\$	

JOANNE LEE KHANG MIN

LKK Auto Consultants Pte Ltd

05 Sep
2019

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG17013199/UHB3Q2-1
Date: 05/09/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100434274
Claimant Vehicle No : SLL6187A	Insured Vehicle No :	SGC8769P
Date of Loss: 07/07/2017	Nature of Claim:	TP
		Claim No: 6458416785SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLL6187A	Engine No:	P520432222
Make & Model:	MAZDA 3, 1.5 SEDAN L SP.6EAT (A)	Chassis No:	JM6BN22A8H0144869
Reg. Date:	02/03/2017 (Man. Year: 2017)	Odometer:	31953 km
Colour:	Grey		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Kumho 6 mm	Rear Left Side:	Kumho 6 mm
Front Right Side:	Kumho 6 mm	Rear Right Side:	Kumho 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,297.60	1,747.20	550.40	23.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,770.00	1,060.00	710.00	40.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,067.60	2,807.20	1,260.40	30.99
Approved Total (Overridden) (S\$)		2,200.00		
	(S\$)	4,067.60	2,200.00	1,867.60
+ GST 7.00/7.00% (S\$)	284.73	154.00	130.73	45.91
Nett Amount (S\$)	4,352.33	2,354.00	1,998.33	45.91
+ Loss of Use (5.0 x S\$100.00/day) (S\$)		500.00		
	(S\$)	2,854.00		
Liabe Amount (50.00%) (S\$)		1,427.00		
+ Doc/Search Fee (S\$)		5.35		
Nett Liability (S\$)		1,432.35		
Global Sum Settlement (S\$)		1,430.00		

INSPECTION

Date of Assignment: 07/07/2017
Date Inspected: 07/07/2017 Inspected At: Pegasus Engineering & Trading Pte Ltd
(HQ)
51 DEFU LANE 10
Singapore 539216

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA

Manager: VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*O/S FRONT DOOR	Badly Dented	1,062.00 FL	*1,062.00 FL
2	1		*FRONT DOOR INNER LOCK	Not Necessary	240.00 FL	*- FL
3	1		*FRONT DOOR INNER LOCK STRIKER	Not Necessary	26.00 FL	*- FL
4	1		*FRONT DOOR POWER WINDOW MOTOR	Not Necessary	142.00 FL	*- FL
5	1		*FRONT DOOR REGULATOR	Not Necessary	120.00 FL	*- FL
6	1		*FRONT DOOR WINDOW GLASS CHANNEL WEATHERSTRIP	Torn	165.00 FL	*165.00 FL
7	1		*FRONT DOOR OUTER WEATHERSTRIP MOULDING	Bent	77.00 FL	*77.00 FL
8	1		*FRONT DOOR HINGE TOP	Bent	42.00 FL	*42.00 FL
9	1		*FRONT DOOR HINGE BOTTOM	Bent	40.00 FL	*40.00 FL
10	1		*FRONT DOOR CHECKER /ARRESTOR	Twisted	37.00 FL	*37.00 FL
11	1		*FRONT DOOR WEATHERSTRIP	Torn	107.00 FL	*107.00 FL
12	1		*FRONT DOOR INNER TRIMBOARD	Dented	320.00 FL	*320.00 FL
13	1		*O/S FRONT FENDER	Dented / Bent	334.00 FL	*334.00 FL
14	1		*FRONT FENDER INNER COWLING	Not Necessary	130.00 FL	*- FL
15	6		*FRONT FENDER INNER COWLING CLIPS	Not Necessary	30.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	2,872.00	2,184.00
- List Item Discount on L Items 20.00/20.00% (S\$)	574.40	436.80
Total Parts (S\$)	2,297.60	1,747.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	100.00	0.00
2	TO RUST-PROOFING OF THE AFFECTED AREAS	New	120.00	60.00
3	PANEL BEATING ,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION ,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	800.00	400.00
4	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	750.00	600.00
Gross Labour Cost (S\$)			1,770.00	1,060.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >