

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 023G

Vehicle Details

Vehicle No.: SJS2420P
Vehicle to be Exported: No
Intended Deregistration Date: 10 Sep 2019
Vehicle Make: HONDA
Vehicle Model: FIT 1.3G A
Primary Colour: Grey
Manufacturing Year: 2009
Engine No.: L13A4223211
Chassis No.: GE61205623
Maximum Power Output: 73.0 kW (97 bhp)
Open Market Value: \$14,900.00
Original Registration Date: 04 Aug 2009
First Registration Date: 04 Aug 2009
Transfer Count: 1
Actual ARF Paid: \$14,900.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 03 Aug 2029
COE Category: A - Car (1600cc & below)
COE Period(Years): 10
PQP Paid: \$29,328.00
COE Rebate Amount: \$29,028.00
Total Rebate Amount: \$29,028.00

The information contained herein is correct as at 10 Sep 2019

OK

2/20/2019

ASS. REC. BY:

REF:

03/ASM19003/20/Gcd3e2

Special Instruction:

Surveyor

GA

ASSIGNMENT (Office)

From (Person)

Wong Wei Fu

of

ASM(CAXA)

Date/Time:

19/2/19 @ 2:18pm

Estimated Cost:

Till to:

OD (TP) WS/TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No:

SJS 2420P

Insured:

SKPS771K

at Workshop n/s

Hiap Tek Automobile

Tel:

9660 1347

of

160 Sin Ming Drive # 05-17

Policy No:

Claim No:

89M01E6U

Sum Insured

Excess:

Make of Veh

(Client's Record)

D.O.A

17/02/2019

CA / REV / REP. / REV 24 HRS

cup

20/2/19

H.O.D. Endorsement:

Date/Time:

3:46pm @ 19/2/19

Person Contacted:

Mr. Ong

Vehicle

IN/OUT

Date/Time

Action/Instruction

(X)

Estimate

agreed

Smuy on 20/2/19

SJS 2420P - NN/EQ111618461/wd

But 9/9/11

SKPS771K

Diamond: 21/2/2019

XKL

ASM(AxA)

00236

20/2/19

SJS2420P

(-2019)
04 Aug 2009

① C/VN / TP / RP / C / O / R / E / L / V / A / H / V / M / V

C/VN / TP / RP / C / O / R / E / L / V / A / H / V / M / V

C/VN / TP / RP / C / O / R / E / L / V / A / H / V / M / V

160 Sin Ming Drive #05-17

SJS2420P

Hip Lok

Drive #05-17

Insured

Policy No.

Claim No.

Insured

Excess

Client's Record

Make of Vehicle

Policy Conditions

Remark: The veh had commenced its repair at the time of inspection

Est. or Market Value

\$11K

BSA - Accident Report

Consistent? Yes or No

GLA - HPI / Loss

Consistent? Yes or No

Est. Repair

8

days

Res.

Yes or No

Est. Sum

20

%

3 Val.

Yes or No

CA - 2 REV / REP / 24 HRS up

Date

Person Contacted

Vehicle IN / OUT

Est. Price

Vehicle in function

\$5000 - \$6000

COE : 8140

C/VN / TP / RP / C / O / R / E / L / V / A / H / V / M / V

Truck / Trailer or

Make

Honda Fit

1339

Colour

Grey

AP

Insured / STD / HI / NA

Sp. Reading

334/61

TP/Code

Insured / STD / HI / NA

Eng/No

C/No

GE6/205623

Gen. Cond. Good / Fair / Poor / Burnt

Steering In order / Jammed / Leaked / Burnt or

Brake

In order / Jammed / Leaked / Burnt or

Mod

Std / SRim / STD AIRim or

Tyre Size

F

175/70R14

R

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal

6

mm

R/Bal

6

mm

L/Bal

6

mm

L/Bal

6

mm

D.O.A.

D.O.I

Survey held at

W/S

20-02-19

upm

Desc. of Damages: ① ② ③ ④ ⑤ ⑥ ⑦ ⑧ ⑨ ⑩ ⑪ ⑫ ⑬ ⑭ ⑮ ⑯ ⑰ ⑱ ⑲ ⑳ ㉑ ㉒ ㉓ ㉔ ㉕ ㉖ ㉗ ㉘ ㉙ ㉚ ㉛ ㉜ ㉝ ㉞ ㉟ ㊱ ㊲ ㊳ ㊴ ㊵ ㊶ ㊷ ㊸ ㊹ ㊺ ㊻ ㊼ ㊽ ㊾ ㊿

The UIC / Chassis frame / Body Structure affected due to collision

1. Add Fee: (Add Page 50)

2.

3. Add Fee: (Add Page 50)

4.

Report Form

1. Add Fee: (Add Page 50)

☐

Preli. Report

☐

Final Report

Days Of Repair:

8

Resurvey No. of Trip:

1

Add Fee:

☐

1. Add Fee: (Add Page 50)

☐

2. Add Fee: (Add Page 50)

☐

3. Add Fee: (Add Page 50)

☐

4. Add Fee: (Add Page 50)

Survey Fee

1. Add Fee: (Add Page 50)

2. Add Fee: (Add Page 50)

3. Add Fee: (Add Page 50)

4. Add Fee: (Add Page 50)

5. Add Fee: (Add Page 50)

6. Add Fee: (Add Page 50)

7. Add Fee: (Add Page 50)

100
100




Service Request Details

Claim

S9M01E6U

Reference

None 

Loss Date

February 17, 2019

Report Date

Feb 18, 2019 2:50:00 PM

Request Date

August 26, 2019

Due Date

September 2, 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Re-inspection

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SJS2420P

MODEL

FIT

Service Address

51 Ubi Avenue 1, #01-25, , 408933

Primary Contact/Insured

WONG WEE KIANG (YUAN WEIQIANG)
61 SUNSET WAY, 02-03, 597086, Singapore
97342011
MD_DSGN@YAHOO.COM.SG

Claim Handler

WONG Wee Fu
6568804888
weefu.wong@axa.com.sg

Additional Instructions

To request for MV and check for CTL

Messages

Invoices

History

Documents 7

Assessment

Metrics

Notes

[New Message](#)

Nivitha (LKK Auto)

From: Shu Pei (LKKAuto) <shupeil@lkkauto.com>
Sent: Monday, 26 August 2019 12:44 PM
To: assignments
Subject: FW: [EXTERNAL] [Re-Inspection] Our ref : 19-A14-10267-VL.jp.sc; Your ref : S9M01E6UMC/WF; Claimant: Eng Lin Kee

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: WONG Wee Fu <weefu.wong@axa.com.sg>
Sent: Monday, 26 August 2019 12:32 PM
To: Sharleen Chee <sharleen.chee@legaloptions.biz>; Admin A <admin-a@lkkauto.com>
Subject: RE: [EXTERNAL] [Re-Inspection] Our ref : 19-A14-10267-VL.jp.sc; Your ref : S9M01E6UMC/WF; Claimant: Eng Lin Kee

Hi Lkk team,

Please attend to RI, previously PRS under CS3/ASM19003120/Gcd3e2.

Thanks

Wee Fu

AXA Insurance Pte Ltd | 8 Shenton Way, #24-01 AXA Tower, Singapore 068811 | www.axa.com.sg

Email: Weefu.wong@axa.com.sg

Please consider the environment before printing this message

This message is confidential. Any unauthorized disclosure, use or dissemination, either whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Sharleen Chee <sharleen.chee@legaloptions.biz>
Sent: 26 August, 2019 11:29 AM
To: WONG Wee Fu <weefu.wong@axa.com.sg>
Subject: [EXTERNAL] [Re-Inspection] Our ref : 19-A14-10267-VL.jp.sc; Your ref : S9M01E6UMC/WF; Claimant: Eng Lin Kee

WITHOUT PREJUDICE

Dear Wee Fu,

We refer to the email below.

Our client would like the re-inspection on the 10th September 2019, 11:00 am at the workshop:

M/s Hiap Lek Automobile Trading at Blk 160 Sin Ming Drive #05-17, Sin Ming Auto City Singapore 575722.

Please contact Mr Ong Han Wei at 9660 1347

Please let us have the confirmation that your surveyor will attend at the said venue at the said date and time in order for us to inform our client accordingly.

Thanks n regards,

Sharleen

Legal Secretary

LEGAL OPTIONS LLC

(GST Registration/UEN No. 201203825R)

Tel (65) 6513-2800 DID (65) 6513-2803 Fax (65) 6438-8275

Information in this message is confidential and may be legally privileged. It is intended solely for the person(s) to whom it is addressed. If you are not the intended recipient, please delete the message and any other record of it from your system, and notify the sender immediately.

----- Original Message -----

Subject: Acknowledgement Your ref : 19-A14-10267-VL.jp.sc Our ref : S9M01E6UMC/WF

From: NIKAM Santosh Pandurang

To: "'jeanny@legaloptions.biz'"

CC: WONG Wee Fu

ACCIDENT INVOLVING SKP5771K AND SJS2420P ON 17-02-2019

Without Prejudice

We acknowledge receipt of your letter dated 19.08.2019 and the enclosures on 21.08.2019.

We would like to conduct a re-inspection of your client's vehicle SJS2420P Please let us know a suitable date and time.

We would appreciate that in letting us know the date, your client could allow us at least 10 days of lead-time. This is to allow us to co-ordinate with the surveyor concerning the re-inspection date and time .

May we hear from you in due course.

For future correspondence, please reply to WONG Wee Fu at weefu.wong@axa.com.sg

Regards,

Santosh Nikam

-----Disclaimer-----

This message may contain confidential information intended solely for the use of the named addressee. If you are not the intended recipient, you should not read, use, disclose or reproduce the content of this message. If you have received this message by mistake, please notify the sender immediately. Any views or opinions presented in this message are solely those of the author and do not necessarily represent those of AXA Singapore - Externals or any other entity of the AXA Group, unless otherwise stated by the sender and duly authorized by the said companies.

-----Disclaimer-----

This message may contain confidential information intended solely for the use of the named addressee. If you are not the intended recipient, you should not read, use, disclose or reproduce the content of this message. If you have received this message by mistake, please notify the sender immediately. Any views or opinions presented in this message are solely those of the author and do not necessarily represent those of AXA Insurance Pte Ltd or any other entity of the AXA Group, unless otherwise stated by the sender and duly authorized by the said companies.

PAR Automotive Consultancy

Regn. No: 52986974L

Thomson Rd Post Office PO Box 029 Singapore 915701. Tel : 64531173, Fax : 64536131.
Consultants: Vehicle appraisal & inspection, accident investigation, expert witness

Report No: 0063-19-HLm

31 July 2019

Eng Lin Kee
160 Sin Ming Drive #05-17 Sin Ming Autocity
Singapore 575722

INVOICE No. 0063-19-HLm

Vehicle No. SJS2420P

<u>S/NO.</u>	<u>SERVICES RENDERED</u>	<u>Amount due</u>
1	Being accident vehicle appraisal services, transport, photographs and re-inspection (work in progress and post repair inspection).	\$899.00
Total amount payable		<u>\$899.00</u>

Kindly cross your cheque in favour of "PAR Automotive Consultancy"

We thank you in anticipation for your prompt payment.

PAR Automotive Consultancy



PAR Automotive Consultancy

Regn. No: 52986974L

Thomson Rd Post Office PO Box 029 Singapore 915701. Tel : 64531173, Fax : 64536131

Consultants: Vehicle appraisal & inspection, accident investigation, expert witness

Report No: 0063-19-HLm

31 July 2019

ACCIDENT VEHICLE SURVEY REPORT

Eng Lin Kee

160 Sin Ming Drive #05-17 Sin Ming Autocity

Singapore 575722

VEHICLE INFORMATION:

Vehicle Reg No.:	SJS2420P	Odometer:	334161km
Make & Model:	Honda Fit 1.3G A	Colour:	Silver
Chassis number:	GE61205623	Date of accident:	17/02/2019
Year of Regn.:	04/08/2009	Date inspected:	19/02/2019
Repairer at:	Hiap Lek Automobile Trading	Date inspected (After Repair):	-
	160 Sin Ming Drive #05-17 Sin Ming Autocity		
	Singapore 575722		

STATIC CHECKS, where applicable:

Steering :	serviceable
Footbrake :	serviceable
Handbrake :	serviceable
Paintwork :	Good
General condition :	Good

TIRE CONDITION:

	<u>LH / Make</u>	<u>RH / Make</u>	<u>Size</u>
Front:	5mm/Bridgestone	5mm/Bridgestone	175/70R14
Rear:	5mm/Bridgestone	5mm/Bridgestone	175/70R14

POINT OF IMPACT AND DAMAGE, where applicable:

Impact on the rear and front portion.

Please see details as described in the Annex for parts and labour.

REMARKS:

We have inspected the above-mentioned vehicle on a "**Without Prejudice**" basis.

Parts and Labour Assessment

Report No: 0063-19-HLm

Vehicle No: SJS2420P

Description of part	Qty	Condition as inspected	Repairer's estimate	Our adjustment
Rear tailgate	1	buckled	736.40	/ 736.40
Rear tailgate glass moulding -top	1	necessary	35.00	/ 35.00
Rear tailgate glass moulding -lower	1	necessary	78.00	/ 78.00 41.2
Rear tailgate outer garnish	1	fractured	119.30	X 119.30
Rear tailgate emblem 'H' logo	1	necessary	25.00	X 25.00
Rear tailgate number plate lamp	2	fractured	76.00	X 76.00
Rear tailgate outer handle	1	fractured	55.00	X 55.00
Rear tailgate hinge RH/LH	2	bent	59.60	X 59.60
Rear tailgate damper RH/LH	2	bent	272.40	X 272.40
Rear tailgate inner trim board	1	deformed	100.20	/ 100.20
Rear tailgate inner trim board clip set	1	necessary	45.00	/ 45.00
Rear tailgate wiper motor	1	shorted	238.00	X 238.00 SVC
Rear tailgate inner lock	1	bent	232.10	/ 232.10 175
Rear boot weatherstrip	1	deformed	92.30	/ 92.30
Rear tail lamp RH/LH	2	fractured	412.40	/ 412.40
Rear bumper	1	deformed	474.40	/ 474.40
Rear bumper tow cover	1	ripped	12.60	/ 12.60
Rear bumper impact bracket RH	1	bent	49.00	/ 49.00
Rear bumper side retainer RH/LH	2	necessary	33.00	/ 33.00
Rear bumper clip set	1	necessary	22.80	/ 22.80
Rear tail lamp inner panel RH/LH	2	buckled	360.00	X 360.00 SVC
Rear end panel	1	buckled	287.40	/ 287.40
Rear end panel top garnish	1	deformed	60.80	/ 60.80
Rear end panel buzzer	1	shorted	132.60	/ 132.60
Rear fender air vent RH/LH	2	deformed	68.00	X 68.00 SVC
Rear fender inner trim RH/LH	2	deformed	500.00	/ 500.00
Rear fender inner trim clip set RH/LH	2	necessary	72.00	/ 72.00 35
Rear sponge tool tray	1	deformed	220.40	/ 220.40
Rear spare tyre well panel	1	buckled	737.00	X 737.00
Rear exhaust silencer box	1	bent	462.40	X 462.40
Rear exhaust silencer box mounting	2	deformed	25.00	X 25.00 SVC
Front bonnet	1	buckled	433.80	/ 433.80
Front bonnet hinge RH/LH	2	bent	62.80	X 62.80
Front bonnet weatherstrip RH/LH	2	necessary	30.00	X 30.00 SVC
Front bonnet lock	1	bent	90.60	/ 90.60
Front grille	1	deformed	137.50	/ 137.50
Front grille emblem 'H' logo	1	necessary	24.00	/ 24.00
Front grille clip set	1	necessary	15.20	/ 15.20

PAR Automotive Consultancy

Front head lamp RH/LH	2	fractured	1,170.00	✓ 1,170.00	
Front head lamp lower bracket RH/LH	2	bent	55.00	✓ 55.00	
Front bumper	1	squashed	523.50	✓ 523.50	458.5
Front bumper tow cover	1	deformed	14.50	X 14.50	SVC
Front bumper lower centre grille	1	deformed	119.60	✓ 119.60	
Front bumper lower moulding	1	deformed	115.10	X 115.10	SVC
Front bumper reinforcement	1	bent	253.90	✓ 253.90	173.3
Front bumper side retainer RH/LH	2	necessary	27.00	✓ 27.00	
Front bumper clip set	1	necessary	22.80	✓ 22.80	
Front support panel assy	1	buckled	381.90	✓ 381.90	
Air con condenser	1	bent	762.80	✓ 762.80	
Air con fan cowling	1	deformed	91.00	X 91.00	
Air con fan blade	1	warped	44.90	X 44.90	SVC
Air con fan motor	1	shorted	233.60	X 233.60	
Radiator assy	1	bent	1,386.20	✓ 1,386.20	1150.9
Radiator reserve tank	1	deformed	45.00	X 45.00	SVC
Radiator top mounting	2	bent	30.00	✓ 30.00	
Radiator fan cowling	1	deformed	89.30	✓ 89.30	
Radiator fan blade	1	warped	54.80	X 54.80	
Radiator fan motor	1	shorted	309.80	X 309.80	SVC
Wiper tank	1	deformed	70.00	X 70.00	
Wiper tank neck	1	deformed	35.50	X 35.50	
Battery cover	1	deformed	86.00	X 86.00	
Battery tray	1	squashed	22.30	X 22.30	
Subtotal before discount			12,832.50	12,832.50	
Percentage discount 0% and 20%			0.00	2,566.50	
Sub-total 1			12,832.50	10,266.00	
Rear tailgate glass sealant	1	necessary	70.00	✓ 70.00	40
Reverse sensor	1	shorted	350.00	✓ 300.00	200
Rear spare tyre well panel sealant	1	necessary	200.00	X 200.00	SVC
Front number plate c/w frame	1	bent	50.00	✓ 50.00	40
Air horn	2	distortion	220.00	X 220.00	SVC
Radiator coolant	1	necessary	80.00	✓ 50.00	30
Subtotal before discount			970.00	890.00	310
Percentage discount 0% and 0%			0.00	0.00	
Sub-total 2			970.00	890.00	
Parts-total			13,802.50	11,156.00	

LABOUR

1. To straighten and panel beating rear RH/LH fender, rear chassis frame member, front RH/LH fender, front chassis frame member, rear and front frame members. To cut/weld rear end panel, rear spare tyre well panel and front support panel. To remove and refit above parts.
2. To putty, re-spray painting and polish affected areas.

3,360.00 2,640.00

2,750.00 2,200.00

PAR Automotive Consultancy

3. To check and rectify wiring system.	120.00	100.00 30
4. To rust proof affected areas.	180.00	120.00 80
5. To remove and refit rear tailgate glass.	150.00	120.00 /
6. To remove, transfer and refit rear tailgate components.	150.00	100.00 60
7. To remove and refit rear exhaust silencer box.	150.00	X 120.00 nn
8. To remove, refit air con condenser and recharge air con gas.	150.00	120.00 /
Labour total	7,010.00	5,520.00 3210
Parts & Labour total	20,812.50	16,676.00

Results of inspection of the accident vehicle are as shown above.

We have taken into consideration the age and condition of the vehicle in our recommendation.

Hence, the recommended cost of repairs based on LUMP SUM repairs is :
and the recommended number of working days for the repairs is :

\$13,300.00

16

h

B J Loi (I Eng. MIMI, AIRTE)
Automotive Appraiser

10406.16
20% : 8300
10 Days.

LEGAL OPTIONS LLC

ADVOCATES & SOLICITORS

Mediators - Commissioners for Oaths - Notary Public

法商律師事務所

Motor Accident & Personal Injuries

Tel: (65) 6513 2800 Fax: (65) 6438 8275

Commercial, Litigation, Property, Trust & Estate

Tel: (65) 6438 8039 Fax: (65) 6734 8230

We do not accept service of Court Documents by fax

Your Ref : SKP 5771K
Our Ref : 19-A14-10267-VL.jp.sc

19th August 2019

M/S AXA INSURANCE SINGAPORE PTE LTD

8 Shenton Way #27-01/02

AXA Tower

Singapore 068811

(Attn: Motor Claims Department)

WONG WEE KIANG 3019771871

Blk 61 Sunset Way

#02-03

Singapore 597086

(Owner of motor vehicle no. SKP 5771K)

Dear Sirs,

CLAIMANT : ENG LIN KEE

ACCIDENT INVOLVING VEHICLE NOS. SJS 2420P, SKP 5771K AND OTHERS
ALONG PIE TOWARDS TUAS NEAR EXIT 12 (KPE/ECP) ON 17/02/2019

We are instructed by the abovenamed to claim damages against your insurers and/or servant and/or agent in connection with a road traffic accident on **17TH FEBRUARY 2019** **ALONG PIE TOWARDS TUAS NEAR EXIT 12 (KPE/ECP)** involving our client's vehicle registration number **SJS 2420P** and motor vehicle registration number **SKP 5771K** driven by your insured's and/or you at the material time.

We are instructed that the accident was caused by your insured's and/or your negligent driving and/or management of your insured's and/or your motor vehicle No. **SKP 5771K**. As a result of the accident, our client's vehicle was damaged and our client has been put to loss and expense, particulars of which are as follows: -

1. Costs of repairs	\$ 13,300.00
2. Rental at 11 days @\$110.00 per day	\$ 1,210.00
3. Loss of use at 5 days @\$120.00 per day	\$ 600.00
4. Loss of use at 2 days @\$120.00 per day (PRI)	\$ 240.00
5. Survey report fees	\$ 899.00
6. LTA search fees	\$ 10.00
7. GIA/Police search and report fees	\$ 59.00
8. Incidentals inclusive GST	\$ 160.50
9. Cost Contribution inclusive GST	\$ 1,070.00
Total :				\$ 17,548.50

60162784


Directors

Joan Lim Pheck Hoon LL.B (Hons)

Victor Leong Wai Meng LL.B (Hons)

Teo Lip Hua Benedict LL.B (Hons) LL.M

AXA INSURANCE PTE LTD



Senior Legal Executive's DID: 6513 2808

Direct Fax: 6438 8275

Email: wanny@legaleoptions.biz

Mailing Address for Accident Claims

Documents Support:

23 Kaki Bukit Avenue 4 #01-01 South Wing,
Singapore 415933

WITHOUT PREJUDICE

BY HAND

CERTIFICATE OF POSTING

(For your information only)



We enclose a copy of each of the following documents for your consideration: -

1. GIA report lodged by our client;
2. LTA Search;
3. Rental invoice and agreement from M/s Win Win Rent-A-Car Pte Ltd;
4. Surveyor's report & invoice from M/s PAR Automotive Consultancy;
5. 129 coloured photographs depicting the damages to motor vehicle SJS 2420P; and
6. Repair bill from M/s Hiap Lek Automobile Trading.

Please note that if you are insured and you wish to claim under your insurance policy, you should immediately pass this letter and all the enclosed documents to your insurer.

Please note that you or your insurer should send to us an acknowledgement of receipt of this letter within 14 days of your receipt of this letter, failing which our client will have no alternative but to commence proceedings against you without further notice to you or your insurer. Our client's claim herein is quantified based on supporting documents in our file. Until a settlement is reached, all negotiations are conducted on the basis that the damages quantified herein are subject to revision if so instructed by our client.

Please also note that if you have a counterclaim against our client arising out of the accident, you are also required to send to us a letter giving full particulars of the counterclaim together with all relevant supporting documents within 8 weeks of your receipt of this letter.

Please be reminded that if you fail to respond with an offer after 8 weeks and 10 days, i.e when an acknowledgement is made by you, pursuant to the protocol, we shall issue a Writ of Summons against you without any further notice, as it is deemed that a notice has been sufficiently given to you after 8 weeks and 10 days and that you have breached the Protocol we will commence proceedings within the requisite 14 days without any further notice.

If you have any queries, please call our Ms Jeanny at 6513 2808 or email her at jeanny@legaloptions.biz and quote the above reference number.

Kindly mail all future correspondence to our **Accident Claims Document Support Address at 23 Kaki Bukit Avenue 4 #01-01 South Wing, Singapore 415933.**

Yours faithfully



Encls.

Cc: Clients

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid

ACCIDENT STATEMENT

Date Of Report	18/02/2019 12:12
Date Of Accident	17/02/2019 12:00
Exact Location Of Accident	PIE TOWARDS TUAS NEAR EXIT 12 (KPE/ECP)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJS2420P
Insured/Policyholder	
Name Of Registered Owner	ENG LIN KEE
NRIC No	S2620023G
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90228622
Alternative Phone No	OFFICE-90228622
Vehicle Particulars	
Manufacturer	HONDA
Model	FIT
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5072979184-03
Cover Note Number	
Driver	
Name of Driver	ENG LIN KEE
NRIC No	S2620023G
Date Of Birth	26/02/1958
Occupation	INDOOR
Date Of Driving Pass	01/08/1997
Driving Experience	21 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90228622
Fax Number	
Contact Number	OFFICE-90228622
Email Address	NOEMAIL

Address	BLK 451 #10-224 TAMPINES STREET 42
Postcode	520451
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) Involved in the accident	5
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : PASSENGER GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER STATEMENT (ATTENDED BY: JAMES NG)

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKP5771K
Vehicle Make/Model/Colour	LEXUS 15250
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	WONG WEE KIANG
NRIC/Passport Number	S7340365J
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SJT1285P
Vehicle Make/Model/Colour	BMW 320i
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number	SGP9894K
Vehicle Make/Model/Colour	HYUNDAI SONATA
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 4

Vehicle Registration Number	SDS31M
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	TAN PENG WEE
NRIC/Passport Number	S8634337A
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the Insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time:

18 FEB 2019

Driver's Signature

(If driver is not the policyholder)

Date & Time:




Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

NG WING KIN JAMES
S7927881E

Sketch Plan #2 Pg. 1



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 17/02/19, @ about 12pm, I am travelling PIE (Taus), near Exit 12 (KPE/ESP) / Bendermer / Kallang. The car ahead of me on lane (1) slow down and stopped. I too stopped with safe keeping distance. When suddenly, I felt an impact on my rear portion and the strong impact cause my vehicle to surge forward and hit on the front vehicle when I get down, I found myself in a 5 cars chain collision.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time: 18 FEB 2019

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: NG WING KIN JAMES
NRIC/FIN No.:

Enquire Vehicle & Owner Information (Vehicle No. SKP5771K As At 17 Feb 2019 / 12:00:00)

Search Reason: Insurance claim in relation to traffic accident
Law Firm Case No.: A14-10267/PW

Owner ID Type: Singapore NRIC
Owner ID: S7340365J
Owner Name: WONG WEE KIANG
Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes
Registered Block/House No.: 61
Registered Street Name: SUNSET WAY
Registered Unit No.: # 02 - 03
Registered Building Name: -
Registered Postal Code: 597086

Vehicle No.: SKP5771K
Make Description/Model: TOYOTA / LEXUS IS250 AUTO STD
Insurance Company Name: AXA INSURANCE PTE LTD



WIN WIN RENT-A-CAR PTE LTD

Invoice

SJS2420P
ENG LIN KEE
BLK 451 TAMPINES STREET 42
#10-224
S(520451)

Invoice No : WPLIN0002906
Invoice Date : 28/2/2019
Due Date : 28/2/2019
VHA No : 3148
Referral ID : H002

Description :	Amount
Rental for 11 Day/s @ \$110 per Day \$	1,210.00

Vehicle No : SLJ5121G

Vehicle Description : Toyota Altis 1.6 A

Rental Period : 17/02/2019 to 28/02/2019

Total Amount Payable : \$ 1,210.00

WIN WIN RENT-A-CAR PTE LTD

8 Kaki Bukit Ave 4 #06-04 Premier@Kaki Bukit Singapore 415875

Tel: 6315 8479 H/P: 9833 0807




VHA No: 3148

Invoice No: WPLIN 2906

Hirer's Vehicle No: SJS2420P

UEN: 201505115E

VEHICLE RENTAL AGREEMENT


HIRER'S PARTICULARS Name: (as in I/C) _____ NRIC / FIN No: _____ Address (Res): _____ _____ Name & Address of Employer: _____ _____ Occupation: _____ Driving Exp: _____ Singapore Driving Licence No: _____ Issue Date: _____ Date of Birth: _____ Tel: (O) _____ (R) _____ HP: _____ ADDITIONAL DRIVER'S PARTICULARS Name: (as in I/C) _____ NRIC / FIN No: _____ Address (Res): _____ _____ Occupation: _____ Driving Exp: _____ Singapore Driving Licence No: _____ Issue Date: _____ Date of Birth: _____ Tel: (O) _____ (R) _____ H/P: _____ VEHICLE CHECK LIST <div style="display: flex; align-items: center;"> <div style="writing-mode: vertical-rl; transform: rotate(180deg); font-size: small; margin-right: 5px;"> INDICATE: D - DENTS A - ACCIDENTS S - SCRATCHES </div> <div style="text-align: center;">  <div style="display: flex; justify-content: space-around; font-size: x-small;"> RIGHT FRONT TOP LEFT </div> </div> </div> MISSING / FAULTY ACCESSORIES / PARTS REMARKS : _____ _____	Vehicle No: SJS21214 Replace Veh No: _____ Mileage Out: 180496 Mileage Out: _____ Make & Model: HCT15 Auto / Manual Out : Date 17/2/19 Time: 1300 HIRE / PERIOD EXPIRY Time: _____ NON-WAIVER EXCESS=\$ 2000/- <table border="1" style="width:100%; border-collapse: collapse; font-size: x-small;"> <tr> <th colspan="3">CHARGES</th> <th></th> <th></th> </tr> <tr> <td>Daily</td> <td>@\$ 110</td> <td>per day</td> <td>\$1210</td> <td>-</td> </tr> <tr> <td>Weekly</td> <td>@\$</td> <td>per week</td> <td></td> <td></td> </tr> <tr> <td>Monthly</td> <td>@\$</td> <td>per month</td> <td></td> <td></td> </tr> <tr> <td>Hours</td> <td>@\$</td> <td>per hour</td> <td></td> <td></td> </tr> <tr> <td>Extension</td> <td>@\$</td> <td></td> <td></td> <td></td> </tr> <tr> <td colspan="3">Delivery/Collection Service</td> <td></td> <td></td> </tr> <tr> <td colspan="3" style="text-align: right;">SUB-TOTAL \$</td> <td></td> <td></td> </tr> </table> <table border="1" style="width:100%; border-collapse: collapse; font-size: x-small;"> <tr> <th colspan="10">PETROL LEVEL</th> </tr> <tr> <td>Out</td> <td>E</td> <td>1/8</td> <td>1/4</td> <td>3/8</td> <td>1/2</td> <td>5/8</td> <td>3/4</td> <td>7/8</td> <td>F</td> </tr> <tr> <td>In</td> <td>E</td> <td>1/8</td> <td>1/4</td> <td>3/8</td> <td>1/2</td> <td>5/8</td> <td>3/4</td> <td>7/8</td> <td>F</td> </tr> <tr> <td colspan="10">Fuel</td> </tr> <tr> <td colspan="10">Traffic / Parking Fines</td> </tr> <tr> <td colspan="3" style="text-align: right;">TOTAL CHARGES \$</td> <td></td> <td></td> </tr> </table> <div style="margin-top: 20px;">  <div style="border-bottom: 1px solid black; width: 100%;"></div> Hirer's Signature </div> <div style="margin-top: 20px;">  <div style="border-bottom: 1px solid black; width: 100%;"></div> Additional Driver's Signature </div>	CHARGES					Daily	@\$ 110	per day	\$1210	-	Weekly	@\$	per week			Monthly	@\$	per month			Hours	@\$	per hour			Extension	@\$				Delivery/Collection Service					SUB-TOTAL \$					PETROL LEVEL										Out	E	1/8	1/4	3/8	1/2	5/8	3/4	7/8	F	In	E	1/8	1/4	3/8	1/2	5/8	3/4	7/8	F	Fuel										Traffic / Parking Fines										TOTAL CHARGES \$				
CHARGES																																																																																																
Daily	@\$ 110	per day	\$1210	-																																																																																												
Weekly	@\$	per week																																																																																														
Monthly	@\$	per month																																																																																														
Hours	@\$	per hour																																																																																														
Extension	@\$																																																																																															
Delivery/Collection Service																																																																																																
SUB-TOTAL \$																																																																																																
PETROL LEVEL																																																																																																
Out	E	1/8	1/4	3/8	1/2	5/8	3/4	7/8	F																																																																																							
In	E	1/8	1/4	3/8	1/2	5/8	3/4	7/8	F																																																																																							
Fuel																																																																																																
Traffic / Parking Fines																																																																																																
TOTAL CHARGES \$																																																																																																

I have read and agree to the terms and condition on both sides of the agreement. If I have presented a charge/credit card for payment. I agree that all amounts payable under this agreement and for parking and traffic infringements may be billed to that account and my signature above will be considered to have been made on the charge/credit card voucher. All information I have given WIN WIN RENT-A-CAR PTE LTD in connection with this agreement is true.

***IMPORTANT**

1. VEHICLE IS STRICTLY PROHIBITED FOR "HIRE FOR REWARDS" USAGE SUCH AS UBER / GRABCAR / GRABSHARE ETC.
2. ONLY PERSON ABOVE 23 YEARS OF AGE WITH MORE THAN 2 YEARS DRIVING EXPERIENCE, AUTHORIZED, LICENSED AND SIGNING THIS AGREEMENT MAY DRIVE THE VEHICLE.
3. ALL PARKING AND TRAFFIC VIOLATIONS ARE THE RESPONSIBILITY OF THE HIRER. AN ADMINISTRATIVE CHARGE WILL BE LEVIED ON ANY TRAFFIC VIOLATIONS REDIRECTED.
4. THE HIRER SHALL BE LIABLE FOR EXCESS CHARGES FOR ANY LATE RETURN AT THE RATE SHOWN PER HOUR OR PER DAY, INCLUSIVE OF CDW AND/OR PAI WHERE APPLICABLE.
5. IN CASE OF ACCIDENT, THE HIRER SHALL REPORT TO RENTAL OFFICE IMMEDIATELY. IF THERE IS BODILY INJURIES, A POLICE REPORT MUST BE MADE WITHIN 24 HOURS.
6. VEHICLE IS STRICTLY FOR SINGAPORE USE ONLY AND MAY NOT BE DRIVEN OUT OF SINGAPORE WITHOUT PRIOR CONSENT OF THE COMPANY WIN WIN RENT-A-CAR PTE LTD.

RETURN OF VEHICLE. THE HIRER / DRIVER IS REQUIRED TO SIGN IN THE COLUMN " SIGNATURE OF HIRER / DRIVER " FAILING WHICH THE DAY AND TIME INSERTED BELOW SHALL BE DEEMED TO BE THE DAY AND TIME THE VEHICLE IS RETURNED TO WIN WIN RENT-A-CAR PTE LTD AND THE SAME SHALL BE ACCEPTED AS CONCLUSIVE EVIDENCE OF THE SAME AND SHALL NOT BE CHALLENGED OR QUESTIONED ON ANY ACCOUNT WHATSOEVER.

DATE IN	TIME IN	MILEAGE	CHECKED BY	REMARKS	
					 SIGNATURE OF HIRER/DRIVER

HIAP LEK AUTOMOBILE TRADING

160 SIN MING DRIVE

#05-17, SIN MING AUTOCITY

SINGAPORE 575722

TEL : 6453 1743

FAX : 6457 6181

FINAL REPAIR BILL

31ST JULY 2019

**To: MR ENG LIN KEE
C/O HIAP LEK AUTOMOBILE TRADING
BLK 160 SIN MING DRIVE
#05-17, SIN MING AUTOCITY
SINGAPORE 575722**

Vehicle No. SJS 2420P

**LUMP SUM REPAIR COST
(INCLUDING OF SUPPLYING PARTS, SPRAY
PAINTING AND LABOUR CHARGES, ETC)**

\$ 13,300.00

Grand Total:

\$ 13,300.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CS3/ASM19003120/Gtf3e2-1

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 13-09-2019



ATTN : WONG WEE FU

Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)

Insured Veh.	SKP 5771K	Veh. Inspected	SJS 2420P
Policy No.		Coverage (\$)	0.00
Claim No.	S9M01E6U	Excess (\$)	0.00
Assign From	WONG WEE FU	Assign Date	26/08/2019

2. Vehicle Particulars & Condition

Make & Model	HONDA FIT 1.3G	c.c	1339
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	GE61205623	Colour	GREY
Odometer	349732	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	175/70 R14	BRIDGESTONE	5 mm
L/H Front Tyre	175/70 R14	BRIDGESTONE	5 mm
R/H Rear Tyre	175/70 R14	BRIDGESTONE	5 mm
L/H Rear Tyre	175/70 R14	BRIDGESTONE	5 mm

4. Description of Damages

THE VEHICLE HAD COMPLETED ITS REPAIR WORKS. REPAIR CONDITION SEE DETAILS.
--

5. General Information

Accident Date	17/02/2019	Inspection Date	10/09/2019
Survey held at	160 SIN MING DRIVE #05-17		
Repairer	HIAP LEK AUTOMOBILE TRADING		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	10 Working Days
-------------------------------------	-----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJS 2420P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR TAILGATE	REPLACED	736.40	736.40
1	REAR TAILGATE GLASS MOULDING - TOP	REPLACED	35.00	35.00
1	REAR TAILGATE GLASS MOULDING - LOWER	REPLACED	78.00	41.20
1	REAR TAILGATE OUTER GARNISH	SERVICEABLE	119.30	-
1	REAR TAILGATE EMBLEM 'H' LOGO	SERVICEABLE	25.00	-
2	REAR TAILGATE NUMBER PLATE LAMP	SERVICEABLE	76.00	-
1	REAR TAILGATE OUTER HANDLE	SERVICEABLE	55.00	-
2	REAR TAILGATE HINGE RH / LH	SERVICEABLE	59.60	-
2	REAR TAILGATE DAMPER RH / LH	SERVICEABLE	272.40	-
1	REAR TAILGATE INNER TRIM BOARD	REPLACED	100.20	100.20
1	SET REAR TAILGATE INNER TRIM BOARD CLIP	REPLACED	45.00	45.00
1	REAR TAILGATE WIPER MOTOR	SERVICEABLE	238.00	-
1	REAR TAILGATE INNER LOCK	REPLACED	232.10	175.00
1	REAR BOOT WEATHERSTRIP	REPLACED	92.30	92.30
2	REAR TAIL LAMP RH / LH	REPLACED	412.40	412.40
1	REAR BUMPER	REPLACED	474.40	474.40
1	REAR BUMPER TOW COVER	REPLACED	12.60	12.60
1	REAR BUMPER IMPACT BRACKET RH	REPLACED	49.00	49.00
2	REAR BUMPER SIDE RETAINER RH / LH	REPLACED	33.00	33.00
1	SET REAR BUMPER CLIP	REPLACED	22.80	22.80
2	REAR TAIL LAMP INNER PANEL RH / LH	SERVICEABLE	360.00	-
1	REAR END PANEL	REPLACED	287.40	287.40
1	REAR END PANEL TOP GARNISH	REPLACED	60.80	60.80
1	REAR END PANEL BUZZER	REPLACED	132.60	132.60
2	REAR FENDER AIR VENT RH / LH	SERVICEABLE	68.00	-
2	REAR FENDER INNER TRIM RH / LH	REPLACED	500.00	500.00
2	SET REAR FENDER INNER TRIM CLIP RH / LH	REPLACED	72.00	35.00
1	REAR SPONGE TOOL TRAY	REPLACED	220.40	220.40
1	REAR SPARE TYRE WELL PANEL	SERVICEABLE	737.00	-
1	REAR EXHAUST SILENCER BOX	SERVICEABLE	462.40	-
2	REAR EXHAUST SILENCER BOX MOUNTING	SERVICEABLE	25.00	-

Report Ref No. CS3/ASM19003120/Gtf3e2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT BONNET	REPLACED	433.80	433.80
2	FRONT BONNET HINGE RH / LH	SERVICEABLE	62.80	-
2	FRONT BONNET WEATHERSTRIP RH / LH	SERVICEABLE	30.00	-
1	FRONT BONNET LOCK	REPLACED	90.60	90.60
1	FRONT GRILLE	REPLACED	137.50	137.50
1	FRONT GRILLE EMBLEM 'H' LOGO	REPLACED	24.00	24.00
1	SET FRONT GRILLE CLIP	REPLACED	15.20	15.20
2	FRONT HEAD LAMP RH / LH	REPLACED	1,170.00	1,170.00
2	FRONT HEAD LAMP LOWER BRACKET RH / LH	REPLACED	55.00	55.00
1	FRONT BUMPER	REPLACED	523.50	458.50
1	FRONT BUMPER TOW COVER	SERVICEABLE	14.50	-
1	FRONT BUMPER LOWER CENTRE GRILLE	REPLACED	119.60	119.60
1	FRONT BUMPER LOWER MOULDING	SERVICEABLE	115.10	-
1	FRONT BUMPER REINFORCEMENT	REPLACED	253.90	173.30
2	FRONT BUMPER SIDE RETAINER RH / LH	REPLACED	27.00	27.00
1	SET FRONT BUMPER CLIP	REPLACED	22.80	22.80
1	FRONT SUPPORT PANEL ASSY	REPLACED	381.90	381.90
1	AIR CON CONDENSER	REPLACED	762.80	762.80
1	AIR CON FAN COWLING	SERVICEABLE	91.00	-
1	AIR CON FAN BLADE	SERVICEABLE	44.90	-
1	AIR CON FAN MOTOR	SERVICEABLE	233.60	-
1	RADIATOR ASSY	REPLACED	1,386.20	1,150.90
1	RADIATOR RESERVE TANK	SERVICEABLE	45.00	-
2	RADIATOR TOP MOUNTING	REPLACED	30.00	30.00
1	RADIATOR FAN COWLING	REPLACED	89.30	89.30
1	RADIATOR FAN BLADE	SERVICEABLE	54.80	-
1	RADIATOR FAN MOTOR	SERVICEABLE	309.80	-
1	WIPER TANK	SERVICEABLE	70.00	-
1	WIPER TANK NECK	SERVICEABLE	35.50	-
1	BATTERY COVER	SERVICEABLE	86.00	-
1	BATTERY TRAY	SERVICEABLE	22.30	-
	LESS 20% DISCOUNT		-	-1,721.54
			12,832.50	6,886.16

Report Ref No. CS3/ASM19003120/Gtf3e2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>SPECIAL NETT ITEMS</u>			
1	REAR TAILGATE GLASS SEALANT (SN)	REPLACED	70.00	40.00
1	REVERSE SENSOR (SN)	REPLACED	350.00	200.00
1	REAR SPARE TYRE WELL PANEL SEALANT (SN)	SERVICEABLE	200.00	-
1	FRONT NUMBER PLATE C/W FRAME (SN)	REPLACED	50.00	40.00
2	AIR HORN (SN)	SERVICEABLE	220.00	-
1	RADIATOR COOLANT (SN)	REPLACED	80.00	30.00
			970.00	310.00
	<u>LABOUR</u>			
	TO STRAIGHTEN AND PANEL BEATING REAR RH / LH FENDER, REAR CHASSIS FRAME MEMBER, FRONT RH / LH FENDER, FRONT CHASSIS FRAME MEMBER, REAR AND FRONT FRAME MEMBERS. TO CUT / WELD REAR END PANEL, REAR SPARE TYRE WELL PANEL AND FRONT SUPPORT PANEL. TO REMOVE AND REFIT ABOVE PARTS.		3,360.00	1,400.00
	TO PUTTY, RE-SPRAY PAINTING AND POLISH AFFECTED AREAS.		2,750.00	1,400.00
	TO CHECK AND RECTIFY WIRING SYSTEM.		120.00	30.00
	TO RUST PROOF AFFECTED AREAS.		180.00	80.00
	TO REMOVE AND REFIT REAR TAILGATE GLASS.		150.00	120.00
	TO REMOVE, TRANSFER AND REFIT REAR TAILGATE COMPONENTS.		150.00	60.00
	TO REMOVE AND REFIT REAR EXHAUST SILENCER BOX.	NOT NECESSARY	150.00	-
	TO REMOVE, REFIT AIR CON CONDENSER AND RECHARGE AIR CON GAS.		150.00	120.00
			7,010.00	3,210.00
	GRAND TOTAL		20,812.50	10,406.16
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			8,300.00

Report Ref No. CS3/ASM19003120/Gtf3e2-1

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.