

12/10/19

ASS. REC. NO.

REF: es/CTI19014972/Gtd30e

Special Instructions:

Envelope: Auto Store

ASSIGNMENT (Office)

From (Person): Chong Boon Sen of CTI Date/Time: 23/8/19 @ 5:17pm

Estimated Cost: _____ Bill to: _____

QD / TP / RES / TP RES / QD RES / EVA / INV / RV / CS

To Inspect Vehicle No: FV1001D Insured: SKX 3784U

at Workshop n/s Sunfu Motor Tel: 6744 7753

of 1 Kelai Bukit Ave 6 #02-43

Policy No: DMPCSN16747418022 Claim No: SNM19D203758C02

Sum Insured: _____ Excess: _____

Make of Vehicle: _____ D.O.A. 12/08/2019
(Client's Record)

CA / REV / REP. / REV 24 HRS H.O.D. Endowment: _____

Date/Time: 11:37am @ 26/8/19 Person Contacted: Mr. James Vehicle: IN/OUT

Date/Time	Action/Instruction
	Inspected (✓)
	FV1001D-X
	SKX 3784U - NA / CTI 17019737/hf
	DOA 12/10/2017

ASS. REC. BY:

6ul

REF:

CTI

ASSIGNMENT

From

Date

26/8/2019

Veh No:

FV10010

Yr Regr:

21 Nov 2018

Estimated Cost:

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To inspect Vehicle No:

FV10010

Make:

Yamaha TMAX530cc 530

at Workshop n/s

Sunfu Motor

Colour:

Black

A/C: Insured / Std / NI / NA

of

1 Kelki Bukit Ave 6 # 02-43

Sp. Reading

-

T/Radio: Insured / Std / NI / NA

Insured:

Autobuy

Eng/No:

C/No:

JYAST 1450000-15645

Policy No.

Gen. Cond: Good / Fair / Poor / Burnt

Claims No.

Steering: In order / Jammed / Leaked / Burnt or

Sum Insured:

Excess:

Brake: In order / Jammed / Leaked / Burnt or

(Client's Record)

Modi: Nil / S/Rim / STD A/Rim or

Make of Veh:

Tyre Size:

F: 120/70 R15

R: 160/60 R15

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

<input checked="" type="checkbox"/> N/S	<input type="checkbox"/> O/S
<input type="checkbox"/>	<input type="checkbox"/>

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Bal. or Market Value:

Front

Rear

IDAC Accident Rpt:

Consistent? : Yes or No

R/Bal.

φ mm

R/Bal.

φ mm

GIA / PR Seen:

Consistent? : Yes or No

L/Bal.

φ mm

L/Bal.

φ mm

Est. Repairs:

2 days

Res.: Yes or No

D.O.A.

D.O.I.

26-08-19

Lum Sum:

%

3 Val.: Yes or No

Survey held at

w/s

4:30 pm

CA / REV / REP. / 24 HRS hp)

Vehicle: IN / OUT

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Date:

Person Contacted:

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

29/10

Finalised \$ 4164 with Yeidao. (Red 738: 15%)

RECEIVED 05 NOV 2019

Signature
5/11/2019

Date/Time, File Pass to?

 : Prel. Report
 : Final Report

Days Of Repair: 2

5/11 Typist

Resurvey No. of Trip: 2

Date/Time, File Return to?

Add Fee:

- : Site Insp (\$)
- : Interview (\$)
- : Tech Invt (\$)
- : Wheel chng (\$)

Survey Fee:

Transportation:

3 + Rd. St

Flores

10000

TOTAL

770

770

Report Format:

TP

Lump Sum / L.S. (\$)

4164

Nivitha (LKK Auto)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Friday, 23 August 2019 5:17 PM
To: Lilian Chia
Cc: anna; assignments
Subject: RE: ACCIDENT INVOLVING OUR INSURED VEHICLE FV1001D AND SKX3784U ON 12/08/2019 / our ref: SNM19D203758

WITHOUT PREJUDICE

Dear Sir,

We will be assigning M/s LKK Auto Consultants Pte Ltd to survey your client's vehicle.

Aside to LKK,

Please proceed to survey the third party vehicle on WP basis.

Thank you.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG 3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Lilian Chia [mailto:sanfumotor0243@gmail.com]

Sent: Friday, 23 August, 2019 5:11 PM

To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>

Cc: anna <anna@sanfumotor.com.sg>

Subject: Re: ACCIDENT INVOLVING OUR INSURED VEHICLE FV1001D AND SKX3784U ON 12/08/2019 / our ref: SNM19D203758

Dear Sir,

You decide I trust you. I am new in this market

On Fri, Aug 23, 2019 at 4:59 PM Chong Boon Sen <boonsen.chong@sg.cntaiping.com> wrote:

Without Prejudice,

Dear Lilian,

You choose LKK/LBS/STA?

Chong Boon Sen

Claims Executive

Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909

DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG 3 Anson Road #16-00 Springleaf Tower Singapore 079909

DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Lilian Chia [<mailto:sanfumotor0243@gmail.com>]

Sent: Friday, 23 August, 2019 4:57 PM

To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>

Cc: anna <anna@sanfumotor.com.sg>

Subject: Re: ACCIDENT INVOLVING OUR INSURED VEHICLE FV1001D AND SKX3784U ON 12/08/2019 / our ref: SNM19D203758

Dear Sir,

Yes, please proceed. Thank you

On Fri, Aug 23, 2019 at 4:54 PM Chong Boon Sen <boonsen.chong@sg.cntaiping.com> wrote:

WITHOUT PREJUDICE

Dear Sir,

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Chong Boon Sen

Claims Executive

Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909

DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平狮城 Taiping SG 3 Anson Road #16-00 Springleaf Tower Singapore 079909

DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Lilian Chia [mailto:sanfumotor0243@gmail.com]

Sent: Friday, 23 August, 2019 3:28 PM

To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>

Cc: Feedback of China Taiping Insurance <feedback@sg.cntaiping.com>; anna <anna@sanfumotor.com.sg>

Subject: Re: ACCIDENT INVOLVING OUR INSURED VEHICLE FV1001D AND SKX3784U ON 12/08/2019 / our ref: SNM19D203758

Dear Sir,

We would like to arrange for a Pre-Inspection for the bike above.

I have attach the Assessment for repair and some other documents for you to view.

Hope to hear from you soon.

On Wed, Aug 21, 2019 at 4:34 PM Chong Boon Sen <boonsen.chong@sg.entaiping.com> wrote:

Without prejudice

Dear Sir,

Would understand you are claiming for third party property damage.

Please submit your Letter of Demand with all supporting documents and quote our reference and attention to our office address as below.

Thank you.

Chong Boon Sen

Claims Executive

Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909

DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平獅城 Taiping SG 3
Anson Road #16-00 Springleaf Tower Singapore 079909

DID: (65) 63896171 | M. (65) XXXX XXXX | F: (65) 6222 1033

From: Lilian Chia [mailto:sanfumotor0243@gmail.com]
Sent: Wednesday, 21 August, 2019 12:13 PM
To: Feedback of China Taiping Insurance <feedback@sg.cntaiping.com>
Cc: DL-CLAIMS <claims@sg.cntaiping.com>; anna <anna@sanfumotor.com.sg>
Subject: ACCIDENT INVOLVING OUR INSURED VEHICLE FV1001D AND SKX3784U ON 12/08/2019

Dear All,

Dear Sir,

Would like to inform that we would like to made a claim for the vehicel number above, may i know how can we start, first time claiming your company.

We are still preparing the Assessment For Repair.

I have attach some info. Hope to hear from you soon.

--

Thank You

Lilian Chia | Direct line +65 9061 3299

SANFU MOTOR PTE LTD

1 Kaki Bukit Ave 6, #02-43, Autobay@Kaki Bukit, Singapore 417883

Tel: (65) 6744 7753 | Fax: (65) 6744 6010 | Co. Reg. No. 200612487G

Business Hours: Mon–Fri: 9am to 7pm | Sat: 9am to 6pm | Sun & Public Holidays Closed



This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

--

Thank You

Lilian Chia | Direct line +65 9061 3299

SANFU MOTOR PTE LTD

1 Kaki Bukit Ave 6, #02-43, Autobay@Kaki Bukit, Singapore 417883

Tel: (65) 6744 7753 | Fax: (65) 6744 6010 | Co. Reg. No. 200612487G

Business Hours: Mon–Fri: 9am to 7pm | Sat: 9am to 6pm | Sun & Public Holidays Closed



This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

--
Thank You

Lilian Chia | Direct line +65 9061 3299

SANFU MOTOR PTE LTD

1 Kaki Bukit Ave 6, #02-43, Autobay@Kaki Bukit, Singapore 417883

Tel: (65) 6744 7753 | Fax: (65) 6744 6010 | Co. Reg. No. 200612487G

Business Hours: Mon–Fri: 9am to 7pm | Sat: 9am to 6pm | Sun & Public Holidays Closed



This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

--
Thank You

Lilian Chia | Direct line +65 9061 3299

SANFU MOTOR PTE LTD

1 Kaki Bukit Ave 6, #02-43, Autobay@Kaki Bukit, Singapore 417883

Tel: (65) 6744 7753 | Fax: (65) 6744 6010 | Co. Reg. No. 200612487G

Business Hours: Mon–Fri: 9am to 7pm | Sat: 9am to 6pm | Sun & Public Holidays Closed



This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	15/08/2019 17:14
Date Of Accident	12/08/2019 10:25
Exact Location Of Accident	TEBAN GARDEN RD BESIDE BLK 39
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FV1001D
Insured/Policyholder	
Name Of Registered Owner	MOHAMAD SYAHMAN BIN AHMAD
NRIC No	S8102329H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-93692694
Alternative Phone No	OFFICE-93692694

Vehicle Particulars

Manufacturer	YAMAHA
Model	TMAX 530 DX

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category MOTORCYCLE

Insurance Company

Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	D18MTMC01007494
Cover Note Number	

Driver

Name of Driver	MOHAMAD SYAHMAN BIN AHMAD
NRIC No	S8102329H
Date Of Birth	22/01/1981
Occupation	INDOOR
Date Of Driving Pass	31/03/2007
Driving Experience	12 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93692694
Fax Number	
Contact Number	OFFICE-93692694
E-Mail Address	NOEMAIL

Address	BLK 762 PASIR RIS ST 71 #08-226
Postcode	510762
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD ON COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TRAFFIC POLICE DIVISION HQ
Police Station Address	ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 65470000 - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT: T/20190813/2126.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKX3784U
Vehicle Make/Model/Colour	
Details Of Properties	VEHICLE B
Vehicle Category	PRIVATE CAR
Name of Driver	ZENG HUAQIANG
NRIC/Passport Number	S7269762F
Contact Number	96712758
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name	MOHAMAD SYAHMAN BIN AHMAD
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	FV1001D
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	YES
Address	
Postcode	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN




DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


As refer to police report.

DECLARATION

We declare the foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



**SINGAPORE
POLICE FORCE**



T/20190813/2126

1 of 3

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20190813/2126

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 13/08/2019 16:51		Vide Report No.:		Station Diary No.:	
Informant's Particulars					
Name of Informant: MOHAMAD SYAHMAN BIN AHMAD			Address: APT BLK 762 PASIR RIS STREET 71 #08-226 SINGAPORE 510762		
ID Type / ID No.: NRIC NO / S8102329H			Contact No.:		Mobile: 93692694
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 38	Date of Birth: 22/01/1981	Type of Informant: Rider		
Race: Malay		Language:		Institution / School Name:	
Occupation: Taxi driver		Driving Licence Information: Class:		Date of Expiry:	

General Information of the Accident				
Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 12/08/2019 10:25	Type of Location:
Location: Along Road 1 TEBAN GARDENS ROAD MAIN ROAD OF BLOCK 39				
Weather:		Road Surface:		Road Speed Limit:
Traffic Flow:		Traffic Control:		Traffic Volume:
Type of Collision:				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FV1001D	Motorcycle	YAMAHA	TMAX530(D X)	Black		0
SKX3784U		HONDA	CIVIC 1.6 VTIS A/T ABS D/AIRBAG 2WD			0



**SINGAPORE
POLICE FORCE**



T/20190813/2126

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

2 of 3

Report No. T/20190813/2126

CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
FV1001D	TENET SOMPO INSURANCE PTE. LTD.	D18MTMC0100749 4	21/11/2018	20/11/2019

Details of Person Involved				
Any Pedestrian Involved: No				
No. of Pedestrians Injured: NIL			Use of Pedestrian Crossing: NA	
Rider				
Name	MOHAMAD SYAHMAN BIN AHMAD		ID No.	S8102329H
Related Vehicle	FV1001D (Motorcycle)		Contact No.	93692694
Hospital/Clinic	NG TENG FONG GENERAL HOSPITAL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	12/08/2019		Date Discharge	13/08/2019
No. of Days granted Medical Leave	13		Degree of Injury	NIL
Driver				
Name	ZENG HUAQIANG		ID No.	S7269762F
Related Vehicle	SKX3784U		Contact No.	96712758
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave	NIL		Degree of Injury	NIL

Brief Details.

ON THE STATED TIME, DATE AND LOCATION,
IT WAS A 2 LANE ROAD AND I WAS TRAVELLING ON THE RIGHT LANE AS THERE WAS ANOTHER CAR ON THE LEFT LANE WANTED TO ENTER INTO A CARPARK NEARBY. AS I NEARED TO THE CARPARK ENTRANCE, A CAR WHICH WAS EXITING THE CARPARK, CAME OUT AND MADE A RIGHT TURN THUS COLLIDED ONTO MY LEFT PORTION WHILE I WAS RIDING STRAIGHT. ONE OF THE PASSER BY ASSISTED ME AND I MADE MY WAY TO THE KERB AND THEN CALLED FOR THE AMBULANCE. SOON RESOURCE ARRIVED AND CONVEYED ME TO THE NEAREST HOSPITAL.



**SINGAPORE
POLICE FORCE**



T/20190813/2126

3 of 3

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000




Report No. T/20190813/2126

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: TP / MOHAMED ANWAR BIN MOHAMED IBRAHIM	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 13/08/2019 16:51
Officer In Charge Of Case: TP / GIT / Sr Staff Sgt MOHAMMED FEROUZ BIN HUSSIEN Contact No.: 65476206	Classification Of Case: 
Authentication Stamp NP168	Signature: 



ASSESSMENT FOR REPAIR : FV1001D
YAMAHA TMAX530(DX)
COE EXPIRY :

Lump Sum

Part by Part

Qty	Description
1	CAP - (exhans end. RPL) X NN
1	COVER,1 - Engine cover (41) - Cut
1	SEAT,RAIL - ATA - Cut
1	STAY,FENDER 1 - Cut
1	COVER,SIDE 5 - ll.
1	COVER,SIDE 1 - Cut.
1	COVER,SIDE 3 - Cut.
1	MOLE,SIDE COVER 1 - Cut.
1	HANDLE COMP. - BT
1	END,GRIP - Cut
1	LEVER 1 - Cut.
1	FOOTREST,REAR 1 - Cut.
1	STAND,MAIN - Cut.
1	STAND,SIDE - Cut.
1	BOARD,FOOTREST - Cut.
1	COVER 1 - Cut - emblem
1	PANEL,CONSOLE 1 - Cut.
1	DUCT,AIR - CRA
1	FENDER,INNER 2 - BR
1	LEG SHIELD 1 - CRA
1	LID - BT
1	PANEL 1 - Cut.
1	EMBLEM - Cut.
1	BODY,COWLING - Cut
1	PLATE,WINDSHIELD - Cut
1	PANEL,INNER 2 - R - BT
1	COVER,FRONT - Cut.
1	FRONT FLASHER LIGHT ASSY 1 - CRA.
1	COVER,FOOTREST - Mis
1	TANK RECOVER - R
1	CAP - Mis
1	COVER - Cut.

Repairer's Estimate	1st Survey	Repair Survey	Final Survey
150.00			
25.00			
375.00			
37.50			
100.00			
225.00			
250.00			
137.50			
125.00			
25.00			
75.00			
37.50			
375.00			
200.00			
150.00			
100.00			
137.50			
75.00			
100.00			
262.50			
25.00			
225.00			
30.00			
462.50			
17.50			
87.50			
350.00			
187.50			
50.00			
75.00			
12.50			
25.00			

4,510.00

4360
 10% : 3924

Special Nett Items

0.00		
0.00		

0.00

Total Parts 4,510.00

Labour Charges

1	TOWING	60.00	40
1	LTA SERACH	2.00	2 X NN
4	Workmanship to renew damage parts	380.00	200
		<u>442.00</u>	

Total Parts & Labours Concluded 4,952.00

Total : 4164

2-3 Days.

part by part.

After repair photos.

Guo Qiang - 82880182

26/8/19.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SANFU MOTOR PTE LTD

Company Reg No.: 200612487G

1 Kaki Bukit Ave 6, #02-43, AutoBay@Kaki Bukit, Singapore 417883

Direct Line: 9061 3299 Tel: (65) 6744 7753 Fax: (65) 6744 6010

Email: sanfumotor0243@gmail.com

...CLAIM SUBFOLDER...(Pending for Survey Report)























































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	05 Nov 2019		05 Nov 2019 09:55 Edit Adj Rpt	S\$4,164.00 Edit Estimates	S\$4,164.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	-, Co. Reg. No.: -								
Main Claimant:	MOHAMAD SYAHMAN BIN AHMAD , ID: S8102329H								
Vehicle Reg. No.:	FV1001D	Date of Loss:	12/08/2019 10:00 - :59 [8 Months and 22 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D203758C02	Policy/Cover Note No.:	DMPCSN16747418022						
Vehicle Reg. No. (Insured):	SKX3784U	Policy No. (Claimant):	D18MTMC01007494						
		Excess:	S\$0.00						
Repairer:	Sanfu Motor Pte Ltd (HQ) 141 Kaki Bt Ave 1 Shun Li Industrial Park, 416005 Kaki Bukit - Tel: 67447753								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Claimant's Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 14/11/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*FV1001D (SNM19D203758C02)
[SKX3784U]
TP
MOHAMAD SYAHMAN BIN AHMAD
Aug 12 2019 10:00AM
[-]
Sanfu Motor Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View
									View in Browser
Assessment Reports									1 per page
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)		Thumbnail	Print				
1	15/08/19 17:25	Accident Statement	1	Load HTM					
Photos/Images									3 per page
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)		Thumbnail	Print				
1	15/08/19 17:24	Driving License <small>[Linked Accident Report Documents]</small>	1	Load JPG	<input checked="" type="checkbox"/>				
2	15/08/19 17:24	CI <small>[Linked Accident Report Documents]</small>	1	Load JPG	<input checked="" type="checkbox"/>				
3	15/08/19 17:24	Accident Photo <small>[Linked Accident Report Documents]</small>	1	Load JPG	<input checked="" type="checkbox"/>				
4	15/08/19 17:24	Accident Photo <small>[Linked Accident Report Documents]</small>	1	Load JPG	<input checked="" type="checkbox"/>				
5	15/08/19 17:24	Accident Photo <small>[Linked Accident Report Documents]</small>	1	Load JPG	<input checked="" type="checkbox"/>				
6	15/08/19 17:24	Accident Photo <small>[Linked Accident Report Documents]</small>	1	Load JPG	<input checked="" type="checkbox"/>				
7	15/08/19 17:24	Accident Photo <small>[Linked Accident Report Documents]</small>	1	Load JPG	<input checked="" type="checkbox"/>				
8	15/08/19 17:24	Accident Photo <small>[Linked Accident Report Documents]</small>	1	Load JPG	<input checked="" type="checkbox"/>				
9	15/08/19 17:24	Accident Photo <small>[Linked Accident Report Documents]</small>	1	Load JPG	<input checked="" type="checkbox"/>				
10	15/08/19 17:24	Accident Photo <small>[Linked Accident Report Documents]</small>	1	Load JPG	<input checked="" type="checkbox"/>				
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print				
1	05/11/19 10:21	General View	1	Load JPG	<input checked="" type="checkbox"/>				
2	05/11/19 10:21	General View	1	Load JPG	<input checked="" type="checkbox"/>				
3	05/11/19 10:21	General View	1	Load JPG	<input checked="" type="checkbox"/>				
4	05/11/19 10:21	General View	1	Load JPG	<input checked="" type="checkbox"/>				
5	05/11/19 10:21	General View	1	Load JPG	<input checked="" type="checkbox"/>				
6	05/11/19 10:21	General View	1	Load JPG	<input checked="" type="checkbox"/>				
7	05/11/19 10:21	General View	1	Load JPG	<input checked="" type="checkbox"/>				
8	05/11/19 10:21	General View	1	Load JPG	<input checked="" type="checkbox"/>				
9	05/11/19 10:21	General View	1	Load JPG	<input checked="" type="checkbox"/>				
10	05/11/19 10:21	General View	1	Load JPG	<input checked="" type="checkbox"/>				
11	05/11/19 10:21	General View	1	Load JPG	<input checked="" type="checkbox"/>				
12	05/11/19 10:21	General View	1	Load JPG	<input checked="" type="checkbox"/>				
13	05/11/19 10:21	General View	1	Load JPG	<input checked="" type="checkbox"/>				
14	05/11/19 10:21	General View	1	Load JPG	<input checked="" type="checkbox"/>				
15	05/11/19 10:21	General View	1	Load JPG	<input checked="" type="checkbox"/>				
16	05/11/19 10:21	General View	1	Load JPG	<input checked="" type="checkbox"/>				
17	05/11/19 10:21	General View	1	Load JPG	<input checked="" type="checkbox"/>				
18	05/11/19 10:21	General View	1	Load JPG	<input checked="" type="checkbox"/>				
19	05/11/19 10:21	General View	1	Load JPG	<input checked="" type="checkbox"/>				
20	05/11/19 10:21	General View	1	Load JPG	<input checked="" type="checkbox"/>				
21	05/11/19 10:21	General View	1	Load JPG	<input checked="" type="checkbox"/>				
22	05/11/19 10:21	General View	1	Load JPG	<input checked="" type="checkbox"/>				
23	05/11/19 10:21	General View	1	Load JPG	<input checked="" type="checkbox"/>				
24	05/11/19 10:21	General View	1	Load JPG	<input checked="" type="checkbox"/>				
25	05/11/19 10:21	General View	1	Load JPG	<input checked="" type="checkbox"/>				

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)	Thumbnail	Print
26	05/11/19 10:21	General View	 Load JPG	<input checked="" type="checkbox"/>
27	05/11/19 10:21	General View	 Load JPG	<input checked="" type="checkbox"/>
28	05/11/19 10:21	General View	 Load JPG	<input checked="" type="checkbox"/>
29	05/11/19 10:21	General View	 Load JPG	<input checked="" type="checkbox"/>
30	05/11/19 10:21	General View	 Load JPG	<input checked="" type="checkbox"/>
31	05/11/19 10:21	General View	 Load JPG	<input checked="" type="checkbox"/>
32	05/11/19 10:21	General View	 Load JPG	<input checked="" type="checkbox"/>
33	05/11/19 10:21	General View	 Load JPG	<input checked="" type="checkbox"/>
34	05/11/19 10:21	General View	 Load JPG	<input checked="" type="checkbox"/>
35	05/11/19 10:21	General View	 Load JPG	<input checked="" type="checkbox"/>
36	05/11/19 10:21	General View	 Load JPG	<input checked="" type="checkbox"/>
37	05/11/19 10:21	General View	 Load JPG	<input checked="" type="checkbox"/>
38	05/11/19 10:21	General View	 Load JPG	<input checked="" type="checkbox"/>
39	05/11/19 10:21	General View	 Load JPG	<input checked="" type="checkbox"/>
40	05/11/19 10:21	General View	 Load JPG	<input checked="" type="checkbox"/>
41	05/11/19 10:21	General View	 Load JPG	<input checked="" type="checkbox"/>
42	05/11/19 10:21	General View	 Load JPG	<input checked="" type="checkbox"/>
43	05/11/19 10:21	General View	 Load JPG	<input checked="" type="checkbox"/>
44	05/11/19 10:21	General View	 Load JPG	<input checked="" type="checkbox"/>
45	05/11/19 10:21	General View	 Load JPG	<input checked="" type="checkbox"/>
46	05/11/19 10:21	General View	 Load JPG	<input checked="" type="checkbox"/>
47	05/11/19 10:21	General View	 Load JPG	<input checked="" type="checkbox"/>
48	05/11/19 10:21	General View	 Load JPG	<input checked="" type="checkbox"/>
49	05/11/19 10:21	General View	 Load JPG	<input checked="" type="checkbox"/>
50	05/11/19 10:21	General View	 Load JPG	<input checked="" type="checkbox"/>
51	05/11/19 10:21	General View	 Load JPG	<input checked="" type="checkbox"/>
52	05/11/19 10:21	General View	 Load JPG	<input checked="" type="checkbox"/>
53	05/11/19 10:21	General View	 Load JPG	<input checked="" type="checkbox"/>
54	05/11/19 10:21	General View	 Load JPG	<input checked="" type="checkbox"/>
55	05/11/19 10:21	General View	 Load JPG	<input checked="" type="checkbox"/>
56	05/11/19 10:21	General View	 Load JPG	<input checked="" type="checkbox"/>
57	05/11/19 10:21	General View	 Load JPG	<input checked="" type="checkbox"/>
58	05/11/19 10:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	05/11/19 10:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	05/11/19 10:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	05/11/19 10:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	05/11/19 10:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	05/11/19 10:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	05/11/19 10:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	05/11/19 10:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	05/11/19 10:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	05/11/19 10:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	05/11/19 10:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	05/11/19 10:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	05/11/19 10:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	05/11/19 10:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	05/11/19 10:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	05/11/19 10:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	05/11/19 10:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	05/11/19 10:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	05/11/19 10:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	05/11/19 10:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	05/11/19 10:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	05/11/19 10:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	05/11/19 10:21	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
81	05/11/19 10:21	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)	Thumbnail	Print
82	05/11/19 10:21	Reinspection Photo		<input checked="" type="checkbox"/>
83	05/11/19 10:21	Reinspection Photo		<input checked="" type="checkbox"/>
84	05/11/19 10:22	After Repair Photo		<input checked="" type="checkbox"/>
85	05/11/19 10:22	After Repair Photo		<input checked="" type="checkbox"/>
86	05/11/19 10:22	After Repair Photo		<input checked="" type="checkbox"/>
87	05/11/19 10:22	After Repair Photo		<input checked="" type="checkbox"/>
88	05/11/19 10:22	After Repair Photo		<input checked="" type="checkbox"/>
89	05/11/19 10:22	After Repair Photo		<input checked="" type="checkbox"/>
90	05/11/19 10:22	After Repair Photo		<input checked="" type="checkbox"/>
91	05/11/19 10:22	After Repair Photo		<input checked="" type="checkbox"/>
92	05/11/19 10:22	After Repair Photo		<input checked="" type="checkbox"/>
93	05/11/19 10:22	After Repair Photo		<input checked="" type="checkbox"/>
94	05/11/19 10:22	After Repair Photo		<input checked="" type="checkbox"/>
95	05/11/19 10:22	After Repair Photo		<input checked="" type="checkbox"/>
96	05/11/19 10:22	After Repair Photo		<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)	Thumbnail	Print
1	15/08/19 17:23	Sketch Plan <small>[Linked Accident Report Documents]</small>		<input type="checkbox"/>
2	15/08/19 17:23	Sketch Plan #2 <small>[Linked Accident Report Documents]</small>		<input type="checkbox"/>
3	15/08/19 17:23	Sketch Plan #3 <small>[Linked Accident Report Documents]</small>		<input type="checkbox"/>
4	15/08/19 17:23	Sketch Plan #4 <small>[Linked Accident Report Documents]</small>		<input type="checkbox"/>
5	15/08/19 17:23	Sketch Plan #5 <small>[Linked Accident Report Documents]</small>		<input type="checkbox"/>

Linked Accident Report Documents

View

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)	Thumbnail	Print
1	15/08/19 17:25	Accident Statement		<input type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)	Thumbnail	Print
1	15/08/19 17:24	Driving License		<input checked="" type="checkbox"/>
2	15/08/19 17:24	CI		<input checked="" type="checkbox"/>
3	15/08/19 17:24	Accident Photo		<input checked="" type="checkbox"/>
4	15/08/19 17:24	Accident Photo		<input checked="" type="checkbox"/>
5	15/08/19 17:24	Accident Photo		<input checked="" type="checkbox"/>
6	15/08/19 17:24	Accident Photo		<input checked="" type="checkbox"/>
7	15/08/19 17:24	Accident Photo		<input checked="" type="checkbox"/>
8	15/08/19 17:24	Accident Photo		<input checked="" type="checkbox"/>
9	15/08/19 17:24	Accident Photo		<input checked="" type="checkbox"/>
10	15/08/19 17:24	Accident Photo		<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)	Thumbnail	Print
1	15/08/19 17:23	Sketch Plan		<input type="checkbox"/>
2	15/08/19 17:23	Sketch Plan #2		<input type="checkbox"/>
3	15/08/19 17:23	Sketch Plan #3		<input type="checkbox"/>
4	15/08/19 17:23	Sketch Plan #4		<input type="checkbox"/>
5	15/08/19 17:23	Sketch Plan #5		<input type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119014972/GTD3E2

Date: 15/11/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN16747418022
Claimant Vehicle No :	FV1001D	Insured Vehicle No :	SKX3784U
Date of Loss:	12/08/2019	Nature of Claim: TP	Claim No: SNM19D203758C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FV1001D	Engine No:	J415E028267
Make & Model:	YAMAHA TMAX530, 530cc (DX)	Chassis No:	JYASJ145000015645
Reg. Date:	21/11/2018 (Man. Year: 2018)	Odometer:	0 km
Colour:	Black		
Engine Capacity:	530 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	120/70 R15	Rear Tyre Size:	160/60 R15
Front Left Side:	Dunlop 4 mm	Rear Left Side:	Dunlop 4 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,510.00	3,924.00	586.00	12.99
Miscellaneous Items	0.00	0.00	0.00	
Labour	442.00	240.00	202.00	45.70
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	4,952.00	4,164.00	788.00	15.91

INSPECTION

Date of Assignment:	05/11/2019		
Date Inspected:	28/08/2019	Inspected At:	Sanfu Motor Pte Ltd (HQ) 1 KAKI BUKIT AVENUE 6 #02-43 AUTOBAY @ KAKI BUKIT SINGAPORE 417883
Estimated Period of Repair:	2.0 days		

Adjuster: XING GUO QIANG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 15 Nov 2019)	
Parts:	N/A	YAMAHA TMAX530 530cc (DX) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FV1001D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*CAP (EXHAUST END RH)	Not Necessary	150.00 F	*- FL
2	1		*COVER, 1 (ENGINE COVER LH)	Cut	25.00 F	*25.00 FL
3	1		*STAY, FENDER 1	Cut	37.50 F	*37.50 FL
4	1		*COVER, SIDE 5	Deformed	100.00 F	*100.00 FL
5	1		*COVER, SIDE 1	Cut	225.00 F	*225.00 FL
6	1		*COVER, SIDE 3	Cut	250.00 F	*250.00 FL
7	1		*MOLE, SIDE COVER 1	Cut	137.50 F	*137.50 FL
8	1		*HANDLE COMP	Bent	125.00 F	*125.00 FL
9	1		*END, GRIP	Cut	25.00 F	*25.00 FL
10	1		*LEVER 1	Cut	75.00 F	*75.00 FL
11	1		*FOOTREST, REAR 1	Cut	37.50 F	*37.50 FL
12	1		*STAND, MAIN	Cut	375.00 F	*375.00 FL
13	1		*STAND, SIDE	Cut	200.00 F	*200.00 FL
14	1		*BOARD, FOOTREST	Cut	150.00 F	*150.00 FL
15	1		*COVER 1 (EMBLEM)	Cut	100.00 F	*100.00 FL
16	1		*PANEL, CONSOLE 1	Cut	137.50 F	*137.50 FL
17	1		*DUCT, AIR	Cracked	75.00 F	*75.00 FL
18	1		*FENDER, INNER 2	Broken	100.00 F	*100.00 FL
19	1		*LEG SHIELD 1	Cracked	262.50 F	*262.50 FL
20	1		*LID	Bent	25.00 F	*25.00 FL
21	1		*PANEL 1	Cut	225.00 F	*225.00 FL
22	1		*EMBLEM	Cut	30.00 F	*30.00 FL
23	1		*BODY, COWLING	Cut	462.50 F	*462.50 FL
24	1		*PLATE, WINDSHIELD	Cut	17.50 F	*17.50 FL
25	1		*PANEL, INNER 2	Bent	87.50 F	*87.50 FL
26	1		*COVER, FRONT	Cut	350.00 F	*350.00 FL
27	1		*FRONT FLASHER LIGHT ASSY 1	Cracked	187.50 F	*187.50 FL
28	1		*COVER, FOOTREST	Missing	50.00 F	*50.00 FL
29	1		*TANK RECOVER	Deformed	75.00 F	*75.00 FL
30	1		*CAP	Missing	12.50 F	*12.50 FL
31	1		*COVER	Cut	25.00 F	*25.00 FL
32	1		*SEAT, RAIL 1	Cut	375.00 F	*375.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	4,510.00	4,360.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	436.00
Total Parts (\$\$)	4,510.00	3,924.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TOWING	New	60.00	40.00
2	LTA SEARCH	New	2.00	0.00
3	WORKMANSHIP TO RENEW DAMAGE PARTS	New	380.00	200.00
Gross Labour Cost (S\$)			442.00	240.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >