

2019/08/01

ASS. REC. BY:

REF: CS3/A2G19014976/Hcf35

Special Instruction:

Surveyor: Hock Ann

ASSIGNMENT (Office)

From (Person): Chin Lee Ying

of

MG

Date/Time: 26/8/19 @ 9.17am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLM 2886L

Insured:

SMM 3308X

at Workshop in/s

platinum workz

Tel:

9238 9179

of

53 Ubi Avenue 1 #01-25

Policy No:

1900112929

Claim No:

7190750779SG

Sum Insured:

Excess:

Make of Veh:

D.O.A.

19/08/19

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

12:05pm 26/8/19

Person Contacted:

YS

Vehicle:

IN/OUT

Date/Time

Action/Instruction

Johnny (X)

SMM 3308X: NA/A2G19014517/24

D.O.A: 19/08/2019

SLM 2886L: NA/A2G19014517/24

D.O.A: 19/08/2019

Dismantle: 28/8/2019

After repair: 30/8/2019

ASS. REC. BY: H. Poon

REF: M19

PRS

# ASSIGNMENT

From:

Date:

26/8/2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLM 2886L

at Workshop m/s

platinum work

of

53 Ubi Ave 1 # 01-25

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5

days

Res.: Yes or No

Lump Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS (up)

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLM 2886 L

Yr Regn:

27/103/2017

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

NISSAN PULSAR 1.2 D14 (AT) C.C. 1137

Colour:

Black

A/C:

Insured / Std / NI / NA

Sp. Reading

56231/km

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

USKDDAC13U0098333

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/50/2R17

R:

205/50/2R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Frnt -> (Hankook) Rr -> (Hankook)

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

19/8/19

D.O.I.

26/8/19

Survey held at

Platinum

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

MU - 56870

PV - 44177

NV - 12600

\* Remarks: This case not Estimate  
do -> (PRS)

- MU 55-56

RECEIVED 04 SEP 2019

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 5

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

\$ + RS, \$

Photos

Others

TOTAL

Report Format: SAR

Lump Sum / L&J: (\$

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	26 Aug 2019 <a href="#">Edit Reg</a>		26 Aug 2019 00:00 <a href="#">Edit Adj Rpt</a>				<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>
------	-----------	---------------	-----------	--------------------------

### CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	Johnny Ch'ng		
Main Claimant:	TEO SUNNY, ID: S1476331G		
Vehicle Reg. No.:	SLM2886L	Date of Loss:	19/08/2019 21:00 - :59
Claim Type:	TP / 7190750779SG	Policy/Cover Note No.:	1900112929 (Comprehensive)
Vehicle Reg. No. (Insured):	SMM3308X	Policy No. (Claimant):	
		Excess:	
Repairer:	Platinum Werkz Pte Ltd (HQ) 53 Ubi Ave 1 01-25 Paya Ubi Industrial Park, 408934 Ubi - Tel: 6741 610		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Loh, Chee-Heng] Chee-Heng.Loh@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by LEE HOCK ANN] ... [Final Rpt due 04/09/2019]		

[View All](#)   [Compose Case Mail](#)


### ASSOCIATED MAIL RECEIVED

- AIG\_SG (27/08/2019): TP GIA REPORT

### ALL ASSOCIATED TASKS View All   Search Tasks   Create New Task   Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

**PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SMM3308X AND SLM2886L ON 19/08/...**

From: Chin, Lee-Ying  
To: assignments, Admin A  
Cc: Fong, Andy-SY  
Sent: 8/26/2019 9:17:31 AM  
Attachments:  GIA.PDF

HI LKK,

Kindly assist to survey after 11am today.

Thanks.

Best Regards

Lee Ying, Chin

AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1947

[Lee-Ying.Chin@aig.com](mailto:Lee-Ying.Chin@aig.com) | [www.aig.sg](http://www.aig.sg)

**From:** Li Ping [mailto:Prs.pd@sllawch.com]

**Sent:** Wednesday, August 21, 2019 5:28 PM

**To:** Hor, Yinnul

**Cc:** Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Parthiban, Theerthan; Subramaniam, Divyashni; Tong, Wahxin

**Subject:** [EXTERNAL] RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SMM3308X AND SLM2886L ON 19/08/2019

This message is from an external sender; be cautious with links and attachments.

**WITHOUT PREJUDICE**

Dear Sir/Mdm,

**ACCIDENT INVOLVING SLM2886L & SMM3308X ALONG SINGAPORE CUSTOM BEFORE SECOND LINK ON 19/08/2019 @ 21:00**

We refer to your letter dated **21 August 2019** confirming your intention to conduct a pre-repair survey on our client's vehicle **SLM2886L**.

We have instructions to reject your surveyor and propose to engage **Winson Goh from WG Appraisal Services**.

Please be informed that said vehicle can be inspected at:

Workshop: Platinumwerkz  
Address: 53 Ubi Avenue 1 #01-25 (Paya Ubi Industrial Park) Singapore 408934  
Contact Person: YS (HP: 9238 9179)

In the event you fail to conduct the pre-repair survey within the next 2 working days, excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will comm

For Surveyor: To initial after Completion

1<sup>st</sup> Inspection  
Appointed surveyor  
(Name & Siganature)  
Date & Time

2<sup>nd</sup> Inspection  
Appointed surveyor  
(Name & Siganature)  
Date & Time

3<sup>rd</sup> Inspection  
Appointed surveyor  
(Name & Siganature)  
Date & Time

Initial and/or legally privileged information. If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, arrive late or contain viruses. Therefore, we do not accept liability for any errors or omissions in the content of this message which may arise as a result of Internet transmission.

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	20/08/2019 13:59
Date Of Accident	19/08/2019 21:00
Exact Location Of Accident	SINGAPORE CUSTOM BEFORE SECOND LINK
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLM2886L
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TEO SUNNY
NRIC No	S1476331G
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-84887281
Alternative Phone No	OFFICE-84887281

### Vehicle Particulars

Manufacturer	NISSAN
Model	PULSAR 1.2L DIG-T
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100504868-02
Cover Note Number	

### Driver

Name of Driver	FRASER KIERAN HOEDEN
NRIC No	S9333068D
Date Of Birth	10/09/1993
Occupation	INDOOR
Date Of Driving Pass	02/05/2019
Driving Experience	0 YEAR AND 3 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-84887281
Fax Number	
Contact Number	OFFICE-84887281
EMail Address	NOEMAIL

Address	BLK 137 BISHAN STREET 12 #05-410
Postcode	570137
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	RELATIVE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : ZHANG QIN, KIMBERLY GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO STATEMENT.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	VIDEO FOOTAGE WITH DRIVER
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMM3308X
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	JOHNNY CHENG
NRIC/Passport Number	S2606795B
Contact Number	
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

No. Of Passenger (Including Driver)

#### DETAILS OF INJURED PERSON 1

Name FRASER KIERAN HOEDEN

Approximate Age

Injuries Sustain BODY

Injured person in which vehicle? SLM2886L

Were seat belts worn? YES

Was this injured conveyed to hospital by ambulance? NO

Address

Postcode

#### DETAILS OF INJURED PERSON 2

Name ZHANG QIN, KIMBERLY

Approximate Age

Injuries Sustain BODY

Injured person in which vehicle? SLM2886L

Were seat belts worn? YES

Was this injured conveyed to hospital by ambulance? NO

Address

Postcode



## Accident Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to rescind policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforsaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents, including their lawyers/law firms, which may be/located outside of Singapore, for one or more of the above purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (a) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, negotiations, law enforcement and government agencies as reasonably required for the purposes stated; or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(if driver is not the policyholder)  
Date & Time:


Reporting Centre Personnel's Signature  
Name:  
NRIC/IN No.:

# Accident Sketch Plan

VEH A SM2886L

VEH B SM3308X

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving ven A and going straight  
 on my line I ~~slow~~ slow down as I was approaching  
 a hump & all of a sudden I was hit by  
 vehicle B from the back vehicle B being SM3308X

## DECLARATION

(We declare the foregoing particulars are true in every respect.)

Policyholder's Signature  
 Date & Time:

Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time:

Reporting Centre Personnel's Signature  
 Name:  
 NRIC/ID No.:

[> Back to OneMotoring](#)

## Enquire Transfer Fee

### Vehicle Details

Vehicle No.:	SLM2886L
Vehicle Type:	P10 - Passenger Motor Car
Vehicle Attachment 1:	No Attachment
Vehicle Scheme:	Normal
Vehicle Make:	NISSAN
Vehicle Model:	PULSAR 1.2L DIG-T
Chassis No.:	VSKDDAC13U0098339
Propellant:	Petrol
Engine No.:	HRA2392250A
Engine Capacity:	1197 cc
Maximum Power Output:	85.0 kW ( 113 bhp)
Maximum Laden Weight:	1750 kg
Unladen Weight:	1265 kg
Year Of Manufacture:	2016
Original Registration Date:	27 Mar 2017
Lifespan Expiry Date:	-
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
Quota Premium:	\$50,889.00
COE Expiry Date:	26 Mar 2027
Road Tax Expiry Date:	26 Sep 2019
PARF Eligibility Expiry Date:	26 Mar 2027
Inspection Due Date:	26 Mar 2020
Intended Transfer Date:	29 Aug 2019
CO2 Emission:	119.00 (g/km)
CEV/VES Rebate Utilised	\$10,000.00
Amount:	
CO Emission:	-
HC Emission:	-
NOx Emission:	-
PM Emission:	-

The current road tax expiry is 26 Sep 2019. You may renew the road tax from 27 Jun 2019 with all pre-requisite(s) fulfilled. If the road tax is renewed after 26 Sep 2019, late renewal fee(s) will be imposed. Please use Enquire Road Tax Payable to check on the late fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

### Amount Payable (From 27 Sep 2019 to 26 Sep 2020)

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
<b>Sub Total:</b>			<b>25.00</b>
Nett Road Tax Amount (After Offsetting Over Payment):	254.00	-	254.00
<b>Total Amount Payable:</b>			<b>279.00</b>

### Amount Payable (From 27 Sep 2019 to 26 Sep 2020)

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
<b>Sub Total:</b>			<b>25.00</b>
Nett Road Tax Amount (After Offsetting Over Payment):	508.00	-	508.00
<b>Total Amount Payable:</b>			<b>533.00</b>

You may print this page for reference.

OK

Print

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type:

Singapore NRIC

Owner ID:

331G

### Vehicle Details

Vehicle No.:

SLM2886L

Vehicle to be Exported:

No

Intended Deregistration Date:

29 Aug 2019

Vehicle Make:

NISSAN

Vehicle Model:

PULSAR 1.2L DIG-T

Primary Colour:

Black

Manufacturing Year:

2016

Engine No.:

HRA2392250A

Chassis No.:

VSKDDAC13U0098339

Maximum Power Output:

85.0 kW (113 bhp)

Open Market Value:

\$17,541.00

Original Registration Date:

27 Mar 2017

First Registration Date:

27 Mar 2017

Transfer Count:

0

Actual ARF Paid:

\$7,541.00

→ 3770.5

### Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

26 Mar 2027

PARF Rebate Amount:

\$5,655.00

### Intended COE Rebate Details

COE Expiry Date:

26 Mar 2027

COE Category:

A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years):

10

QP Paid:

\$50,889.00

COE Rebate Amount:

\$38,522.00

Total Rebate Amount:

\$44,177.00

The information contained herein is correct as at 29 Aug 2019

OK Balance : 7 years 7 months

Depreciation: 7000

$7000 \div 12 = 583 \text{ months}$

$49000 + 4081 + 3770$   
 $= 56851$

MV - 56800  
 PV - 44177  
 NV - 12600

MV - 5556



Nissan Pulsar Price Range Depreciation 2017 Vehicle Type

Advanced Search

Home » Used Cars » Thrive Auto » Nissan Pulsar 1.2A DIG-T

## Nissan Pulsar 1.2A DIG-T

Overview Financial Accessories Similar Research Photos Map

<b>Price</b>	\$62,800		
<b>Depreciation</b>	\$7,340 /yr <small>View models with similar depre</small>	<b>Reg Date</b>	04-Aug-2017 (7yrs 11mths 5days COE left)
<b>Mileage</b>	N.A.	<b>Manufactured</b>	2016
<b>Road Tax</b>	\$508 /yr	<b>Transmission</b>	Auto
<b>Dereg Value</b>	\$41,733 as of today (change)	<b>OMV</b>	\$19,094
<b>COE</b>	\$44,002	<b>ARF</b>	\$9,094
<b>Engine Cap</b>	1,197 cc	<b>Power</b>	85.0 kW (113 bhp)
<b>Curb Weight</b>	1,270 kg	<b>No. of Owners</b>	1
<b>Type of Vehicle</b>	Hatchback		

### Features

Powerful And Fuel Economy 1.2 Turbocharged Engine, SRS Airbags, Class-Leading Wheelbase With Amazing Legroom, Intelligent Keyless Push Start, ABS. View specs of the Nissan Pulsar (2017-2017)

### Accessories

Black Sporty Leather Seats, 17" Factory Sports Rims, Bluetooth Connectivity, Reverse Sensors, Solar Film, Fog Lamps, Idle Start-Stop.

### Description

Best Priced Unit In The Market! Full Agent Service. Valid Agent Warranty Till 2022 (Unlimited Mileage)! Feels And Looks As Good As New! No Accidents, No Repairs Need, Car Has Been Well Taken Care Of And Parked Under Sheltered Carpark, Selling Due To Growing Family And Upgrading To MPV. In House Loan Or Bank Loan Available! Don't Miss! Call For A Viewing Appointment Today!

### Category

PARF Car

### Status

Available

### Resources



#### Car Valuation - Free

Find out the market value of your existing car for free. Get started



#### Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. Find out more

Posted on: 17-Aug-2019 | Last Updated on: 26-Aug-2019

### Upfront Payment


<b>Transf</b>	\$25	
<b>Dc</b>	\$18,840 (change)	Maximum 70% loan



Location Map

### Price Chart

### Summary



Click on the point to view the vehicle

Shortlist Compare Add note  
Report Error More Actions

### Seller Information

<b>Company</b>	Thrive Auto » dealer's pricelist » 14 vehs sold   17 vehs available
<b>Address</b>	61 Ubi Avenue 2 #03-07 Search cars nearby this location
<b>Location</b>	Automobile Megamart
<b>Office No</b>	64750078
<b>Contact Person(s)</b>	Alvin 97274730

**DOWNTOWN EAST**  
**31 AUG - 01 SEP 2019**  
**10AM TO 8PM**

**WIN a 2D1N stay at Amara Sanctuary Resort Sentosa!**  
**AND**  
**MOBIL 1 Engine Oil Giveaway!**

Nissan Pulsar Price Range Depreciation 2017 Vehicle Type

Home » Used Cars » Autotraders Pte Ltd » Nissan Pulsar 1.2A DIG-T

## Nissan Pulsar 1.2A DIG-T

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

PREMIUM AD



**Price** \$64,800

**Depreciation** \$7,930 /yr  
View models with similar depre

**Reg Date** 08-May-2017  
(7yrs 8mths 8days COE left)

**Mileage** 23,888 km (10.3k /yr)

**Manufactured** 2017

**Road Tax** \$508 /yr

**Transmission** Auto

**Dereg Value** \$45,346 as of today (change)

**OMV** \$17,532

**COE** \$51,600

**ARF** \$7,532

**Engine Cap** 1,197 cc

**Power** 85.0 kW (113 bhp)

**Curb Weight** 1,265 kg

**No. of Owners** 1

**Type of Vehicle** Hatchback

### Features

Powerful And Fuel Economy 1.2 TurboCharged Engine, SRS Airbags, Class-Leading Wheelbase With Amazing Legroom, Intelligent Keyless Push Start, ABS. View specs of the Nissan Pulsar (2017-2017)

### Accessories

Black Sporty Leather Seats, 17" Factory Sports Rims, Bluetooth Connectivity, Reverse Sensors, Solar Film, Fog Lamps, Idle Start-Stop.

### Description

We Can Help To Convert To Z10 Usage If Needed. In House Loan Or Bank Loan Available! Balloon Scheme Available! Fast, Easy And Loan Approval! We Are sgCarMart Premium Dealer! Buy With Confidence! Viewing And Test Drive Available Daily Including Weekend From 10.30 A.M. To 6.30 P.M.! All Our Vehicles Has Undergone A 120 Points Check By Our In House Workshop.

### Category

PARF Car, Premium Ad Car

### Status

Available

### Resources



Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. Find out more



Car Valuation - Free


Find out the market value of your existing car for free. Get started



Location Map

Price Chart

Summary



Click on the point to view the vehicle

Shortlist

Compare

Add note

Report Error

More Actions

### Seller Information

#### Company

Autotraders Pte Ltd

dealer's pricelist

82 vehs sold | 29 vehs available

★ PREMIUM DEALER 2019 ★

Post Compare

Updated on: 29-Aug-2019



# MOTORCAR (Rear)

## Rear Portion

Vehicle No: SLM 2886L

NAC	INC	Item	CON	ACQ	Q5
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper			
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips			
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer			
1149	993045	Rear Bumper Reinforcement			
1150	992970	Rear Bumper Beam Lipsticker			
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector			
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor			
1159	993327	Rear End Panel			
1160	993339	Rear End Panel Top Garnish			
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp			
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp			
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid			
1171	991328	Bootlid Emblem			
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock			
1178	990377	Bootlid Rubber			
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate			
1182	991328	Tailgate Emblem			
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board			

NAC	INC	Item	CON	ACQ	Q5
1202	993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel			
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe			
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim			
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993401	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1255	990247	Sticker			
		Boot Compartment Sponge			

No of Items: \_\_\_\_\_

Assessor: H. Ann

29/8/2019

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	26 Aug 2019 <a href="#">Edit Reg</a>		26 Aug 2019 00:00 <a href="#">Edit Adj Rpt</a>	<b>\$0.00</b> <a href="#">Edit Estimates</a>	<b>\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

Show All

[Created by adjuster]

Insured:	Johnny Ch'ng, Co. Reg. No.: -		
Main Claimant:	TEO SUNNY, ID: S1476331G		
Vehicle Reg. No.:	SLM2886L	Date of Loss:	19/08/2019 21:00 - :59 [28 Months and 23 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 7190750779SG	Policy/Cover Note No.:	1900112929 (Comprehensive)
Vehicle Reg. No. (Insured):	SMM3308X	Policy No. (Claimant):	
		Excess:	
Repairer:	Platinum Werkz Pte Ltd (HQ) 53 Ubi Ave 1 01-25 Paya Ubi Industrial Park, 408934 Ubi - Tel: 6741 610		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Loh, Chee-Heng] Chee-Heng.Loh@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by LEE HOCK ANN] ... [Final Rpt due 04/09/2019]		

[View All](#) | [Compose Case Mail](#) |

- AIG\_SG (27/08/2019): **TP GIA REPORT**

View All | Search Tasks | Create New Task | Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									































































## Claim Documents

**\*SLM2886L (7190750779SG)**  
**[SMM3308X]**

**TP**  
**TEO SUNNY**  
**Aug 19 2019 9:00PM**  
**[Johnny Ch'ng]**  
**Platinum Werkz Pte Ltd**

<a href="#">Upload Documents</a> <a href="#">Upload Photos</a> <a href="#">Compose New Letter</a> <a href="#">Upload Video</a> <a href="#">Upload Audio</a>			<b>View</b> <a href="#">View in Browser</a>	
<b>Assessment Reports</b>			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	27/08/19 17:20	<b>Accident Statement</b> From: OD - Reg. No: SMM3308X, Claimant: JOHNNY CH'NG	Load HTM	<input type="checkbox"/>
<b>Photos/Images</b>			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	03/09/19 15:35	<b>Chassis Number</b>	Load JPG	<input checked="" type="checkbox"/>
2	03/09/19 15:36	<b>Odometer Reading</b>	Load JPG	<input checked="" type="checkbox"/>
3	03/09/19 15:37	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
4	03/09/19 15:37	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
5	03/09/19 15:37	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
6	03/09/19 15:37	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
7	03/09/19 15:37	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
8	03/09/19 15:37	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
9	03/09/19 15:37	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
10	03/09/19 15:37	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
11	03/09/19 15:37	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
12	03/09/19 15:37	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
13	03/09/19 15:37	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
14	03/09/19 15:37	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
15	03/09/19 15:37	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
16	03/09/19 15:37	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
17	03/09/19 15:37	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
18	03/09/19 15:37	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
19	03/09/19 15:37	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
20	03/09/19 15:37	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
21	03/09/19 15:37	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
22	03/09/19 15:37	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
23	03/09/19 15:37	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
24	03/09/19 15:37	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
25	03/09/19 15:38	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
26	03/09/19 15:38	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
27	03/09/19 15:38	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
28	03/09/19 15:38	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
29	03/09/19 15:38	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
30	03/09/19 15:38	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
31	03/09/19 15:38	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
32	03/09/19 15:38	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
33	03/09/19 15:38	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
34	03/09/19 15:38	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
35	03/09/19 15:38	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
36	03/09/19 15:38	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
37	03/09/19 15:38	General View	 Load JPG	<input checked="" type="checkbox"/>
38	03/09/19 15:38	General View	 Load JPG	<input checked="" type="checkbox"/>
39	03/09/19 15:38	General View	 Load JPG	<input checked="" type="checkbox"/>
40	03/09/19 15:38	General View	 Load JPG	<input checked="" type="checkbox"/>
41	03/09/19 15:38	General View	 Load JPG	<input checked="" type="checkbox"/>
42	03/09/19 15:38	General View	 Load JPG	<input checked="" type="checkbox"/>
43	03/09/19 15:38	General View	 Load JPG	<input checked="" type="checkbox"/>
44	03/09/19 15:38	General View	 Load JPG	<input checked="" type="checkbox"/>
45	03/09/19 15:38	General View	 Load JPG	<input checked="" type="checkbox"/>
46	03/09/19 15:38	General View	 Load JPG	<input checked="" type="checkbox"/>
47	03/09/19 15:38	General View	 Load JPG	<input checked="" type="checkbox"/>
48	03/09/19 15:38	General View	 Load JPG	<input checked="" type="checkbox"/>
49	03/09/19 15:39	General View	 Load JPG	<input checked="" type="checkbox"/>
50	03/09/19 15:39	General View	 Load JPG	<input checked="" type="checkbox"/>
51	03/09/19 15:39	General View	 Load JPG	<input checked="" type="checkbox"/>
52	03/09/19 15:39	General View	 Load JPG	<input checked="" type="checkbox"/>
53	03/09/19 15:39	General View	 Load JPG	<input checked="" type="checkbox"/>
54	03/09/19 15:39	General View	 Load JPG	<input checked="" type="checkbox"/>
55	03/09/19 15:39	General View	 Load JPG	<input checked="" type="checkbox"/>
56	03/09/19 15:39	General View	 Load JPG	<input checked="" type="checkbox"/>
57	03/09/19 15:39	General View	 Load JPG	<input checked="" type="checkbox"/>
58	03/09/19 15:39	General View	 Load JPG	<input checked="" type="checkbox"/>
59	03/09/19 15:39	General View	 Load JPG	<input checked="" type="checkbox"/>
60	03/09/19 15:39	General View	 Load JPG	<input checked="" type="checkbox"/>
61	03/09/19 15:39	General View	 Load JPG	<input checked="" type="checkbox"/>
62	03/09/19 15:39	General View	 Load JPG	<input checked="" type="checkbox"/>
63	03/09/19 15:39	General View	 Load JPG	<input checked="" type="checkbox"/>
64	03/09/19 15:39	General View	 Load JPG	<input checked="" type="checkbox"/>
65	03/09/19 15:39	General View	 Load JPG	<input checked="" type="checkbox"/>
66	03/09/19 15:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	03/09/19 15:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	03/09/19 15:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	03/09/19 15:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	03/09/19 15:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	03/09/19 15:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	03/09/19 15:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	03/09/19 15:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	03/09/19 15:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	03/09/19 15:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	03/09/19 15:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	03/09/19 15:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	03/09/19 15:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	03/09/19 15:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	03/09/19 15:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
81	03/09/19 15:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
82	03/09/19 15:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
83	03/09/19 15:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
84	03/09/19 15:42	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
85	03/09/19 15:42	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
86	03/09/19 15:42	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
87	03/09/19 15:42	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
88	03/09/19 15:42	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
89	03/09/19 15:42	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page ▼	✓
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
90	03/09/19 15:42	Reinspection Photo	 Load JPG	✓
91	03/09/19 15:43	After Repair Photo	 Load JPG	✓
92	03/09/19 15:43	After Repair Photo	 Load JPG	✓
93	03/09/19 15:43	After Repair Photo	 Load JPG	✓
94	03/09/19 15:43	After Repair Photo	 Load JPG	✓
95	03/09/19 15:43	After Repair Photo	 Load JPG	✓
96	03/09/19 15:43	After Repair Photo	 Load JPG	✓
97	03/09/19 15:43	After Repair Photo	 Load JPG	✓
98	03/09/19 15:43	After Repair Photo	 Load JPG	✓
99	03/09/19 15:43	After Repair Photo	 Load JPG	✓
100	03/09/19 15:43	After Repair Photo	 Load JPG	✓
101	03/09/19 15:43	After Repair Photo	 Load JPG	✓
102	03/09/19 15:43	After Repair Photo	 Load JPG	✓
103	03/09/19 15:43	After Repair Photo	 Load JPG	✓
104	03/09/19 15:43	After Repair Photo	 Load JPG	✓
105	03/09/19 15:43	After Repair Photo	 Load JPG	✓
106	03/09/19 15:43	After Repair Photo	 Load JPG	✓
107	03/09/19 15:44	After Repair Photo	 Load JPG	✓
108	03/09/19 15:44	After Repair Photo	 Load JPG	✓
109	03/09/19 15:44	After Repair Photo	 Load JPG	✓
110	03/09/19 15:44	After Repair Photo	 Load JPG	✓
111	03/09/19 15:44	After Repair Photo	 Load JPG	✓
112	03/09/19 15:44	After Repair Photo	 Load JPG	✓

## Documents Checklist

### DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

### Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19014976/HCF3S2  
Date: 11/09/2019

## REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900112929  
Claimant Vehicle No: SLM2886L Insured Vehicle No: SMM3308X  
Date of Loss: 19/08/2019 Nature of Claim: TP Claim No: 7190750779SG

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SLM2886L Engine No: HRA2392250A  
Make & Model: NISSAN PULSAR, 1.2 L DIG-T (A) Chassis No: VSKDDAC13U0098339  
Reg. Date: 27/03/2017 (Man. Year: 2016) Odometer: 56231 km  
Colour: Black  
Engine Capacity: 1197 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 205/50ZR17 Rear Tyre Size: 205/50ZR17  
Front Left Side: Hankook 6 mm Rear Left Side: Hankook 6 mm  
Front Right Side: Hankook 6 mm Rear Right Side: Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment: 26/08/2019  
Date Inspected: 26/08/2019 Inspected At: Platinum Werkz Pte Ltd (HQ)  
53 Ubi Ave 1 01-25 Paya Ubi Industrial Park  
Singapore 408934  
Estimated Period of Repair: 5.0 days

Adjuster: LEE HOCK ANN

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Bent	0.00 F	*-F
2	6		*REAR BUMPER CLIPS	Necessary	0.00 F	*-F
3	1		*REAR BUMPER REINFORCEMENT	Repair	0.00 F	*-F
4	1		*REAR BUMPER LIPSTICKER	Necessary	0.00 F	*-F
5	2		*REAR BUMPER SPONGE LH/RH	Cracked	0.00 F	*-F
6	1		*SET REVERSE SENSOR	Shorted	0.00 F	*-F
7	1		*REAR END PANEL	Repair	0.00 F	*-F
8	1		*REAR END PANEL TOP GARNISH	Cracked	0.00 F	*-F
9	1		*TAILGATE	Dented	0.00 F	*-F
10	1		*TAILGATE EMBLEM	Necessary	0.00 F	*-F
11	1		*TAILGATE LOGO PULSAR	Necessary	0.00 F	*-F
12	1		*REAR WINDSCREEN MOULDING	Necessary	0.00 F	*-F
13	1		*REAR WINDSCREEN SEALANT	Necessary	0.00 F	*-F
14	1		*REAR WINDSCREEN INNER SEAL	Necessary	0.00 F	*-F
15	1		*BOOT COMPARTMENT SPONGE	Chipped	0.00 F	*-F
16	1		*TAILGATE RUBBER	Crushed	0.00 F	*-F

F=Franchise part.

Total Parts (\$\$)

0.00

0.00

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >