

22/07/2019

ASS. REC. BY:

REF:

3
C8 INC 19014477/71yd3⁵²

Special Instruction:

Surveyor: Tauhiah

ASSIGNMENT (Office)

From (Person): Daniel Koh

of

INC

Date/Time: 26/8/19 @ 9:38am

Estimated Cost:

Bill to:

OD / TP / FWS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

QX 447S

Insured:

SJS 4980B

at Workshop m/s

Lim Tan Motor

Tel:

90033052 / 6355 2240

of

Blk 176 Sin Ming Drive # 03-09

Policy No:

Claim No:

M1/1058762-001

Sum Insured:

Excess:

Make of Veh:

D.O.A.

2/8/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 10:40am @ 26/8/19

Person Contacted:

Sufyan

Vehicle

IN OUT

Date/Time	Action/Instruction
	<u>1. Inspr 55 Newton Rd # Revenue House B4.</u>
	<u>QX 447S - X</u>
	<u>SJS 4980B - X</u>
<u>9/3</u>	<u>Workshop is under Lim Tan Workshop</u>
	<u>Workshop submit independent surveyor report.</u>

Nivitha (LKK Auto)

From: Daniel Koh <daniel.koh@income.com.sg>
Sent: Monday, 26 August 2019 1:05 PM
To: 'assignments@lkkauto.com'
Cc: admin-d@lkkauto.com
Subject: FW: TP CASES FARMED OUT TO LKK ON 26/8/2019

Dear LKK,

Resend with claim number & OIC

From: Daniel Koh
Sent: Monday, 26 August 2019 9:38 AM
To: 'assignments@lkkauto.com' <assignments@lkkauto.com>
Cc: 'admin-d@lkkauto.com' <admin-d@lkkauto.com>; Teng Ken Leong <kenleong.teng@income.com.sg>; Thio Tse Kiat <tsekiat.thio@income.com.sg>
Subject: FW: TP CASES FARMED OUT TO LKK ON 26/8/2019

Dear LKK,

Please assist to survey the following vehicles as per Mr Teng's instruction :-

SN	OIC	Claim No.	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	Survey Time	OIV	DOA	Additional Remarks
----	-----	-----------	---------	---------------	------------------	------------------	-------------	-----	-----	--------------------

1	MUHAMMAD AIRWAN	MT/1058656- 002	SJT7959P	AUBURN AUTO PTE LTD	176 SING MING DRIVE #04- 18 SIN MING AUTOCARE SINGAPORE 575721	Edmund / 8787 5012	GBH4856E	19/8/2019	Call workshop first before going down**
2	JEFF LIN	MT/1059034- 002	SLU9482E	AUTOSOON PTE LTD	BLK 176 SIN MING DRIVE #01- 10 SIN MING AUTOCARE 575721	Agnes Lee/ 6846 9428 / 6748 6558	GBC3787D	22/8/2019	
3	SERENE LIM	MT/1058714- 002	GBG1889K	HOME ADDRESS	176 SIN MING DRIVE #02- 01 SIN MING AUTOCARE SINGAPORE 575721	LK Wong 9736 8619 /	SMK6038R	20/8/2019	LKW Auto Services
4	AZHARI	MT/1058762- 001	QX447S	HOME ADDRESS	55 NEWTON ROAD # REVENUE HOUSE B4 CARPARK SINGAPORE 307987	Sufyan / 6355 2240	SJS4980B	2/8/2019	SINGAPORE CUSTOMS - Revenue House B4 carpark (call Sufyan first @6355240)
5	ENG HUEY HUEY	MT/1059241- 002	SLM6796L	LEONG AUTO PTE LTD	160 SIN MING DRIVE #02- 13 SIN MING AUTOCITY	Daniel Tan/Cady Lee / 9692 4113	SLX8891Z	23/8/2019	

Please contact workshops.

Please revert to officer-in-charge after survey.

Thank you.

Daniel Koh
Senior Admin Assistant
Motor Insurance
T +65 6430 7901
www.income.com.sg



in with
you

At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.
Find out more at Income.com.sg/careers

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.


**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 1

PRE-REPAIR INSPECTION REPORT				
NTUC INCOME INSURANCE CO-OPERATIVE LTD		Ref: CS3/INC19014977/T1yd3s2		
73 BRAS BASAH ROAD		Date: 10-03-2020		
#05-01 NTUC TRADE UNION HOUSESINGAPORE				
189556				
ATTN: AZHARI		Code: INC		
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	SJS 4980B	Veh. Inspected	QX 447S	
Policy No.		Coverage (\$)	0.00	
Claim No.	MT/1058762-001	Excess (\$)	0.00	
Assign From	DANIEL KOH	Assign Date	26/08/2019	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN SYLPHY	c.c	0	
Engine No.	HIDDEN	Year of Reg.	0	
Chassis No.		Colour	BRONZE	
Odometer	168487 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	FALKEN	6 mm	
L/H Front Tyre	205/55 R16	FALKEN	6 mm	
R/H Rear Tyre	205/55 R16	FALKEN	6 mm	
L/H Rear Tyre	205/55 R16	FALKEN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.				
5. General Information				
Accident Date	02/08/2019	Inspect Date / Time	26/08/2019 (02:30 PM)	
Survey held at	55 NEWTON RD#REVENUE HOUSE B4			
Repairer	LIM TAN MOTOR PTE LTD			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

Report Ref No. CS3/INC19014977/T1yd3s2

Inspected By

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.