

22/02/2019

ASS. REC. BY:

REF: CS3 / AIG19014980 / FCF302 Special Instructions

Signature: PamASSIGNMENT (Office)From (Person): Chin Lee Ying of AIG Date/Time: 26/8/19 @ 11:02am

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLT 6642K Insured: SMD 7357Aat Workshop in/s Hing Hong Painter Tel: 6453 5779of 160 Sin Ming Drive # 06-10Policy No: 1800105037 Claim No: 5676452917SG

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 23/8/2019
(Officer's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: _____

Date/Time: 11:58am @ 26/8/19 Person Contacted: Henny Vehicle IN / OUT

Date/Time	Action/Instruction
	<u>Vehicle (x)</u>
	<u>SMD 7357A : X</u>
	<u>SLT 6642K : X</u>
	<u>Dismantle: 27/8/2019</u>

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLT 6642K

at Workshop m/s: Lian Heng Painter

of 160 Sin Ming Drive #06-10

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

days

Res.:

Yes or No

Lump Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No: SLT 6642K

Yr Regn: NOV / 2017

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Vezel

C.C. 1496

Colour: white

A/C: Insured / Std / NI / NA

Sp. Reading: 38343

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: DAA-RV3

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/60R16

R: 215/60R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 4 mm

R/Bal. 4 mm

L/Bal. 4 mm

L/Bal. 4 mm

D.O.A. 23/08/2019

D.O.I. 26/08/2019

Survey held at

Lian Heng Painter

Des. of Damages: PIR / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Range: \$2000-3300

Repair days: 5 days

MV: \$71000

PV: \$43072

NV: \$27000

Date/Time, File Pass to?

☐: Prel. Report

Days Of Repair: 5

Resurvey No. of Trip: 1

1)

☐: Final Report

Date/Time, File Return to?

2)

Add Fee: ☐: Site Insp (\$☐: Interview (\$☐: Tech. Invs (\$☐: Weekend (\$

Report Format: PRE

Lump Sum / I.B.I. (\$

Survey Fee: 180

Transportation:

G + RS, \$1

Photos

Others

TOTAL

191

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	27 Aug 2019 Edit Reg		26 Aug 2019 00:00 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	SIM BAN TEK		
Main Claimant:	AUTO EXCHANGE LEASING PTE LTD		
Vehicle Reg. No.:	SLT6642K	Date of Loss:	23/08/2019 10:00 - :59
Claim Type:	TP / 5676452917SG	Policy/Cover Note No.:	1800105037 (Comprehensive)
Vehicle Reg. No. (Insured):	SMD7357A	Policy No. (Claimant):	
		Excess:	
Repairer:	Lian Heng Painter Company (HQ) BLK 11 Sin Ming Industrial Estate Sector B, #01-87, 575655 Sin Ming - Tel:		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Lee, Ming-Yao] MingYao.Lee@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by PARASURAM SHANMUGAM] ... [Final Rpt due 04/09/2019]		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

- AIG_SG (28/08/2019): TP GIA REPORT

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHIC...

From: Chin, Lee-Ying

To: assignments, Admin A

Cc: Fong, Andy-SY

Sent: 8/26/2019 11:02:46 AM

Attachments:  23082019150840.pdf

Hi LKK,

Kindly assist to survey, vehicle in workshop.

Thanks.

Best Regards

Lee Ying, Chin

AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1947

Lee-Ying.Chin@aig.com | www.aig.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Please reply to our Branch Office for this matter

Nedumaran Muthukrishnan
LLB (hons) [Buckingham]
Barrister at Law (Lincoln's Inn)

Branch Office: 11 Sin Ming Road
#B2-09 (Unit 2) Thomson V Two
Singapore 575629
Tel : 6509-8480 / 6509-8481
Fax : 6509-8482
Email : igene.lim@mneduco.com.sg
serene.tan@mneduco.com.sg

Our Reference : MN/IG/L1/1913239/st
Your Reference : SMD 7357A

23rd August 2019

AIG ASIA PACIFIC INSURANCE PTE LTD
Singapore

BY FAX 6835-7416 ONLY

Dear Sirs,

1. NOTICE OF ACCIDENT TO INSURERS AND PRE-REPAIR SURVEY WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 2 OF THE STATE COURTS PRACTICE DIRECTIONS (AMENDMENT NO. 1 OF 2016)
2. ACCIDENT ON 23/8/2019 INVOLVING VEHICLE NOS. SLT 6642K AND SMD 7357A ALONG ION SHOPPING CENTRE CARPARK AT ABOUT 1050 HOURS.

We are instructed by AUTO ECHANGE LEASING PTE LTD (owner of motor vehicle no. SLT 6642K) and/or LIAN HENG PAINTER COMPANY (the motor workshop for SLT 6642K) to notify you of a road traffic accident on 23/8/2019 at about 1050 hours along ION SHOPPING CENTRE CARPARK involving our client's vehicle registration number [SLT 6642K] and [SMD 7357A] driven by you at the material time. A copy of the Singapore accident statement/traffic police report filed is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before we proceed to repair the damaged vehicle, please let us know **within 2 working days** of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you with the stipulated timeline, we shall proceed to repair the vehicle without further reference to you.

Yours faithfully,

M NEDUMARAN & CO

NEDUMARAN MUTHUKRISHNAN
(Branch Office)

c.c.	1)	SIM BAN TEK	(Vehicle : SMD 7357A)
	2)	Lian Heng Painter Company 160 Sin Ming Drive #06-10 Sin Ming AutoCity Singapore 575722 Tel : 6453-5779 / 9863-2371 (Mr Henry/Nomy)	(Vehicle : SLT 6642K) Fax : 6453-3173

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	350D

Vehicle Details

Vehicle No.:	SLT6642K
Vehicle to be Exported:	No
Intended Deregistration Date:	27 Aug 2019
Vehicle Make:	HONDA
Vehicle Model:	VEZEL HYBRID 1.5X AUTO
Primary Colour:	White
Manufacturing Year:	2017
Engine No.:	LEB5953151
Chassis No.:	RU31253134
Maximum Power Output:	112.0 kW (150 bhp)
Open Market Value:	\$25,291.00
Original Registration Date:	06 Nov 2017
First Registration Date:	06 Nov 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00 $\times 50\%$ = \$2500

Intended PARF Rebate Details

PARF Eligibility:	Yes ✓
PARF Eligibility Expiry Date:	05 Nov 2027
PARF Rebate Amount:	\$3,750.00

Intended COE Rebate Details

COE Expiry Date:	05 Nov 2027
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$48,005.00
COE Rebate Amount:	\$39,322.00
Total Rebate Amount:	\$43,072.00

The information contained herein is correct as at 27 Aug 2019

DOA: 23/08/2019

Remaining: 7 years 2 months 14 days (86.4 months) OK

Repn: \$9500 (\$791.6 (monthly))

$86.4 \times \$791.6 = \68394.24

$\$68394.24 + \$2500 = \underline{\underline{\$70894.24}}$

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

Vw Beetle Classic Plate \$25k.

Great Car!
Direct Owner STA Ad


HIN LUNG AUTO
HoBee Group
One Stop Car Hub
Finance, Insurance, Workshop
New and Used Cars

30 years
of experience

Browse by Category ▼

« Back (1 2 3) Next »





Sort by Date Posted ▼

20 results/

55 vehicles

Honda Vezel

Advanced Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Stat
Search Selection	Honda Vezel		Any	Any	2017	Any	Any	Any	Av
	Honda Vezel 1.5A X		\$73,800	\$8,830 /yr	04-Apr-2017	1,496 cc	33,800 km	SUV	Av
Well Maintained By 1 Owner. Do Not Miss This Beautiful Unit, Flawless And Excellent Condition, Nice Number! STA Or Vicom Inspection Welcome. Loan / Trade-in Available. Call Now Before It Is Gone.									
Viking Motor Pte Ltd									
Posted: 27-Aug-2019 Tags: 2017 Honda Vezel, 2017 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda									
	Honda Vezel 1.5A RS		\$77,000	\$8,670 /yr	03-May-2017	1,496 cc	46,271 km	SUV	Av
Only 1 Owner, Rare High Spec Vezel 1.5A RS (Non Hybrid) Model In The Market, Authentic Low Mileage, Silent Undercarriage, Smooth Gearbox Transmission. Accident Free, Perfect Chassis. No Repairs Needed. High In-House Financing Available Easily, Call Us Now Or Visi...									
Posted: 26-Aug-2019 Tags: 2017 Honda Vezel, 2017 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda									
	Honda Vezel 1.5A X		\$72,500	\$8,800 /yr	12-Apr-2017	1,496 cc	-	SUV	Av
Elegant White SUV, One Owner Only, Low Maintenance Cost, Very Well Maintained, Easy Financing, Flexible In-house Loan Packages Available.									
Prime Motor & Leasing									
Posted: 25-Aug-2019 Tags: 2017 Honda Vezel, 2017 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda									
	Honda Vezel Hybrid 1.5A X Honda Sensing		\$82,800	\$9,630 /yr	28-Dec-2017	1,496 cc	28,000 km	SUV	Av
Fuel Type: Petrol-Electric									
Offer Bank Interest Rate From 1.98%. Free 2 Years Hybrid Battery Warranty With Certified 120 Points Test Report With Detailed Chassis Inspection. Extra Passengers Safety With Honda Sensing Technology. Blue Body With Black Interior. 1 x Free Servicing At Our Authorize...									
Dynamic Motoring									
Posted: 25-Aug-2019 Tags: 2017 Honda Vezel, 2017 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda									

Car Buying

Car Selling

Car Ownership

Buying a pre-owned car
Unsure of its Condi
Get, STA Car Evali

Car Aftermarket

On The Move

Lifestyle

**Honda Vezel Hybrid 1.5A X****\$76,800****\$9,570 /yr**

31-May-2017

1,496 cc

31,288 km

SUV

Av**Fuel Type:** Petrol-Electric

Nice Old/Bidded 2 Digits Car Plate Going Along, FOC! Low Mileage Done 31288km! Excellent Condition, Must See. 1 Owner, Sale Due To Overseas Job Posting. New Paintwork. Optional Warranty Package Available. 100% Accident-Free. Owner Consignment. Call Now!

Lake View Credit Pte Ltd

Posted: 25-Aug-2019 Tags: 2017 Honda Vezel, 2017 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda

**Honda Vezel Hybrid 1.5A X****\$80,800****\$9,970 /yr**

04-Jul-2017

1,496 cc

23,000 km

SUV

Av**Fuel Type:** Petrol-Electric

Attractive Interest Rates Starting From 2.28%! Very Beautiful Purplish Black Vezel Hybrid! Powerful Yet Low Petrol Consumption! Safety Honda Sensing Functions With Auto Lane Departure Warning! Well Taken Care By Previous Owner! STA Evaluation Highly Recommende...

Posted: 24-Aug-2019 Tags: 2017 Honda Vezel, 2017 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda

Compare

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	23/08/2019 15:56
Date Of Accident	23/08/2019 10:50
Exact Location Of Accident	ION SHOPPING CENTRE CAR PARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLT6642K
Insured/Policyholder	
Name Of Registered Owner	AUTO EXCHANGE LEASING PTE LTD
Co Reg No	201608350D
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-87386755
Alternative Phone No	OFFICE-87386755

Vehicle Particulars

Manufacturer	HONDA
Model	VEZEL-1.5 HYBRID X (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	TOKIO MARINE INSURANCE SINGAPORE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	19-MI001157-R02
Cover Note Number	

Driver

Name of Driver	JAMES YAP PENG GUAN
NRIC No	S7017554A
Date Of Birth	30/05/1970
Occupation	OUTDOOR
Date Of Driving Pass	04/10/2004
Driving Experience	14 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97345516
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	167 SUNRISE TERRACE
Postcode	805370
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	NO
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMD7357A
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	GOH HOON CHIN
NRIC/Passport Number	S1835950B
Contact Number	98446150
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN




IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.


8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the Information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

 Policyholder's Signature Date & Time:	 Driver's Signature (If driver is not the policyholder) Date & Time:	 Reporting Centre Person's Signature Name: <i>Enkh Tser</i> NRIC/FIN No.:
---	--	---

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

As I was driving straight and slow in 10m car park when vehicle 'B' SMD 7357A suddenly dashed out from the left refused to stop at the stop sign turned lane came abruptly and collided onto the left side of my vehicle SLT 6642K.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:



Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name: EBYK TAN

NRIC/FIN No.:

Condition (CON)

(01)Item (2)Denied (3)Disrupted (4)Cracked (5)Cut (6)Scratched
(07)Deformed (08)Shifted (09)Buckled (10)Broken (11)Necessary (12)Missing
(13)Torn (14)Unconfirmed (15)Not Working

MOTOR CAR (LH)

ACTION (AC)

(1)Replace (✓) (2)Repair (X) (3)Check (?)
(4)Not Consistent (NC)

Aug 2005

Left Portion

NAC	INC	Item	CON	AC	Qty
1255	995326	Frt LH Door	DD	✓	
1256	995140	Frt LH Door Protector	nc	✓	
1257	995104	Frt LH Door Hinge	BT	✓	
1258	995142	Frt LH Door Wing Mirror			
1259	995102	Frt LH Door Garnish			
1260	991593	Frt LH Door Glass Outer Moulding			
1261	991588	Frt LH Door Glass Inner Moulding			
1262	995103	Frt LH Door Glass			
1263	991595	Frt LH Door Glass Regulator	DB	✓	
1264	991596	Frt LH Door Glass Regulator Motor			
1265	991662	Frt LH Door Rubber			
1266	991636	Frt LH Door Outer Handle			
1267	991607	Frt LH Door Inner Handle			
1268	991625	Frt LH Door Lock w/Key			
1269	991624	Frt LH Door Lock	BT	✓	
1270	991562	Frt LH Door Central Lock			
1271	991675	Frt LH Door Switch			
1272	991617	Frt LH Door Inner Trim Board			
1273	991568	Frt LH Door Checker			
1274	991575	Frt LH Door Felt			
1275	991688	Frt LH Door Wire Harness			
1276	991683	Frt LH Door Window Glass Pillar			
1277	991640	Frt LH Door Outer Pillar			
1278	991613	Frt LH Door Inner Pillar			
1279	991646	Frt LH Door Pillar Inner Garnish			
1280	990554	Centre Pillar LH			
1281	990542	Centre Inner Pillar LH			
1282	990517	Centre Pillar Upper Garnish LH			
1283	990564	Centre Pillar Lower Garnish LH			
1284	991670	Frt LH Door Step Garnish			
1285	994052	Rocker Panel LH	DD R	✓	
1286	994049	Rocker Panel Inner Panel LH			
1287	994046	Rocker Panel Garnish LH			
1288	994055	Rocker Panel Outer Side Skirt LH	Cut	✓	
1004	991300	Frt Bumper			
1006	991325	Frt Bumper Bracket			
1007	991462	Frt Bumper Side Retainer			
1008	991433	Frt Bumper Reinforcement			
1010	991468	Frt Bumper Sponge			
1011	991427	Frt Bumper Protector			
1014	991301	Frt Bumper Moulding			
1015	991407	Frt Bumper Lower Spoiler			
1029	995153	Frt LH Headlamp Assy			
1031	995088	Frt LH Side Lamp			
1096	995070	Frt LH Fender			
1098	995147	Frt LH Fender Lamp			
1099	995148	Frt LH Fender Protector			

Vehicle No: SLT 6642K

NAC	INC	Item	CON	AC	Qty
1289	995156	Rear LH Door	DD	✓	
1290	993282	Rear LH Door Protector	nc	✓	
1291	995194	Rear LH Door Hinge	BT	✓	2
1292	993228	Rear LH Door Garnish			
1293	993278	Rear LH Door Glass Outer Moulding			
1294	993231	Rear LH Door Glass Inner Moulding			
1295	995190	Rear LH Door Glass			
1296	993238	Rear LH Door Glass Regulator	DS	✓	
1297	995192	Rear LH Door Glass Regulator Motor			
1298	993294	Rear LH Door Rubber			
1299	993275	Rear LH Door Outer Handle			
1300	993250	Rear LH Door Inner Handle			
1301	993261	Rear LH Door Lock	BT	✓	
1302	993256	Rear LH Door Inner Trim Board			
1303	993218	Rear LH Door Checker	DS	✓	
1304	993230	Rear LH Door Glass Channel			
1305	993242	Rear LH Door Glass Triangle Garnish			
1306	993285	Rear LH Door 1/4 Glass			
1307	993288	Rear LH Door 1/4 Glass Rubber			
1308	993287	Rear LH Door 1/4 Glass Pillar			
1309	993305	Rear LH Door Step Garnish			
1310	993309	Rear LH Door Switch			
1311	994070	Roof Top Panel			
1312	994098	Roof Top Moulding			
1313	994085	Roof Top Air-bag			
1314	994084	Roof Top Air-bag Sensor			
1315	994083	Roof Top Air-bag Control Unit			
1011	992958	Rear Bumper			
1017	992976	Rear Bumper Bracket			
1018	993068	Rear Bumper Side Retainer			
1019	993045	Rear Bumper Reinforcement			
1021	993077	Rear Bumper Sponge			
1024	993040	Rear Bumper Protector			
1026	993026	Rear Bumper Moulding			
1027	993023	Rear Bumper Lower Spoiler			
1028	993851	Rear LH Taillamp			
1029	993436	Rear LH Fender			
1030	993449	Rear LH Fender Protector			
1036	990247	Sticker			
		rear wheel arch	Cut	✓	

No of Items: 11

Assessor: Ram






































...CLAIM SUBFOLDER...(Pending for Survey Report)























CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	27 Aug 2019 Edit Reg		26 Aug 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case




















Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	SIM BAN TEK , Co. Reg. No.: -								
Main Claimant:	AUTO EXCHANGE LEASING PTE LTD								
Vehicle Reg. No.:	SLT6642K	Date of Loss:	23/08/2019 10:00 - :59 [21 Months and 17 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 5676452917SG	Policy/Cover Note No.:	1800105037 (Comprehensive)						
Vehicle Reg. No. (Insured):	SMD7357A	Policy No. (Claimant):							
		Excess:							
Repairer:	Lian Heng Painter Company (HQ) BLK 11 Sin Ming Industrial Estate Sector B, #01-87, 575655 Sin Ming - Tel:								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Lee, Ming-Yao] MingYao.Lee@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by PARASURAM SHANMUGAM] ... [Final Rpt due 04/09/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG (28/08/2019): TP GIA REPORT 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete 									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLT6642K (5676452917SG)
[SMD7357A]
TP
AUTO EXCHANGE LEASING PTE LTD
Aug 23 2019 10:00AM
[SIM BAN TEK]
Lian Heng Painter Company

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Photos/Images															3 per page			<input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail			Print		
1	29/08/19 10:27	General View													 Load JPG			<input checked="" type="checkbox"/>		
2	29/08/19 10:27	General View													 Load JPG			<input checked="" type="checkbox"/>		
3	29/08/19 10:27	General View													 Load JPG			<input checked="" type="checkbox"/>		
4	29/08/19 10:27	General View													 Load JPG			<input checked="" type="checkbox"/>		
5	29/08/19 10:27	General View													 Load JPG			<input checked="" type="checkbox"/>		
6	29/08/19 10:27	General View													 Load JPG			<input checked="" type="checkbox"/>		
7	29/08/19 10:27	General View													 Load JPG			<input checked="" type="checkbox"/>		
8	29/08/19 10:27	General View													 Load JPG			<input checked="" type="checkbox"/>		
9	29/08/19 10:27	General View													 Load JPG			<input checked="" type="checkbox"/>		
10	29/08/19 10:27	General View													 Load JPG			<input checked="" type="checkbox"/>		
11	29/08/19 10:27	General View													 Load JPG			<input checked="" type="checkbox"/>		
12	29/08/19 10:27	General View													 Load JPG			<input checked="" type="checkbox"/>		
13	29/08/19 10:27	General View													 Load JPG			<input checked="" type="checkbox"/>		
14	29/08/19 10:27	General View													 Load JPG			<input checked="" type="checkbox"/>		
15	29/08/19 10:27	General View													 Load JPG			<input checked="" type="checkbox"/>		
16	29/08/19 10:27	General View													 Load JPG			<input checked="" type="checkbox"/>		
17	29/08/19 10:27	General View													 Load JPG			<input checked="" type="checkbox"/>		
18	29/08/19 10:27	General View													 Load JPG			<input checked="" type="checkbox"/>		
19	29/08/19 10:27	General View													 Load JPG			<input checked="" type="checkbox"/>		
20	29/08/19 10:27	General View													 Load JPG			<input checked="" type="checkbox"/>		
21	29/08/19 10:27	General View													 Load JPG			<input checked="" type="checkbox"/>		
22	29/08/19 10:27	General View													 Load JPG			<input checked="" type="checkbox"/>		
23	29/08/19 10:27	General View													 Load JPG			<input checked="" type="checkbox"/>		
24	29/08/19 10:27	General View													 Load JPG			<input checked="" type="checkbox"/>		
25	29/08/19 10:27	General View													 Load JPG			<input checked="" type="checkbox"/>		
26	29/08/19 10:27	General View													 Load JPG			<input checked="" type="checkbox"/>		
27	29/08/19 10:27	General View													 Load JPG			<input checked="" type="checkbox"/>		
28	29/08/19 10:27	General View													 Load JPG			<input checked="" type="checkbox"/>		
29	29/08/19 10:27	General View													 Load JPG			<input checked="" type="checkbox"/>		
30	29/08/19 10:27	General View													 Load JPG			<input checked="" type="checkbox"/>		
31	29/08/19 10:27	General View													 Load JPG			<input checked="" type="checkbox"/>		
32	29/08/19 10:27	General View													 Load JPG			<input checked="" type="checkbox"/>		
33	29/08/19 10:27	General View													 Load JPG			<input checked="" type="checkbox"/>		
34	29/08/19 10:27	General View													 Load JPG			<input checked="" type="checkbox"/>		
35	29/08/19 10:27	General View													 Load JPG			<input checked="" type="checkbox"/>		
36	29/08/19 10:27	General View													 Load JPG			<input checked="" type="checkbox"/>		
37	29/08/19 10:27	General View													 Load JPG			<input checked="" type="checkbox"/>		

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	29/08/19 10:27	General View	 Load JPG	<input checked="" type="checkbox"/>
39	29/08/19 10:27	General View	 Load JPG	<input checked="" type="checkbox"/>
40	29/08/19 10:27	General View	 Load JPG	<input checked="" type="checkbox"/>
41	29/08/19 10:27	General View	 Load JPG	<input checked="" type="checkbox"/>
42	29/08/19 10:27	General View	 Load JPG	<input checked="" type="checkbox"/>
43	29/08/19 10:27	General View	 Load JPG	<input checked="" type="checkbox"/>
44	29/08/19 10:27	General View	 Load JPG	<input checked="" type="checkbox"/>
45	29/08/19 10:27	General View	 Load JPG	<input checked="" type="checkbox"/>
46	29/08/19 10:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	29/08/19 10:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	29/08/19 10:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	29/08/19 10:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	29/08/19 10:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	29/08/19 10:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	29/08/19 10:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	29/08/19 10:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	29/08/19 10:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	29/08/19 10:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	29/08/19 10:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	29/08/19 10:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	29/08/19 10:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	29/08/19 10:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	29/08/19 10:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	29/08/19 10:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	29/08/19 10:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	29/08/19 10:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	29/08/19 10:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	29/08/19 10:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	29/08/19 10:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	29/08/19 10:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	29/08/19 10:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	29/08/19 10:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	29/08/19 10:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	29/08/19 10:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	29/08/19 10:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
73	29/08/19 10:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
74	29/08/19 10:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
75	29/08/19 10:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
76	29/08/19 10:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
77	29/08/19 10:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
78	29/08/19 10:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
79	29/08/19 10:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
80	29/08/19 10:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
81	29/08/19 10:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
82	29/08/19 10:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
83	03/09/19 10:05	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
84	03/09/19 10:05	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
85	03/09/19 10:05	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
86	03/09/19 10:05	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
87	03/09/19 10:05	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
88	03/09/19 10:05	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
89	03/09/19 10:05	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
90	03/09/19 10:05	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
91	03/09/19 10:05	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
92	03/09/19 10:05	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
93	03/09/19 10:05	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
94	03/09/19 10:05	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
95	03/09/19 10:05	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
96	03/09/19 10:05	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
97	03/09/19 10:05	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
98	03/09/19 10:05	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
99	03/09/19 10:05	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
100	03/09/19 10:05	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
101	03/09/19 10:05	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
102	03/09/19 10:05	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
103	03/09/19 10:05	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
104	03/09/19 10:05	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
105	03/09/19 10:05	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	28/08/19 11:08	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19014980/FCF3E2

Date: 10/09/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

1800105037

Claimant Vehicle No : SLT6642K

Insured Vehicle No : SMD7357A

Date of Loss: 23/08/2019

Nature of Claim:

TP

Claim No: 5676452917SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLT6642K**

Make & Model: HONDA VEZEL, 1.5 HYBRID X (A)

Engine No: LEB5953151

Reg. Date: 06/11/2017 (Man. Year: 2017)

Chassis No: RU31253134

Colour: White

Odometer: 38343 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16

Rear Tyre Size: 215/60 R16

Front Left Side: Dunlop 4 mm

Rear Left Side: Dunlop 4 mm

Front Right Side: Dunlop 4 mm

Rear Right Side: Dunlop 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 26/08/2019

Date Inspected: 26/08/2019 Inspected At:

160 Sin Ming Drive #06-10

Repairer : Lian Heng Painter Company (HQ)

Estimated Period of Repair: 5.0 days

Adjuster: PARASURAM SHANMUGAM

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT LH DOOR	Dented	0.00 F	*- F
2	1		*FRT LH DOOR PROTECTOR	Necessary	0.00 F	*- F
3	1		*FRT LH DOOR HINGE	Bent	0.00 F	*- F
4	1		*FRT LH DOOR GLASS REGULATOR	Distorted	0.00 F	*- F
5	1		*FRT LH DOOR LOCK	Bent	0.00 F	*- F
6	1		*ROCKER PANEL LH	Repair	0.00 F	*- F
7	1		*ROCKER PANEL OUTER SIDE SKIRT LH	Cut	0.00 F	*- F
8	1		*REAR LH DOOR	Dented	0.00 F	*- F
9	1		*REAR LH DOOR PROTECTOR	Necessary	0.00 F	*- F
10	2		*REAR LH DOOR HINGE	Bent	0.00 F	*- F
11	1		*REAR LH DOOR GLASS REGULATOR	Distorted	0.00 F	*- F
12	1		*REAR LH DOOR LOCK	Bent	0.00 F	*- F
13	1		*REAR LH DOOR CHECKER	Distorted	0.00 F	*- F
14	1		*REAR WHEELARCH	Cut	0.00 F	*- F
F=Franchise part.						
				Total Parts (\$\$)	0.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >