Buryeupr : _ V	Danie I koh		INMENT (Office)		claling
		of	INC	D	nte/Time: 0618/1909:
Estimated Cost	TP RES / OD RE		Bill to:		
	icle No:			Insured:	SLX88912
nt Workshop m	/s	eong Aur		Tel:	9692 4113
Policy No:	100 -111	1 119 011	Claim No:	17/	059241-002
Stan Insured:			Excess:		
C. L CST 1					
				D	.O.A. 23/8/2019
(Client's Record)		TRS			
Client's Record)	REP. / REV 24 F 0-46cmG 26/8	IRS	cted: Shawr		H.O.D. Endorsement:
(Client's Record) CA / REV / Date/Time; /	REP. / REV 24 B 0-46cmG 26/8	Person Contac			H.O.D. Endorsement:
(Client's Record) CA / REV / Date/Time; /	REP. / REV 24 H	Person Contact			H.O.D. Endorsement:
Make of Veh: (Client's Record) CA / REV / Date/Time; /	REP. / REV 24 B 0-46cmG 26/8	Person Contact			H.O.D. Endorsement:
(Client's Record) CA / REV / Date/Time; /	REP. / REV 24 H b-46cmG - Sla Action/Instruction SL A 6 7-96 SLX 869	Person Contact Internal (**) L-× IZ-×		\Ve	H.O.D. Endorsement:
(Client's Record) CA / REV / Date/Time; /	REP. / REV 24 H b-46cmG - Sla Action/Instruction SL A 6 7-96 SLX 869	Person Contact Internal (**) L-× IZ-×		\Ve	H.O.D. Endorsement:

ASS. REC. BY:	
renneth	ASSIGNMENT
From: Date:	
Estimated Cost:	- () (YERRON: U /)
OD (TP /WS / TP RES / OD RES / EVA / INV / MV	Type: M.Car/ M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or
To Inspect Vehicle No:	(A)
at Workshop m/s	Make: Mit At trage c.c /18
of Least	Colour M. Rec A/C: Insured / Std / NI / NA
Insured:	Sp.Reading 227328 T/Radio: Insured / Std / NI / NA
Policy No.	Eng/No:
Claims No.	CNO: MMBSTA13AHI+ 00450
Const.	Cond. Good) Fair / Poor / Burnt
(Client's Record)	Steering: Inorder's Jammed / Leaked / Burnt or
Make of Veh:	Brake: Inorder / Jammed / Leaked / Burnt or
	Modi: NII / S/RIm / STP A/Rim or
(Policy Condition)	Tyre Size: F. 5/Km 185/55R15
(Policy Condition) Remark: The veh had commenced its	R: Ydco
repair at the time of inspection.	O/S BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
44.1	TOYO/YOKO or Falken
Bal, or Market Value: 6 50 k	Front
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. R/Bal. S
GIA / PR Seen: Consistent? : Yes or No	L/Bal. Pmm L/Bal. 5
Est. Repairs: 09 days Res.: Yes or No	D.O.A. 23/8/19 D.O.I. 2/78/19
Lum Sum: 20 % 3 Val.: Yes or No	Cummu hold at
CA / REV / REP. / 24 HRS	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
- Vehicle: IA	11 OUT N/S body
Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
	anected due to collision.
File pars To	4
CA not ready	
PECEIVE	TT 2 T 66T 2019
RECEIVE	D 2 Z 667 2019
RECEIVE	D 2 2 687 2019
RECEIVE	U 2 2 667 2019
RECEIVE	U 2 7 667 2019
RECEIVE	D 2 2 667 2019 Days Of Repair: 9
Who hair : Final Report	Resurvey No. of Trips
WID MMH : Final Report utc/Time, File Return to?	Resurvey No. of Trip:
W/10 hung : Final Report	Resurvey No. of TrIp: / Survey Fee: 290
: Prell. Report : Final Report uto/Time, File Return to? Add	Resurvey No. of TrIp: / Survey Fee: 290 Fee: : Site Insp (\$)S - RSSI
Prell. Report: : Final Report atc/Time, File Return to? Add in the port in t	Resurvey No. of Trip: / Survey Fee: 250 Fee: Site Insp (\$) S-RS_SI Interview (\$) FIRE S
: Prell. Report : Final Report uto/Time, File Return to? Add	Resurvey No. of Trip: / Survey Fee: 290 Transportation: See: 290 Transportation: See: Si See: Si

Nivitha (LKK Auto)

From:

Sent: To:

Daniel Koh <daniel.koh@income.com.sg>

Monday, 26 August 2019 1:05 PM

'assignments@lkkauto.com'

admin-d@lkkauto.com

Cc: Subject:

FW: TP CASES FARMED OUT TO LKK ON 26/8/2019

Dear LKK,

Resend with claim number & OIC

From: Daniel Koh

Sent: Monday, 26 August 2019 9:38 AM

To: 'assignments@lkkauto.com' <assignments@lkkauto.com>

Cc: 'admin-d@lkkauto.com' <admin-d@lkkauto.com>; Teng Ken Leong <kenleong.teng@income.com.sg>; Thio Tse Kiat <tsekiat.thio@income.com.sg>

Subject: FW: TP CASES FARMED OUT TO LKK ON 26/8/2019

Dear LKK,

Please assist to survey the following vehicles as per Mr Teng's instruction :-

	_	
	Additions	Remarks
		DOA
		OIV
	Survey	Time
		WorkShop Contact
	WorkShop	Address
	WorkShop	Name
		Vehicle
	7	Claim No.
		OIC
-	200	SN

Call workshop first before going down***		LKW Auto Services	SINGAPORE CUSTOMS - Revenue House B4 carpark (call Sufyan first	(0.0222240)
19/8/2019	22/8/2019	20/8/2019	2/8/2019	23/8/2019
GBH4856E	GBC3787D	SMK6038R	SIS4980R	SLX8891Z
			14:30-	
Edmund / 8787 5012	Agnes Lee/ 6846 9428 / 6748 6558	LK Wong / 9736 8619	Sufvan / 6355 2240	Daniel Tan/Cady Lee
176 SING MING DRIVE #04- 18 SIN MING AUTOCARE SINGAPORE 575721	BLK 176 SIN MING DRIVE #01- 10 SIN MING	176 SIN MING DRIVE #02- 01 SIN MING AUTOCARE SINGAPORE	SS NEWTON ROAD # REVENUE HOUSE B4 CARPARK SINGAPORE	160 SIN MING DRIVE #02- 13 SIN MING AUTOCITY
AUBURN AUTO PTE LTD	AUTOSOON PTE LTD	HOME	HOME	LEONG AUTO PTE LTD
9959TIS	SLU9482E	GBG1889K	QX447S	19629W1S
MT/1058656- 002	MT/1059034- 002	MT/1058714- 002	MT/1058762- 001	MT/1059241- 002
MUHAMMAD	JEFF LIN	SERENE LIM	AZHARI	ENG HUEY HUEY
н	2	м	4	2

Please contact workshops.

Please revert to officer-in-charge after survey.

Senior Admin Assistant www.income.com.sg Motor Insurance T+65 6430 7901 Daniel Koh













as an employer and what we want our people to exemplify.

Find out more at income.com.sg/careers

At Income, we are 'In with You' on Performance, Growth,

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

> Back to OneMotoring

-Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID: Vehicle Details	456E
Vehicle No.:	SLM6796L
Vehicle to be Exported:	No
Intended Deregistration Date:	15 Oct 2019
Vehicle Make:	MITSUBISHI
Vehicle Model:	ATTRAGE 1.2 CVT
Primary Colour:	Red
Manufacturing Year:	2016
Engine No.:	3A92UDT1048
Chassis No.:	MMBSTA13AHH004567
Maximum Power Output:	57.0 kW (76 bhp)
Open Market Value:	\$13,706.00
Original Registration Date:	06 Apr 2017
First Registration Date:	06 Apr 2017
Transfer Count:	0
Actual ARF Paid: Intended PARF Rebate Details	\$5,000.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	05 Apr 2027
PARF Rebate Amount: Intended COE Rebate Details	\$3,750.00
COE Expiry Date:	05 Apr 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$49,430.00
COE Rebate Amount:	\$36,941.00
Total Rebate Amount:	\$40,691.00

The information contained herein is correct as at 15 Oct 2019

SGCARMART.COM

Login Sign up

New Cars

Post an Ad

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources

Car Accessories & Products

Pimping up your ride? Browse thousands of car products for even more choices! Read honest reviews by our trusted consumers before you make a purchase.

Post an Advertisement Sell it yourself! Advertise it at just \$58 until it's SOLD!

Advertiser Login

Ways of Selling

1 And Only 528i M-Sports Individual, Rarel

Mileage, PML Unit, Very High

Direct Owner StarAd



▼ 20 results/page Sort by Date Posted ۳ Browse by Category 4 vehicles Mitsubishi Attrage Price Depreciation Reg Date Eng Cap Mileage Veh Type Model Search Selection Mitsubishi Attrage Available Any 2017 Any Anv Any \$49,800 14,332 km Available Mitsubishi Attrage 1.2A \$6,030 /vr 17-Aug-2017 1,193 cc Sedan 5 Years Agent Warranty, 1 Careful Owner, Value For Money With High Trade In Available. PREMIUM AD Mayfair Motoring Tags: 2017 Mitsubishi Attrage, 2017 mitsubishi attrage, Mitsubishi Attrage, mitsubishi attrage, Mitsubishi, Posted: 14-Oct-2019 Attrage, attrage, Used Mitsubishi Mitsubishi Attrage 1.2A \$49,800 \$6,460 /yr 09-Feb-2017 1.193 cc 24,929 km Sedan Available Full Agent Service And Maintained Since Day 1! Tip Top Condition With Low Mileage Clocked! Totally Look Like New Car Condition! Low Depreciation, Low Maintenance, Low Monthly Repayment! Trade In Welcome! Flexible Bank/In House Financing Available With Fast And... PREMIUM AD Benefit Auto Enterprise Pte Ltd Tags: 2017 Mitsubishi Attrage, 2017 mitsubishi attrage, Mitsubishi Attrage, mitsubishi attrage, Mitsubishi, Pasted: 09-Oct-2019 Attrage, attrage, Used Mitsubishi Mitsubishi Attrage 1.2A \$52,900 \$6,260 /yr 02-Nov-2017 1,193 cc 20,000 km Available Sedan Look No Further! Best Value For Your Money. Direct Owner'S Beautiful Grey, Nov '2017' Mitsubishi Attrage 1.2 CVT, Selling Due To Upgrading To New Car. Low Fuel Consumption, Low Maintenance. Original Paintwork Condition & Well Taken Care By Owner, Trade In... PREMIUM AD Tags: 2017 Mitsubishi Attrage, 2017 mitsubishi attrage, Mitsubishi Attrage, mitsubishi attrage, Mitsubishi, Attrage, Used Mitsubishi Mitsubishi Attrage 1.2A \$6,540 /yr 17-Aug-2017 1.193 cc 23,000 km Available Non Private Hire Unit! AA Trust Certified Pre-Owned Vehicle! Best Value For Your Money! Low Fuel Consumption, Low Maintenance! Original Paintwork Condition And Well Taken Care By Owner! Flexible Bank And In House Loan Available! Trade In Welcome! Hurry Call... AA Trust Automotive Tags: 2017 Mitsubishi Attrage, 2017 mitsubishi attrage, Mitsubishi Attrage, mitsubishi attrage, Mitsubishi, Attrage, attrage, Used Mitsubishi Posted: 23-Aug-2019 Save this search criteria, to get email alerts whenever a match is found Mileage Depreciation Reg Date Eng Cap Veh Type For old advertisements, view Expired ads ▼ results/page

> New Cars Used Cars | Sell My Car | Directory | Products | Insurance | Article | Forum | Resources Home

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used Mitsubishi Attrage, Mitsubishi Attrage, singapore, used Mitsubishi Attrage, well mileage cars, car brands, carpark rates & car insurance. Find buy used Mitsubishi Attrage, Mitsubishi Attrage, singapore, used Mitsubishi Attrage, mitsubishi Attrage, auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used Mitsubishi Attrage, Mitsubishi Attrage, singapore or even buy used Mitsubishi Attrage, singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current, sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

out Us | Careers | Contact Us | Sitemap | Terms of Service | Privacy Policy | Personal Data Protection Statement ©2004-2019 sgCarMart. All rights reserved.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATE	ΛEΝ	TV.
A A A A A A A A A A A A A A A A A A A		

26/08/2019 15:16 Date Of Report 23/08/2019 12:20 Date Of Accident

ORCHARD ROAD OUTSIDE CONCORDE HOTEL Exact Location Of Accident

SINGAPORE Country/State of Loss

DETAILS OF OWN VEHICLE

SLM6796L Vehicle Registration Number

Insured/Policyholder

ALEX 77 Name Of Registered Owner

53356456E Co Reg No

GMTANFAMILY911@GMAIL.COM **Email Address**

Mobile Phone No

OFFICE-90115021 Alternative Phone No

Vehicle Particulars

MITSUBISHI Manufacturer

ATTRAGE-1.2 CVT (A) Model

Exact Purpose for which vehicle was being used at

time of accident

Are you claiming under your own insurance policy

for repair to your vehicle?

If No, Please state action to be taken

THIRD PARTY PRIVATE HIRE

Vehicle Category

Insurance Company

NTUC INCOME INSURANCE CO-OPERATIVE LTD Name of Insurance Company

COMPREHENSIVE Type Of Coverage

NO Fleet Policy

5107422510 Policy Number

Cover Note Number

Driver

TAN PENG THONG Name of Driver

S7726238E NRIC No 11/09/1977 Date Of Birth INDOOR Occupation 28/11/1997 Date Of Driving Pass

21 YEARS AND 8 MONTHS **Driving Experience**

MALE Gender

(LOCAL) +65-83999224 Mobile Number

Fax Number

Contact Number

NOEMAIL **EMail Address**

Address

BLK 336B ANCHORVALE CRESCENT #03-40

Postcode

542336

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLISION - CHANGE/CROSS LANE

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO 2

Number of vehicles (including own vehicle)

involved in the accident

YES

Was any body injured in the Accident? Was any injured conveyed to hospital by

ambulance?

NO

Was any other material or property damaged?

YES

I have been approached by unknown person(s)

soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

4

Passenger 1

NAME:

: PASSENGER 1

GENDER:

: MALE

Passenger 2

NAME:

: PASSENGER 2

GENDER:

: FEMALE

Passenger 3

NAME:

: PASSENGER 3

GENDER:

: FEMALE

Details of Police Action

Was the accident reported to the police?

YES

If Yes, Please state which Police Station

Police Station Name

Police Station Address

SENGKANG NPC

ROAD: 2 SENGKANG SQUARE #01-02 , POSTCODE: 545025 , COUNTRY:

SINGAPORE

Police Station Contact

TEL NO: - FAX NO:

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN & POLICE REPORT.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SLX8891Z

Vehicle Make/Model/Colour

Details Of Properties

Page 2 of 14

PRIVATE CAR

Vehicle Category

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

TAN PENG THONG

Approximate Age

Injuries Sustain

Injured person in which vehicle?

Were seat belts worn?

YES

Was this injured conveyed to hospital by ambulance?

NO

Address

Postcode

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

- Please report <u>correctly</u> the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s)
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

(ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Driver's Signature

(If driver is not the policyholder) 299 89-50gn

Date & Time:

Reporting Centre Personnel's Signature Name:

NRIC/FIN No.:

A:SLM 6796L B:SLX 8891Z	ORCHARD ROAD. ONTSIDE CONCORDE HOTEL A A A A A A A A A A A A A
DESCRIBE CIRCUMSTANCES	THE ACCIDENT . 112-19 AS2 7 12:24
RE	ER TO POLICE REPORT : 7 20190823 2175
* Repair ofli	workslip &
DECLARATION I/We declare the pregoing part	Driver's Signature Reporting Centre Personnel's Signature
Policyholder Signature Date & Time:	(If driver is not the policyholder) Date & Time: NRIC/FIN No.:

Sketch Plan #2 Pg. 1





Police Station Of Origin: Sengkang N.P.C 2 Sengkang Square #01-02 SINGAPORE

Report No. T/20190823/2175

545025 Tel No: 1800-343 8999

REPORT OF A TRAFFIC ACCIDENT Date/Time Report Made: 23/08/2019 19:25			Vide Report No.:	Station Diary No. 192	
Informa	nt's Particu	ılars		10 10 10 10 10 10 10 10 10 10 10 10 10 1	
Name of	Informant: NG THONG		Address: APT BLK 336B ANCHORVAL SINGAPORE 542336	E CRESCENT #03-40	
ID Type / ID No.: NRIC NO / S7726238E			Contact No.: Home/Office:	Mobile: 83999224	
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Age: Date of Birth:		Date of Birth: 11/09/1977	Type of Informant: Driver	To the time of Only and Names	
Race: Chinese			Language: English	Institution / School Name:	
Occupation: GRAB DRIVER			Driving Licence Information: Class: 3,4	Date of Expiry:	

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 23/08/2019 12:20	Type of Location Straight Road
Location: Along Road 1 ORCHARD R		Road Surface:		Road Speed Limit:
Clear		Dry		Traffic Volume:
Traffic Flow: One Way		Traffic Control: Not Controlled		Light
Olie vvay	ion:			Anyone conveyed by ambulance:

Details of V			Model	Color	Condition	No of Passenge
Vehicle No.	Туре	Make	Model	00.0.		3
SLX6796L						
				_		0
SLX8891Z						

1. 1 6.2 (1.6) (1.6) (1.6) (1.6) (1.6) (1.6) (1.6) (1.6) (1.6) (1.6) (1.6) (1.6) (1.6) (1.6) (1.6) (1.6) (1.6)
Cassaing: NA
Use of Pedestrian Crossing: NA

Sketch Plan #2 Pg. 2



2 of 3

Police Station Of Origin: Sengkang N.P.C 2 Sengkang Square #01-02 SINGAPORE

Report No. T/20190823/2175

545025

Tel No: 1800-343 8999

CONTINUATION OF REPORT

Driver	A STATE OF THE STA	A Company of the Park	I ID No	a lanear	S7726238E	
Name	TAN PENG THONG		ID No.	2	3//20230L	
Related Vehicle	SLX6796L		Contact No		93999224	
Hospital/Clinic	SENGKANG GENERAL HOSP LTD.	ITAL PTE.	Class Driving Licent Expiry	e & Date	Class: 3,4 Date of Expiry: NIL	
Date Treatment	23/08/2019	Date Dis	charge		3/2019	
No. of Days gran	ted Medical Leave 03	Degree o	of Injury	NIL		
Driver			TID No.	CHELL	S7714763B	
Name	LEE TZE WHYE (LI ZHIWEI)		ID No	•	377147000	
Related Vehicle	SLX8891Z		Conta	ct No.	NIL	
Hospital/Clinic	NIL		Class Drivin Licen Expir	g	Class: NIL Date of Expiry: NIL	
Date Treatment	NIL	Date Dis		NIL		
	ted Medical Leave NIL	Degree	of Injury	NIL		

Brief Details.

On the 23/08/2019 at about 1220hrs, I was driving my vehicle SLX6796L along orchard road beside Concorde hotel. While I was driving on lane three, there was a vehicle SLX8891Z which was beside my vehicle and wanted to change lane. While changing lane, the said vehicle collided onto the left side portion of my vehicle. After the accident, both parties exchange particulars. The left side of my vehicle is damaged. As I felt pain on my body, I went to consult the doctor at Sengkang General Hospital and received three days of MC from 23/08/2019 till 25/08/2019.

Sketch Plan #2 Pg. 3





3 of 3

Police Station Of Origin: Sengkang N.P.C 2 Sengkang Square #01-02 SINGAPORE 545025 Tel No: 1800-343 8999 Report No. T/20190823/2175

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report: F / Sgt 3 DALJIT SINGH	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 23/08/2019 19:25
Officer In Charge Of Case: TP / AEIT / SI ANG YI TING, STEPHANIE Contact No.: 65476414	Classification Of Case.
Authentication Stamp	as one Parise of social

LEONG AUTO PTE LTD

16 Sin Ming Industrial Estate Sector A, #01-91, Singapore 575674
Tel: 64562218 Fax: 64599942 Email: Sales@leongauto.com.sg
Business Registration No. 201312846W
GST Registration No. 201312846W

Not Nothonial ESTIMATE
Date:
Businey After Point 9day

24/8/2019 23/8/2019

Vehicle No: SLM6796L

Make & Model: Mitsubishi Attrage

	Qty	el: Mitsubishi Attrage Item Description	Par	ts Price	Surveyor
1	1	Front Bumper RX	\$		Carroyor
2	1	Front Bumper L/H Retainer Sec. X	\$	-	
3	1	Front L/H Fender B4	\$	-	
4	1	Front L/H Fender Inner Shield 7	\$	-	
5		Front L/H Fender 1/4 Garnish	4		
6	1	Front L/H Door BT	Φ	-	
7		Front L/H Door Window Glass Moulding ?	\$	-	
	1		\$	-	
9	1		\$	-	
	1	Front E/T Boor Lock Catch		-	
10 11	1		\$	-	
	1	A TANAN CONTROL OF THE PROPERTY OF THE PROPERT		-	
12	1	Tront Entrador Total Trindon Trial Togalator	\$		
13	1	Front L/H Door Black Tape	\$	-	
14 15	2	Front L/H Door Hinges ? Front L/H Door Checker ?	\$	-	
	1		\$	-	
16	1	Rear L/H Door Moulding 2	\$	-	
17	1	Rear L/H Door Window Glass Moulding 7	\$	-	
18	1	Rear L/H Door Lock Mechanism	\$	-	
19	1	Rear L/H Door Lock Catch	\$	-	
20	1	Rear L/H Door Weatherstrip	\$	-	
21	1	Rear L/H Door Inner Trim Board 7	\$	-	
22	1	Rear L/H Door Power Window with Regulator 7	\$	-	
23	1	Rear L/H Door Black Tape	\$	-	
24	2	Rear L/H Door Hinges	\$		
25	1	Rear L/H Door Checker	\$	-	
26	1	Rear L/H Fender	Saca	uto Consulia	ts hence notify
27	1	Rear L/H Fender Inner Shield	Me Re	enairer of the	followings
28	1	Rear Bumper ?	- 17715	MIXEN DELINERALIS	H SDAILY DAMINING
29	1	Rear Bumper L/H Retainer	\$ 0.00	play dameged of	rtisi during resurvey.
30	1	Front L/H Rim		prices are-subject	
31	1	Front L/H Shock Absorber	\$	being survey is of	
32	1	Front L/H Wheel Bearing .	\$	gal modification Empiriture Norway	
33	1	Front L/H Knuckle Arm 7	Ya Sub	act to final above	must be resurveyed a val from Insurance Co
34	1	Front L/H Lower Arm 7	Ψ		
35	1	Front L/H Stabilizer Link		ledged by-Repair	
	1	Rear w/s glass mill X	\$	193 -	
			\$	-	
			\$		
		Less 15%	\$	170	
			\$	-	
		Special Nett Items			_
1		Sundries	\$	50.00	7
		Front Bumper Clips		∼ 50.00	X
		Front L/H Fender Inner Shield Clips		50.00	1
		Front L/H Door Inner Trim Board Clips	\$	50.00	7
		Rear L/H Door Inner Trim Board Clips	\$	50.00	7
6	1 set	Rear L/H Fender Inner Shield Clips	\$ 1	~ 50.00	×

7	1 set	Rear Bumper Clips	\$	50.00	?
8	1	Front L/H Tyre	\$	380.00	7
	1	Rear wis glass sealant 120 Your		730.00	2
		in in Damping seal 120th 3050	,		
		Total Parts	\$	730.00	
	S/N	Labour Description		Amount	Amount
	1	Labour for panel beating, cut, weld, straighten and replace front and Rear door, and Rear Fender	\$	2,200.00	1000 12001 2001 1201
	2	To putty and spray painting front and rear portion.	\$	1,800.00	12001
	3	To check wiring for front and rear Door	\$	80.00	ar 301
	4	To apply anti rust proofing to front affected area.	\$	250.00	1201
	5	To remove and install inner garnish and trim to facilitate the repair.	\$	350.00	1001
	6	To remove and install rear fuel tank to facilitate the repairs.	\$	150.00	601
	7	To remove & refit boot lid componenet to replace door, check & re-adjust the close gap and alignment and water seepage	\$	120.00	_
		Total labour :	\$	4,680.00	
		Total parts :	\$		
		Total labour :	\$	4,680.00	9
		Total repair cost : (Before GST)			

Remove & install rear 11/5 150 1200

To perform at whoel Alighment 150 606

Work Order:

R033475

VIN:

SLM6796L

Year:

Date

23.8.19 17:08



Mitsubishi: Mirage/Attrage: 2012- (Including G4)

Front : Left

Actual	Before	Specified Range
-2°37'	-2°37'	-0°40' 0°50'
2°47'	2°47'	3°15' 4°45'
0°27'	0°27'	-0°07' 0°07'
15°48'	15°48'	10°05' 13°05'
13°11'	13°11'	9°25' 13°55'
10 11	6	

Camber Caster Toe SAI Included Angle Turning Angle Diff.

Actual	Before	Specified Range
-0°32'	-0°33'	-0°40' 0°50'
3°23'	3°23'	3°15' 4°45'
0°13'		-0°07' 0°07'
13°28'	13°29'	10°05' 13°05'
12°56'		9°25' 13°55'

Front

Cross Camber **Cross Caster** Cross SAI **Total Toe** Cross Turn Diff.

Actual	Before	Specified Range
-2°05'	-2°04'	-0°30' 0°30'
-0°35'	-0°35'	-0°30' 0°30'
2°20'	2°19'	
0°40'	0°41'	-0°14' 0°14'

Rear: Left

Specified Range Before Actual -1°45' -0°15' -1°45' 1°45 -0°01' 0°13' 0°09

Camber Toe

Rear : Right						
Actual	Before	Specified Range				
-1°47'	-1°48'	-1°45' -0°15'				
0°06'	0°05'	-0°01' 0°13'				

Rear

Cross Camber **Total Toe** Thrust Angle

Actual	Before	Specified Range
0°02'	0°03'	-0°30' 0°30'
0°15'	0"14"	-0°02' 0°26'
0°02'	0°02'	

Kg

LEONG AUTO PTE LTD

16 Sin Ming Industrial Estate Sector A, #01-91, Singapore 575674
Tel: 64562218 Fax: 64599942 Email: Sales@leongauto.com.sg
Business Registration No. 201312846W
GST Registration No. 201312846W

ESTIMATE sony After Poin 24/8/2019 Date: DOA: 23/8/2019 Vehicle No: SLM6796L Make & Model: Mitsubishi Attrage S/N Qty Item Description Parts Price Surveyor RX 1 Front Bumper mgim \$ 713.00-2 Front Bumper L/H Retainer \$ 41.00 - X 3 Front L/H Fender 438 \$ 569.00-4 Front L/H Fender Inner Shield \$ 102.00-\$99,00 -5 Front L/H Fender 1/4 Garnish 876.50 \$962.00-6 Front L/H Door 7 Front L/H Door Window Glass Moulding \$172.00 -Front L/H Door Lock Mechanism 8 \$ 311.00 Front L/H Door Lock Catch 9 \$2200 \$140.00-Front L/H Door Weatherstrip 10 11 Front L/H Door Inner Trim Board \$803 00mount Front L/H Door Power Window with Regulator 352 12 \$506.00-\$ 3000 13 Front L/H Door Black Tape ner. \$107.00 14 2 Front L/H Door Hinges 1 our 42 15 Front L/H Door Checker Sn X \$4-9.00 -1 846. \$1,000000 16 Rear L/H Door Rear L/H Door Window Glass Moulding \$81,00-17 RX 18 Rear L/H Door Lock Mechanism 12 X \$ 22.00 -19 Rear L/H Door Lock Catch \$140.00-20 Rear L/H Door Weatherstrip 21 Rear L/H Door Inner Trim Board Sn Rear L/H Door Power Window with Regulator 35272 22 \$506.00 -23 ne \$ 30.00 Rear L/H Door Black Tape 1 24 2 Rear L/H Door Checker Rear L/H Door Checker 723 Rear L/H Door Hinges RX 25 Sux 1 26 \$ 41.00 27 Rear L/H Fender Inner Shield \$ 758 -00 28 1 Rear Bumper \$ 28.00 29 1 Rear Bumper L/H Retainer 760.00-30 1 Front L/H Rim 480 \$325.00-31 1 Front L/H Shock Absorber 4\$122.00-32 1 Front L/H Wheel Bearing M \$ 353.00. 33 1 Front L/H Knuckle Arm Talken 304 1115326.00-34 Front L/H Lower Arm alisnmy 35 Front L/H Stabilizer Link \$ 30.00-MAY ST? \$ W/s glass in b \$ \$ 6,640 996 Less 15% \$ \$ 5-644 Special Nett Items M 50.00 Sundries \$ ~~ 50.00 Х 1 set Front Bumper Clips \$ 2 Ma 50.00 1 set Front L/H Fender Inner Shield Clips 3 MG 50.00 1 set Front L/H Door Inner Trim Board Clips 4 N~ 50.00 5 1 set Rear L/H Door Inner Trim Board Clips 1 set Rear L/H Fender Inner Shield Clips ~~ 50.00

7 1 set Rear Bumper Clips
8 1 Front L/H Tyre
1 Room W/s 3/ass sealout M 120 Pains 730.00 7
1 a 0amping seal 120 3050
Total Parts
Mn \$ 730.00 5914

S/N	Labour Description	Amount	Amount	
	Labour for panel beating, cut, weld, straighten and replace		14	
1	front and Rear door, and Rear Fender	\$ 2,200.00	1000	
2	To putty and spray painting front and rear portion.	\$ 1,800.00	12001	
3	To check wiring for front and rear Door	\$ 80.00	ar 301	
4	To apply anti rust proofing to front affected area. To remove and install inner garnish and trim to facilitate the	\$ 250.00	1201	
5	repair.	\$ 350.00	1001	
6	To remove and install rear fuel tank to facilitate the repairs. To remove & refit boot lid componenet to replace door,	\$ 150.00	601	
7	check & re-adjust the close gap and alignment and water seepage	\$ 120.00		
	Total labour:	\$ 4,680.00	2550	4950
	Total parts : Total labour :	\$ 4,680.00	5914 7550	
	Total repair cost : (Before GST)		8464	

Remove & install rear w/s 150 1200

" " fort c/H undercerraige 380 ? 1800

perform 4 whool Hlighment 150 600

70% → 6771.20 6750

4088.30



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT NTUC INCOME INSURANCE CO-OPERATIVE LTD CS/INC19014984/Kqd3e2 Ref: Date: 25-10-2019 73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556 Code: INC ATTN: ENG HUEY HUEY Policy Particulars :- THIRD PARTY CLAIM 1. Veh. Inspected **SLM 6796L** Insured Veh. SLX 8891Z 0.00 Coverage (\$) Policy No. 0.00 MT/1059241-002 Excess (\$) Claim No. 26/08/2019 DANIEL KOH **Assign Date Assign From** Vehicle Particulars & Condition 2. 1193 Make & Model MITSUBISHI ATTRAGE (A) C.C 2017 Year of Reg. HIDDEN Engine No. METALLIC RED Chassis No. MMBSTA13AHH004567 Colour IN ORDER Odometer 227328 KM Steering STANDARD ALLOY RIM IN ORDER Modification **Brakes** GOOD General **Conditions of Tyres** 3. Make Balance Size **FALKEN** 8 mm 185/55 R15 R/H Front Tyre 8 mm 185/55 R15 **FALKEN** L/H Front Tyre YOKOHAMA 5 mm 185/55 R15 R/H Rear Tyre YOKOHAMA 5 mm 185/55 R15 L/H Rear Tyre **Description of Damages** 4. THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS. **General Information** 5. Inspect Date / Time 26/08/2019 (11:24 AM) **Accident Date** 23/08/2019 Survey held at LEONG AUTO PTE LTD 160 SIN MING DRIVE #02-13 SIN MING AUTOCITY SINGAPORE 575722 Remarks 5a. A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. **Estimate Days of Repair** 5b. ESTIMATED NORMAL PERIOD FOR REPAIR: 9 Working Days



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLM 6796L

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER	MTG CRACKED	713.00	713.00
	FRONT BUMPER L/H RETAINER	SERVICEABLE	41.00	8
1	FRONT L/H FENDER	BENT	569.00	438.00
1	FRONT L/H FENDER INNER SHIELD	CRACKED	102.00	102.0
1	FRONT L/H FENDER 1/4 GARNISH	SERVICEABLE	99.00	6
1	FRONT L/H DOOR	BENT	962.00	876.5
1	FRONT L'H DOOR WINDOW GLASS MOULDING	DENTED	172.00	172.0
1	FRONT L/H DOOR LOCK MECHANISM	TO REPAIR SEE LABOUR	311.00	
1	FRONT L/H DOOR LOCK CATCH	TO REPAIR SEE LABOUR	22.00	
1	FRONT L/H DOOR WEATHERSTRIP	CUT	140.00	140.0
	FRONT L/H DOOR INNER TRIM BOARD	MTG CRACKED	803.00	750.0
	FRONT L/H DOOR POWER WINDOW WITH REGULATOR	BENT	506.00	352.0
	FRONT L/H DOOR BLACK TAPE	NECESSARY	30.00	30.0
	FRONT L/H DOOR HINGES	LOWER BENT	107.00	53.5
	FRONT L/H DOOR CHECKER	SERVICEABLE	49.00	
	REAR L/H DOOR	BENT	1,080.00	846.0
1	REAR L/H DOOR WINDOW GLASS MOULDING	NECESSARY	81.00	81.0
1	REAR L/H DOOR LOCK MECHANISM	TO REPAIR SEE LABOUR	311.00	
1	REAR L/H DOOR LOCK CATCH	TO REPAIR SEE LABOUR	22.00	
1	REAR L/H DOOR WEATHERSTRIP	SERVICEABLE	140.00	
	REAR L/H DOOR INNER TRIM BOARD	SERVICEABLE	782.00	
	REAR L/H DOOR POWER WINDOW WITH REGULATOR	DISTORTED	506.00	352.
1	REAR L/H DOOR BLACK TAPE	NECESSARY	30.00	30.
	REAR L/H DOOR HINGES	TO REPAIR SEE LABOUR	54.00	
1	REAR L/H DOOR CHECKER	SERVICEABLE	49.00	P
	REAR L/H FENDER	BENT	974.00	923.
	REAR L/H FENDER INNER SHIELD	SERVICEABLE	41.0	o

Report Ref No. CS/INC19014984/Kqd3e2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1	REAR BUMPER	MTG CRACKED	758.00	758.00
1	REAR BUMPER L/H RETAINER	SERVICEABLE	28.00	-
1	FRONT L/H RIM	DENTED	760.00	480.00
1	FRONT L/H SHOCK ABSORBER	BENT	325.00	325.00
1	FRONT L/H WHEEL BEARING	NECESSARY	122.00	122.00
	FRONT L/H KNUCKLE ARM	BENT	353.00	329.00
1	FRONT L/H LOWER ARM	DISTORTED	326.00	304.00
1	FRONT L/H STABILIZER LINK	SERVICEABLE	30.00	-
1	REAR W/S GLASS MLD (NPA)	NOT NECESSARY	-	-
	LESS 15% DISCOUNT		-1,709.70	-1,226.55
			9,688.30	6,950.45
	SPECIAL NETT ITEMS			
1	SUNDRIES (SN)	NECESSARY	50.00	50.00
1	SET FRONT BUMPER CLIPS (SN)	NOT NECESSARY	50.00	-
1	SET FRONT L/H FENDER INNER SHIELD CLIPS (SN)	NECESSARY	50.00	50.00
1	SET FRONT L/H DOOR INNER TRIM BOARD CLIPS (SN)	NECESSARY	50.00	50.00
1	SET REAR L/H DOOR INNER TRIM BOARD CLIPS (SN)	NOT NECESSARY	50.00	-
-1	SET REAR L/H FENDER INNER SHIELD CLIPS (SN)	NOT NECESSARY	50.00	-
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	50.00	50.00
1	FRONT L/H TYRE (SN)	SERVICEABLE	380.00	-
1	REAR W/S GLASS SEALANT (SN)	NECESSARY	120.00	40.00
1	REAR W/S GLASS DAMPING SEAL (SN)	NECESSARY	120.00	30.00
	A Community (Control of the Control		970.00	270.00
	LABOUR			
	LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN AND REPLACE FRONT AND REAR DOOR, AND REAR FENDER. INCLUSIVE OF THE REPAIR OF FRONT L/H DOOR LOCK MECHANISM, FRONT L/H DOOR LOCK CATCH, REAR L/H DOOR LOCK MECHANISM, REAR L/H DOOR LOCK CATCH AND REAR L/H DOOR HINGES.		2,200.00	
	TO PUTTY AND SPRAY PAINTING FRONT AND REAR PORTION.		1,800.00	
	TO CHECK WIRING FOR FRONT AND REAR DOOR.		80.00	30.00

Report Ref No. CS/INC19014984/Kqd3e2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	TO APPLY ANTI RUST PROOFING TO FRONT AFFECTED AREA.		250.00	120.00
	TO REMOVE AND INSTALL INNER GARNISH AND TRIM TO FACILITATE THE REPAIR.		350.00	100.00
	TO REMOVE AND INSTALL REAR FUEL TANK TO FACILITATE THE REPAIRS.		150.00	60.00
	TO REMOVE AND REFIT BOOT LID COMPONENT TO REPLACE DOOR, CHECK & RE-ADJUST THE CLOSE GAP AND ALIGNMENT AND WATER SEEPAGE.		120.00	120.00
	REMOVE & INSTALL REAR W/S.		150.00	120.00
	REMOVE & INSTALL FRT L/H UNDERCARRIAGE.		380.00	180.00
	TO PERFORM 4 WHEEL ALIGNMENT.		150.00	60.00
			5,630.00	3,090.00
	GRAND TOTAL		16,288.30	10,310.45

RECOMMENDED COST OF LUMP SUM REPAIRS	8,200.00
(TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)	

Report Ref No. CS/INC19014984/Kqd3e2

KONG SENG CHEONG

Licensed Appraiser

K.K.LAU CPT(RET)

K.K.LAU CPI(REI)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.