



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM19014986/Eps3q2

8 SHENTON WAY #24-01  
AXA TOWERSINGAPORE 068811

Date : 14-05-2020



ATTN:STACEY NG

Code : ASM

#### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLR 8406Z	Veh. Inspected	SLL 7827E
Policy No.	GA367891	Coverage (\$)	0.00
Claim No.	S9M01Y9I	Excess (\$)	0.00
Assign From		Assign Date	26/08/2019

#### 2. Vehicle Particulars & Condition

Make & Model	KIA FORTE K3	c.c	1591
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	KNAFJ411MH5708152	Colour	BLUE
Odometer	130531	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

#### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	KUMHO	5 mm
L/H Front Tyre	195/65 R15	KUMHO	5 mm
R/H Rear Tyre	195/65 R15	KUMHO	5 mm
L/H Rear Tyre	195/65 R15	KUMHO	5 mm

#### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.
---

#### 5. General Information

Accident Date	19/07/2019	Inspection Date	26/08/2019
Survey held at	60 JALAN LAM HUAT #04-01		
Repairer	LION CITY RENTALS PTE LTD		

#### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

#### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	2 Working Days
-------------------------------------	----------------