## LCRF PTE LTD CARROS CENTER 60 JALAN LAM HUAT #04-01 S(737869) Main +65 62524991

Ms AXA Insurance Pte Ltd

Date: 19/7/2019

Attn: MOTOR CLAIMS DEPT

**ESTIMATE** 

VEHICLE NO.: SLL7827E

CHASSIS NO: KNAFJ411MH5708152 MAKE / MODEL: KIA Forte K3 1.6 Auto DATE OF ACCIDENT: 19/07/2019

Your Insured: SLR8406Z

MILEAGE:

1

## **LABOUR CHARGES**

\$600.00 750

To labour charge for knocking out dents of F/R fender and F/R door

2 To respray F/R fender and F/R door

\$600.00 \$000 LABOUR TOTAL S\$: \$1,200.00 TOTAL S\$: \$1,200.00 7% GST \$84.00 GRAND TOTAL S\$: \$1,116.00

Stor CLKK) Who print 248/19, 11.01an
2 dy

P/P

Ry A: Sy

## LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer Signature:

oignat

Date: