

Cecilia

利 沈 車 噴 漆 私 人 有 限 公 司
RAAIM CAR BODYWORKS PTE LTD

Blk 2 Kranji Loop #01-04 Singapore 739538

Tel: 6694 3197 Fax: 6694 3191

FINALIZATION FORM

ATTN TO: STEVE / LKK
Surveyor Name and Company

Date of Accident : **23-Aug-2019**

BILL TO: AXA
TP Insurer

VEHICLE REG. NO.

TYPE OF CLAIM: TP

SLC3731X

Make / Model : **B180 STYLE (R16 LED)**

COST OF CLAIMS

Parts Cost / List : \$ 7,812.00

Supp. Parts : \$ 802.00

Special Nett : \$ 155.00

Total Parts : \$ 7,907.60

Total Labour : \$ 1,520.00

TOTAL REPAIR COST : \$ 9,427.60

Total Parts Cost/List :	\$	8,614.00
Plus / Less : 10%	\$	861.40
Total :	\$	7,752.60

Lump Sum Discount : 20%	\$	1,885.52
Lump Sum Amount:	\$	7,542.08

Final Lump Sum Amount : \$ 7,500.00

Submitted by / Date : PAULO

No. of Repair Days: 6

Confirmed by / Date : _____

P- 6122.70
M- 155
L- 1720
Supp- 721.80
8719.50
L/S - 6975.60
- 7000

利 汽 車 噴 漆 有 限 公 司
RAAIM CAR BODYWORKS PTE LTD

Blk 2 Kranji Loop #01-04 Singapore 739538

Tel: 6694 3197 Fax: 6694 3191

Vehicle Reg. No.: **SLC3731X**
Vehicle Reg. Date: **12/5/2016**
Make / Model: **B180 STYLE (R16 LED)**
Engine No.: **.27091030912087.**
Chassis No.: **WDD2462422J388785**

Store (CLKK)

will Arrive

6 days

L/S

Rey AL

26/8/19, 12.00pm

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	1	Tail gate / DD		\$ 1,945.00		\$ 1,945.00
2	1	Tail gate lock / BT		\$ 292.00		\$ 292.00
3	1	Tail gate striker X		\$ 32.00		
4	2	Tail gate stay LH/RH X		\$ 72.00		
5	1	Tail gate logo X		\$ 49.00		\$ 49.00
6	1	Tail gate emblem / MC		\$ 83.00		\$ 83.00
7	1	Tail gate outer garnish chrome X		\$ 235.00		
8	2	Tail gate lamp LH/RH (LH) / CUT		\$ 890.00		\$ 445.00
9	1	Tailgate wiper motor X		\$ 265.00		
10	1	Tail gate weatherstrip / CR4		\$ 202.00		\$ 202.00
11	1	Tail gate inner board X		\$ 218.00		
12	1	Tail gate inner board Lamp X		\$ 55.00		
13	1	Tail gate inner handle X		\$ 85.00		
14	1set	Tailgate windscreen glass moulding / MC		\$ 680.00		\$ 680.00
15	2	Tail lamp LH/RH (LH) / CUT		\$ 976.00		\$ 488.00
16	2	Tail lamp panel LH/RH X		\$ 410.00		
17	2	Plate Lamp LH/RH X		\$ 80.00		
18	1	Antenna sensor X				
19	1	Rear end panel outer / DD		\$ 1,004.00		\$ 1,004.00
20	1	Rear end panel inner X R		\$ 590.00		
21	1	Rear end panel garnish / CR4		\$ 382.00		\$ 382.00
22	1	Spare tyre well panel X		\$ 850.00		
23	1	Spare tyre board X		\$ 165.00		
24	1	Spare tyre bracket X				
25	1	Spare tyre insulator X		\$ 755.00		
26	1	Spare tyre tool tray X				
27	1	Rear bumper / DD		\$ 1,518.00		\$ 1,518.00
28	1	Rear bumper chrome garnish upper / CUT		\$ 245.00		\$ 245.00
29	1	Rear bumper chrome garnish lower / CRA		\$ 211.00		\$ 211.00
30	1set	Rear bumper clips / MC		\$ 30.00		\$ 30.00
31	2	Rear bumper side retainer LH/RH / BR		\$ 50.00		\$ 50.00
32	2	Rear bumper bracket LH/RH X		\$ 112.00		
33	2	Rear fender LH/RH X		\$ 4,640.00		
34	2	Rear fender air duct LH/RH X		\$ 78.00		
35	1	Rear tow hook cover X		\$ 47.00		
36	1	Exhaust muffler X		\$ 1,180.00		
37	1Set	Exhaust muffler mounting X		\$ 74.00		
38	1	Exhaust heat shield X		\$ 132.00		
39	1SET	Reverse sensor (IPC) Short		\$ 188.00		\$ 188.00
40	1	Reverse Camera X		\$ 1,535.00		

1790 /
181 /

210 /

890 /

1429 /

6803

- 10%

6122.70

利 汽 車 噴 漆 有 限 公 司
RAAIM CAR BODYWORKS PTE LTD

Blk 2 Kranji Loop #01-04 Singapore 739538

Tel: 6694 3197 Fax: 6694 3191

Vehicle Reg. No. : SLC3731X
Vehicle Reg. Date: 12/5/2016
Make / Model : B180 STYLE (R16 LED)
Engine No. : .27091030912087.
Chassis No. : WDD246242J388785

PAGE 2

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
41	1	Spare tyre panel sealant X				
42	1	Spare tyre sound damper X				
43	1	Sundries / NPC			\$ 30.00	/
44	1	Tail gate seal / NPC			\$ 30.00	/
45	1	Rear number plate with frame / CUT			\$ 35.00	/
46	1	Rear windscreen glass sealant / NPC			\$ 40.00	/
47	1	Rear windscreen glass primer & cleaner / NPC			\$ 20.00	/
48	1	Rear end panel sealant X				
49	0	0				
50	0	0				
51	0	0				
52	0	0				
53	0	0				
54	0	0				
55	0	0				
56	0	0				
57	0	0				
58	0	0				
59	0	0				
60	0	0				
61	0	0				
62	0	0				
63	0	0				
64	0	0				
65	0	0				
66	0	0				
67	0	0				
68	0	0				
69	0	0				
70	0	0				
71	0	0				
72	0	0				
73	0	0				
74	0	0				
75	0	0				
76	0	0				
77	0	0				
78	0	0				
79	0	0				
80	0	0				

\$ 155.00 /

Tel: 6694 3197 Fax: 6694 3191

PAGE 1

[illegible]

Date:

利 汎 車 噴 漆 有 限 公 司
RAAIM CAR BODYWORKS PTE LTD

Blk 2 Kranji Loop #01-04 Singapore 739538

Tel: 6694 3197 Fax: 6694 3191

Vehicle Reg. No. : **SLC3731X**

Vehicle Reg. Date: **12/5/2016**

Make / Model : **B180 STYLE (R16 LED)**

Engine No. : **.27091030912087.**

Chassis No. : **WDD2462422J388785**

PAGE 1

Supplementary Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	1	REAR BUMPER REINFORCEMENT / DD		\$ 480.00		\$ 480.00
2	1	REAR BUMPER LOWER (BLACK) / CP4		\$ 167.00		\$ 167.00
3	1	REAR BUMPER CENTER BRACKET / CP4		\$ 155.00		\$ 155.00
4						
5						
6						
7						
8						
9						
10						
11						
12						
13						
14						
15						
16						
17						
18						
19						
20						
21						
22						
23						
24						
25						
26						
27						
28						
29						
30						

802
10%
721.80

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

利汽车喷漆私人有限公司
RAAIM CAR BODYWORKS PTE LTD

SLC3731X

Raaim Car Bodyworks Pte Ltd (Co.Reg. No: 201327842N)
Blk 2 Kranji Loop #01-04 Singapore 739538
Tel: 6694 3197 Fax: 6694 3191

ACCIDENT REPAIR ESTIMATE

TP INSURER : AXA
OWN INSURER : NTUC
CLAIM TYPE : TP
Date of Accident : 23/8/2019

Vehicle Reg. No. : SLC3731X
Vehicle Reg. Date: _____
Make / Model : MERCEDES. B180
Engine No. : _____
Chassis No. : WDD24624221388785

*Resurvey Steve
27/8/19*

COST OF CLAIMS

Parts Cost / List Items : \$ -
Plus/Less 10% \$ -
Total Cost / List : \$ -
Special Nett Items : \$ 820.00
Total Parts Amount : \$ 820.00
Total Labour Amount : \$ 4,970.00
Gross Total : \$ 5,790.00
GST % : 7% \$ 405.30
Nett Amount : \$ 6,195.30

Surveyor Name and Company :

Date of survey : _____
Part by Part / Lump Sum : _____ days
Resurvey Before Paint / After Paint
Authorize/Not Authorize/Without Prejudice
Email : _____
Fax No : _____
HP No : _____

This claim is handled by : PAULO

利 汽 车 喷 漆 有 限 公 司
RAAIM CAR BODYWORKS PTE LTD

Blk 2 Kranji Loop #01-04 Singapore 739538

Tel: 6694 3197 Fax: 6694 3191

Vehicle Reg. No.: **SLC3731X**
Vehicle Reg. Date: **0/1/1900**
Make / Model: **MERCEDES. B180**
Engine No.: **0**
Chassis No.: **WDD2462422J388785**

Steve (LKK)
5377 8813
Steve.km@lkk.com

WHL ML 26/8/19, 12.00pm
6 \$ days
L/S
Ry AG

Steve 27/8/19

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	1	Tail gate / DD				
2	1	Tail gate lock / BT				
3	1	Tail gate striker X				
4	2	Tail gate stay LH/RH X				
5	1	Tail gate logo / MC				
6	1	Tail gate emblem / MC				
7	1	Tail gate outer garnish chrome X				
8	1	Tail gate lamp LH/RH (LH) / CWT				
9	2	Tailgate wiper motor X				
10	1	Tail gate weatherstrip / CR4				
11	1	Tail gate inner board ? X				
12	1	Tail gate inner board Lamp X				
13	1	Tail gate inner handle X				
14	1set	Tailgate windscreen glass moulding / MC				
15	2	Tail lamp LH/RH (LH) / CWT				
16	2	Tail lamp panel LH/RH X				
17	2	Plate Lamp LH/RH X				
18	1	Antenna sensor ? X				
19	1	Rear end panel outer X / DD				
20	1	Rear end panel inner X / R				
21	1	Rear end panel garnish ? / CR4				
22	1	Spare tyre well panel X				
23	1	Spare tyre board X				
24	1	Spare tyre bracket X				
25	1	Spare tyre insulator X				
26	1	Spare tyre tool tray X				
27	1	Rear bumper / DD				
28	1	Rear bumper chrome garnish upper / CWT				
29	1	Rear bumper chrome garnish lower / CRA				
30	1set	Rear bumper clips / MC				
31	2	Rear bumper side retainer LH/RH / BR				
32	2	Rear bumper bracket LH/RH ? X				
33	2	Rear fender LH/RH X				
34	2	Rear fender air duct LH/RH X				
35	1	Rear tow hook cover X				
36	1	Exhaust muffler X				
37	1Set	Exhaust muffler mounting X				
38	1	Exhaust heat shield X				
39	1SET	Reverse sensor (1K) SHOT				
40	1	Reverse Camera X				

利 汽 车 喷 漆 有 限 公 司
RAAIM CAR BODYWORKS PTE LTD

Blk 2 Kranji Loop #01-04 Singapore 739538

Tel: 6694 3197 Fax: 6694 3191

Vehicle Reg. No. : SLC3731X
Vehicle Reg. Date: 0/1/1900
Make / Model : MERCEDES. B180
Engine No. : 0
Chassis No. : WDD246242J388785

PAGE 2

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
41	1	Spare tyre panel sealant X			\$ 100.00	
42	1	Spare tyre sound damper X			\$ 250.00	
43	1	Sundries / AK			\$ 60.00	30
44	1	Tail gate seal / AK			\$ 100.00	30
45	1	Rear number plate with frame / (11)			\$ 50.00	35
46	1	Rear windscreen glass sealant / AK			\$ 100.00	40
47	1	Rear windscreen glass primer & cleaner / AK			\$ 60.00	20
48	1	Rear end panel sealant X			\$ 100.00	
49	0	0				
50	0	0				
51	0	0				
52	0	0				
53	0	0				
54	0	0				
55	0	0				
56	0	0				
57	0	0				
58	0	0				
59	0	0				
60	0	0				
61	0	0				
62	0	0				
63	0	0				
64	0	0				
65	0	0				
66	0	0				
67	0	0				
68	0	0				
69	0	0				
70	0	0				
71	0	0				
72	0	0				
73	0	0				
74	0	0				
75	0	0				
76	0	0				
77	0	0				
78	0	0				
79	0	0				
80	0	0				

\$ 820.00

Tel: 6694 3197 Fax: 6694 3191

PAGE 1

[illegible]

\$

利 汽 车 喷 漆 有 限 公 司
RAAIM CAR BODYWORKS PTE LTD

Blk 2 Kranji Loop #01-04 Singapore 739538

Tel: 6694 3197 Fax: 6694 3191

Vehicle Reg. No. : SLC3731X
Vehicle Reg. Date: 12/5/2016
Make / Model : B180 STYLE (R16 LED)
Engine No. : .27091030912087.
Chassis No. : WDD2462422J388785

Steve 27/5/19

PAGE 1

Supplementary Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	1	REAR BUMPER REINFORCEMENT / <i>CR4</i>				
2	1	REAR BUMPER LOWER (BLACK) / <i>CR4</i>				
3	1	REAR BUMPER CENTER BRACKET / <i>CR4</i>				
4						
5						
6						
7						
8						
9						
10						
11						
12						
13						
14						
15						
16						
17						
18						
19						
20						
21						
22						
23						
24						
25						
26						
27						
28						
29						
30						