(C3/MSC	9 19014999 / Ugf3n2
(08/11/43) wef REF:	M516/
ASS. REC. BY: March	
t ASS	IGNMENT 7
From: Date:	Veh No: SLL 30024 Yr Regn: 417
Estingated Cost:	Type: M.Carl M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD IT WS ITP RES / OD RES / EVA / INV / MV	Truck/Trailer or
To Inspect Vehicle No: SLL 30024	Make: Mezbe 3 c.c 1496
at Workshop m/s	Colour 3hul A/C: Insured / Std / NI / NA
of	Sp.Reading 4698 T/Radio: Insured / Std / NI / NA
SLA 7018A	Eng/No:
Insured: SLP 7018 A Policy No. 2911 4756 MKF	C/No: JM6BN22A8H0141435
6041 8	Gen. Cond: Good / Fair / Poor / Burnt
Oldinis No.	Steering: Inorder Jammed / Leaked / Burnt or
Sulli liladied.	Brake: Inorder / Jammed / Leaked / Burnt or
(Client's Record) Make of Veh:	Modi: Nil /S/Rim / STD A/Rim or
Make of Vetr.	Tyre Size: F: 205/602/6
	R:
(Policy Condition) N/S O/S	BS DUN EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
Remark: The veh had commenced its N/S O/S repair at the time of inspection.	TOYO / YOKO or
(2)	
Bal, Of Walket Value.	Front Rear R/Bal. 7 mm
IDAC Accident Rport: Consistent? : Yes or No	L/Bal. 7 mm L/Bal. 7 pm
Consistent?: Yes or No	11 - 1/2/2
Est. Repairs: 4 days Res.: Yes or No	(4/0/1/)
Lum Sum: 20 % 3 Val.: Yes or No	Survey held at
CA / REV / REP. / 24 HRS	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
Vehicle: IN / C	The U/C / Chassis frame / Body Structure affected due to collision.
	Tills did i diadala fiama i 200) 4
The state of the s	
27/8/19@ 9.76 as Eneil GIA & POLICE	voport to MSIG.
18/19@ 9.76 an Emil 41A & policy 16/9/19 4/5 & 5500 Confine 16/9/19@ 3.070 revised to Many	with Alu (Red \$ 11543, 68%) monsyo
וון ווון	We have
16/9/19@ 3,0pm revised to Mrap	Shao via meninen.
	The state of the s
RECEIVED	1 8 SEP 2019
Date/Time, File Pass to? : Preli. Report	Days Of Repair:
18/9 MM : Final Report	Resurvey No. of Trip: Survey Fee:
Date/Time, File Return to?	Transportation: 200
2) Add	Fee: : Site Insp (\$)s+Rss \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \
nare d	: Interview (\$) Photos
Report Format: MER-P	:Tech. Invs (\$); Others
Lump Sum / I.B.d.: (\$ 5500)	:Weekend (\$
W - S	TOTAL 211

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To:

MSIG Insurance (Singapore) Pte. Ltd.

4 Shenton Way #21-01 SGX Centre 2 Singapore 068807

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn:

Koh Ming Shao

Date: 16 Sep 2019

Preliminary Advice

Insured Vehicle No : SLP7019A

TP Vehicle No Make

: SLL3002U

Accident Date Assignment Date : 24/08/2019 : 27/08/2019

: MAZDA 3

Est. Duration of Repair

Date of Inspection : 26/08/2019

: 4.00

Inspection At

: FASTECH AUTO PTE LTD (HQ)

1 KAKI BUKIT AVE 6, #01-46/48/50 AUTOBAY

SINGAPORE 417883

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	17,043.00
Revised Amount	:S\$	6,893.20
Check Items (Estimated)	:S\$	0.00
Total	:S\$	6,893.20
Lump Sum Repair	:S\$	5,500.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

į –	V.	The vehicle is economical/not economical	al for	repair.
	- 80	THE VEHICLE IS CONTOURNED THE		

(X) The above survey was conducted on a 'without prejudice' basis.

Shiau Chan (LKKAuto)

From:

Shiau Chan (LKKAuto)

Sent:

Tuesday, 27 August 2019 9:26 AM

To:

motorsurvey@sg.msig-asia.com

Cc:

SUR; KKLau; Accounts (LKKAuto)

Subject:

DIRECT SURVEY INSPECTION ON WORKSHOP - FASTECH AUTO PTE LTD, DOA:

24/08/2019, SLL 3002U (TP VEHICLE), SLP 7019A (OI VEHICLE)

Attachments:

SLL3002 PR.pdf; SLL3002 GIA.pdf

Dear Sir/Madam,

Please be informed that we had inspected the vehicle SLL 3002U at M/s: FASTECH AUTO PTE LTD, 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883.

Enclosed herewith a copy of TP's GIA and police report. The estimated cost of repair will forward to you shortly.

Meanwhile, kindly provide us the claim reference number for our necessary action.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933) SGCARMART.COM

Login Sign up

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources

UPLOAD A PHOTO

of your beloved car to Facebook & tag @mobillubes #askforMobil OR

FOLLOW US on Lazada

Flash it at our booth to redeem a token to play F1 Red Bull Simulator!



Post an Advertisement Sell it yourself! Advertise it at just \$58 until it's SOLD! Porsche Boxster S 3.2.



Brand New Paint, Many Wear And Tear Parts Replaced, Call To Direct Owner StarAd

YONG LEE SENG MOTOR PTE LTD

Post an Ad

Advertiser Login

Ways of Selling

~ Browse by Category

« Back (1 2) Next =

Sort by Date Posted

✓ 20 results/page ✓

38 vehicles

Mazda 3

Price

Depreciation

Reg Date

Eng Cap

Mileage

Advanced Search 🐹

Mazda 3

Make

Model

Any

Any

2017

Any

Veh Type

Submit (

Available

Search Selection

Mazda 3 1.5A Sunroof

\$67,800

\$8,240 /yr

17-Apr-2017

1,496 cc

36,000 km Sedan Available

One Owner. Well Maintained. Low Mileage Done. Excellent Condition. Reliable And Efficient. Flexible Loan Options Or 100% Loan Approv.

Benefit Auto Enterprise Pte Ltd

Posted: 26-Aug-2019 Tags: 2017 Mazda 3, 2017 mazda 3, Mazda 3, mazda 3, Mazda, 3, Used Mazda

Mazda 3 1.5A Sunroof

\$68,500

\$8,300 /vr

30-Mar-2017

1,496 cc 16,100 km Sedan

Sedan

Available

Elegant Silver, With Sunroof, Very Low Mileage Done, One Owner Only, Low Maintenance Cost, Very Well Maintained, Easy Financing, Fl...

Posted: 25-Aug-2019 Tags: 2017 Mazda 3, 2017 mazda 3, Mazda 3, mazda 3, Mazda, 3, Used Mazda



Mazda 3 1.5A Sunroof

\$69,800

\$8,150 /yr

1,496 cc

11,780 km

08-Aug-2017 Excellent Condition With 100% Accident Free. View To Believe. Genuine Low Mileage Of 11,780 Km Done And Last Serviced By Mazda M..

Ka-Hup Vehicles Trading

Posted: 25-Aug-2019 Tags: 2017 Mazda 3, 2017 mazda 3, Mazda 3, mazda 3, Mazda, 3, Used Mazda



Mazda 3 1.5A Sunroof

\$67.800

\$7,840 /vr

29-Aug-2017

Sedan

Available

SECTION OF STREET

Available

PREMIUM AD

27,381 km 1,496 cc SunRoof Model! Comes With New 6 Months Road Tax! Well Maintained And Best Price In The Market! Tip Top Condition. Loan/Trade-In...

Mayfair Motoring

Posted: 24-Aug-2019 Tags: 2017 Mazda 3, 2017 mazda 3, Mazda 3, mazda 3, Mazda, 3, Used Mazda



Extra Layer Of Protection For Car Doors

Honda Freed 2017 Protective Door Moulding, your extra layer of protection from other cars doors swing open widely.

Find out more!



Mazda 3 1.5A

\$64,800

\$7,980 /yr

22-Feb-2017

1,496 cc

62,000 km

Sedan

Available

Flexible Bank/In House Loan Available. We Offer High Trade In Price As Well! Excellent Condition And Very Well Maintain With Original I...

Posted: 24-Aug-2019 Tags: 2017 Mazda 3, 2017 mazda 3, Mazda 3, mazda 3, Mazda, 3, Used Mazda



Mazda 3 1.5A Sunroof

\$72,000

\$8,130 /vr

22-Nov-2017

1,496 cc

7,400 km

Sedan

Available

DIRECT CHINES

CONTRACTOR AND A

PARF Car, Low Mileage Car, Seldom Used Car, Original Dealer Warranty, Road Tax Till End Nov.

Posted: 24-Aug-2019 Tags: 2017 Mazda 3, 2017 mazda 3, Mazda 3, mazda 3, Mazda, 3, Used Mazda

Mazda 3 HB 1.5A Deluxe

\$7,630 /vr \$69,600

26-Oct-2017

1,496 cc

38,000 km

Available Hatchback

Agent Serviced, 1 Owner, Reverse Camera, Fuel Efficient, Well Maintained, Multi Loan Options Available, Call To Make An Appointment F...

Compare

Posted: 24-Aug-2019 Tags: 2017 Mazda 3, 2017 mazda 3, Mazda 3, mazda 3, Mazda, 3, Used Mazda

https://www.sgcarmart.com/used_cars/listing.php?RGD=2017&MOD=Mazda 3&RPG=20&VEH=0&A... 26-Aug-19

QP Paid:

COE Rebate Amount:

Total Rebate Amount:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	800G
Vehicle Details	
Vehicle No.:	SLL3002U
Vehicle to be Exported:	No
Intended Deregistration Date:	26 Aug 2019
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA3 4-DOOR SEDAN 1.5L SP.6EAT
Primary Colour:	Blue
Manufacturing Year:	2017
Engine No.:	P520429180
Chassis No.:	JM6BN22A8H0141435
Maximum Power Output:	88.0 kW (118 bhp)
Open Market Value:	\$14,951.00
Original Registration Date:	21 Feb 2017
First Registration Date:	21 Feb 2017
Transfer Count:	1
Actual ARF Paid:	\$9,951.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	20 Feb 2027
PARF Rebate Amount:	\$7,463.00
Intended COE Rebate Details	
COE Expiry Date:	20 Feb 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
	440 754 00

The information contained herein is correct as at 26 Aug 2019

OK

\$49,751.00

\$37,261.00

\$44,724.00

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

Fax Number

Contact Number

EMail Address

- 1. Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to
- repudiate policy liability. 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

- This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

	ACCIDENT STATEMENT
Date Of Report	26/08/2019 16:17
ANGS 10 (5) (10 PENDE 1997)	24/08/2019 10:35
	JUNC OF AIRPORT & HOUGANG AVE 3
	SINGAPORE
	ETAILS OF OWN VEHICLE
Vehicle Registration Number	SLL3002U
Insured/Policyholder	
Name Of Registered Owner	KUA QI FENG
NRIC No	S8971800G
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-81681926
Alternative Phone No	OFFICE-81681926
Vehicle Particulars	
Manufacturer	MAZDA
Model	MAZDA 3
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPCSN3049921900
Cover Note Number	
Driver	
Name of Driver	KUA QI FENG
NRIC No	S8971800G
Date Of Birth	22/11/1989
Occupation	INDOOR
Date Of Driving Pass	09/04/2008
Driving Experience	11 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81681926

OFFICE-81681926

NOEMAIL

Address

BLK 658C PUNGGOL EAST #12-729

Postcode

823658

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

OWNER

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLISION - CROSS JUNCTION

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles (including own vehicle) involved in the accident

Was any body injured in the Accident?

YES

Was any injured conveyed to hospital by

NO

ambulance?

YES

Was any other material or property damaged?

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

1

Details of Police Action

Was the accident reported to the police? If Yes. Please state which Police Station

YES

Police Station Name

PUNGGOL N.P.C

Police Station Address

ROAD: 21A TEBING LANE, POSTCODE: 828837, COUNTRY:

SINGAPORE

Police Station Contact

TEL NO: - FAX NO:

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

REFER TO POLICE REPORT T/20190825/2084

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SLP7019A

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

Page 2 of 17

No. Of Passenger (Including Driver)

No. Of Passenger (including Driver)		
	DETAILS OF INJURED PERSON 1	
Name	KUA QI FENG	
Approximate Age		
Injuries Sustain	BODY	
Injured person in which vehicle?	SLL3002U	
Were seat belts worn?	YES	
Was this injured conveyed to hospital by ambulance?	NO	
Address		
Postcode		

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report goggestly the details of the accisons to speed up the cisites process.
- 2. This form must be completed by the Polloybolder and/or the Authorised Drives.
- Information provided must be as <u>hopping and accurate as possible</u>. Any will inforepresentation or withholding of material facts way allow insurance companies to <u>hopping a policy liability</u>.
- 4. The have and acceptance of this Form by insurance companies is not an advisation of policy liability on the part of the insurance competed.
- 5. Any false reporting may be referred to the Police for Investigation.
- The report will be forwarded by the insurers of the GAA florands Management Centre entablished by the Jewens insurance Association of Singapore (GIA) for entitiving and that copies of this report will for a fee be made available upon application. immeded parties
- So the independ of this report to the insurers, you harnby consent to the archiving of this report at the nestre and to copies of the report heing made analysis efereand.
- 2. Consent under the Personal Data Protection Act (PDPA)

Lunderstand, economiedge, agree and consent that:


- (a) My injurier, my workshop and the Conersi insurance hasociation of Singapore ("qua") may/ere permitted to callect, use, disclose end/or process my personal deter/personal information act out in this (form) and any other personal information provided by me or possessed by my injurier (collectively the "Personal Information") and disclose and transfer auch Personal Information to all learnings who have insured vehicle(s) involved in this socialent followers which have beautifully referred to a at the "survers", the foaters' leavers from, the insured survey auctionity of Singapora and uny relevant government agrees/authority (such as the police), for the purpose(s) of ...
 - (i) processing, handling analysis dealing with my claims including the settlement of the claims and any necessary investigations relating to the dislinar;
 - (a) investigating the accident and/or my claims,
 - (iii) carrying out end/or dealing with my instructions or responding to any anquires by med
 - [hij advishatering my claims (including the marting of correspondence, statements, travokes, reports or nutties to this, which could involve disclosure of certain personal data about my to bring about delivery of the same as well as on the external cover of envelopes/mail pediagraf; analyse
 - (v) complying with applicable law is administering, processing, handling smaller dealing with my definal (culeralized) the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) breaked in the occident and the insurers' lawyers/few firms, may/are permitted to collect, use, studies and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information mayidan be distilised by any of the inquirers and/or GIA to their third party service providers or agents/including their isosperulaus firms), which may be shed outside of Singapora, for one or more of the above Purposes.
- (d) my Pector at information will also be collected and used to compile claims bistory for the pursoos of freed detection, executipation and management to present and all future claims.
- (e) the information so collected under (c) above may be shared / disclosed:
 - (i) so all insurers and/or any other third purses that assist in evaluating, investigating, controlling or managing floud, regulations, was enforcement and government agencies as reasonably required for the purposes statest, or
 - (8) for complying with requirements under any regulations, level or court orders.

Orher's Signature of driver is not the policyholderi Date & Tierer

tre Personnel's Signature

codare rumarhidarin, rti

Accident Sketch Plan



Date of Accident	: 24/8/19 Accident Time: 10:3 5/15(24-HR-Format)
	: Junction of Airport Ald & Hongey Ave 3
Accident Place	
Vehicle. No. (Car Plate No.)	:SLL 3 0024 Make/Model: Mazda 3
Insurace Company	: china Taiping Policy No: DMPCSN3U489219
Owner or Company Name /IC No.	: Kua Q' Feng / 5897 180067
Owner or Company Contact No.	:Owner's Hp 81681926 Company Tel
DRIVER'S Name / IC No.	: as above
DRIVER'S Date Of Birth	: 22/11/1981 DRIVER'S License Pass Date 9/4/2003
Relationship of Owner & Driver	: Spouse \ Parents \ Children \ Sibling \ Employee\ Others:
DRIVER'S Address	: BIK 658 L Punggol East #12-729
DRIVER'S Contact No./ Alt No.	:1)2)
DRIVER'S Occupation	: INDOOR \ OUTDOOR (e.g. working inside or outside office)
Email Address	
Weather & Road Surface	: CLEAR & DRY \ RAINING & WET \ AFTER RAIN & WET
Reporting Type	: Reporting Only \ Claim Other Party \ Claim Own Insurance
Number of Passengers (Including D	Driver):
Was there any video Captured by captured by captured purpose for which vehicle was Any Injury (If YES, Pls state):	as being used at the time of accident: Private use \ Work purpose
Other	Party Driver's Particular (if any)
Vehicle. No: SLP701	9 A Vehicle, No:
Vehicle Make\Model:	Vehicle Make\Model:
Name Driver:	Name Driver:
IC No. Driver/Contact:	IC No. Driver/Contact:

* NEW - Passenger's name & gender:

SKETCH PLAN

IMPORTANT NOTICE

- Please report <u>correctly</u> the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the Insurers' lawyers/law firms, the ivionetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s)
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Driver's Signature (If driver is not the policyholder) Date & Time: Date & Time:

Reporting Centre Personnel's Signature

NRIC/FIN No .:

					A	11/3/202
					A	LL3002
					0	OPTOTO
					D	
	4		*			
		1B14				
	4-1-1-1-1-					
		- A				
	+++++	++++++			-	111111
SCRIBE CIRCUMSTANCES OF	THE ACCIDENT	T				
1						
			100000			
				2-00		
					. 1	
polne to	41.0	police	report	T/201	90825/	2084
Refne to	the	police	report	T/201	90825/	2084
Refne to	the	police	report	T/201	90825/	2084
Refne to	the	police	report	T/201	90825/	2084
Refue to	the	police	report	T/201	90825/	2084
Refne to	the	police	report	T/201	90825/	2084
Refue to	the	police	report	T/201	90825/	2084
Refne to	the	police	report	7/201	90825/	2084
Refue to	the	police	report	T/201	90825/	2084
Refne to	the	police	report	T/201	90825/	2084
Refne to	the	police		7/201	90825/	2084
Refue to	the	police		T/201	90825/	2084
Refne to	the	police		7/201	90825/	2084
Refue to	the	police		7/201	90825/	2084
Refne to	the	police		7/201	90825/	2084
Refne to	the	police		7/201	90825/	2084
Refne to	the	police		T/201	90825/	2084
Refne to	the	police		T/201	90825/	2084
Refne to	the	police		7/201	90825/	2084
Refue to	the	police		T/201	90825/	2084

Policyholder's Signature Date & Time: Driver's Signature (If driver is not the policyholder) Date & Time: Reporting Centre Personnel's Signature Name: NRIC/FIN No.:





Police Station Of Origin:

Punggol N.P.C 21A Tebing Lane SINGAPORE 828837 Tel No: 1800-6049999

1 of 4

Report No. T/20190825/2084

Date/Time Report Made:			Vide Report No.: Station 61		
25/08/2019 18:37				01	
Informa	nt's Particu	ulars		1660年1月2日 - 美国工作工作	
Name of KUA QI	Informant: FENG		Address: APT BLK 658C PUNGGOL E/ 823658	AST #12-729 SINGAPORE	
ID Type / ID No.: NRIC NO / S8971800G			Contact No.: Home/Office: Mobile: 81681926		
National SINGAP	ity: ORE CITIZ	EN	Email:		
Sex: Male	Age: 29	Date of Birth: 22/11/1989	Type of Informant: Driver		
Race: Chinese			Language: English	Institution / School Name:	
Occupation: BANKER			Driving Licence Information: Class: 3	Date of Expiry:	

Type of Accident:	Non-Injury Others	Drink Drive: No	Date/Time of Accident: 24/08/2019 10:35	Type of Location X-Junction
AIRPORT RO	VENUE 3	AND HOUGANG AVE 3		
Weather: Clear	AIRFORT ROAD	Road Surface: Dry		Road Speed Limit:
Traffic Flow:	e Way	Traffic Control: Traffic Light - Wo	rking	Traffic Volume: Moderate
Dual Carriage		The second secon		Anyone conveyed by

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SLL3002U	Car	MAZDA	MAZDA3 4- DOOR SEDAN 1.5L SP.6EAT	Blue	Slightly Damaged	0
SLP7019A	Car				Slightly Damaged	0

Details of Vehicle Insurance				
	Insurance Company	Insurance No	Effective	Expiry Date





2 of 4

Report No. T/20190825/2084

Police Station Of Origin: Punggol N.P.C 21A Tebing Lane SINGAPORE 828837 Tel No: 1800-6049999

CONTINUATION OF REPORT

Details of Vehicle Insurance					
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date	
SLL3002U	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.	DMPCSN30499219 00	09/07/2019	08/07/2020	

Details of Perso		10000	A STANK BEEN			Here selected to produce
Any Pedestrian Ir No. of Pedestrian	AND DESCRIPTION OF THE PERSON NAMED IN COLUMN TWO IS NOT THE PERSON NAMED IN COLUMN TWO IS NAMED IN COLUM		Use of Peo	destrian	Cross	sing: NA
Driver					(E-2)	
Name	KUA QI FENG			ID No		S8971800G
Related Vehicle	SLL3002U (Car)			Conta	ct No.	81681926
Hospital/Clinic	INTEMEDICAL 24 H	R CLINIC		Class Driving Licent Expiry	g ce &	Class: 3 Date of Expiry: NIL
Date Treatment	24/08/2019		Date Disc	The second second	-	3/2019
No. of Days gran	ted Medical Leave	03	Degree of		NIL	1
Driver						
Name	TAN CHENG SOON			ID No		S1804789F
Related Vehicle	SLP7019A (Car)			Conta	ct No.	96669592
Hospital/Clinic	NIL			Class Drivin Licent Expiry	g	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Disc	harge	NIL	
No. of Days gran	ted Medical Leave	NIL	Degree of	Injury	NIL	

Brief Details.

On 24/08/2019 at about 1035hrs, I was driving my vehicle bearing vehicle number SLL3002U along Airport Rd. As I was approaching the junction of Airport Rd and Hougang Ave 3, I observed that the traffic light was still green in my favour. I then proceeded on. Suddenly I saw another vehicle bearing vehicle number SLP7019A that was driving on the opposite lane/direction making a right turn onto Hougang Ave 3 from Airport Rd. I tried to make an emergency brake but was unable to do so. My vehicle then collided onto the mentioned vehicle.

We then stopped by the road side and alighted from the vehicle. We exchanged particulars also. No one informed that they were injured at the point of time.

However, on the same day in the evening, I felt pain on my neck, upper body and lower back area. I then consulted the doctor and was granted 3 days MC.

That is all.



1.



Police Station Of Origin: Punggol N.P.C 21A Tebing Lane SINGAPORE 828837 Tel No: 1800-6049999

Report No. T/20190825/2084

3 of 4

CONTINUATION OF REPORT





Police Station Of Origin: Punggol N.P.C 21A Tebing Lane SINGAPORE 828837 Tel No: 1800-6049999 4 of 4 Report No. T/20190825/2084

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report: F / Sgt 3 LOUIS SEAH ZHENG LIANG	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 25/08/2019 18:37
Officer In Charge Of Case: TP / GIA / Staff Sgt WONG SIEU LUI Contact No.: 65476151	Classification Of Case:
Authentication Stamp NP168	20120 19

FASTECH AUTO PTE LTD BLK 1 KAKI BUKIT AVE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883

VEHICLE No.SLL 3002U

26/8/19 2/5 \$5500

1PC	BONNET 1067-30	SUM/SUC \$1,266.50 X
2PCS	BONNET HINGES@\$66.50	w \$88.50
1PC	BONNET INNER RUBBER 63.60	17 \$299.00 X
1PC	BONNET LOCK	9 y \$1,245.00
1PC	FRONT BUMPER 103/. 70	NSSM \$1,243.00 0 C
2PCS	FRONT BUMPER SIDE RETAINERS@\$90.50 25-120	Sy \$751.00_
1PC	FRONT BUMPER REINFORCEMENT 444.50	nu \$60.00
1SET	FRONT BUPMER CLIPS 170.00	De \$151.00
1PC	FRONT BUMPER REINFORCEMENT PROTECTOR 92-70	3131.00 X
1PC	FRONT BUMPER CENTRE LOWER GRILLE	M.J \$35.00
1PC	FRONT BUMPER LOWER COVER N/S	cre \$450.00
1PC	FRONT BUMPER FOG LAMP N/S 34-30	\$68.00
1PC	FRONT BUMPER FOG LAMP COVER N/S 46.40	cre \$225.00
1PC	FRONT grille top brocked 102.40	1
1PC	FRONT BUMPER TOP GRILLE 334.00	Mu/mis \$355.00
1PC	FRONT GRILLE \$\frac{1.60}{2}	cre \$688.00
1PC	FRONT GRILLR LOGO Y4.70	ne \$105.00
1PC	FRONT SUPPORT PANEL	\$705.00 %
1PC	SPONT LICENCE DI ATE W/HOLDER	\$1 \$50.00
2PCS	FRONT HEADLAMPS @\$2201.00 1070 50x 2 = 01 +1	\$4,402.00
2PCS	FRONT GRILLE CHROME MOULDINGS @\$265.00 /76.70	MSCN \$530.00 12C
1PC	AIR CON CONDENSER	11 \$1,019.00 ×
1PC	RADIATOR	17 \$1,465.00 ×
1PC	FRONT FENDER INNER SHIELD N/S 181. 20 201	70.1 \$245.00
1PC	FRONT LICENCE PLATE GARNISH	\$85.00
110		\$14,783. 96 50

TO CHECK WIRING TO SPRAY RUST PROOFING TO REFILL AIR CON GAS LABOUR FOR PANEL BEATING & REPLACING PARTS TO PUTTY & SPRAY PAINTING

\$80.00 30 \$80.00 30 11 \$120.00 X \$900.00 580 \$1,080.00 750 \$17,043.00

TOTAL

LKK Auto Consultants hence notify the Repairer of the following:

- = To recurvey before/after spray painting
- . To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis.
- No illegal modification(s) is allowed
- . Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25. Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CC3/MSG19014999/UQF3N2

Date:

18/09/2019

REFERENCE

Handling

MSIG Insurance (Singapore) Pte. Ltd.

Policy No:

29114756MKF

Claimant

Insurer:

SLL3002U

Insured Vehicle No:

SLP7019A

Vehicle No: Date of Loss:

24/08/2019

Nature of Claim:

TP

Odometer:

Claim No: 604658

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SLL3002U

Make & Model:

MAZDA 3, 1.4 SEDAN 1.5L SP.6EAT (A)

21/02/2017 (Man. Year: 2017)

P520429180 Engine No: JM6BN22A8H0141435 Chassis No:

46988 km

Colour:

Reg. Date:

Blue 1496 cc

Engine Capacity: Market Value/New Car

Price:

N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes Engine Modification:

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:

205/60 R16

Rear Tyre Size:

205/60 R16 Dunlop 7 mm

Front Left Side: Front Right Side: Dunlop 7 mm Dunlop 7 mm Rear Left Side: Rear Right Side:

18,236.55

Dunlop 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS Parts Miscellaneous Items	Repairer's 14,783.50 0.00	Adjuster's 5,503.20 0.00	9,280.30 0.00	Diff % 62.77
Labour Paintwork Labour	2,260.00 0.00	1,390.00 0.00	870.00 0.00	38.50
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$) Approved Total (Overridden) (S\$)	17,043.50	6,893.20 5,500.00	10,150.30	59.56
(S\$) + GST 7.00/7.00% (S\$)	17,043.50 1,193.05	5,500.00 385.00	11,543.50 808.05	67.73 67.73
Nett Amount (S\$)	18.236.55	5,885.00	12,351.55	67.73

INSPECTION

Date of Assignment:

27/08/2019

Date Inspected:

26/08/2019 Inspected At:

Nett Amount (S\$)

Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50

Autobay

Singapore 417883

Estimated Period of Repair:

4.0 days

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Version: 1.0 (Last Synchronised: 18 Sep 2019) Part Source: MRM-SG

MAZDA 3 1.4 SEDAN 1.5L SP.6EAT (A) (Catalogue:Merimen Singapore 1.0) 143 Parts:

(Price-denominated Standard List) Repairer's Labour:

Print Code: (Unsubmitted, no print-code for SLL3002U)

These estimates are valid only if they contain the print code (above) on all estimate pages, running page Validity:

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
	-	*BONNET	Bent/Buckled	1,266.50 F	*1,067.30 FL
1	1	*BONNET HINGES	Not Necessary	133.00 F	*-FL
2 3	1	*BONNET INNER RUBBER	Necessary Not Necessary	88.50 F 299.00 F	*63.60 FL *- FL
4	1	*BONNET LOCK	Distorted		*1,031.70 FL
5	1	*FRONT BUMPER	N/s Bent	181.00 F	*25.20 FL
6	1	*FRONT BUMPER SIDE RETAINERS	Bent	751.00 F	*444.50 FL
7	1	*FRONT BUMPER REINFORCEMENT *SET FRONT BUMPER CLIPS	Necessary	60.00 F	*50.00 FL
8	1	*FRONT BUMPER REINFORCEMENT PROTECTOR	Deformed	151.00 F	*92.70 FL
9	1	*FRONT BUMPER CENTRE LOWER GRILLE	Not Necessary	181.50 F	*-FL
10	1	*FRONT BUMPER LOWER COVER N/S	Missing	35.00 F	*35.00 FL
11	1	*FRONT BUMPER FOG LAMP N/S	Cracked	450.00 F	*325.50 FL
12	1	*FRONT BUMPER FOG LAMP COVER N/S	Good	68.00 F	
13 14	1	*FRONT GRILLE TOP BRACKET	Cracked	225.00 F	
15	1	*FRONT BUMPER TOP GRILLE	Broken/Missing	355.00 F	
16	1	*FRONT GRILLE	Cracked	688.00 F	
17	1	*FRONT GRILLE LOGO	Necessary	105.00 F	
18	1	*FRONT SUPPORT PANEL	Repair	705.00 F	
19	1	*FRONT LICENCE PLATE W/HOLDER	Bent	50.00 F	
20	2	*FRONT HEADLAMPS	Cracked	4,402.00 F	
21	1	*FRONT GRILLE CHROME MOULDINGS	N/s Cracked	530.00 F	
22	1	*AIR CON CONDENSER	Not Necessary	1,019.00 F	
23	1	*RADIATOR	Not Necessary	1,465.00 F	
24	1	*FRONT FENDER INNER SHIELD N/S	Torn	245.00 F	
25	1	*FRONT LICENCE PLATE GARNISH	Torn	85.00 F	*85.00 FI
F=F	ranchis	e part. L=ListItemDisc.			
			Sub Total (S\$		6,879.00
		- List Item Discount on L Items	0.00/20.00% (S\$	0.00	1,375.80
			Total Parts (S\$	14,783.50	5,503.20

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommer	habr	Labour
Recommen	lueu	Labour

Ke No	Particulars	Lab.Type	Repairer's	Amount
-	Talloadia			
Lab	our Items	147250	80.00	30.00
1	TO CHECK WIRING	New	80.00	30.00
2	TO SPRAY RUST PROOFING	New		0.00
3	TO REFILL AIR CON GAS	New	120.00	
8	LABOUR FOR PANEL BEATING & REPLACING PARTS	New	900.00	580.00
5	TO PUTTY & SPRAY PAINTING	New	1,080.00	750.00
	Gross Labo	ur Cost (S\$)	2,260.00	1,390.00
	and the state of t	ing this print-out		
	Report was unsubmitted dur	ing this print-out.		

< END OF ESTIMATES >