



Your Ref: S8L016NP

Date: 13th September 2019

Our Ref: CS1/CWF19015035/Etd3s2

M/s AXA Insurance Pte Ltd

C/o: Crawford & Company International Pte Ltd
8 Shenton Way #03-01
AXA Tower
Singapore 068811

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: XD 8010M
INSURED VEHICLE: UNKNOWN ACCIDENT DATE: 29/10/2018**

We thank you for your instruction on 22/08/2019.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of XD 8010M from M/s Constant Appraiser Services.
- b) Final Repair Bill of XD 8010M from M/s Vfix Auto Service Pte Ltd.
- c) Singapore Accident Statement of Vehicle XD 8010M.
- d) Damaged vehicle photographs of XD 8010M.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: XD 8010M
Make & Model	: Mitsubishi FV51JJD4RDEA
Year of Registration	: 2013
Chassis Number	: FV51JJA10180
Engine Capacity	: 12882 cc

2. We recommend that the repairs of the entire damage require about 14 (Fourteen) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.