MESSAGES

CLAIMS



General & Workshop De	tails Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary		
General Details			Workshop De	tails				
Involving	TPVD MERCEDES-BENZ A180 (SMG4673R)	(R17 SR)	Total Rebate Am	49008	3			
Date of Loss	21 August 2019		Nett Loss Amou	nt \$25,992	2.00			
Time of Loss	9.10		Assigned Works	hop LKK AU	LKK AUTO CONSULTANTS PTE LTD (TP)			
Loss Description	SJM7107T > SLH6061A (INSD) SLK2463J	Days of work completion *	20	20				
Comment								



MESSAGES

CLAIMS



General & Workshop	Details Ve	hicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labou	r Miscellaneous	Summary
Vehicle & Driver De	etails						
Vehicle Registration#	SMG4673	BR		Purchase Date	dd	/mm/yyyy	#
Registration State	SINGAP	ORE		Registration Date	* 04,	/06/2015	#
Mileage	57142			Age of Vehicle	4		
CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION		Driver Details			
Manufacturing				CATEGORY	FNOL INFO	RMATION	POST SURVEY INFORMATION
Year				Driver Name	CHIA YET	LIM (XIE YILIN)	
Make	TPVD MERCEDES- BENZ	MERCEDES E	BENZ	Date of Birth	31 May 19	90	dd/mm/y ##

CATEGORY	POLICY AND POR (ARALTICAR)	A180 (R17 SR)	CATEGORY Age	FNOL INFORMATION 29	POST SURVEY INFORMATION
Туре		•	Occupation	Unknown	
ype of Paint			Education Qualification	Other	,
Chassis No		WDD1760422J36644	Driving Experience	0	
ingine No		27091030628924	Driver License #		
ngine Capacity		1595	License Type		
um Insured		0	License Issue Date		dd/mm/y ∰
∕larket Value		75000	License Expiration Date		dd/mm/y

C.T.C.C.D./	FUOL INFORMATION	POST SURVEY
CATEGORY	FNOL INFORMATION	INFORMATION
Address	91 COMPASSVALE BOW,	
Address	#11-38, 544688, Singapore	
Address type	Personal Correspondence	
Gender	Female	
Marital status	Unknown	
ldentification #	S9018004E	

MESSAGES

CLAIMS



General & Workshop Detail	ls Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labou	ır	Miscellaneous	Summary		
Detailed Assessment			Condition of Vehicle at time of survey						
Inspection Date *	30/08/2019	#	General condition	G	ood		•		
Total Loss	Yes No		Steering (Serviceab	ile)	Yes				
Towing Charges	0		Footbrake (Servicea	able)	Yes	No			
Voluntary Excess Compulsory Excess	0		Handbrake (Serviceable)		Yes	No			
Young/Inexperienced/ Unnamed Driver	0		Engine Modification	n	Yes	No			
Excess			Pre-accident condit	tion	iood		•		

Other Excess		Tyre Condition	
Age of Tyres		Spare wheel	
Front Tyre Size	225/45R17	Rear Tyre Size	225/45R17
Front left side	PIRELLI6mm	Rear left side	PIRELLI6mm
Front right side	PIRELLI6mm	Rear right side	PIRELLI6mm

MESSAGES

CLAIMS



General & Workshop Detai	ls Vehicle & Driver Details	Vehicle Conditi	on Taxes & Ratio	Parts & Labour	Miscellaneous	Summary
Tax Eligibility & Addition	al Deduction for Parts					
Depr./Bttr%			Salvage%			
Discount%	10		Settlement%	100		
Paint Labour/Material R	atio					
Paint Labour Ratio	20		Paint Material R	Ratio 80		
Cash Loss		Yes N	lo			
Part Supplied by AXA		Yes N	lo			

MESSAGES

CLAIMS



Gener	General & Workshop Details		Vehicle &	Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary						
Parts															
Add	Approve	Deny	Submit A	П											
	EDIT	SR NO	QUAN	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
	-	0	1		REAR BUMPER	Deformed	0	1350	No		10			1215	Reviewinį
ш	,	0	2		REAR BUMPER RETAINER	Serviceable	0	0	No		10			0	Deny
a	,	0	1		REAR BUMPER DIFFUSER	Twisted	0	175	No		10			157.5	Reviewinį
	,	0	1		REAR BUMPER TOW COVER	Serviceable	0	0	No		10			0	Deny
	,	0	2		REAR REVERSE SENSOR	Shorted	0	290	No		10			522	Reviewinį
	,	0	1		REAR TAIL GATE	Repair	o	0	No		10			0	Deny
0	,	0	1		REAR WINDSCREEN MOULDING	Serviceable	0	0	No		10			0	Deny
	,	0	1		REAR END PANEL	Repair	0	0	No		10			0	Deny

	EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
	,	0	1		REAR REINFORCEMENT BEAM	Bent	0	680	No		10			612	Reviewinį
8	,	0	1		REAR LOCKING MECHANISM	Serviceable	0	0	No		10			0	Deny
9	,	0	1		REAR LOCKING PIN	Serviceable	0	0	No		10			0	Deny
	,	0	2		REAR TAIL LAMP	Serviceable	0	0	No		10			0	Deny
9	,	0	1		FRONT BUMPER	Deformed	0	1200	No		10			1080	Reviewinį
9	,	0	2		FRONT BUMPER RETAINER	Cracked	0	30	No		10			54	Reviewin
	,	0	1		FRONT CENTER GRILLE	Cracked	0	490	No		10			441	Reviewin
	,	0	1		FRONT MERCEDES EMBLEM W/SENSOR	Shorted	0	460	No		10			414	Reviewinį
W	,	0	2		FRONT PARKING SENSOR	Shorted	0	290	No		10			522	Reviewinį
9	,	0	1		FRONT TOW COVER	Serviceable	0	0	No		10			0	Deny
8	,	0	2		FRONT LOWER SIDE GRILLE	Twisted	o	40	No		10			72	Reviewinį
	,	0	1		FRONT SPONGE	Damaged	0	145	No		10			130.5	Reviewinį

	EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
B	,	0	1		FRONT HEADLAMP O/S	Cracked	0	890	No		10			801	Reviewinį
	,	0	1		FRONT HEADLAMP N/S	Serviceable	0	0	No		10			0	Deny
Labour															
Add	Approve	Deny	Submit A	п											
	EDIT	SR NO	REPAII (LABO	R/REPLACE UR)	PART NAME		ESTIMATE LABOUR AMOUNT	ADJUSTED L	ABOUR	ESTIMATE PAINT AMOUNT		ADJUSTED PAINT		TION BOUR)	COMMENT
	0	0			LABOUR FOR CHE ON WIRING	CKING	0	30		0	C)	Rev	riewing	
u	,	o			LABOUR FOR DISMANTLING & REPLACING OF AC DAMAGED PARTS, INCLUDING WELD KNOCKING, REPAI STRAIGHTENING, RESHAPE & ADJUS OF END PANEL, }	ING, RING,	0	950		0	()	Rev	riewing	
	,	0			REINFORCEMENT REAR TAIL GATE, R BUMPER ASSY, RE. LAMP, HINGES, FR BUMPER, FRONT HEADLAMP & GRI	EAR AR TAIL ONT	0	0		0	Ó	0	Rev	viewing	
п	•	0			LABOUR FOR TRANSFERING OF WINDSCREEN, WI ARM, MOTOR, EM LICENSE PLATE	PER	0	0		0	,	0	De	ny	

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT
e e	0		SPRAYPAINTING & PUTTY OF END PANEL, SUPPORT PANEL, TAIL GATE, REAR BUMPER, FRONT BUMPER & FENDER	0	1100	0	0	Reviewing	
•	0		WHEEL ALIGNMENT	0	0	0	0	Deny	



MESSAGES

CLAIMS



General & Workshop Details		Vehicle & Driver Details		Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary	
Add	Approve	Deny	Submit All		FCTIMATED	ADJUSTED			
	EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED	COMMENT	REMOVE	
	P	0	FRONT CARPLATE & BRACKET	Reviewing		40	BENT	d	

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details		Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary
Estimated Claim Amount	\$0.00			Adjusted Claim Amount	\$8,141.0	00	
CATEGORY		ESTIMATE	ADJUSTED				
Spare Parts		\$0.00	\$6,021.00				
Labour		\$0.00	\$2,080.00				
Miscellaneous		\$0.00	\$40.00			_	

Submit for Review



MESSAGES

CLAIMS



Genera	al & Worksho	p Details	Vehicle & D	river Details	Vehicle Condition	Taxes & Ratio	Parts & Lab	oour Mis	scellaneous	Summary
Add	Approve	Deny	Submit All		ESTIMATED	ADJUSTED				
	EDIT	NO	NAME	ACTION	AMOUNT	AMOUNT	COMMENT	REMOVE		
	ø	0	FINAL LUMP SUM	Reviewing		6500		ŵ		

CLAIMS



Assessment Details

General & Workshop Details		Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary
Estimated Claim Amount	\$0.00			Adjusted Claim Amount	\$6,500.0	00	
CATEGORY		ESTIMATE	ADJUSTED				
Miscellaneous		\$0.00	\$6,500.00				

Submit for Review