

ASS. REC. BY:

REF:

CS3/CT319015074/Gcf3²

Special Instruction:

Surveyor:

Gao Qing

ASSIGNMENT (Office)

From (Person):

Tan Kah Leong

of

CTI

Date/Time:

27.8.19 13.37pm

Estimated Cost:

Bill to:

OD/TP WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

FBL 32x

Insured:

GBD 9567C

at Workshop m/s

Pnsn Motorworks

Tel:

96612955

of

108 Kaki Bukit Ave 4 #05-01/02

Policy No:

DMCVSA30503819000

Claim No:

SYM19D223960102

Sum Insured:

Excess:

Make of Veh:

D.O.A. 23.8.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

27.8.19 1.46p.m

Person Contacted:

Kenneth

Vehicle IN/OUT

Date/Time

Action/Instruction (X) Estimate Inspection: 160 Sin Ming Drive #01-14

GBD 9567C NA/CTI18000924/h4 D.O.A. 15/01/2018

FBL 32x .x

Dismantle: 30/8/2019.

1001-13

PPS

Surveyor:

612

REF:

CT:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s Prism Motorworks

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: FBL 32X Yr Regn: 21 Feb 2017

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Kawasaki ZX1000cc 998

Colour: Green A/C: Insured / Std / NI / NA

Sp. Reading: 15139 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JKAZX100JKA.025120

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 120/70 ZR17

R: 190/50 ZR17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or METZELER

Front

Rear

R/Bal. 4 mm R/Bal. 4 mm

L/Bal. _____ mm L/Bal. _____ mm

D.O.A. _____ D.O.I. 28-08-19

Survey held at w/s 11:30

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

~~\$6000~~ \$5000 - \$6000

29/8/2019

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 3

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

Add Fee:

☐ : Site Insp (\$) \$ + RS \$

☐ : Interview (\$) Photos

☐ : Tech. Invs (\$) Others

☐ : Weekend (\$)

Report Format : PPS

Lump Sum / I.B.I: (\$)

TOTAL

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	27 Aug 2019		27 Aug 2019 13:37 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:		TAY SOO HIA (NON-DRIVER), ID: S1415358F							
Main Claimant:		MUHAMMAD ASHRAF BIN MAT ISA, ID: S9330968E							
Vehicle Reg. No.:		FBL32X	Date of Loss:	23/08/2019 07:00 - :59 [30 Months and 2 Days From LTA Reg Date (Man Yr)]					
Claim Type:		TP / SNM19D203960C02	Policy/Cover Note No.:	DMCVSN30503819000					
Vehicle Reg. No. (Insured):		GBD9567C	Policy No. (Claimant):	5105703790					
			Excess:	\$0.00					
Repairer:		Prism Motorworks Pte Ltd (HQ) NO. 8 KAKI BUKIT AVE 4 #05-01/02, PREMIER BUILDING SINGAPORE 415875, 415875 Kaki Bukit - Tel: 96612955							
Handling Insurer:		China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Tan Kah Leong - 63896193]							
Claimant's Insurer:		NTUC Income Insurance Co-operative Ltd (HQ) - Tel:							
Adjuster:		LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 05/09/2019]							
Driver/Custodian (Insured):		TAY CHOR HOW (61 / Male), NRIC: S1295804H Email:							
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	26/08/2019 16:38
Date Of Accident	23/08/2019 07:45
Exact Location Of Accident	ANG MO KIO AVE 5 TWDS ITE CENTRAL
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBL32X
Insured/Policyholder	
Name Of Registered Owner	MUHAMMAD ASHRAF BIN MAT ISA
NRIC No	S9330968E
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-93288233
Alternative Phone No	Others-93288233

Vehicle Particulars

Manufacturer	KAWASAKI
Model	ZX1000K
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	5105703790
Cover Note Number	

Driver

Name of Driver	MUHAMMAD ASHRAF BIN MAT ISA
NRIC No	S9330968E
Date Of Birth	01/09/1993
Occupation	INDOOR
Date Of Driving Pass	07/11/2018
Driving Experience	0 YEAR AND 9 MONTH

Gender	MALE
Mobile Number	(LOCAL) +65-93288233
Fax Number	
Contact Number	OTHERS-93288233
EMail Address	NOEMAIL
Address	BLK 575 HOUGANG STREET 51
	#03-55
Postcode	530575
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER ATTACHED.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBD9567C
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	NA
NRIC/Passport Number	

Contact Number
Address

NA

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan


SKETCH PLAN


IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was riding my bike along Any Moko Ave 5. I'm riding straight in my lane at a designated speed while travelling in my lane, suddenly a vehicle van 63D9567C cut into my lane and hit onto my bike.

As I was going at a low speed, I did not fall off my bike.

Vehicle 'B' driver stayed inside his van while I ask him to come out and exchange particulars. We then mention we will let our insurance handle.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Signature
Policyholder's Signature
Date & Time:

Signature
Driver's Signature
(If driver is not the policyholder)
Date & Time:

Signature
Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	968E

Vehicle Details

Vehicle No.:	FBL32X
Vehicle to be Exported:	No
Intended Deregistration Date:	29 Aug 2019
Vehicle Make:	KAWASAKI
Vehicle Model:	ZX1000K
Primary Colour:	Green
Manufacturing Year:	2014
Engine No.:	ZXT00JE019443
Chassis No.:	JKAZXT00JKA025120
Maximum Power Output:	-
Open Market Value:	\$12,979.00
Original Registration Date:	21 Feb 2017
First Registration Date:	21 Feb 2017
Transfer Count:	1
Actual ARF Paid:	\$1,947.00

Intended PARF Rebate Details

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	20 Feb 2027
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$6,101.00
COE Rebate Amount:	\$4,564.00
Total Rebate Amount:	\$4,564.00

The information contained herein is correct as at 29 Aug 2019

OK

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	27 Aug 2019		27 Aug 2019 13:37 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	TAY SOO HIA (NON-DRIVER), ID: S1415358F		
Main Claimant:	MUHAMMAD ASHRAF BIN MAT ISA, ID: S9330968E		
Vehicle Reg. No.:	FBL32X	Date of Loss:	23/08/2019 07:00 - :59 [30 Months and 2 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM19D203960C02	Policy/Cover Note No.:	DMCVSN30503819000
Vehicle Reg. No. (Insured):	GBD9567C	Policy No. (Claimant):	S105703790
		Excess:	S\$0.00
Repairer:	Prism Motorworks Pte Ltd (HQ) NO. 8 KAKI BUKIT AVE 4 #05-01/02, PREMIER BUILDING SINGAPORE 415875, 415875 Kaki Bukit - Tel: 96612955		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Tan Kah Leong - 63896193]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 05/09/2019]		
Driver/Custodian (Insured):	TAY CHOR HOW (61 / Male), NRIC: S1295804H Email:		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***FBL32X (SNM19D203960C02)**
[GBD9567C]

TP

MUHAMMAD ASHRAF BIN MAT ISA

Aug 23 2019 7:00AM



















































[TAY SOO HIA (NON-DRIVER)]

Prism Motorworks Pte Ltd

Upload Documents Upload Photos Compose New Letter

View View in Browser

Assessment Reports				1 per page	
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)		Thumbnail	Print
1	26/08/19 17:25	Accident Statement	i	Load HTM	
Photos/Images				3 per page	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	29/08/19 12:56	General View	i	Load JPG	
2	29/08/19 12:56	General View	i	Load JPG	
3	29/08/19 12:56	General View	i	Load JPG	
4	29/08/19 12:56	General View	i	Load JPG	
5	29/08/19 12:56	General View	i	Load JPG	
6	29/08/19 12:56	General View	i	Load JPG	
7	29/08/19 12:56	General View	i	Load JPG	
8	29/08/19 12:56	General View	i	Load JPG	
9	29/08/19 12:56	General View	i	Load JPG	
10	29/08/19 12:56	General View	i	Load JPG	
11	29/08/19 12:56	General View	i	Load JPG	
12	29/08/19 12:56	General View	i	Load JPG	
13	29/08/19 12:56	General View	i	Load JPG	
14	29/08/19 12:56	General View	i	Load JPG	
15	29/08/19 12:56	General View	i	Load JPG	
16	29/08/19 12:56	General View	i	Load JPG	
17	29/08/19 12:56	General View	i	Load JPG	
18	29/08/19 12:56	General View	i	Load JPG	
19	29/08/19 12:56	General View	i	Load JPG	
20	29/08/19 12:56	General View	i	Load JPG	
21	29/08/19 12:56	General View	i	Load JPG	
22	29/08/19 12:56	General View	i	Load JPG	
23	29/08/19 12:56	General View	i	Load JPG	
24	29/08/19 12:56	General View	i	Load JPG	
25	29/08/19 12:56	General View	i	Load JPG	
26	29/08/19 12:56	General View	i	Load JPG	
27	29/08/19 12:56	General View	i	Load JPG	
28	29/08/19 12:56	General View	i	Load JPG	
29	29/08/19 12:56	General View	i	Load JPG	
30	29/08/19 12:56	General View	i	Load JPG	
31	29/08/19 12:56	General View	i	Load JPG	
32	29/08/19 12:56	General View	i	Load JPG	
33	29/08/19 12:56	General View	i	Load JPG	
34	29/08/19 12:56	General View	i	Load JPG	
35	29/08/19 12:56	General View	i	Load JPG	
36	29/08/19 12:56	General View	i	Load JPG	
37	29/08/19 12:56	General View	i	Load JPG	


Assessment Reports			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)	Thumbnail	Print
38	29/08/19 12:56	General View	 Load JPG	<input checked="" type="checkbox"/>
39	29/08/19 12:56	General View	 Load JPG	<input checked="" type="checkbox"/>
40	29/08/19 12:56	General View	 Load JPG	<input checked="" type="checkbox"/>
41	29/08/19 12:56	General View	 Load JPG	<input checked="" type="checkbox"/>
42	29/08/19 12:56	General View	 Load JPG	<input checked="" type="checkbox"/>
43	29/08/19 12:56	General View	 Load JPG	<input checked="" type="checkbox"/>
44	29/08/19 12:56	General View	 Load JPG	<input checked="" type="checkbox"/>
45	29/08/19 12:56	General View	 Load JPG	<input checked="" type="checkbox"/>
46	29/08/19 12:56	General View	 Load JPG	<input checked="" type="checkbox"/>
47	29/08/19 12:56	General View	 Load JPG	<input checked="" type="checkbox"/>
48	29/08/19 12:56	General View	 Load JPG	<input checked="" type="checkbox"/>
49	29/08/19 12:56	General View	 Load JPG	<input checked="" type="checkbox"/>
50	29/08/19 12:56	General View	 Load JPG	<input checked="" type="checkbox"/>
51	29/08/19 12:56	General View	 Load JPG	<input checked="" type="checkbox"/>
52	29/08/19 12:56	General View	 Load JPG	<input checked="" type="checkbox"/>
53	29/08/19 12:56	General View	 Load JPG	<input checked="" type="checkbox"/>
54	29/08/19 12:56	General View	 Load JPG	<input checked="" type="checkbox"/>
55	29/08/19 12:56	General View	 Load JPG	<input checked="" type="checkbox"/>
56	29/08/19 12:56	General View	 Load JPG	<input checked="" type="checkbox"/>
57	29/08/19 12:56	General View	 Load JPG	<input checked="" type="checkbox"/>
58	29/08/19 12:56	General View	 Load JPG	<input checked="" type="checkbox"/>
59	29/08/19 12:56	General View	 Load JPG	<input checked="" type="checkbox"/>
60	29/08/19 12:56	General View	 Load JPG	<input checked="" type="checkbox"/>
61	29/08/19 12:56	General View	 Load JPG	<input checked="" type="checkbox"/>
62	29/08/19 12:56	General View	 Load JPG	<input checked="" type="checkbox"/>
63	29/08/19 12:56	General View	 Load JPG	<input checked="" type="checkbox"/>
64	29/08/19 12:56	General View	 Load JPG	<input checked="" type="checkbox"/>
65	29/08/19 12:56	General View	 Load JPG	<input checked="" type="checkbox"/>
66	29/08/19 12:56	General View	 Load JPG	<input checked="" type="checkbox"/>
67	29/08/19 12:56	General View	 Load JPG	<input checked="" type="checkbox"/>
68	29/08/19 12:56	General View	 Load JPG	<input checked="" type="checkbox"/>
69	29/08/19 12:56	General View	 Load JPG	<input checked="" type="checkbox"/>
70	29/08/19 12:56	General View	 Load JPG	<input checked="" type="checkbox"/>
71	29/08/19 12:56	General View	 Load JPG	<input checked="" type="checkbox"/>
72	29/08/19 12:56	General View	 Load JPG	<input checked="" type="checkbox"/>
73	29/08/19 12:56	General View	 Load JPG	<input checked="" type="checkbox"/>
74	29/08/19 12:56	General View	 Load JPG	<input checked="" type="checkbox"/>
75	29/08/19 12:56	General View	 Load JPG	<input checked="" type="checkbox"/>
76	29/08/19 12:56	General View	 Load JPG	<input checked="" type="checkbox"/>
77	29/08/19 12:56	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
78	29/08/19 12:56	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
79	09/09/19 11:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
80	09/09/19 11:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
81	09/09/19 11:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
82	09/09/19 11:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
83	09/09/19 11:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
84	09/09/19 11:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
85	09/09/19 11:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
86	09/09/19 11:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
87	09/09/19 11:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
88	09/09/19 11:43	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
89	09/09/19 11:43	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
90	09/09/19 11:43	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)	Thumbnail	Print
91	09/09/19 11:43	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
92	09/09/19 11:43	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
93	09/09/19 11:43	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
94	09/09/19 11:43	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
95	09/09/19 11:43	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
96	09/09/19 11:43	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
97	09/09/19 11:43	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
98	09/09/19 11:43	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
99	09/09/19 11:43	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
100	09/09/19 11:43	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
101	09/09/19 11:44	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
102	09/09/19 11:44	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
103	09/09/19 11:44	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
104	09/09/19 11:44	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
105	09/09/19 11:44	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
106	09/09/19 11:44	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
107	09/09/19 11:44	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
108	09/09/19 11:44	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
109	09/09/19 11:44	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
110	09/09/19 11:44	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
111	09/09/19 11:44	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
Documentation			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	27/08/19 13:37	INSD GBD9567C GIA REPORT		
2	27/08/19 13:37	PRS		

Linked Accident Report Documents

View

Assessment Reports			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)	Thumbnail	Print
1	26/08/19 17:25	Accident Statement		
Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)	Thumbnail	Print
1	26/08/19 16:54	Accident Photo		<input checked="" type="checkbox"/>
2	26/08/19 16:54	Accident Photo		<input checked="" type="checkbox"/>
3	26/08/19 16:54	Accident Photo		<input checked="" type="checkbox"/>
4	26/08/19 16:54	Accident Photo		<input checked="" type="checkbox"/>
5	26/08/19 16:54	Accident Photo		<input checked="" type="checkbox"/>
6	26/08/19 16:54	Accident Photo		<input checked="" type="checkbox"/>
7	26/08/19 16:54	Accident Photo		<input checked="" type="checkbox"/>
8	26/08/19 16:54	Accident Photo		<input checked="" type="checkbox"/>
9	26/08/19 16:54	Accident Photo		<input checked="" type="checkbox"/>
10	26/08/19 16:54	Accident Photo		<input checked="" type="checkbox"/>
11	26/08/19 16:54	Accident Photo		<input checked="" type="checkbox"/>
12	26/08/19 16:54	Accident Photo		<input checked="" type="checkbox"/>
13	26/08/19 16:54	Accident Photo		<input checked="" type="checkbox"/>
14	26/08/19 16:54	Accident Photo		<input checked="" type="checkbox"/>
15	26/08/19 16:54	Accident Photo		<input checked="" type="checkbox"/>
Documentation			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)	Thumbnail	Print
1	26/08/19 16:57	Sketch Plan		

Assessment Reports			1 per page ▾	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)	Thumbnail	Print
2	26/08/19 16:57	Sketch Plan #2	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI19015074/GCF3S2
Date: 12/09/2019

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSN30503819000
Claimant Vehicle No: FBL32X Insured Vehicle No: GBD9567C
Date of Loss: 23/08/2019 Nature of Claim: TP Claim No: SNM19D203960C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: FBL32X Engine No: ZXT00JE019443
Make & Model: KAWASAKI ZX1000E, 998cc Chassis No: JKAZXT00JKA025120
Reg. Date: 21/02/2017 (Man. Year: 2014) Odometer: 15139 km
Colour: Green
Engine Capacity: 998 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 120/70 ZR17 Rear Tyre Size: 190/50 ZR17
Front Left Side: Metzeler 4 mm Rear Left Side: Metzeler 4 mm
Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 27/08/2019
Date Inspected: 28/08/2019 Inspected At: 160 SIN MING DRIVE #01-14
Estimated Period of Repair: 3.0 days Repairer: Prism Motorworks Pte Ltd

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000.00 - \$6,000.00

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 12 Sep 2019)

Parts: N/A KAWASAKI ZX1000E 998cc (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for FBL32X)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >