

Surveyor: Rasul

ASSIGNMENT (Office)

From (Person): Pirel Food Wingao of MSIG Date/Time: 23.8.19 1732p.m

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: 4L552P Insured: 4P 17995

at Workshop m/s Yee Keang Motor Tel: 97808928

of NO 14 Brnjura Road

Policy No: A29117735 MKC Claim No: 603570

Sum Insured: Excess:

Make of Veh: D.O.A. 16.8.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS ^{mp?} H.O.D. Endorsement:

Date/Time: 23.8.19 246p.m Person Contacted: Mr How Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	4L552P - CS/IN/19014732/Kuf3 D.O.A-3/16/08/2019
	4P 17995 - CS/IN/19014732/Kuf3 D.O.A -16/08/2019
29/8/19 @ 1.22pm	revised to Pirel Food via Messenger.
	Panel finalised CS \$ 1450, 2 days (Red \$ 2290, 61%).

ASSIGNMENT

From: Date: 28/08/2019

Estimated Cost:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: YL552P

at Workshop m/s Yee Keong Motor

of No. 14 Penjuru Road

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh: After 12pm

Mr. Hiew

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS ^{hup}

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: YL552P Yr Regn: 2001 / NOV

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: MITSUBISHI FM657MSRPEC c.c 7545

Colour: WHITE A/C: Insured / Std / NI / NA

Sp. Reading: 45574 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: FM657MB00301

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 295/80R22.5

R: -

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or GOLDSTEIN

Front

Rear

R/Bal. 7 mm R/Bal. 6/6 mm

L/Bal. 7 mm L/Bal. 6/6 mm

D.O.A. 16/08/19 D.O.I. 28/08/19

*Survey held at YEE KEONG

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S FR

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 11 SEP 2019

10/9/2019

Date/Time, File Pass to?

☐ : Preli. Report

1) 11/9/2019

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 2

Resurvey No. of Trip: 2

Add Fee: ☐ Site Insp (\$)

☐ Interview (\$)

☐ Tech. Insp (\$)

☐ Weekend (\$)

Survey Fee:

Transportation:

S + RS. \$

Photos

Others

TOTAL

Report Format: MER-TP

Lump Sum / Hk: 1450

150
11

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	16 Aug 2019		23 Aug 2019 17:32 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	HONG CHENG AIR-CONDITIONING ENGINEERING PTE LTD, Co. Reg. No.: 199703892K		
Main Claimant:	HWA LIAN HENG CO PTE LTD, Co. Reg. No.: 199400434W		
Vehicle Reg. No.:	YL552P	Date of Loss:	16/08/2019 10:00 - :59 [213 Months and 3 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 603570	Policy/Cover Note No.:	A29117735MKC(COMP) (Comprehensive) Coverage: 16/03/2019 - 15/03/2020
Vehicle Reg. No. (Insured):	YP1799S	Policy No. (Claimant):	
		Excess:	
Repairer:	Yee Keong Motor Engineering (HQ) No. 14 Penjuru Road, 609125 Jurong West - Tel: 97808928		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Fievel Foo Wenyao - 6643 1316]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Imm.Advice due 24/08/2019]		
Driver/Custodian (Insured):	THIYAGARAJAN SATHISKUMAR (), NRIC: G6619540L, Tel: +6590862469 Email:		
Adj Asg. Remarks:	on WP. Liab: NA. Agree on SJE. Assign: LKK Auto Consultants Pte Ltd. Contact: Mr Hiew @ 9780 8928.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.



ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Fievel Foo Wen Yao

Date: 29 Aug 2019

Preliminary Advice

Insured Vehicle No	: YP1799S	Accident Date	: 16/08/2019
TP Vehicle No	: YL552P	Assignment Date	: 23/08/2019
Make	: MITSUBISHI FM657MSRDEC	Est. Duration of Repair	: 3.00
Date of Inspection	: 28/08/2019		
Inspection At	: YEE KEONG MOTOR ENGINEERING (HQ) NO. 14 PENJURU ROAD SINGAPORE 609125		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	3,740.00
Revised Amount	:S\$	1,750.00
Check Items (Estimated)	:S\$	530.00
Total	:S\$	2,280.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	16/08/2019 14:08
Date Of Accident	16/08/2019 10:50
Exact Location Of Accident	22 WOODLANDS LINK C/PARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	YL552P
Insured/Policyholder	
Name Of Registered Owner	HWA LIAN HENG CO PTE LTD
Co Reg No	199400434W
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-93592904

Vehicle Particulars

Manufacturer	MITSUBISHI
Model	LORRY
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	5076116316-03
Cover Note Number	

Driver

Name of Driver	WANG BIN
NRIC No	G2897599L
Date Of Birth	24/09/1994
Occupation	OUTDOOR
Date Of Driving Pass	23/01/2017
Driving Experience	2 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93592904
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address ---
 Postcode
 Was driver an employee of the Insured's Company YES
 If No, Relationship of the Driver with the Insured
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident SIDE SWIPE
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance?
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

PLS REFER ATTACHED ACCIDENT REPORT FROM THE DRIVER.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number YP1799S
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category COMMERCIAL VEHICLE
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #3 Pg. 1

16 August 2019

I, Wang Bin (FIN: G2897599L), driver of YL552P, hereby make a report on the following incident at work on 16/08/2019 at about 10.50am.

As I was about to leave the carpark in 22 Woodlands Link suddenly vehicle YP1799S (Driver Thiagarajan Sathiskumar SPASS: O 34796858) hit my vehicle.

I was already out of the carpark lot driving on the main driveway suddenly the vehicle travelled at high-speed into my lane, passing the center road divider, trying to overtake my vehicle and collided with my vehicle on the driver side. I got off my vehicle to inspect the situation. My vehicle suffered dents to the driver side wheel, door and mud guard. The other vehicle left signal light and door is damaged.

No one was injured in the incident.

I am making this report for insurance claim purposes.

YEE KEONG MOTOR ENGINEERING

No. 14 Penjuru Road, Singapore 609125
TEL/FAX: 62620218 | MOBILE: 97808928

Est YL 552 P

Date 28/8/19

- 1) Fender (R) crn ✓ \$1050 f
- 2) Fender bracket ? ✓ \$180 +
- 3) Rear Mudguard ? ✓ \$350 +
- 4) Tyre rim cover bt ✓ \$200 +
- 5) Mud flap X gnc \$50 +
- 6) Step panel X gnc \$320 +
- 7) Step bracket @ 20 X gnc \$240 +

Supply labour to remove and
refit the necessary affected
parts replace fender, step panel
and straighten the relevant areas

~~\$800~~ 300

spray painting

~~\$500~~ 200

Rasul

Hp 90010068

3 days

4/3

28/08/19 @ 1545

Reey after repair

TOTAL \$3740

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

YEE KEONG MOTOR ENGINEERING

No. 14 Penjuru Road, Singapore 609125
TEL/FAX: 62620218 | MOBILE: 97808928

Est YL 552 P

Date 28/8/19

- | | | | |
|---------------------------------------|--------|---|----------------------------|
| 1) Fender (R) cra ✓ | \$1050 | } | 1780
252
<u>1335</u> |
| 2) Fender bracket ? 1/ ✓ | \$180 | | |
| 3) Rear mudguard ? de ✓ | \$350 | | |
| 4) Tyre rim cover 1/2 1/ ✓ | \$200 | | |
| 5) mud flap ? X sue | \$50 | | |
| 6) Step panel ? X sue | \$320 | | |
| 7) Step bracket x120 X sue | \$240 | | |

Supply labour to remove and
re-fit the necessary affected
parts. replace fender, step panel
and straighten the relevant areas
spray painting

~~\$800~~ ²⁰⁰⁰ 300 } 500
~~\$500~~ 200 } 500

Resue

10/9/19

HP 90010068

TOTAL \$3740

1335

500

1835

202

1468

4/5 - 1,450

2 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

2 days

4/5

28/08/19 @ 1545

Resy after repair

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	16 Aug 2019		23 Aug 2019 17:32 Edit Adj Rpt	S\$1,450.00 Edit Estimates	S\$1,450.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS			[Created by insurer]						
Insured:	HONG CHENG AIR-CONDITIONING ENGINEERING PTE LTD , Co. Reg. No.: 199703892K								
Main Claimant:	HWA LIAN HENG CO PTE LTD , Co. Reg. No.: 199400434W								
Vehicle Reg. No.:	YL552P	Date of Loss:	16/08/2019 10:00 - :59 [213 Months and 3 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 603570	Policy/Cover Note No.:	A29117735MKC(COMP) (Comprehensive) Coverage: 16/03/2019 - 15/03/2020						
Vehicle Reg. No. (Insured):	YP1799S	Policy No. (Claimant):							
		Excess:							
Repairer:	Yee Keong Motor Engineering (HQ) No. 14 Penjuru Road, 609125 Jurong West - Tel: 97808928								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Fievel Foo Wenyao - 6643 1316]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 22/09/2019]								
Driver/Custodian (Insured):	THIYAGARAJAN SATHISKUMAR (), NRIC: G6619540L, Tel: +6590862469 Email:								
Adj Asg. Remarks:	on WP. Liab: NA. Agree on SJE. Assign: LKK Auto Consultants Pte Ltd. Contact: Mr Hiew @ 9780 8928.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***YL552P (603570)**
[YP1799S]

TP

HWA LIAN HENG CO PTE LTD

Aug 16 2019 10:00AM

[HONG CHENG AIR-CONDITIONING ENGINEERING PTE LTD]

Yee Keong Motor Engineering

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

[View](#)
[View in Browser](#)

Assessment Reports

No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	23/08/19 10:08	Accident Statement From: SC - Reg. No: YP1799S, Claimant: HONG CHENG AIR-CONDITIONING ENGINEERING PTE LTD	Load HTM	<input type="checkbox"/>
2	23/08/19 10:08	Addendum Sheet From: SC - Reg. No: YP1799S, Claimant: HONG CHENG AIR-CONDITIONING ENGINEERING PTE LTD	Load TIF	<input type="checkbox"/>
3	23/08/19 10:08	Accident Statement Addm. #1 From: SC - Reg. No: YP1799S, Claimant: HONG CHENG AIR-CONDITIONING ENGINEERING PTE LTD	Load HTM	<input type="checkbox"/>
4	23/08/19 10:08	Addendum Sheet From: SC - Reg. No: YP1799S, Claimant: HONG CHENG AIR-CONDITIONING ENGINEERING PTE LTD	Load TIF	<input type="checkbox"/>
5	23/08/19 10:08	Accident Statement Addm. #2 From: SC - Reg. No: YP1799S, Claimant: HONG CHENG AIR-CONDITIONING ENGINEERING PTE LTD	Load HTM	<input type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	29/08/19 13:21	Adjuster Immediate Advice	Load HTM	<input type="checkbox"/>

Photos/Images

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	10/09/19 11:42	Odometer Reading	Load JPG	<input checked="" type="checkbox"/>
2	10/09/19 11:42	Chassis Number	Load JPG	<input checked="" type="checkbox"/>
3	10/09/19 11:42	General View	Load JPG	<input checked="" type="checkbox"/>
4	10/09/19 11:42	General View	Load JPG	<input checked="" type="checkbox"/>
5	10/09/19 11:42	General View	Load JPG	<input checked="" type="checkbox"/>
6	10/09/19 11:42	General View	Load JPG	<input checked="" type="checkbox"/>
7	10/09/19 11:42	General View	Load JPG	<input checked="" type="checkbox"/>
8	10/09/19 11:42	General View	Load JPG	<input checked="" type="checkbox"/>
9	10/09/19 11:42	General View	Load JPG	<input checked="" type="checkbox"/>
10	10/09/19 11:42	General View	Load JPG	<input checked="" type="checkbox"/>
11	10/09/19 11:42	General View	Load JPG	<input checked="" type="checkbox"/>
12	10/09/19 11:42	General View	Load JPG	<input checked="" type="checkbox"/>
13	10/09/19 11:42	General View	Load JPG	<input checked="" type="checkbox"/>
14	10/09/19 11:42	General View	Load JPG	<input checked="" type="checkbox"/>
15	10/09/19 11:42	General View	Load JPG	<input checked="" type="checkbox"/>
16	10/09/19 11:42	General View	Load JPG	<input checked="" type="checkbox"/>
17	10/09/19 11:42	General View	Load JPG	<input checked="" type="checkbox"/>
18	10/09/19 11:42	General View	Load JPG	<input checked="" type="checkbox"/>
19	10/09/19 11:42	General View	Load JPG	<input checked="" type="checkbox"/>
20	10/09/19 11:42	General View	Load JPG	<input checked="" type="checkbox"/>
21	10/09/19 11:42	General View	Load JPG	<input checked="" type="checkbox"/>
22	10/09/19 11:42	General View	Load JPG	<input checked="" type="checkbox"/>
23	10/09/19 11:42	General View	Load JPG	<input checked="" type="checkbox"/>
24	10/09/19 11:42	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
25	10/09/19 11:42	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
26	10/09/19 11:42	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
27	10/09/19 11:42	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
28	10/09/19 11:42	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
29	10/09/19 11:42	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
30	10/09/19 11:42	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page ▼	✓
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
31	10/09/19 11:42	Reinspection Photo	Load JPG	✓
32	10/09/19 11:42	Reinspection Photo	Load JPG	✓
33	10/09/19 11:42	Reinspection Photo	Load JPG	✓
34	10/09/19 11:42	Reinspection Photo	Load JPG	✓
35	10/09/19 11:42	Reinspection Photo	Load JPG	✓
36	10/09/19 11:42	Reinspection Photo	Load JPG	✓
37	10/09/19 11:42	Reinspection Photo	Load JPG	✓
38	10/09/19 11:42	Reinspection Photo	Load JPG	✓
39	10/09/19 11:42	Reinspection Photo	Load JPG	✓
40	10/09/19 11:42	Reinspection Photo	Load JPG	✓
41	10/09/19 11:42	Reinspection Photo	Load JPG	✓
42	10/09/19 11:42	Reinspection Photo	Load JPG	✓
43	10/09/19 11:42	Reinspection Photo	Load JPG	✓
44	10/09/19 11:42	Reinspection Photo	Load JPG	✓
45	10/09/19 11:42	Reinspection Photo	Load JPG	✓
46	10/09/19 11:42	Reinspection Photo	Load JPG	✓
47	10/09/19 11:42	Reinspection Photo	Load JPG	✓
48	10/09/19 11:42	Reinspection Photo	Load JPG	✓
49	10/09/19 11:42	Reinspection Photo	Load JPG	✓
Documentation			1 per page ▼	✓
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	23/08/19 10:08	PRI	Load DOCX	
2	23/08/19 10:08	TP YL552P E-REPORT	Load PDF	
3	23/08/19 15:52	Agree on SJE	Load PDF	
4	23/08/19 15:52	Workshop Details	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
<p>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</p> <div style="border: 1px solid black; height: 100px; width: 100%;"></div> <p>Show Remarks To: <input type="checkbox"/> Handling Insurer</p> <p><small>Note: Remarks are private unless you show it to other parties.</small></p>				

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19015079/R1QF3S2
Date: 17/09/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: A29117735MKC(COMP)
Claimant Vehicle No : YL552P **Insured Vehicle No :** YP1799S
Date of Loss: 16/08/2019 Nature of Claim: TP Claim No: 603570

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **YL552P**
Make & Model: MITSUBISHI FM657MSRDEC, 7.5 D (M) Engine No: 6D16946459
Reg. Date: 13/11/2001 (Man. Year: 2001) Chassis No: FM657MB00301
Colour: White Odometer: 49574 km
Engine Capacity: 7545 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 295/80 R22.5 Rear Tyre Size: 295/80 R22.5 (D)
Front Left Side: GOLDSHIELD 7 mm Rear Left Side: GOLDSHIELD 6/6 mm
Front Right Side: GOLDSHIELD 7 mm Rear Right Side: GOLDSHIELD 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	2,390.00	1,335.00	1,055.00	44.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,350.00	500.00	850.00	62.96
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,740.00	1,835.00	1,905.00	50.94
Approved Total (Overridden) (S\$)		1,450.00		
Nett Amount (S\$)	3,740.00	1,450.00	2,290.00	61.23

INSPECTION

Date of Assignment: 23/08/2019
Date Inspected: 28/08/2019 Inspected At: Yee Keong Motor Engineering (HQ)
Estimated Period of Repair: 2.0 days No. 14 Penjuru Road
Singapore 609125

Adjuster: MOHD RASUL

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 16 Sep 2019)	
Parts:	N/A	MITSUBISHI FM657MSRDEC 7.5 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YL552P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FENDER (R)	Cracked	1,050.00 F	*1,050.00 FL
2	1		*FENDER BRACKET	Bent	180.00 F	*180.00 FL
3	1		*REAR MUDGUARD	Deformed	350.00 F	*350.00 FL
4	1		*TYRE RIM COVER	Bent	200.00 F	*200.00 FL
5	1		*MUDFLAP	Serviceable	50.00 F	*-FL
6	1		*STEP PANEL	Serviceable	320.00 F	*-FL
7	2		*STEP BRACKET	Serviceable	240.00 F	*-FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	2,390.00	1,780.00
- List Item Discount on L Items 0.00/25.00% (S\$)	0.00	445.00
Total Parts (S\$)	2,390.00	1,335.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	SUPPLY LABOUR TO REMOVE AND REFIT THE NECESSARY AFFECTED PARTS. REPLACE FENDER, STEP PANEL AND STRAIGHTEN THE RELEVANT AREAS.	New	800.00	300.00
2	SPRAY PAINTING.	New	550.00	200.00
Gross Labour Cost (\$\$)			1,350.00	500.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >