

22/03/2012

ASS. REC. BY:

REF: es/ALG190150e4/Ky d3 n2

Special Instructions:

Surveyor: Kenneth

ASSIGNMENT (Office)

nelinon

From (Person): Parthiban Theethan

of ALG

Date/Time: 27/8/2019 @ 12.34pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLZ 7427C

Insured:

S/N 251A

at Workshop in/s

Trust Autoworks

Tel:

9108 2728.

of

BLK 5035 # 01-345 AMK Ind. park 2

Policy No:

Claim No: 270514240459005

Sum Insured:

Excess:

Make of Veh:

D.O.A.

25/08/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

hp

H.O.D. Endorsement:

Date/Time:

2.43pm 27/8/19

Person Contacted:

Anthony

Vehicle IN / OUT

Date/Time

Action/Instruction

Voluntary /

SLZ 7427C -X

S/N 251A -X

16/9 11/19 @ 440d email &amp; Confirm (Red \$7746.32, 63%)

ASS. REC. BY:

REF: AIG

## ASSIGNMENT

From:

Date:

2/9/2019

Veh No:

SLZ 7427C

Tr Regn:

04, 13

Estimated Cost:

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

OD / ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLZ 7427C

Make:

Mercedes

C.C.

1796

at Workshop m/s

Trust Autoworks

Colour:

M. Blue

A/C:

Insured / Std / NI / NA

of Blk 5035 # 01-345 AMK Ind. Prlc 2

Sp. Reading

77008

T/Radio: Insured / Std / NI / NA

Insured:

Eng/No:

Policy No.

C/No:

WDD 2120472A 677927

Claims No.

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: ☒ Inorder / Jammed / Leaked / Burnt or

(Client's Record)


Brake: ☒ Inorder / Jammed / Leaked / Burnt or

Make of Veh:

Modi: Nil / S/Rim / STD A/Rim or

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Tyre Size:

F:

245/40ZR18

R:

265/35ZR18

BS / DUN / EXNOVA / GY / FS / LIZA / ☒ MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS <sup>1up</sup>

Vehicle: IN / OUT

Date:

Person Contacted:

Front

Rear

R/Bal.

7

mm

R/Bal.

3

mm

L/Bal.

7

mm

L/Bal.

3

mm

D.O.A.

25/8/1P

D.O.I.

219/19

Survey held at

✓

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Rec

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

2/9

GIA &amp; Est not ready

RECEIVED 30 SEP 2019

Date/Time, File Pass to?



Preli. Report

1)



Final Report

Date/Time, File Return to?

2)

27/9/19 - Typist

Days Of Repair:

4

Resurvey No. of Trip:

1

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Invs (\$)



Weekend (%)

Survey Fee:

Transportation:

3 + RS, SI

Photos:

Others:

TOTAL

250

11

261

Report Format:

Lump Sum / I.E.I: (\$)

\$4400f

**PRE-REPAIR INSPECTION REQUEST – SLZ7427C vs SJN251A on 25.08.2019**

From: Parthiban, Theerthan  
To: assignments@lkkauto.com, admin-a@lkkauto.com  
Cc: Fong, Andy-SY, Chin, Lee-Ying, Abu Kassim, Noor Mariesa, Azlan, Syazairdina, Chan, Yoke Shi, Hor, Yinrul, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur, Parthiban, Theerthan, Subramaniam, Divyashni  
Sent: 8/27/2019 12:34:33 PM  
Attachments: 20190827094913101.pdf

Hi,

Please refer to the enclosed request from Chia S Arul LLC.

Claim no : 2705142404SG005  
Case Owner : CHEE HENG LOH

If you have any queries/concerns, please let us know.  
Kindly assist to assign **Kenneth Kong** as Single Joint Expert as requested.

Thank you.

Regards,

Theerthan R Parthiban (Troy)  
AIG  
Senior Claims Examiner, Auto  
Singapore Claims Operations | AIG Shared Services

Tel: 8001206556 Ext: 1002217  
Theerthan.Parthiban@aig.com | www.aig.com.sg

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

**This message is from an external sender; be cautious with links and attachments.**

Dear Sirs,

Our client is agreeable to your proposed surveyor, Kenneth Kong from LKK Auto Consultants.

Regards,  
**Ms Kelley Choong (Legal Secretary)**  
M/s Chia S Arul LLC  
151 Chin Swee Road  
#03-09 Manhattan House  
Singapore 169876  
Tel: (65) 6733 4647 Fax: (65) 6733 8183

This e-mail is from M/s Chia S Arul LLC, a firm of Advocates and Solicitors in Singapore, and is intended solely for the named addressee. It contains confidential and/or legally privileged information. If the e-mail has reached you in error, please delete the e-mail immediately and inform us of the error. You may contact us at [info@chiaarul.com](mailto:info@chiaarul.com). Internet communications cannot be guaranteed to be secured or error-free as information could be intercepted, corrupted, lost, arrive late or contain viruses. The sender therefore does not accept liability for any errors or omissions in the context of this message which arise as a result of Internet transmission.

From: Parthiban, Theerthan <Theerthan.Parthiban@aig.com>  
Sent: Tuesday, August 27, 2019 11:14 AM  
To: kelley@chiaarul.com  
Cc: Fong, Andy-SY <Andy-SY.Fong@aig.com>; Chin, Lee-Ying <Lee-Ying.Chin@aig.com>; Abu Kassim, Noor Mariesa <NoorMariesa.AbuKassim@aig.com>; Azlan, Syazairdina <Syazairdina.Azlan@aig.com>; Chan, Yoke Shi <yokeshi.chan@aig.com>; Hor, Yinrul <Yinrul.Hor@aig.com>; Lim, Sheng Yang <ShengYang.Lim@aig.com>; Mithoosingh, Aashweenjeetkaur <Aashweenjeetkaur.Mithoosingh@aig.com>; Parthiban, Theerthan <Theerthan.Parthiban@aig.com>; Subramaniam, Divyashni <Divyashni.Subramaniam@aig.com>; Tong, Wahxin <Wahxin.Tong@aig.com>  
Subject: aigencrypt PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SJN251A AND SLZ7427C ON 25.08.2019

Without Prejudice

Your Reference : SLZ7427C (kc)  
Our Reference : 2705142404SG003

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd

Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thank you.

Regards,

Theerthan R Parthiban (Troy)  
AIG  
Senior Claims Examiner, Auto  
Singapore Claims Operations | AIG Shared Services

Tel: 8001205556 Ext: 1002217  
[Theerthan.Parthiban@aig.com](mailto:Theerthan.Parthiban@aig.com) | [www.aig.com.sg](http://www.aig.com.sg)

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

**From:** Kelley Choong [<mailto:kelley@chiaarul.com>]  
**Sent:** Tuesday, August 27, 2019 9:51 AM  
**To:** 'Md Ishak, Mohd Imran'; Tan, Lily (AIG); AIG SGP, Claims-Survey  
**Cc:** 'Anthony Cheong'  
**Subject:** [EXTERNAL] PRE-INSPECTION OF SLZ 7427C (KC)

This message is from an external sender; be cautious with links and attachments.

Dear Sirs,

Enclosed PRI for your attention.

Please let us have your list of surveyors.

Regards,  
**Ms Kelley Choong (Legal Secretary)**

M/s Chia S Arul LLC  
151 Chin Swee Road  
#03-09 Manhattan House  
Singapore 169876

Tel: (65) 6733 4647 Fax: (65) 6733 8183

This e-mail is from M/s Chia S Arul LLC, a firm of Advocates and Solicitors in Singapore, and is intended solely for the named addressee. It contains confidential and /or legally privileged information. If the e-mail has reached you in error, please delete the e-mail immediately and inform us of the error. You may contact us at [info@chiaarul.com](mailto:info@chiaarul.com). Internet communications cannot be guaranteed to be secured or error-free as information could be intercepted, corrupted, lost, arrive late or contain viruses. The sender therefore does not accept liability for any errors or omissions in the context of this message which arise as a result of Internet transmission.

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

**CHIA S ARUL LLC**  
ADVOCATES & SOLICITORS  
UEN 201330709H

ARULCHELVAN S • A. RAVIDASS • DON TAN

---

Our Ref : SLZ 7427C (kc)

Your Ref :

27 August 2019

**AIG Asia Pacific Insurance Pte Ltd**  
78 Shenton Way #08-16  
Chartis Building  
Singapore 079120

**BY EMAIL**

Dear Sir,

RE: PROPERTY DAMAGE CLAIM  
CLAIMANT : CHANG PHUI MING  
ACCIDENT INVOLVING SLZ 7427C & SJN 251A ALONG JURONG EAST ST 24  
CARPARK ON 25 AUGUST 2019

1. We act for **Chang Phui Ming**, the owner of motor vehicle no. SLZ 7427C, which was involved in the aforesaid accident.
2. We hereby give you **NOTICE** that we are claiming against your insured motor vehicle no. SJN 251A for damages, costs and disbursements as a result of your insured driver's negligence.
3. Kindly let us know if you wish to conduct a pre-repair inspection on our client's motor vehicle at M/s Trust Autoworks at Blk 5035 #01-345 Ang Mo Kio Industrial Pk 2 Singapore 569538 and kindly arrange with Mr Anthony Cheong at T: 9108 2728.
4. If we do not hear from you within the next **two (2) working days**, we shall advise our client to proceed with their own inspection and repairs.
5. Please reply either by fax at 6733 8183 or by email to [kelly@chiaarul.com](mailto:kelly@chiaarul.com).

Yours faithfully,



**MR ARULCHELVAN S**

cc: Client (By email)

---

Renneth

MVA119112133-01 / VAC - Bukit Batok  
ENTRY DATE & TIME: 26/08/2019 13:26  
SUBMITTED BY: SUSAN SEAH SOH ENG

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	26/08/2019 13:26
Date Of Accident	25/08/2019 12:30
Exact Location Of Accident	JURONG EAST ST 24 CARPARK
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLZ7427C
<b>Insured/Policyholder</b>	
Name Of Registered Owner	CHANG PHUI MING
NRIC No	S7485914C
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97509443
Alternative Phone No	OFFICE-97509443
<b>Vehicle Particulars</b>	
Manufacturer	MERCEDES-BENZ
Model	E250-1.8 CGI ESTATE (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
<b>Insurance Company</b>	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5103860756 (CLASSIC)
Cover Note Number	
<b>Driver</b>	
Name of Driver	LIM FUI LING
NRIC No	S7478895E
Date Of Birth	16/05/1974
Occupation	OUTDOOR
Date Of Driving Pass	17/11/2007
Driving Experience	11 YEARS AND 9 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-97509443
Fax Number	
Contact Number	OFFICE-97509443
Email Address	NOEMAIL

Address 416 BUKIT BATOK WEST AVENUE 4  
 #02-254  
 Postcode S650416  
 Was driver an employee of the Insured's Company NO  
 If No, Relationship of the Driver with the Insured SPOUSE  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

#### General Information of the Accident

Type Of Accident SIDE SWIPE  
 Weather Conditions CLEAR  
 Road Surface DRY

#### Other Information

Was any foreign vehicle involved in this accident? NO  
 Number of vehicles (including own vehicle) involved in the accident 2  
 Was any body injured in the Accident? NO  
 Was any injured conveyed to hospital by ambulance?  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (including Driver) 5

Passenger 1 NAME: : -  
 GENDER: : MALE

Passenger 2 NAME: : -  
 GENDER: : MALE

Passenger 3 NAME: : -  
 GENDER: : FEMALE

Passenger 4 NAME: : -  
 GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police? NO  
 If Yes, Please state which Police Station  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

#### Circumstances of Accident

PLEASE SEE ATTACHED SKETCH PLAN

#### Attachment(s)

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? NO  
 Was there any audio recorded? NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJN251A  
 Vehicle Make/Model/Colour MERCEDES BENZ  
 Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)



Sketch Plan Pg. 1

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

**8. Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:


Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

IDAC BUKIT BATOK (VAC)  
511 Bukit Batok Street 23  
Singapore 658645  
Tel: 6660 3312 Fax: 6580 0722  
Email: vacbb@singnet.com.sg

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving my car in the carpark drive way. Suddenly vehicle (B) SYN251A drive out from his parking lot and hit on my rear left side portion.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

26 AUG 2019

IDAC SINGAPORE  
611 Bukit Batok Street 23  
Singapore 659545  
Tel: 6560 3312 Fax: 6569 0722  
Email: vacbb@singnet.com.sg

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

## Measurement Summary

Car standard measurement

Beissbarth © \* SL

M \* R+ \*\* OK \* MERCEDES-BENZ\_STANDARD / 3.01 / 293 / C

Date: 03.09.2019 12:54:21

Before



Version (program)  
v5.0b3224/v5.0b3224

Version (FWA)  
v5.0b1801

Version (target data)  
MERCEDES-BENZ v03.01

Serial number  
QZ0000178

Last service  
16.03.2019

### Rear Axle

		Initial Measurement	Target Data
Camber	left	-1°51'	
	right	-1°09'	
Cross Camber		-0°42'	[0°30']
Individual Toe	left	+0°00'	
	right	+0°20'	
Cross Toe		-0°20'	[0°15']
Total Toe		+0°19'	
Setback		-0°14'	
Geometrical driving axis		+0°10'	-0°15' [+0°00'] +0°15'

### Front Axle

		Initial Measurement	Target Data
Castor 20°	left	+6°46'	
	right	+6°53'	
K.P.I. 20°	left	+22°11'	
	right	+10°40'	
Toe out on turns	left	-2°02'	
	right	-2°13'	-0°30' [-1°54'] +0°30'
Camber	left	-0°53'	
	right	-0°22'	
Cross Camber		-0°31'	[0°24']
Individual Toe	left	+0°22'	
	right	+0°04'	-0°05' [+0°05'] +0°05'
Total Toe		+0°26'	-0°10' [+0°10'] +0°10'
Setback		-0°06'	
Included Angle 20°	left	+21°10'	
	right	+10°24'	

**Measurement printout**

Car standard measurement

Beissbarth © \* SL

M \* R+ \*\* OK \* MERCEDES-BENZ\_STANDARD / 3.01 / 293 / C

Date: 04.09.2019 10:38:46

Version (program)  
v5.0b3224/v5.0b3224Version (FWA)  
v5.0b1801Version (target data)  
MERCEDES-BENZ v03.01Serial number  
QZ0000178Last service  
16.03.2019**Customer**

Vehicle

Order

Vehicle: **MERCEDES-BENZ v03.01**

MERCEDES-BENZ \* E-Class \* 212 (W) ECE / USA \* Standard suspension, FA Steel-, RA Steel suspension

Rear Axle		Initial Measurement	Target Data	Final Measurement
Camber	left	-1°38'		-1°25'
	right	-1°07'		-1°20'
Cross Camber		-0°31'	[0°30' ]	-0°05'
Individual Toe	left	-0°03'		+0°06'
	right	+0°15'		+0°06'
Cross Toe		-0°18'	[0°15' ]	+0°00'
Total Toe		+0°12'		+0°12'
Setback		-0°11'		-0°04'
Geometrical driving axis		+0°09'	-0°15' [+0°00' ] +0°15'	
Front Axle		Initial Measurement	Target Data	Final Measurement
Castor 20°	left	+6°42'		+6°42'
	right	+6°58'		+6°56'
K.P.I. 20°	left	+17°52'		
	right	+16°17'		
Toe out on turns	left	-2°08'	-0°30' [-1°54' ] +0°30'	
	right	-2°15'		
Camber	left	-0°52'		-0°40'
	right	-0°23'		-0°35'
Cross Camber		-0°29'	[0°24' ]	-0°05'
Individual Toe	left	+0°23'	-0°05' [+0°05' ] +0°05'	+0°05'
	right	-0°05'		+0°05'
Total Toe		+0°18'	-0°10' [+0°10' ] +0°10'	+0°10'
Setback		-0°06'		+0°01'
Included Angle 20°	left	+17°02'		
	right	+15°54'		

Hy

# Trust Autoworks

Mailing address : Blk 225 #07-579 Ang Mo Kio Ave 1 Singapore 560225  
Tel : 91082728

Chang Phui Ming  
Blk 416 #02-254  
Bukit Batok West Ave 4  
Singapore 650416

Not Authorized  
11 Sep @ 4400h  
Resurvey After Paint

Vehicle No : SLZ 7427 C  
Make : Mercedes E250  
Year : 2012

Qty	Description	Unit Price	Amount
-----	-------------	------------	--------

## Estimate Cost Of Repair

1 pc	Rear n/s door assy	
1 pc	Rear n/s door weatherstrip	X
1 pc	Rear n/s door inner lock	X
1 pc	Rear n/s door glass regulator motor	X
1 pc	Rear bumper	photo
1 pc	Rear n/s bumper side retainer	photo
1 pc	Rear n/s tail-lamp assy	photo
1 pc	Rear n/s fender	photo
1 pc	Rear n/s shock absorber	2 photo
1 pc	Rear n/s lower arm	photo
1 pc	Rear n/s knuckle arm	photo
1 pc	Rear n/s knuckle bearing	photo
1 pc	Rear n/s trailing arm	photo
1 pc	Rear n/s side control arm	photo

R	\$2,025.00	X
Sn	\$405.00	X
n	\$355.00	X
se	\$400.00	X 468
nd/mg	\$1,265.00	
n	\$110.25	
sn	\$755.00	
n	\$1,680.00	X
n	\$475.00	
n	\$455.00	
n	\$550.00	
n	\$205.00	
n	\$255.00	
n	\$296.00	X
	\$9,079.25	6,391.25
Less 10 %	\$907.93	639.13
	\$8,171.32	5752.12

## S Nett

1 pc	Rear n/s tyre rim	
10	Clip	

nd	\$650.00	✓
nd	\$25.00	✓

## Labour Charges

Remove/renew the above parts. Knock out & straighten n/s door centre pillar etc

\$1,200.00 4001

To putty & spray paint on accident affected portion

\$1,200.00 4801

Check/reconnect wiring

\$30.00 201

balance c/f \$11,276.32

KK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

SLZ 7427 C

balance b/f \$11,276.32

Labour Charges

To spray anti rust on accident affected portion.

*nn* \$180.00 *X*

Remove/refit rear n/s door glass, mechanism, inner lock, trim board to new door.

*nn* \$150.00 *λ*

Remove/renew rear n/s undercarriages.

\$480.00 *2001*

Check and realign wheel alignment

\$60.00 *✓*

Total \$12,146.32

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG19015084/KYD3N2

Date: 03/10/2019

**REFERENCE**

<b>Handling Insurer:</b>	AIG Asia Pacific Insurance Pte. Ltd.	<b>Policy No:</b>	1800001676
<b>Claimant Vehicle No :</b>	SLZ7427C	<b>Insured Vehicle No :</b>	SJN251A
<b>Date of Loss:</b>	25/08/2019	<b>Nature of Claim:</b>	TP
		<b>Claim No:</b>	2705142404SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

<b>Reg No:</b>	SLZ7427C	<b>Engine No:</b>	27186030540713
<b>Make &amp; Model:</b>	MERCEDES-BENZ E250, 1.8 CGI ESTATE (A)	<b>Chassis No:</b>	WDD2120472A677927
<b>Reg. Date:</b>	15/04/2013 (Man. Year: 2012)	<b>Odometer:</b>	77098 km
<b>Colour:</b>	Metallic Blue		
<b>Engine Capacity:</b>	1796 cc		
<b>Market Value/New Car Price:</b>	N/A		
<b>Sum Insured (S\$):</b>	Market Value/New Car Price		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

<b>General Condition:</b>	<b>Steering (Serviceable):</b>	Yes	<b>Footbrake (Serviceable):</b>	Yes
<b>Handbrake (Serviceable):</b>	<b>Engine Modification:</b>	No	<b>Pre-accident Condition:</b>	

**CONDITION OF TYRES**

<b>Front Tyre Size:</b>	245/40ZR18	<b>Rear Tyre Size:</b>	265/35ZR18
<b>Front Left Side:</b>	Michelin 7 mm	<b>Rear Left Side:</b>	Michelin 3 mm
<b>Front Right Side:</b>	Michelin 7 mm	<b>Rear Right Side:</b>	Michelin 3 mm

The above values represent the remaining tyre treads depth

**COST OF CLAIMS**

	Repairer's	Adjuster's	Difference	Diff %
Parts	8,846.32	4,338.22	4,508.10	50.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,300.00	1,160.00	2,140.00	64.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>12,146.32</b>	<b>5,498.22</b>	<b>6,648.10</b>	<b>54.73</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,400.00</b>		
<b>Nett Amount (S\$)</b>	<b>12,146.32</b>	<b>4,400.00</b>	<b>7,746.32</b>	<b>63.78</b>

**INSPECTION**

Date of Assignment: 27/08/2019

Date Inspected: 02/09/2019 Inspected At:

BLK 5035 #01-345

AMK IND PARK 2

REPAIRER: TRUST AUTOWORKS

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR N/S DOOR ASSY	Repair	2,025.00 FL	*- FL
2	1	*REAR N/S DOOR WEATHERSTRIP	Serviceable	185.00 FL	*- FL
3	1	*REAR N/S DOOR INNER LOCK	Repair	355.00 FL	*- FL
4	1	*REAR N/S DOOR GLASS REGULATOR MOTOR	Serviceable	468.00 FL	*- FL
5	1	*REAR BUMPER	Dented/Mtg Cracked	1,265.00 FL	*1,265.00 FL
6	1	*REAR N/S BUMPER SIDE RETAINER	Distorted	110.25 FL	*110.25 FL
7	1	*REAR N/S TAIL-LAMP ASSY	Cut	755.00 FL	*755.00 FL
8	1	*REAR N/S FENDER	Repair	1,680.00 FL	*- FL
9	1	*REAR N/S SHOCK ABSORBER	Bent	475.00 FL	*475.00 FL
10	1	*REAR N/S LOWER ARM	Distorted	455.00 FL	*455.00 FL
11	1	*REAR N/S KNUCKLE ARM	Bent	550.00 FL	*550.00 FL
12	1	*REAR N/S KNUCKLE BEARING	Necessary	205.00 FL	*205.00 FL
13	1	*REAR N/S TRAILING ARM	Distorted	255.00 FL	*255.00 FL
14	1	*REAR N/S SIDE CONTROL ARM	Serviceable	296.00 FL	*- FL
15	1	*REAR N/S TYRE RIM	Dented	650.00 FS	*650.00 FS
16	10	*CLIP	Necessary	25.00 FS	*25.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,754.25	4,745.25
- List Item Discount on L Items 10.00/10.00% (\$\$)	907.93	407.03
Total Parts (\$\$)	8,846.32	4,338.22

Report was unsubmitted during this print-out.



## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	REMOVE/RENEW THE ABOVE PARTS,KNOCK OUT & STRAIGHTEN N/S DOOR CENTRE PILLAR ETC	New	1,200.00	400.00
2	TO PUTTY & SPRAY PAINT ON ACCIDENT AFFECTED PORTION	New	1,200.00	480.00
3	CHECK/RECONNECT WIRING	New	30.00	20.00
4	TO SPRAY ANTI RUST ON ACCIDENT AFFECTED PORTION	New	180.00	0.00
5	REMOVE/REFIT REAR N/S DOOR GLASS,MECHANISM,INNER LOCK,TRIM BOARD TO NEW DOOR	New	150.00	0.00
6	REMOVE/RENEW REAR N/S UNDERCARRIAGE	New	480.00	200.00
7	CHECK AND REALIGN WHEEL ALIGNMENT	New	60.00	60.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,300.00</b>	<b>1,160.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >