

T2867500

ASS. REC. BY:

REF:

CS/INC19015094/Gsd367

Special Instructions:

Assigner: Quo Ding

ASSIGNMENT (Office)

From (Person): Daniel Koh

of

INC

Date/Time:

9:39am @ 27/8/19

Estimated Cost:

Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SMH 5725M

Insured:

SJE 9606C

at Workshop m/s

Bomo Motor

Tel:

9776 2689

of

17 Ubi Road 4

Policy No:

Claim No:

MT/1056837-002

Sum Insured:

Excess:

Make of Veh:

D.O.A.

6/8/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 10:17am @ 27/8/19

Person Contacted:

Raymond

Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction
	Estimated <input checked="" type="checkbox"/>
30/08/19	Confirmed P/P \$ 1,700/- @ 3 days with X/A (\$ 3,908.70 Red - 70%)

## ASSIGNMENT

From:

Date:

07/8/19

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SMH 572SM

at Workshop m/s

Borneo motor

of

17 ubi Road 4

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

Car In  
Raymond

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

(up)

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SMH 572SM

Yr Regn:

28 Jan 2019

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Prius plus 1798

Colour:

Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

40635

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JTD8536490J038030

Gen. Cond:

Good / Fair / Poor / Burnt

Steering:

In order / Jammed / Leaked / Burnt or

Brake:

In order / Jammed / Leaked / Burnt or

Modi:

Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/60 R16

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

27-08-19

Survey held at

w/s

3:30pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

30/08/19

1) Typ. 4

Date/Time, File Return to?

2)

Report Format:

Lump Sum (L&amp;M):

1,700/- P/P

Days Of Repair:

3

Resurvey No. of Trip:

1

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

Survey Fee:

290

Transportation:

S + RS: \$

Photos

Others

TOTAL

290

**Nivitha (LKK Auto)**

**From:** Daniel Koh <daniel.koh@income.com.sg>  
**Sent:** Tuesday, 27 August 2019 10:05 AM  
**To:** 'assignments@lkkauto.com'  
**Cc:** admin-d@lkkauto.com  
**Subject:** FW: TP CASES FARMED OUT TO LKK ON 27/8/2019

Dear LKK,  
  
Resend with full details.

**From:** Daniel Koh  
**Sent:** Tuesday, 27 August 2019 9:39 AM  
**To:** 'assignments@lkkauto.com' <assignments@lkkauto.com>  
**Cc:** 'admin-d@lkkauto.com' <admin-d@lkkauto.com>; Teng Ken Leong <kenleong.teng@income.com.sg>; Thio Tse Kiat <tsekiat.thio@income.com.sg>  
**Subject:** FW: TP CASES FARMED OUT TO LKK ON 27/8/2019

Dear LKK,  
  
Please assist to survey the following vehicles as per Mr Teng's instruction :-

SN	OIC	Claim No.	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	Survey Time	OIV	DOA	Additional Remarks
1	MUHAMMAD AIRWAN	MT/1059382-001	SMJ9095K	AUTO INSURE PTE LTD	6 MARSILING LANE	Mr Sam Goh / 9743 6363		PC4792R	24/8/2019	3157 2624 / 3157 2628

2	ENG HUEY HUEY	MT/1058999- 002	SJW7925X	AUTOLUTION INDUSTRIAL PTE LTD	19 UBI ROAD 4 SINGAPORE 408623	Elmer Alfonso / 9645 0084	14:00- 16:00	SLZ4235J	21/8/2019	67038691
3	SERENE LIM	MT/1056837- 002	SMH5725M	BORNEO MOTORS UBI SERVICE CENTRE	BLK 17 UBI ROAD 4 SINGAPORE 408611	Raymond Seah / 9776 2689	13:00- 15:00	SJE9665C	6/8/2019	
4	DAVID PHUA	MT/1059292- 002	SKX1688C	MY CAR CONSULTANT PTE LTD	53 UBI AVENUE 1 #01-33 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934	Kai Ling / 9868 6000		SKJ4629C	22/8/2019	
5	SERENE LIM	MT/1059373- 001	SFR4607H	PROGRESSIVE CAR CARE PTE LTD	BLK 3022A #01- 45/46 UBI ROAD 1 SINGAPORE 408716	Pei Wen NG / 6741 5336		SJA2264T	24/8/2019	
6	FIONA SHEN	MT/1055613- 001	SKP7070L	PROGRESSIVE CAR CARE PTE LTD	BLK 3022A #01- 45/46 UBI ROAD 1 SINGAPORE 408716	Pei Wen NG / 6741 5336	14:00- 16:00	FN8375X	27/7/2019	

Please contact workshops.

Please revert to officer-in-charge after survey.

Thank you.

Daniel Koh  
Senior Admin Assistant  
Motor Insurance  
T +65 6430 7901

[www.income.com.sg](http://www.income.com.sg)

**income**  
made different



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.

Find out more at [income.com.sg/careers](http://income.com.sg/careers)

**in** with  
you

---

#### Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

[Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Owner ID Type:	Singapore NRIC
Owner ID:	567F
Vehicle No.:	SMH5725M
Vehicle to be Exported:	No
Intended Deregistration Date:	27 Aug 2019
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS PLUS (AUTO)
Primary Colour:	Silver
Manufacturing Year:	2018
Engine No.:	2ZR0D05526
Chassis No.:	JTDZS3EU90J038030
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$30,006.00
Original Registration Date:	28 Jan 2019
First Registration Date:	28 Jan 2019
Transfer Count:	0
Actual ARF Paid:	\$24,009.00

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Jan 2029
PARF Rebate Amount:	\$18,006.00

COE Expiry Date:	27 Jan 2029
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$31,809.00
COE Rebate Amount:	\$29,192.00
Total Rebate Amount:	\$47,198.00

The information contained herein is correct as at 27 Aug 2019

OK

## Guo Qiang (LKKAUTO)

---

**From:** Guo Qiang (LKKAUTO)  
**Sent:** Thursday, 29 August, 2019 5:55 PM  
**To:** Raymond Seah PTCBC  
**Cc:** Veron Chen (LKKAUTO)  
**Subject:** RE: FINALIZE FOR SMH5725M

Dear Raymond,

Confirmed COR \$1700 before GST @ 3 working days.

Regards,  
Guo Qiang

---

**From:** Raymond Seah PTCBC [mailto:Raymond.Seah@borneomotors.com.sg]  
**Sent:** Thursday, 29 August, 2019 5:36 PM  
**To:** Guo Qiang (LKKAUTO)  
**Cc:** Veron Chen (LKKAUTO)  
**Subject:** FINALIZE FOR SMH5725M

Dear Guo Qiang,  
Attach are photos and estimate of SMH5725M to finalize.  
Thanks  
Raymond Seah  
9776 2689

---

**From:** Ubi\_ToyotaBP@inchcape.com.sg <Ubi\_ToyotaBP@inchcape.com.sg>  
**Sent:** Thursday, August 29, 2019 5:28 PM  
**To:** Raymond Seah PTCBC  
**Subject:** Scan Data from [FX20FF88]

This e-mail (and any attachment) is intended for the addressee(s) only and contains information that is legally privileged and confidential. If you are not the intended recipient, please be advised that you have received this e-mail in error and that any use, dissemination, distribution, printing or copying of this communication is unauthorized and strictly prohibited. Kindly notify us by replying to the sender's e-mail address and delete this e-mail immediately. E-mail transmissions cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, delayed or incomplete, or could contain viruses. We therefore do not accept liability for any errors or omissions in the contents of this e-mail which arise as a result of e-mail transmission, and you are advised to carry out your own virus checks and confirm the accuracy of the contents of this e-mail before relying on it for any purpose.

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	08/08/2019 14:53
Date Of Accident	06/08/2019 21:30
Exact Location Of Accident	ALONG CHANGI CITY POINT DROP OFF POINT.
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMH5725M
<b>Insured/Policyholder</b>	
Name Of Registered Owner	LEE SIK BEEN
NRIC No	S2595567F
Email Address	SBLEE61@YAHOO.COM.SG
Mobile Phone No	(LOCAL) +65-96886863
Alternative Phone No	OTHERS-96886863

### Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS PLUS (AUTO)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	FWD SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	PNCV2019-00000108
Cover Note Number	NA

### Driver

Name of Driver	LEE SIK BEEN
NRIC No	S2595567F
Date Of Birth	09/11/1961
Occupation	OUTDOOR
Date Of Driving Pass	22/06/1985
Driving Experience	34 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-96886863
Fax Number	
Contact Number	OTHERS-96886863
Email Address	SBLEE61@YAHOO.COM.SG



Address	NA
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
POLICE STATION NAME [OTHER]	MACPHERSON N P P
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO POLICE REPORT NO: T/20190807/2124 LODGED AT MACPHERSON NPP. ON 6/9/19 AT ABOUT 2130 HRS, I WAS WAITING FOR MY PASSENGER AT CHANGI CITY POINT PICK UP/DROP OFF POINT, WHEN ONE VEHICLE (SJE9665C) WHO WAS BEHIND OF ME PICKED HIS PASSENGER UP AND DRIVING AWAY. WHILE HE WAS MAKING HIS WAY OUT OF THE PICK UP POINT, HIS VEHICLE COLLIDED INTO MY REAR RIGHT BUMPER. AS SUCH, I CAME DOWN TO MAKE A CHECK. WE THEN EXCHANGE OUT PARTICULARS AND CLAIMING OUR OWN INSURANCE. THERE IS NO INJURIES SUFFERED AT THAT POINT OF TIME AND NO AMBULANCE / POLICE ATTENDED TO US. I AM UNSURE IF THERE IS ANY CCTV NEARBY WHICH COULD CAPTURE THE WHOLE INCIDENT. I AM MAKING THIS REPORT FOR THE INSURANCE CLAIM PURPOSE AGAINST HIS INSURANCE.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJE9665C
Vehicle Make/Model/Colour	HONDA / CIVIC 1.6L VTI AUTO
Details Of Properties	NA
Vehicle Category	PRIVATE CAR
Name of Driver	TAN SONG LEONG
NRIC/Passport Number	S7133357D
Contact Number	98539413
Address	
Postcode	

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

2

Passenger 1

NAME: : PASSENGER 1

GENDER: :

#### DETAILS OF INJURED PERSON 1

Name

LEE SIK BEEN

Approximate Age

Injuries Sustain

3 DAYS MEDICAL LEAVE

Injured person in which vehicle?

SMH5725M

Were seat belts worn?

YES

Was this injured conveyed to hospital by ambulance?

NO

Address

Postcode

# Sketch Plan

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)
 

I understand, acknowledge, agree and consent that

  - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
    - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
    - (ii) investigating the accident and/or my claims;
    - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
    - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
    - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
  - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
  - (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

VERIFIED BY AJAX MARS  
REPORTING OFFICER  
JOHNNY VOO

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre  
Personnel

## Sketch Plan

Along City Point Drop off Point / Pick up Point.

A: SIMH5725M  
B: SJF966SC

## POLICE REPORT



**SINGAPORE  
POLICE FORCE**



T/20190807/2134

1 of 3

Police Station Of Origin:  
MacPherson NPP  
54 Pipl Road #01-82/84 SINGAPORE  
370054  
Tel No. 1800-7449999

Report No: T/20190807/2134

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made:  
07/08/2019 17:58

Video Report No.

Station Diary No.  
9

**Informant's Particulars**

Name of Informant LEE SIK BEEN			Address APT BLK 92A PIPIT ROAD #10-87 SINGAPORE 371092		
ID Type / ID No. NRIC NO / S2595567F			Contact No. Home/Office Mobile: 96886863		
Nationality SINGAPORE CITIZEN			Email		
Sex Male	Age 57	Date of Birth 09/11/1961	Type of Informant Driver		
Race Chinese			Language		Institution / School Name
Occupation Taxi driver			Driving Licence Information Class: 2B, 2A, 2, 3 Date of Expiry		

**General Information of the Accident**

Type of Accident	Injury Others	Drink Drive No	Date/Time of Accident 06/08/2019 21:30	Type of Location Roundabout
Location Along Road 1 CHANGI BUSINESS PARK CENTRAL 1				
Changi City Point Drop Off/Pick Up Point				
Weather Clear		Road Surface Dry		Road Speed Limit
Traffic Flow One Way		Traffic Control Not Controlled		Traffic Volume Light
Type of Collision Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance No

**Details of Vehicle Involved**

Vehicle No	Type	Make	Model	Color	Condition	No of Passenger
SJE9665C	Car	HONDA	CIVIC 1.6L VTI AUTO	Silver	Slightly Damaged	1
SMH5725M	Car	TOYOTA	PRIUS PLUS (AUTO)	Silver	Slightly Damaged	0

**Details of Vehicle Insurance**

Vehicle No	Insurance Company	Insurance No	Effective	Expiry Date
SMH5725M	FWD Singapore Pte. Ltd	PNCV2019-00000108	28/01/2019	27/01/2020

## POLICE REPORT



**SINGAPORE  
POLICE FORCE**

Police Station Of Origin:  
MacPherson NPP  
54 Phipps Road #01-82/84 SINGAPORE  
370054  
Tel No: 1800-7449999

T/20190807/2124

2 of 3

Report No. T/20190807/2124

## CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	LEE SIK BEEN	ID No.	S2595567F
Related Vehicle	SMH5725M (Car)	Contact No.	96886863
Hospital/Clinic	SINGHEALTH POLYCLINICS - GEYLANG	Class of Driving Licence & Expiry Date	Class: 2B,2A,2,3 Date of Expiry: NIL
Date Treatment	07/08/2019	Date Discharge	NIL
No. of Days granted Medical Leave	03	Degree of Injury	Slight
Name			
	Tan Song Leong	ID No.	S7133357D
Related Vehicle	NIL	Contact No.	98539413
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

**Brief Details.**

On 6/9/19 at about 2130hrs, I was waiting for my passenger at Changi City Point Pick up/ Drop off point when one vehicle (SJE9665C) who was behind of me picked his passenger up and driving away. While he was making his way out of the pick up point, his vehicle collided into my rear right bumper. As such, I came down to make a check. We then exchange our particulars and claiming our own insurance. There is no injuries suffered at that point of time and no ambulance/police attended to us. I am unsure if there is any CCTV nearby which could capture the whole incident. I am making this report for insurance claim purpose against his insurance.

POLICE REPORT



SINGAPORE  
POLICE FORCE

Police Station Of Origin:  
MacPherson NPP  
54 Phipps Road #01-82/84 SINGAPORE  
370054  
Tel No: 1800-7449999



Report No: 12251904801/1/1/1/1

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan.

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

G /

Sgt 2 MELSON CHEW WEI JIE

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / AEIT /

Sgt 2 SHARIFAH NOR FARIZAN BINTE SYED  
MOHD SAID

Contact No. 65476172

Authentication Stamp

NP188

Signature Of Informant:

Date/Time  
07/08/2019 17:58

Classification Of Case:





Co Reg No : 196700086Z  
GST Reg No : MR-8500000-9

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :

www.toyota.com.sg

Toyota Bodycare Centre

17 Ubi Road 4

Singapore 409611

Tel no.: 6631 1188

# ESTIMATE

Account Detail				Account No		Customer Detail			
THIRD PARTY CLAIM <i>11011</i> <i>Chel</i>				S1000020 / TPCLAIM		Mr Lee Sik Been 92A Pipit Road #10-87 Singapore 371092 Mobile: 96886863			
				Document No					
				0					
				Document Date					
				13/08/2019					
Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks		
18	AWXEBW S2	ZVW40R	28/01/2019	SMH5725M	0	18799	69UL/SMH5725M-		
Chassis No		Engine No		Terms	Service Engineer	Vehicle In	Collected On		
JTDZS3EU90J038030		22R0D05526		60	Raymond Seah L M	--/--/----	0.00 --/--/---- 0.00		
L	Cd	Job/Parts Description				Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES TP VEH: SJE9665C ACC DATE: 06/08/2019 TP INS; NO OF REPAIR DAYS: DATE-IN: DATE SURVEY: BY: AUTHORISED ON: -TP/DS CLAIM							✓ 30.00
2	B	BP-ECU2 TO RESET ECU AND REPROGRAMME							✓ <del>180.00</del>
3	B	BP-LAB2 TO CHECK WIRING AND LIGHTING. TO WATER TEST FOR LEAK.							NN X 122.40
4	B	BP-LAB2 R/I REAR REVERSE SENSOR TO FACILITATE REPAIRS AND TEST FUNCTION.							✓ 180.00
5	B	BP-LAB2 TO REPLACE/REPAIR REAR ACCIDENT DAMAGE PARTS. STRAIGHTEN/REALIGN ALL OTHER AFFECTED AREAS.							720 1440.00
6	B	BP-RES2 TO SPRAY PAINT ON REAR ACCIDENT AFFECTED AREAS.							590 1770.00
7	1	T81910-47010 REFLECTOR ASSY,				1.00	59.80		NN 59.80 X
8	2	T52159-47912 COVER, RR BUMPER				1.00	556.40		Repair 556.40 X
9	3	S52161-OK040 CLIPS				4.00	4.10		NN 16.40 X
10	4	T52575-47030 RETAINER, RR BUMPER				1.00	59.10		NN 59.10 X
Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.									
For & on behalf of Borneo Motors			Customer's Signature			Change Summary			Total
<i>[Signature]</i>			Please acknowledge receipt of vehicle			Parts			Less
						Labour			
						Materials			
						Lubrication/Fluid			
						Others			
									Amount Due

PLEASE TEAR ALONG PERFORATED LINE

4036241

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED  
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 13/08/2019  
TIME 18:05

4036241

VEHICLE NO SMH5725M

SIGNATURE  
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

Inchcape

CUSTOMER

Co Reg No : 196700086Z  
GST Reg No : MR-8500000-9**ESTIMATE**

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account &amp; more!

Account Detail				Account No		Customer Detail			
<b>THIRD PARTY CLAIM</b>				<b>S1000020 /TPCLAIM</b>		<b>Mr Lee Sik Been</b> <b>92A Pipit Road</b> <b>#10-87</b> <b>Singapore 371092</b>  <b>Mobile: 96886863</b>			
				Document No					
				0					
Document Date				13/08/2019					
Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks		
18	AWXEBW S2	ZVW40R	28/01/2019	SMH5725M	0	18799	69UL/SMH5725M-		
Chassis No		Engine No		Terms	Service Engineer	Vehicle In	Collected On		
JTDZS3EU90J038030		2ZR0D05526		60	Raymond Seah L M	--/--/----	0.00 --/--/---- 0.00		
L	Cd	Job/Parts Description				Qty	Unit Price	Disc %	Amount
11	5	T52576-47030 RETAINER, RR BUMPER				1.00	59.10		59.10 X
12	6	T52155-47010 SUPPORT, RR BUMPER				1.00	142.80		142.80 X
13	7	T52156-47010 SUPPORT, RR BUMPER				1.00	142.80		142.80 X
14	8	T76891-47040 SPOILER, RR NO.1				1.00	849.90		849.90 X
<p>3 Days. before part photos. Gno Qiang - 8288 0282 Gno Qiang @ lkkauto.com 27/8/19.</p> <p><i>[Signature]</i> 29/8/19</p> <p>1700</p> <div><p>LKK Auto Consultants hence notify the Repairer of the following:</p><ul style="list-style-type: none"><li>• To resurvey before/after spray painting</li><li>• To display damaged part(s) during resurvey</li><li>• Parts prices are subject to confirmation</li><li>• Third party survey is on a "Without Prejudice" basis</li><li>• No illegal modification(s) is allowed</li><li>• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company</li></ul><p>Acknowledged by Repairer</p><p>Signature: _____</p><p>Date: _____</p></div> <p>Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.</p>									
For & on behalf of Borneo Motors		Customer's Signature		Change Summary		Total		5,608.70	
		Please acknowledge receipt of vehicle		Parts	1,886.30	GST 7.00%		392.61	
				Labour	3,722.40				
				Materials	0.00	Less		0.00	
				Lubrication/Fluid	0.00				
				Others	0.00	Amount Due		6,001.31	

PLEASE TEAR ALONG PERFORATED LINE

4036242

4036242

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED  
VEHICLE TO LEAVE THE COMPANY PREMISES.DATE 13/08/2019  
TIME 18:05

VEHICLE NO SMH5725M

CUSTOMER

SIGNATURE  
FOR BORNEO MOTORS (SINGAPORE) PTE LTD**Borneo Motors**





Co Reg No : 196700086Z  
GST Reg No : MR-8500000-9

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

# ESTIMATE

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :  
www.toyota.com.sg

Toyota Bodycare Centre  
17 Ubi Road 4  
Singapore 409611  
Tel no: 6631 1188

Account Detail		Account No	Customer Detail
THIRD PARTY CLAIM		S1000020 / TPCLAIM	Mr Lee Sik Been 92A Pipit Road #10-87 Singapore 371092 Mobile: 96886863
		Document No	
		Document Date	
		0	
		29/08/2019	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
18	AWXEBW	S2	ZVW40R	28/01/2019	SMH5725M	0	18799 9UL/SMH5725M-06081
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		

JTDZS3EU90J038030 2ZROD05526 60 Raymond Seah L M 27/08/2019 15.46 29/08/2019 18.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES TP VEH:SJE9665C ACC DATE:06/08/2019 TP INS:NTUC NO OF REPAIR DAYS:03 DATE-IN:27/09/2018 DATE SURVEY:27/09/2019 BY:LKK- GUO QIANG AUTHORISED ON:15/08/2019 -TP/DS CLAIM				30.00
2	B	BP-ECU2 TO RESET ECU AND REPROGRAMME				180.00
3	S	BP-SUBLET R/I REAR REVERSE SENSOR TO FACILITATE REPAIRS AND TEST FUNCTION.	A45			180.00
4	S	BP-SUBLET TO REPAIR REAR ACCIDENT DAMAGE PARTS.STRAIGHTEN/REALIGN ALL OTHER AFFECTED AREAS.	A45			720.00
5	S	BP-SUBLET TO SPRAY PAINT ON REAR ACCIDENT AFFECTED AREAS.	A45			590.00
Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000km (whichever comes first) to enjoy warranty benefits. Conditions apply.						

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts 0.00	1,700.00
		Labour 210.00	GST 7.00%
		Materials 1,490.00	119.00
		Lubrication/Fluid 0.00	Less 0.00
		Others 0.00	
			Amount Due 1,819.00

PLEASE TEAR ALONG PERFORATED LINE

O SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED  
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 29/08/2019  
TIME 09:25

VEHICLE NO SMH5725M

CUSTOMER

SIGNATURE  
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

Inchcape

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

**DAMAGE ASSESSMENT REPORT**

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC19015094/Gsd3e2

73 BRAS BASAH ROAD  
#05-01 NTUC TRADE UNION HOUSESINGAPORE  
189556

Date: 04-09-2019



ATTN : SERENE LIM

Code: INC

**1. Policy Particulars :- THIRD PARTY CLAIM**

Insured Veh.	SJE 9665C	Veh. Inspected	SMH 5725M
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1056837-002	Excess (\$)	0.00
Assign From	DANIEL KOH	Assign Date	27/08/2019

**2. Vehicle Particulars & Condition**

Make & Model	TOYOTA PRIUS PLUS	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	JTDZS3EU90J038030	Colour	SILVER
Odometer	40635 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

**3. Conditions of Tyres**

	Size	Make	Balance
R/H Front Tyre	205/60 R16	YOKOHAMA	6 mm
L/H Front Tyre	205/60 R16	YOKOHAMA	6 mm
R/H Rear Tyre	205/60 R16	YOKOHAMA	6 mm
L/H Rear Tyre	205/60 R16	YOKOHAMA	6 mm

**4. Description of Damages**

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.
--

**5. General Information**

Accident Date	06/08/2019	Inspect Date / Time	27/08/2019 ( 03:00 PM )
Survey held at	BORNEO MOTORS (S) PTE LTD 17 UBI ROAD 4 SINGAPORE 408611		

**5a. Remarks**

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

**5b. Estimate Days of Repair**

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

**ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMH 5725M**

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	SUNDRIES (SN)	NECESSARY	30.00	30.00
1	REFLECTOR ASSY (SN)	NOT NECESSARY	59.80	-
1	COVER, RR BUMPER (SN)	TO REPAIR SEE LABOUR	556.40	-
4	CLIPS (SN)	NOT NECESSARY	16.40	-
1	RETAINER, RR BUMPER (SN)	NOT NECESSARY	59.10	-
1	RETAINER, RR BUMPER (SN)	NOT NECESSARY	59.10	-
1	SUPPORT, RR BUMPER (SN)	NOT NECESSARY	142.80	-
1	SUPPORT, RR BUMPER (SN)	NOT NECESSARY	142.80	-
1	SPOILER, RR NO.1 (SN)	NOT NECESSARY	849.90	-
			1,916.30	30.00
	<b><u>LABOUR</u></b>			
	TO RESET ECU AND REPROGRAMME.		180.00	180.00
	TO CHECK WIRING AND LIGHTING. TO WATER TEST FOR LEAK.	NOT NECESSARY	122.40	-
	R/I REAR REVERSE SENSOR TO FACILITATE REPAIRS AND TEST FUNCTION.		180.00	180.00
	TO REPLACE / REPAIR REAR ACCIDENT DAMAGE PARTS. STRAIGHTEN / REALIGN ALL OTHER AFFECTED AREAS. INCLUSIVE OF THE REPAIR OF COVER, RR BUMPER.		1,440.00	720.00
	TO SPRAY PAINT ON REAR ACCIDENT AFFECTED AREAS.		1,770.00	590.00
			3,692.40	1,670.00
	<b>GRAND TOTAL</b>		<b>5,608.70</b>	<b>1,700.00</b>
	<b>RECOMMENDED COST OF REPAIRS (CONFIRMED)</b>			<b>1,700.00</b>

Report Ref No. CS/INC19015094/Gsd3e2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE,  
MinstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.