

INSURANCE

INS. CASE OWNER:

VALU

CC 4 ASM AXA 1901 5098, K. A. J. K.

LRK:
IDAC:

Surveyor:

Kenneth

DOI:

ASSIGNMENT
21/9/19

Date / Time:

27/8/19

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SGN 8754X

Name of Insured:

TAN KIM SENG

Insured Tel No.:

HP:

Excess Sec II : \$5

D.O.A.:

22/8/19

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

SA00244X / 13786

Policy No.:

60797761

Make / Model:

MINI COOPER

Place of Accident:

turn of roadways into park

If NO, Driver Name / Age:

Driver Tel No.:

(VAL: YES / NO)

Of GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

GRD 6483E



INSRS:
WSP:
Tel:
Liability:
RMKS:

Cheng
Hoe



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/Time		STAGE	DATE / PIC
27/9	waiting unclear send TP (Reg. AVF)	Non-Reporting 1st (1st)	
27/9	send WI (Reg. AVF)	Non-Reporting 1st (2nd)	
27/9	TP got no AVF. Pending of AVF.	Non-Reporting 1st (Final)	
27/9	TP got no AVF. send in Asp. seek AXA instruction to settle or best.	Notification 1st (if non-pickup)	
27/9	20/90 email send TP. (Pending confirmation)	Call OI	
27/9	TP seek mandate.	After call 1st to OI	
27/9	Pending mandate approval.	Documentation Check List: Handler	Typist
27/9	offer \$2380 (Pending acceptance)	Notification 1st (if non-pickup)	
27/9	TP seek \$2380 on send (Pending AVF).	After call 1st to OI	
27/9	20/90 email send TP. (Pending confirmation)	Authorisation To Act	
27/9	TP seek mandate.	Release Voucher	
27/9	Pending mandate approval.	Final Repair Bill	
27/9	offer \$2380 (Pending acceptance)	Car Rental Invoice	
27/9	TP seek \$2380 on send (Pending AVF).	Towing Invoice	
27/9	20/90 email send TP. (Pending confirmation)	LTA / GIA	
27/9	TP seek mandate.	Medical Bill	
27/9	Pending mandate approval.	PIR	
27/9	offer \$2380 (Pending acceptance)	Mandate/Reject Instruction	
27/9	TP seek \$2380 on send (Pending AVF).	LOD	
27/9	20/90 email send TP. (Pending confirmation)	Payment Breakdown Form	
27/9	TP seek mandate.	Post-Repair Photos	
27/9	Pending mandate approval.	Others	

PRELIMINARY ADVICE	Date/Time:	Sent By:	Confirm with:	Confirm by:
Repair Cost:	\$5 4200.00	5 days	Reduction: \$1840.87 = 30	Confirm by: Kenneth
FINAL SETTLEMENT	Date/Time:	Confirm with:	Email:	Call:
Final Liability:	% 50	(Agreed / Assessed) BOLA S/N No.:	NIL	
Repair Cost:	\$5 2747.00			
Loss of Rental (LOR):	\$5 25.00	(5 50 x 5 days)		
Loss of Use (LOU):	\$5 25.00	(5 50 x 5 days)		
Loss of Income (LOI):	\$5 -	(5 x 5 days)		
LOR only ☐ LOU only ☐ LOR + LOU ☐ LOR + LOI ☐		(Tick only one)		
GIA/LTA Search	\$5 8.00			
Medical:	\$5 -			
Disbursement:	\$5 -	(e.g. Tow/ Independent)		
Legal Cost:	\$5 -			
Total:	\$5 2380.00	Global Sum \$5:		
FINAL PAYMENT	Date/Time:	Confirm with:	Email:	Call:
Payee 1:	\$5 2380.00	Name 1:	Cheng Hoe Motor Pte Ltd	
Payee 2: (Strike if N.A.)	\$5 -	Name 2:		
Payee 3: (Strike if N.A.)	\$5 -	Name 3:		

27/9/2020

ASS. REC. BY:

REF: AA/

9

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Soon:

Est. Repairs:

Lum Sum:

Consistent? : Yes or No

Consistent? : Yes or No

Res.: Yes or No

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

File pass toLS 44200/- (Red 41840.87 / 30%)

Date/Time, File Pass to?

☐

: Prel. Report

1)

Date/Time, File Return to?

☐

: Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S - RS - SI

Fuels

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐


: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$



Veh No:

GBD 6483^E

Yr Regn:

02 15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

NIS Costa

c.c

2853

Colour:

White

A/C:

Insured / Std / NI / NA

Sp. Reading

221283

T/Radio:

Insured / Std / NI / NA

Eng/No:

7

C/No:

JNISC 21420856901

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: NIS / S/Rim / STD A/Rim or

Tyre Size:

F:

195R1518

R:

155R1318101

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Conda

Front

Rear

R/Bal.

6

mm

R/Bal.

66

mm

L/Bal.

6

mm

L/Bal.

66

mm

D.O.A.

22/8/19

D.O.I.

21/9/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotors@singnet.com.sg
GST:201001158E RCB NO:201001158E

GBD 6483E
TP/AXA

M/S : AXA INSURANCE (S) PTE LTD
8 SHENTON WAY
#27-02 AXA TOWER
SINGAPORE 068811

TEL: 63387288 FAX: 68804739
ATTN: Motor Claim Department

Estimate No: ES1992057/YISHUN
Date: 21 Sep 2019
Policy No: Z/18/VC00/102421
Veh Reg No: GBD6483E
Make/Model: NISSAN CABSTAR 3.0
5M/T ABS 2DR 2WD
EURO 5

WS Ref: TP/AXA
Claim Type: Third Party
Accident Date: 22/08/2019
TP Veh Reg No: SGN8754Z

Chassis No: JN1SC2F24Z0856901
Engine No: ZD30345041K
Reg. Date: 11/02/2015

Estimate Repair Cost to Vehicle No :GBD6483E

PAGE:1/1

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
Net Price				
1 FRONT BUMPER	1,155.10	1 PC	1,155.10	✓
2 FRONT BUMPER RH BRACKET	283.10	1 PC	283.10	✓
3 FRONT BUMPER CLIPS	3.50	6 PCS	21.00	✓
4 FRONT GRILLE	461.90	1 PC	461.90	✓
5 FRONT GRILLE CLIPS	5.00	6 PCS	30.00	✓
6 RH HEADLAMP	473.40	1 PC	473.40	✓
7 RH HEADLAMP LOWER GARNISH	81.30	1 PC	81.30	✓
8 FRONT RH CORNAL PANEL	398.00	1 PC	398.00	✓
9 FRONT RH DOOR	1,474.80	1 PC	1,474.80	✓
10 FRONT RH DOOR LAMP	109.80	1 PC	109.80	✓
11 FRONT RH DOOR BOTTOM HINGE	99.80	1 PC	99.80	✓
12 FRONT PANEL EMBLEM "CABSTAR"	74.30	1 PC	74.30	✓
13 FRONT RH SIDE MIRROR	171.80	1 PC	171.80	✓
			4,834.30	
		Less 10%	483.43	4,350.87
Special Net				
14 FRONT RH DOOR COY STICKER	20.00	1 PC	20.00	✓
			20.00	20.00
Labour				
15 REMOVE & REFIX FRT BUMPER ASSY,GRILLE,HEADLAMPS,FRT RH CORNAL PANEL,FRT RH DOOR & ATTACHMENT,TO STRAIGHTEN,KNOCK & REPAIR FRT RH W/SCREEN PILLAR & REALIGN THE SAME	700.00	1 LA	700.00	600
16 REMOVE & REFIX FRT RH DOOR GLASS,CHECK CENTRAL LOCKING & POWER MIRROR	60.00	1 LA	60.00	✓
17 PUTTY & RESPRAY PAINT ON FRT BUMPER BRACKET,FRT RH DOOR,FRT RH W/SCREEN PILLAR,FRT RH CORNAL PANEL,FRT PANEL & ALL AFFECTED AREAS	700.00	1 LA	700.00	600
18 RUSTPROOFING	30.00	1 LA	30.00	✓
19 TO REWRITE ADVERTISEMENT	180.00	1 LA	180.00	✓
			1,670.00	1,670.00
			Total	S\$ 6,040.87
			Add GST @ 7%	422.86
			Total Amount Payable	S\$ 6,463.73

LIK Auto Consultants hereby notify the Repaker of the following:
• To resurvey before repainting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No dispute/contestation is allowed
• Supplementary items must be removed and is subject to final approval from Insurance Company
Acknowledged by Repaker:
Signature:
Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

Enquire Vehicle & Owner Information (Vehicle No. SGN8754Z As At 22 Aug 2019 / 16:35:00)**Law Firm Search Details**

Search Reason: Insurance claim in relation to traffic accident

Law Firm Case No.: CHM-GBD6483

Current Owner Details

Owner ID Type: Singapore NRIC

Owner ID: S0165495J

Owner Name: TAN KIN SENG

Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes

Registered Block/House No.: 32

Registered Street Name: WOODLANDS CRESCENT

Registered Unit No.: # 06 - 06

Registered Building Name: -


Registered Postal Code: 738087

Current Vehicle Details

Vehicle No.: SGN8754Z

Make Description/Model: MAZDA / MAZDA3SP LUX

Insurance Company Name: AXA INSURANCE PTE LTD


























Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 27/12/2019

Survey Details:

Date of loss	22-Aug-19
Date of appointment	27-Aug-19
Date of survey	21-Sep-19
Location of survey	CHENG HOE MOTOR PL

Vehicle Details:

Claim Type:	Third party
Vehicle number	GBD 6483E
Make and Model	NISSAN CABSTAR 3.0
Date of registration	11/2/2015
Excess	
Market Value	\$33,000
Parf Rebate	\$22,618
Nett Loss	\$10,382

Repair details:

Initial Estimate	\$ 6,040.87
------------------	-------------

Proposed/Revised repair cost:

Parts	\$ 3,871.64
Check items (estimate)	\$ -
Labour	\$ 1,470.00
Total	\$ 5,341.64
Lump Sum(if applicable)	\$ 4,200.00
Number of days for repair	5



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

CONFLICTING VERSION. NO EVIDENCE FROM BOTH PARTIES

Mandate:

Liability(TP)	50%	
Proposed repair cost	\$ 2,247.00	W/GST
Loss of use	\$ 150.00	5days x \$60
Loss of rental	\$ -	
Loss of income	\$ -	
LTA search fees	\$ 8.00	
Others	\$ -	
Proposed Total	\$ 2,405.00	



<MANDATE IA> - S9M01Y4X {ACCIDENT INVOLVING SGN 8754X & GBD 6483E ON 22/08/2019}

Type

🔔 Question

Message

LIABILITY: 50% CONFLICTING VERSION, BOTH PARTIES GOT NO EVIDENCE. - INFORMED OI ABOUT TP CLAIM AND NCD ISSUE. AGREED TO SETTLE AT BEST. WE SEEK YOUR MANDATE AT \$2405.00 (CLAIMING LOU). MANDATE IA HAS BEEN UPLOADED IN SMARTCLAIM. KINDLY LET US HAVE YOUR APPROVAL/INSTRUCTION. THANKS - CCL 27/12/2019

Reply



Service Request Details

Claim

S9M01Y4X

Reference

None

Loss Date

August 22, 2019

Report Date

Aug 26, 2019 9:35:00 AM

Request Date

August 26, 2019

Due Date

September 2, 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

P: June

T: 10.18 AM

V: GH

E: ✓

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

GBD6483E



Model

CABSTAR 3.0 5M/T ABS 2DR 2WD EURO 5

Service Address

...

Primary Contact/Insured

TAN KIN SENG

32 WOODLAND CRESCENT #06-06, NORTHOAKS, 738087, Singapore

96378910

Claim Handler

OH Vale

6568804897

vale.oh@axa.com.sg

Additional Instructions

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

[New Message](#)

Catherine Chong (LKK Auto)

From: Cheng Hoe Motor Pte Ltd (Yishun-June) <chmotor@singnet.com.sg>
Sent: Saturday, 24 August, 2019 4:49 PM
To: SG AXA Insurance SM AXA SGP - Motor Survey
Subject: [EXTERNAL] Repair Survey (Single Joint Expert) - GBD6483E, doa 22/8/19 (Yr insured SGN8754Z)
Attachments: 6483pdf.pdf
Categories: Mateen

Dear Sir,

OUR CLIENT – GBD6483E

D

ATE OF ACC : 22.8.19 @ 4.35pm

Y

R

INSURED : SGN8754Z

Kindly provide us of your surveyor listing for the selection on the survey.

Thank you.

Regards

June

Cheng Hoe Motor Pte Ltd

Tel :67556142

Fax : 67557719

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

TAX INVOICE

M/S : AXA INSURANCE (S) PTE LTD
8 SHENTON WAY
#27-02 AXA TOWER
SINGAPORE 068811

TEL: 63387288 FAX: 68804739
ATTN: Motor Claim Department

WS Ref: TP/AXA
Claim Type: Third Party
Accident Date: 22/08/2019
TP Veh Reg No: SGN8754Z

NO: CL8191460
Date: 17 Dec 2019
Policy No: Z/18/VC00/102421
Veh Reg No: GBD6483E
Make/Model: NISSAN CABSTAR 3.0
5M/T ABS 2DR 2WD EURO 5
Job No: JC1601144

Description	Quantity	List Price	PAGE:1
			Amount
To Supply all replaced parts, all necessary and agreed labour & miscellaneous charges. (As recommended by your appointed surveyor)	1 PC	SS 4,200.00	SS 4,200.00

Total	SS 4,200.00
Add GST @ 7%	294.00
Total Amount payable	SS 4,494.00

For Cheng Hoe Motor Pte Ltd



E. & O. E.

AUTHORISED SIGNATURE



Re:RE: Re:RE: Re:SEEK INSTRUCTION - BOTH PARTIES GOT NO AVF

Type

🔗 Question

Message

Hi Pls proceed as per IA @ 50%-VO

Reply



CHENG HOE MOTOR PTE LTD

Blk 1019, Yishun Industrial Park A, #01-374/382, Singapore 768761
Tel : 67556142 Fax : 67557719
Email: chmotor@singnet.com.sg

Date: 26 DEC 2019

AXA Insurance (S) Pte Ltd
C/O LKK Auto Consultants

Attn : THE MOTOR CLAIMS DEPT

Dear Sir / Madam

**ACCIDENT INVOLVING VEHICLE NO. GBD6483E & SGN8754Z ON 22/08/2019
JUNCTION OF WLDS IND PK E4 & E5.**

We are authorized by GBD6483E for their above matter.

Record reveals that you are the insurer of SGN8754Z. We therefore wish to seek compensation from you as below:-

1. Cost of Repairs	S\$ 4494.00
2. Loss of Use	S\$ 300.00
3. Hire of Vehicle	S\$ 0.00
4. LTA Search Fee/GIA Reports	S\$ 8.00
TOTAL	S\$ 4802.00

Please let us have your reply soonest possible.

Thank you.

Yours faithfully

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD		Ref : CC4/ASM19015098/Kga3q2		
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:VALE OH		Date : 05-03-2020 Code : ASM		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SGN 8754Z	Veh. Inspected	GBD 6483E	
Policy No.	GA279723/1	Coverage (\$)	0.00	
Claim No.	S9M01Y4X	Excess (\$)	0.00	
Assign From		Assign Date	27/08/2019	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN CABSTAR	c.c	2953	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	JN1SC2F24Z0856901	Colour	WHITE	
Odometer	221283	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15X8	CONDOR	6 mm	
L/H Front Tyre	195 R15X8	CONDOR	6 mm	
R/H Rear Tyre	155 R13X8 (D)	CONDOR	6/6 mm	
L/H Rear Tyre	155 R13X8 (D)	CONDOR	6/6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	22/08/2019	Inspection Date	21/09/2019	
Survey held at	CHENG HOE MOTOR PL BLK 1019 YISHUN IND. PARK A #01-374/382 SINGAPORE 768761			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBD 6483E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER (N) (CONSISTENT)	BUCKLED	1,155.10	1,155.10
1	FRONT BUMPER RH BRACKET (N) (CONSISTENT)	TO REPAIR SEE LABOUR	283.10	-
6	FRONT BUMPER CLIPS @\$3.50 (N) (CONSISTENT)	NECESSARY	21.00	21.00
1	FRONT GRILLE (N) (CONSISTENT)	MTG CRACKED	461.90	461.90
6	FRONT GRILLE CLIPS @\$5.00 (N) (CONSISTENT)	NECESSARY	30.00	30.00
1	RH HEADLAMP (N) (CONSISTENT)	MTG CRACKED	473.40	473.40
1	RH HEADLAMP LOWER GARNISH (N) (CONSISTENT)	CRACKED	81.30	81.30
1	FRONT RH CORNAL PANEL (N) (CONSISTENT)	BENT	398.00	398.00
1	FRONT RH DOOR (N) (CONSISTENT)	BENT	1,474.80	1,474.80
1	FRONT RH DOOR LAMP (N) (CONSISTENT)	BUCKLED	109.80	109.80
1	FRONT RH DOOR BOTTOM HINGE (N) (CONSISTENT)	TO REPAIR SEE LABOUR	99.80	-
1	FRONT PANEL EMBLEM 'CABSTAR' (N) (CONSISTENT)	NECESSARY	74.30	74.30
1	FRONT RH SIDE MIRROR (N) (CONSISTENT)	SERVICEABLE	171.80	-
	LESS 10% DISCOUNT		-483.43	-427.96
			4,350.87	3,851.64
SPECIAL NETT ITEMS				
1	FRONT RH DOOR COY STICKER (SN) (CONSISTENT)	NECESSARY	20.00	20.00
			20.00	20.00
LABOUR				
	REMOVE & REFIX FRT BUMPER ASSY ,GRILLE ,HEADLAMPS ,FRT RH CORNAL PANEL ,FRT RH DOOR & ATTACHMENT ,TO STRAIGHTEN ,KNOCK & REPAIR FRT RH W/SCREEN PILLAR & REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF FRONT BUMPER RH BRACKET AND FRONT RH DOOR BOTTOM HINGE .		700.00	600.00
	REMOVE & REFIX FRT RH DOOR GLASS ,CHECK CENTRAL LOCKING & POWER MIRROR .		60.00	60.00
	PUTTY & RESPRAY PAINT ON FRT BUMPER BRACKET ,FRT RH DOOR ,FRT RH W/SCREEN PILLAR ,FRT RH CORNAL PANEL ,FRT PANEL & ALL AFFECTED AREAS.		700.00	600.00

Report Ref No. CC4/ASM19015098/Kga3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	RUSTPROOFING.		30.00	30.00
	TO REWRITE ADVERTISEMENT .		180.00	180.00
			1,670.00	1,470.00
GRAND TOTAL			6,040.87	5,341.64
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,200.00

Report Ref No. CC4/ASM19015098/Kga3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

Service Request Details

Claim	S9MA01V4X
Reference	CCA/ASM19015098/Kga3q2
Loss Date	22 August 2019
Report Date	26 Aug 2019 9:35:00 AM
Request Date	26 August 2019
Due Date	

Vendor Name	LKX AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Services	Pending verification - Direct Settlement

Actions

Next Step

Wait for Approve Invoice

Add Invoice

Vehicle Information	
Incident Vehicle Registration #	CB06483E
Make	TPVO NISSAN
Model	CARSTAR 3.0 SM/T ABS 2DR 2WD EURO S
Service Address	
...	
Primary Contact/Insured	
TAN KIN SENG 32 WOODLAND CRESCENT #06-06, NORTHDAKS, 738087, Singapore 96378910	

Claim Handler	
OH Yale 6568804897 yale.oh@axa.com.sg	

Additional Instructions

Messages Invoices History Documents Assessment Metrics Notes

Document Type

Document SubType

+ Upload Documents

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
------	------	----------	--------	------------------

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 LKKInvoice1 (6).pdf	Invoice	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	19 March 2020
 LTA SEARCH.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	19 March 2020
 LKKInspection (2).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	19 March 2020
 LKKAdjustment1a (2).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	19 March 2020
 PAYMENT BREAKDOWN EXPRESS SETTLEMENT FORM.pdf	Forms / Claim Documents	Satisfaction / Discharge Voucher	LKK AUTO CONSULTANTS PTE LTD (TP)	19 March 2020
 AUTHORIZATION TO ACT FORM.pdf	Forms / Claim Documents	POA / Authority Letter	LKK AUTO CONSULTANTS PTE LTD (TP)	19 March 2020
 LETTER TO OI.pdf	Letters and Correspondence	Policy Holders / Insured	LKK AUTO CONSULTANTS PTE LTD (TP)	19 March 2020
 TP FINAL EST LIST.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	27 December 2019
 MANDATE IA DO 27122019.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	27 December 2019
 IA.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	27 December 2019
 LKK RESURVEY PHOTO 2.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	27 December 2019
 LKK SURVEY PHOTO.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	27 December 2019
 LOD AND OTHER DOCUMENTS.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	27 December 2019
 PAUF COE REBATE.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	27 December 2019

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPDATED
 LKX RESURVEY PHOTO.pdf	Reports & Statement	Others	LKX AUTO CONSULTANTS PTE LTD (TP)	27 December 2019
 LA.pdf	Reports & Statement	Others	LKX AUTO CONSULTANTS PTE LTD (TP)	12 November 2019
 SGH 8754X GOOGLE MAP.jpg	Evidence	Others	LKX AUTO CONSULTANTS PTE LTD (TP)	9 October 2019
 SURVEY LIST SEND TO WORKSHOP.mig	Letters and Correspondence	Workshop	KADRI Mateen	26 August 2019
 GIA REPORT OF SGH8754Z (INSGU).PDF	Reports & Statement	GIA Report	KADRI Mateen	26 August 2019
 GIA REPORT OF GIBDA83E (TP).PDF	Reports & Statement	GIA Report	KADRI Mateen	26 August 2019
 EMAIL FROM WORKSHOP (THIRD PARTY PNL).mig	Letters and Correspondence	Workshop	KADRI Mateen	26 August 2019
 EMAIL.mig	Letters and Correspondence	Workshop	KADRI Mateen	26 August 2019