



Your Ref: 19.26222 PD-O

Date: 18th September 2019

Our Ref: CS1/LAW19015112/Eyd3s2

M/s AXA Insurance Pte Ltd
c/o Seah Ong & Partners LLP
36 Robinson Road
#12-03 City House
Singapore 068877

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SJS 6237B
INSURED VEHICLE: SBR 567M ACCIDENT DATE: 23/11/2018

We thank you for your instruction on 25/08/2019.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SJS 6237B from M/s Constant Appraiser Services.
- b) Final Repair Bill of SJS 6237B from M/s Toh Painting & Services Pte Ltd.
- c) Singapore Accident Statement of Vehicles SJS 6237B and SBR 567M.
- d) Damaged vehicle photographs of SJS 6237B.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SJS 6237B
Make & Model	: Mazda 2
Year of Registration	: 2009
Chassis Number	: JM0DE10Y190134358
Engine Capacity	: 1498 cc

2. We recommend that the repairs of the entire damage require about 5 (Five) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.