

ASS. REC. BY:

REF: CS/MSG19015132/Hsf302

Special Instruction:

Survivor: Hock An

ASSIGNMENT (Office)

Merimen

From (Person): Pauline Tham of MSG Date/Time: 27/08/2019

Estimated Cost: Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No: SKW 3225Y Insured: SLA 4360

at Workshop m/s Auto Bullox Pte Ltd Tel: 97699299

of 53 Ubi Ave 2 #01-19

Policy No: 1000890591 Claim No: 230696

Sum Insured: Excess:

Make of Veh: D.O.A. 23/08/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

"up"

H.O.D. Endorsement:

Date/Time: 27/08/2019 04:40pm Person Contacted: Kaman Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SLA 4360: NA/DA218001240/114 D.O.A: 19/01/2018
	SKW 3225Y: X
22/08/19	@ 14:46 pm revised PA to Pauline Tham Via email.

H-Ann

REF: MS19

ASSIGNMENT

From: Date: 28.8.2019

Estimated Cost:

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKW 3225Y

at Workshop m/s Auto Bullox

of 53 ubi Ave 1 #01-19

Insured

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S
X	X

Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SKW 3225Y Yr Regn: 29/09/2015

Type: (M.Car) / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: H-veze / 115X AT cc 1496

Colour: white A/C: Insured / Std / NI / NA

Sp. Reading: 42649 km T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: RU 11100782

Gen. Cond: Good / (Fair) / Poor / Burnt

Steering: (Inorder) / Jammed / Leaked / Burnt or

Brake: (Inorder) / Jammed / Leaked / Burnt or

Modi: Nil / (S/Rim) / STD A/Rim or

Tyre Size: F: 215/60R16

R: 215/60R16

BS: (DUN) / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Fit and for sun band

Front

Rear

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. 5 mm L/Bal. 5 mm

D.O.A. 23/08/2019 D.O.I. 28/8/19

Survey held at Auto Bullox pte ltd

Des. of Damages: Frt / (Rear) / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 09 SEP 2019

* This case have Extinction #

MV - 52200

PV - 40427

NV - 11700

MV - 51-52

* This case workshop agree by Elma / Kanan
Total L/S amount \$4350
to Finished #

29/8

Date/Time, File Pass to?

09/09/19

1) Typist

Date/Time, File Return to?

2)

☐ : Preli. Report☒ : Final Report

Days Of Repair: 6

Resurvey No. of Trip: 2

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee: 200

Transportation

) S + RS, SI

) Photos

) Officers

TOTAL

Report Format :

Lump Sum / I.B.I. (\$) 4,350/- L/S

211

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	26 Aug 2019 16:23		27 Aug 2019 16:01 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	ONG I LING (WANG AILING), ID: S7633403Z, Tel: +6590301595, Email: IL_ONG@YAHOO.COM.SG								
Main Claimant:	LIM PEI SHAN, ID: S80411211								
Vehicle Reg. No.:	SKW3225Y	Date of Loss:	23/08/2019 23:00 - :59 [42 Months and 4 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 230696	Policy/Cover Note No.:	1000890591 (Comprehensive) Coverage: 19/02/2019 - 18/02/2020						
Vehicle Reg. No. (Insured):	SLA436D	Policy No. (Claimant):	D18MTPV01015732						
		Excess:	S\$0.00						
Repairer:	Auto Bullox Pte Ltd (HQ) 53 UBI AVE 1, #01-19 PAYA UBI INDUSTRIAL PARK, 408934 Ubi - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Pauline Tham - 6594 2545]								
Claimant's Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 28/08/2019]								
Driver/Custodian (Insured):	ONG I LING (WANG AILING) (42 / Female) , NRIC: S7633403Z, Tel: +6590301595 Email: IL_ONG@YAHOO.COM.SG								
Adj Asg. Remarks:	on WP. Llab: clear choose LKK.								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
There are no mail for this case.									
ALL ASSOCIATED TASKS									
View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 121I

Vehicle Details

Vehicle No.: SKW3225Y
Vehicle to be Exported: No
Intended Deregistration Date: 28 Aug 2019
Vehicle Make: HONDA
Vehicle Model: VEZEL 1.5X A
Primary Colour: White
Manufacturing Year: 2015
Engine No.: L15B4020780
Chassis No.: RU11100782
Maximum Power Output: 96.0 kW (128 bhp)
Open Market Value: \$18,313.00
Original Registration Date: 29 Sep 2015
First Registration Date: 29 Sep 2015
Transfer Count: 0
Actual ARF Paid: \$8,313.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 28 Sep 2025
PARF Rebate Amount: \$6,234.00

Intended COE Rebate Details

COE Expiry Date: 28 Sep 2025 ✓
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$56,209.00
COE Rebate Amount: \$34,193.00
Total Rebate Amount: \$40,427.00

The information contained herein is correct as at 28 Aug 2019

OK Balance 6 year 1 month

MV - 52200

PV - 40427

NV - 11700

MV - 5152

Depreciation: 7900 year

$7900 \div 12 = 658$ month

$47400 + 658 + 4156 = 52214$

[> Back to OneMotoring](#)

Enquire Transfer Fee

Vehicle Details

Vehicle No.:	SKW3225Y
Vehicle Type:	P10 - Passenger Motor Car
Vehicle Attachment 1:	No Attachment
Vehicle Scheme:	Normal
Vehicle Make:	HONDA
Vehicle Model:	VEZEL 1.5X A
Chassis No.:	RU11100782
Propellant:	Petrol
Engine No.:	L15B4020780
Engine Capacity:	1496 cc
Maximum Power Output:	96.0 kW (128 bhp)
Maximum Laden Weight:	1465 kg
Unladen Weight:	1190 kg
Year Of Manufacture:	2015
Original Registration Date:	29 Sep 2015
Lifespan Expiry Date:	-
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
Quota Premium:	\$56,209.00
COE Expiry Date:	28 Sep 2025
Road Tax Expiry Date:	28 Sep 2019
PARF Eligibility Expiry Date:	28 Sep 2025
Inspection Due Date:	28 Sep 2020
Intended Transfer Date:	28 Aug 2019
CO2 Emission:	117.00 (g/km)
CEV/VES Rebate Utilised Amount:	\$10,000.00
CO Emission:	-
HC Emission:	-
NOx Emission:	-
PM Emission:	-

The current road tax expiry is 28 Sep 2019. You may renew the road tax from 29 Jun 2019 with all pre-requisite(s) fulfilled. If the road tax is renewed after 28 Sep 2019, late renewal fee(s) will be imposed. Please use Enquire Road Tax Payable to check on the late fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable (From 29 Sep 2019 to 28 Mar 2020)

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
Sub Total:			25.00
Nett Road Tax Amount (After Offsetting Over Payment):	341.00	-	341.00
Total Amount Payable:			366.00

Amount Payable (From 29 Sep 2019 to 28 Sep 2020)

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
Sub Total:			25.00
Nett Road Tax Amount (After Offsetting Over Payment):	682.00	-	682.00
Total Amount Payable:			707.00

You may print this page for reference.

OK

Print



Honda Vezel

Price Range

Depreciation

2016

Vehicle Type

Advanced Search

Home » Used Cars » ST Carz Pte Ltd » Honda Vezel 1.5A X

Honda Vezel 1.5A X

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

ST CARZ



Price \$67,800

Depreciation \$8,940 /yr
View models with similar depre

Reg Date 15-Aug-2016
(6yrs 11mths 16days COE left)

Mileage 43,000 km (14.2k /yr)

Manufactured 2016

Road Tax \$682 /yr

Transmission Auto

Dereg Value \$44,910 as of today (change)

OMV \$20,805

COE \$52,503

ARF \$11,127

Engine Cap 1,496 cc

Power 96.0 kW (128 bhp)

Curb Weight 1,190 kg

No. of Owners 1

Type of Vehicle SUV

Features

Powerful 1.5L I-VTEC Engine Producing 128Bhp, Earth Dream Technology, Keyless Entry/Start/Stop, CTBA, Cruise Control. View specs of the Honda Vezel

Accessories

Upholstery Leather Seats, Pioneer DVD Player With Reverse Camera/Reverse Sensors, Sport Rims, Fog Lamps, Electric Parking Brake, Auto Brake Hold, ECON

Description

Offer Interest 1.98% Only! 1 Owner Only! Low Mileage Done! Not Used For PHV Car! Most Popular SUV In The Market! 100% Accident Free! Comes With 6 Months Free Warranty! STA Evaluation Welcome! View To Believe! High And Flexible Loan Available! High Trade In For Your Used Car! Don't Wait! Call Us Now To Make An Appointment To View Now!

Category

PARF Car

Status

Available

Resources



Car Valuation - Free

Find out the market value of your existing car for free. Get started



Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. Find out more

Post Compare


Updated on: 27-Aug-2019



Location Map

Price Chart

Summary



Click on the point to view the vehicle

Shortlist

Compare

Add note

Report Error

More Actions

Seller Information

Company

ST Carz Pte Ltd

» dealer's pricelist
» 32 vehs sold | 26 vehs available

Address

210 Turf Club Road Lot B48/50
Search cars nearby this location

Location

Car Mall @ The Grandstand

Office No

64654747

Contact Person(s)

Chris Liao

83565566



Honda Vezel

Price Range

Depreciation

2015

Vehicle Type

Advanced Search

Home » Used Cars » Apex Automotive » Honda Vezel 1.5A X

Honda Vezel 1.5A X

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

Price \$57,590

Depreciation

\$8,780 /yr

View models with similar depre

Reg Date

21-Sep-2015

(6yrs 22days COE left)

Mileage

47,000 km (11.9k /yr)

Manufactured

2015

Road Tax

\$682 /yr

Transmission

Auto

Dereg Value

\$40,634 as of today (change)

OMV

\$18,719

COE

\$56,209

ARF

\$8,719

Engine Cap

1,496 cc

Power

96.0 kW (128 bhp)

Curb Weight

1,190 kg

No. of Owners

1

Type of Vehicle

SUV

Features

Multi-Function Steering Wheel, Keyless Engine Start, Auto Headlights, Rain Sensing Wipers, Electrical Retractable Side Mirrors. View specs of the Honda Vezel (2014)

Accessories

Smart Key, Front Fog Lamps, Auto Climate Control Aircon, Knockdown Rear Seats.

Description

Car Is Almost New Condition, Low Depreciation, High Loan, Bank Loan, In House Loan Are All Available Now! Trade In Are Welcome Too! Call Us Now For A Viewing!

Category

PARF Car

Status

Available

Resources



Car Valuation - Free

Find out the market value of your existing car for free. Get started



Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. Find out more

Posted on: 25-Aug-2019 | Last Updated on: 29-Aug-2019

Upfront Payment

Transfer Fee

\$25

Down Payment

\$17,277 (change)

1st Ins

\$660

To

\$17,962

(Without Insurance)

Maximum 70% Loan

Based on 2.98% interest rate


Check with seller for exact figure

Singapore Financial Info



Price Chart

Summary



Click on the point to view the vehicle

Shortlist

Compare

Add note

Report Error

More Actions

Seller Information

Company

Apex Automotive

» dealer's pricelist

» 31 vehs sold | 14 vehs available

Address

10 Buroh Street #02-20

Search cars nearby this location

Location

West Connect Building

Office No

62513972

Contact Person(s)

Dion Tan

88625982

Shawn

88694660

Tan

93547280

Dennon

97264907

Hock Ann (LKK Auto)

From: motoricarz garage <motoricarzgarage@gmail.com>
Sent: Monday, 9 September, 2019 9:35 AM
To: Hock Ann (LKK Auto)
Cc: SUR
Subject: Re: SKW 3225Y FINALIZED CALCULATE EXTIMATE

Dear Mr. Hock Ann,

We accept your offer. Please kindly proceed.

Thank you.

\$ 4350 L/ sump

6 days

Best Regards,
Elma

On Mon, Sep 9, 2019 at 8:39 AM Hock Ann (LKK Auto) <HockAnn@lkkauto.com> wrote:

Dear Kaman ,

Kindly check about last week you already refer the vehicle SKW 3225Y Honda vezel finalized calculate estimate ?

Total L/sump amount \$ 4350

COR- \$ 4350

DOR- 6 DAYS

If agree total L/sump amount and repair days ,please to updated email back asap.

Thanks.

Best Regards,

Hock Ann| Assistant Automotive Assessor

LKK Auto Consultants

Phone: 6741 3061 | Email: HockAnn@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Hock Ann (LKK Auto)

Sent: Friday, 6 September, 2019 2:52 PM

To: motoricarzgarage@gmail.com

Cc: SUR

Subject: RE: SKW 3225Y FINALIZED CALCULATE EXTIMATE

Dear kaman ,

May know your already refer the total L/sump amount \$ 4350 for vehicle SKW 3225Y HONDA VEZEL finalized calculate?

COR - \$ 4350

DOR – 6 days

If agree total L/sump amount and repair days ,please to updated soon .

Thanks.

Best Regards,

Hock Ann| Assistant Automotive Assessor

LKK Auto Consultants

Phone: 6741 3061 | Email: HockAnn@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Hock Ann (LKK Auto)

Sent: Thursday, 5 September, 2019 6:04 PM

To: motoricarzgarage@gmail.com

Cc: SUR

Subject: SKW 3225Y FINALIZED CALCULATE EXTIMATE

Hi kamen,

Kindly attached refer SKW 3225Y Honda vezel finalized calculate estimate ,

Please refer adjustment estimate calculate finalized if done , please to update soon asap .

Thanks.

Best Regards,

Hock Ann | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 6741 3061 | Email: HockAnn@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Pauline Tham

Date: 29 Aug 2019

Preliminary Advice

Insured Vehicle No	: SLA436D	Accident Date	: 23/08/2019
TP Vehicle No	: SKW3225Y	Assignment Date	: 27/08/2019
Make	: HONDA JAZZ	Est. Duration of Repair	: 6 days
Date of Inspection	: 28/08/2019		
Inspection At	: Auto Bullox Pte Ltd (HQ) 53 UBI AVE 1, #01-19 PAYA UBI INDUSTRIAL PARK Singapore 408934		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	11,355.49
Revised Amount	:S\$	6,537.86
Check Items (Estimated)	:S\$	0.00
Total	:S\$	6,537.86
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	24/08/2019 10:11
Date Of Accident	23/08/2019 23:40
Exact Location Of Accident	NICOLE HIGHWAY
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKW3225Y
Insured/Policyholder	
Name Of Registered Owner	LIM PEI SHAN
NRIC No	S8041121I
Email Address	JOEY.PS@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-97656799
Alternative Phone No	OTHERS-97656799

Vehicle Particulars

Manufacturer	HONDA
Model	VEZEL-1.5 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	D18MTPV01015732
Cover Note Number	

Driver

Name of Driver	LIM PEI SHAN
NRIC No	S8041121I
Date Of Birth	15/12/1980
Occupation	INDOOR
Date Of Driving Pass	23/03/2006
Driving Experience	13 YEARS AND 5 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-97656799
Fax Number	
Contact Number	OTHERS-97656799
EEmail Address	JOEY.PS@HOTMAIL.COM

Address	BLK 233 PAYAR LEBAR ROAD #02-01 LE CRESCENDO
Postcode	409044
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLA436D (Honda Jazz 1.5 VTR)
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Accident Sketch Plan

7/30/2019

Protected By Symantec

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

① Centre Lane of Nicoll Highway - many vehicles
Stopped due to road works at the first left lane.
SEW3225Y Stopped for at least 3-5 secs and
SLA4360 didn't stop in time to hit right @
the back of SEW3225Y.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: 24 Aug 2019
10:13

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

<https://docisolation.prod.fim.glass/?guid=414f273b-c9ae-4984-b888-b7006fbf9c60>

Common Statement

7/30/2019

Protected By Symantec

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow Insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the Insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) Investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 24 Aug 2019
10-10 am

Driver's Signature


(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Driving License



AUTO BULLOX PTE LTD

53 Ubi Avenue 1#01-19 Paya Ubi Industrial Park Singapore 408934
Tel: 6844 4290 Fax: 6841 6043 Email: carzgarage@gmail.com

Kaman Koh: 9769 9299

Register No.: 53188526K

Estimate

Vehicle: SKW3225Y

Make & Model: HONDA VEZEL

No	Particular	Qty	Amount
	<u>List Price</u>		
1	Rear boot ✓ BT	1 pc	1,053.30
2	Rear boot Logo ganish X SVC	1 pc	218.70
3	Rear windscreen moulding ✓ REC	1 pc	133.87
4	Rear 'HONDA' logo ✓ REC	1 pc	59.70
5	Rear 'VEZEL' wording ✓ REC	1 pc	60.61
6	Rear boot inner trim board ✓ -photo CRU	1 pc	277.97
7	Rear boot absorber @ \$130.50 X SVC	2 pcs	261.00
8	Rear end panel ✓ -photo BT	1 pc	583.99
9	Rear end panel garnish ✓ CRA	1 pc	116.49
10	Rear bumper ✓ DD	1 pc	608.50
11	Rear bumper reflector @ \$111.32 X SVC	2 pcs	222.64
12	Rear bumper retainer @ \$27.28 ✓ REC	2 pcs	54.56
13	Rear boot tail lamp @ \$340 ✓ CRA R/HV ✓ CRA	2 pcs	680.00
14	Rear bumper end corner @ 214.72 ✓ HX SVC R/H → R SVC X	2 pcs	429.44
15	Rear tail lamp @ \$718.08 ✓ HX SVC R/HV ✓ CRA	12 pcs	1,436.16
16	Rear boot weather strip ✓ CRU	1 pc	149.16
17	Rear undercarriage ganish ✓ CRU	1 pc	250.80
18	Rear spare tyres tank R X SVC	1 pc	662.20
19	Rear bonnet lock ✓ JM	1 pc	173.20
20	Rear compartment central board ✓ DIS	1 pc	267.10
21	Rear boot inner trim board X SVC	1 pc	277.97
22	Rear Buzzle sensor \$165 ✓ CRA		7,974.36
23	Rear tool box form \$195 ✓ LESS 20% CRA		(1,594.87)
	Sub-Total cost for parts		6,379.49
	<u>Part Replacement - Special</u>		
	<u>Nett Item</u>		
1	Tailgate outer garnish clip set (NEC)		28.00
2	Tailgate inner trim board clip set (NEC)		34.00
3	Rear bumper end clip @ \$16 set (NEC)		32.00
4	Rear end panel garnish clip set (NEC)		24.00
5	Rear undercarriage garnish clip set (NEC)		34.00

Rearers sensor 1 set 4 pcs @ 280 \$200 ✓ short

6	Rear fender inner cushion clip <i>set (nec)</i>		34.00	\$15
Sub-Total cost for parts			186.00	
Labour & MISC Charges				
1	To remove, refix rear windscreen		200.00	\$100
2	To remove, refix seat & interior trim garnish		160.00	\$40
3	To remove, refix reverse sensor/ camera		120.00	\$30
4	To vacume, waxing & cleaning interior		180.00	X
5	To check rear wiring		80.00	\$20
6	To spray undercoating		250.00	\$30
7	To spray painting accident area <i>3.5 ps</i>		1,800.00	\$700
8	Panel beating, remove, refix, cut, wilding & etc <i>→ + remove Rear Boot</i>		2,000.00	\$900
Sub-Total Labour <i>4.5 ps component labor</i>			4,790.00	
Grand Total			11,355.49	

To remove, refix rear boot assy \$80

tp case

*- without prejudice
resurvey after paint*

*- Hock Award
85311883*

- 28/8/19

- 11.50 AM

- Hock Award @ HkC.com

- L/S repair

6 Days

*[Signature]
29/8/19*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Parts = 4214.76

less 20%

3371.80

Parts = 3371.80

special
nett = 280

labour = 1820

5471.80

L/s less - 20%

4377.44

Total

L/s amount = \$4350

11927.49

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	26 Aug 2019 16:23		27 Aug 2019 16:01 Edit Adj Rpt	S\$4,350.00 Edit Estimates	S\$4,350.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS		[Created by Insurer]							
Insured:	ONG I LING (WANG AILING), ID: S7633403Z, Tel: +6590301595, Email: IL_ONG@YAHOO.COM.SG								
Main Claimant:	LIM PEI SHAN, ID: S80411211								
Vehicle Reg. No.:	SKW3225Y	Date of Loss: 23/08/2019 23:00 - :59 [46 Months and 25 Days From LTA Reg Date (Man Yr)]							
Claim Type:	TP / 230696	Policy/Cover Note No.: 1000890591 (Comprehensive) Coverage: 19/02/2019 - 18/02/2020							
Vehicle Reg. No. (Insured):	SLA436D	Policy No. (Claimant): D18MTPV01015732							
		Excess: S\$0.00							
Repairer:	Auto Bullox Pte Ltd (HQ) 53 UBI AVE 1, #01-19 PAYA UBI INDUSTRIAL PARK, 408934 Ubi - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Pauline Tham - 6594 2545]								
Claimant's Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by LEE HOCK ANN] ... [Final Rpt due 26/09/2019]								
Driver/Custodian (Insured):	ONG I LING (WANG AILING) (42 / Female), NRIC: S7633403Z, Tel: +6590301595 Email: IL_ONG@YAHOO.COM.SG								
Adj Asg. Remarks:	on WP. Liab: clear choose LKK.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									























































Claim Documents















































*SKW3225Y (230696)
[SLA436D]
TP
LIM PEI SHAN
Aug 23 2019 11:00PM
[ONG I LING (WANG AILING)]
Auto Bullox Pte Ltd


































Upload Documents | Upload Photos | Compose New Letter

View View in Browser v

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	27/08/19 13:38	Accident Statement From:OD - Reg. No: SLA436D, Claimant: Ong I Ling		Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	29/08/19 14:46	Adjuster Immediate Advice		Load HTM	
Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	04/09/19 08:39	Chassis Number		Load JPG	<input checked="" type="checkbox"/>
2	04/09/19 08:39	Odometer Reading		Load JPG	<input checked="" type="checkbox"/>
3	04/09/19 08:41	General View		Load JPG	<input checked="" type="checkbox"/>
4	04/09/19 08:41	General View		Load JPG	<input checked="" type="checkbox"/>
5	04/09/19 08:41	General View		Load JPG	<input checked="" type="checkbox"/>
6	04/09/19 08:41	General View		Load JPG	<input checked="" type="checkbox"/>
7	04/09/19 08:41	General View		Load JPG	<input checked="" type="checkbox"/>
8	04/09/19 08:41	General View		Load JPG	<input checked="" type="checkbox"/>
9	04/09/19 08:41	General View		Load JPG	<input checked="" type="checkbox"/>
10	04/09/19 08:41	General View		Load JPG	<input checked="" type="checkbox"/>
11	04/09/19 08:41	General View		Load JPG	<input checked="" type="checkbox"/>
12	04/09/19 08:41	General View		Load JPG	<input checked="" type="checkbox"/>
13	04/09/19 08:41	General View		Load JPG	<input checked="" type="checkbox"/>
14	04/09/19 08:41	General View		Load JPG	<input checked="" type="checkbox"/>
15	04/09/19 08:41	General View		Load JPG	<input checked="" type="checkbox"/>
16	04/09/19 08:42	General View		Load JPG	<input checked="" type="checkbox"/>
17	04/09/19 08:42	General View		Load JPG	<input checked="" type="checkbox"/>
18	04/09/19 08:42	General View		Load JPG	<input checked="" type="checkbox"/>
19	04/09/19 08:42	General View		Load JPG	<input checked="" type="checkbox"/>
20	04/09/19 08:42	General View		Load JPG	<input checked="" type="checkbox"/>
21	04/09/19 08:42	General View		Load JPG	<input checked="" type="checkbox"/>
22	04/09/19 08:42	General View		Load JPG	<input checked="" type="checkbox"/>
23	04/09/19 08:42	General View		Load JPG	<input checked="" type="checkbox"/>
24	04/09/19 08:42	General View		Load JPG	<input checked="" type="checkbox"/>
25	04/09/19 08:42	General View		Load JPG	<input checked="" type="checkbox"/>
26	04/09/19 08:42	General View		Load JPG	<input checked="" type="checkbox"/>
27	04/09/19 08:42	General View		Load JPG	<input checked="" type="checkbox"/>
28	04/09/19 08:42	General View		Load JPG	<input checked="" type="checkbox"/>
29	04/09/19 08:42	General View		Load JPG	<input checked="" type="checkbox"/>
30	04/09/19 08:42	General View		Load JPG	<input checked="" type="checkbox"/>
31	04/09/19 08:43	General View		Load JPG	<input checked="" type="checkbox"/>
32	04/09/19 08:43	General View		Load JPG	<input checked="" type="checkbox"/>
33	04/09/19 08:43	General View		Load JPG	<input checked="" type="checkbox"/>
34	04/09/19 08:43	General View		Load JPG	<input checked="" type="checkbox"/>
35	04/09/19 08:43	General View		Load JPG	<input checked="" type="checkbox"/>
36	04/09/19 08:43	General View		Load JPG	<input checked="" type="checkbox"/>
37	04/09/19 08:43	General View		Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
38	04/09/19 08:43	General View	 Load JPG	<input checked="" type="checkbox"/>
39	04/09/19 08:43	General View	 Load JPG	<input checked="" type="checkbox"/>
40	04/09/19 08:43	General View	 Load JPG	<input checked="" type="checkbox"/>
41	04/09/19 08:43	General View	 Load JPG	<input checked="" type="checkbox"/>
42	04/09/19 08:43	General View	 Load JPG	<input checked="" type="checkbox"/>
43	04/09/19 08:43	General View	 Load JPG	<input checked="" type="checkbox"/>
44	04/09/19 08:43	General View	 Load JPG	<input checked="" type="checkbox"/>
45	04/09/19 08:43	General View	 Load JPG	<input checked="" type="checkbox"/>
46	04/09/19 08:43	General View	 Load JPG	<input checked="" type="checkbox"/>
47	04/09/19 08:45	General View	 Load JPG	<input checked="" type="checkbox"/>
48	04/09/19 08:45	General View	 Load JPG	<input checked="" type="checkbox"/>
49	04/09/19 08:45	General View	 Load JPG	<input checked="" type="checkbox"/>
50	04/09/19 08:45	General View	 Load JPG	<input checked="" type="checkbox"/>
51	04/09/19 08:45	General View	 Load JPG	<input checked="" type="checkbox"/>
52	04/09/19 08:45	General View	 Load JPG	<input checked="" type="checkbox"/>
53	04/09/19 08:45	General View	 Load JPG	<input checked="" type="checkbox"/>
54	04/09/19 08:45	General View	 Load JPG	<input checked="" type="checkbox"/>
55	04/09/19 08:46	General View	 Load JPG	<input checked="" type="checkbox"/>
56	04/09/19 08:46	General View	 Load JPG	<input checked="" type="checkbox"/>
57	04/09/19 08:46	General View	 Load JPG	<input checked="" type="checkbox"/>
58	04/09/19 08:46	General View	 Load JPG	<input checked="" type="checkbox"/>
59	04/09/19 08:46	General View	 Load JPG	<input checked="" type="checkbox"/>
60	04/09/19 08:46	General View	 Load JPG	<input checked="" type="checkbox"/>
61	04/09/19 08:46	General View	 Load JPG	<input checked="" type="checkbox"/>
62	04/09/19 08:46	General View	 Load JPG	<input checked="" type="checkbox"/>
63	04/09/19 08:48	General View	 Load JPG	<input checked="" type="checkbox"/>
64	04/09/19 08:48	General View	 Load JPG	<input checked="" type="checkbox"/>
65	04/09/19 08:48	General View	 Load JPG	<input checked="" type="checkbox"/>
66	04/09/19 08:48	General View	 Load JPG	<input checked="" type="checkbox"/>
67	04/09/19 08:48	General View	 Load JPG	<input checked="" type="checkbox"/>
68	04/09/19 08:48	General View	 Load JPG	<input checked="" type="checkbox"/>
69	04/09/19 08:48	General View	 Load JPG	<input checked="" type="checkbox"/>
70	04/09/19 08:48	General View	 Load JPG	<input checked="" type="checkbox"/>
71	04/09/19 08:48	General View	 Load JPG	<input checked="" type="checkbox"/>
72	04/09/19 08:48	General View	 Load JPG	<input checked="" type="checkbox"/>
73	04/09/19 08:48	General View	 Load JPG	<input checked="" type="checkbox"/>
74	04/09/19 08:48	General View	 Load JPG	<input checked="" type="checkbox"/>
75	04/09/19 08:48	General View	 Load JPG	<input checked="" type="checkbox"/>
76	04/09/19 08:48	General View	 Load JPG	<input checked="" type="checkbox"/>
77	04/09/19 08:48	General View	 Load JPG	<input checked="" type="checkbox"/>
78	04/09/19 08:48	General View	 Load JPG	<input checked="" type="checkbox"/>
79	04/09/19 08:48	General View	 Load JPG	<input checked="" type="checkbox"/>
80	04/09/19 08:48	General View	 Load JPG	<input checked="" type="checkbox"/>
81	04/09/19 08:48	General View	 Load JPG	<input checked="" type="checkbox"/>
82	04/09/19 08:48	General View	 Load JPG	<input checked="" type="checkbox"/>
83	04/09/19 08:48	General View	 Load JPG	<input checked="" type="checkbox"/>
84	04/09/19 08:48	General View	 Load JPG	<input checked="" type="checkbox"/>
85	04/09/19 08:48	General View	 Load JPG	<input checked="" type="checkbox"/>
86	04/09/19 08:48	General View	 Load JPG	<input checked="" type="checkbox"/>
87	04/09/19 08:49	General View	 Load JPG	<input checked="" type="checkbox"/>
88	04/09/19 08:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
89	04/09/19 08:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
90	04/09/19 08:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
91	04/09/19 08:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
92	04/09/19 08:50	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
93	04/09/19 08:50	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
94	04/09/19 08:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
95	04/09/19 08:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
96	04/09/19 08:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
97	04/09/19 08:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
98	04/09/19 08:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
99	04/09/19 08:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
100	04/09/19 08:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
101	04/09/19 08:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
102	04/09/19 08:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
103	04/09/19 08:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
104	04/09/19 08:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
105	04/09/19 08:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
106	04/09/19 08:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
107	04/09/19 08:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
108	04/09/19 08:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
109	04/09/19 08:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
110	04/09/19 08:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
111	04/09/19 08:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
112	04/09/19 08:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
113	04/09/19 08:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
114	04/09/19 08:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
115	04/09/19 08:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
116	04/09/19 08:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
117	04/09/19 08:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
118	04/09/19 08:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
119	04/09/19 08:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
120	04/09/19 08:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
121	04/09/19 08:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
122	04/09/19 08:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
123	04/09/19 08:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
124	04/09/19 08:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
125	04/09/19 08:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
126	04/09/19 08:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
127	04/09/19 08:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
128	04/09/19 08:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
129	04/09/19 08:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
130	04/09/19 08:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
131	04/09/19 08:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
132	04/09/19 08:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
133	04/09/19 08:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
134	04/09/19 08:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
135	04/09/19 08:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
136	04/09/19 08:52	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
137	04/09/19 08:52	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
138	04/09/19 08:52	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
139	04/09/19 08:52	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
140	04/09/19 08:52	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
141	04/09/19 08:52	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
142	04/09/19 08:52	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
143	04/09/19 08:52	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
144	04/09/19 08:52	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
145	04/09/19 08:52	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
146	04/09/19 08:52	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
147	04/09/19 08:52	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
148	04/09/19 08:52	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
149	04/09/19 08:52	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
150	04/09/19 08:52	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
151	04/09/19 08:52	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
152	04/09/19 08:52	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
153	04/09/19 08:52	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
154	04/09/19 08:52	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
155	04/09/19 08:52	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
156	04/09/19 08:52	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
157	04/09/19 08:52	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
158	04/09/19 08:52	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
159	04/09/19 08:52	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
160	04/09/19 08:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
161	04/09/19 08:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
162	04/09/19 08:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
163	04/09/19 08:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
164	04/09/19 08:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
165	04/09/19 08:54	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
166	04/09/19 08:54	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
167	04/09/19 08:54	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
168	04/09/19 08:54	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
169	04/09/19 08:54	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
170	04/09/19 08:54	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
171	04/09/19 08:54	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
172	04/09/19 08:54	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
173	04/09/19 08:54	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
174	04/09/19 08:54	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
175	04/09/19 08:54	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
176	04/09/19 08:54	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
177	04/09/19 08:54	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	27/08/19 13:09	Valid DL From:OD - Reg. No: SLA436D, Claimant: Ong I Ling	 Load PDF	
2	27/08/19 12:57	TP GIA report- SKW3225Y From:OD - Reg. No: SLA436D, Claimant: Ong I Ling	 Load PDF	
3	27/08/19 13:42	PRI from Auto Bullox Pte Ltd	 Load PDF	
4	27/08/19 14:13	liability cleared	 Load PDF	
5	27/08/19 14:13	email to workshop	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19015132/HQF3E2

Date: 18/09/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 1000890591

Claimant Vehicle No : SKW3225Y

Insured Vehicle No : SLA436D

Date of Loss: 23/08/2019

Nature of Claim: TP

Claim No: 230696

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKW3225Y

Make & Model: HONDA VEZEL, 1.5 X (A)

Engine No: L15B4020780

Reg. Date: 29/09/2015 (Man. Year: 2015)

Chassis No: RU11100782

Colour: White

Odometer: 42649 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16

Rear Tyre Size:

215/60 R16

Front Left Side: Dunlop 5 mm

Rear Left Side:

Dunlop 5 mm

Front Right Side: Dunlop 5 mm

Rear Right Side:

Dunlop 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,133.49	3,651.81	3,481.68	48.81
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,790.00	1,820.00	2,970.00	62.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,923.49	5,471.81	6,451.68	54.11
Approved Total (Overridden) (S\$)		4,350.00		
Nett Amount (S\$)	11,923.49	4,350.00	7,573.49	63.52

INSPECTION

Date of Assignment: 27/08/2019

Date Inspected: 28/08/2019 Inspected At:

Auto Bullox Pte Ltd (HQ)
53 UBI AVE 1, #01-19 PAYA UBI
INDUSTRIAL PARK
Singapore 408934

Estimated Period of Repair: 6.0 days

Adjuster: LEE HOCK ANN

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 18 Sep 2019)
Parts:	M1-SUV	HONDA VEZEL 1.5 X (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKW3225Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT	Bent	1,053.30 FL	*953.30 FL
2	1		*REAR BOOT LOGO GARNISH	Serviceable	215.70 FL	*- FL
3	1		*REAR WINDSCREEN MOULDING	Necessary	133.87 FL	*85.00 FL
4	1		*REAR HONDA LOGO	Necessary	59.70 FL	*59.70 FL
5	1		*REAR VEZEL WORDING	Necessary	60.61 FL	*60.61 FL
6	1		*REAR BOOT INNER TRIM BOARD	Crushed	277.97 FL	*225.00 FL
7	2		*REAR BOOT ABSORBER	Serviceable	261.00 FL	*- FL
8	1		*REAR END PANEL	Bent	583.99 FL	*470.00 FL
9	1		*REAR END PANEL GARNISH	Cracked	116.49 FL	*116.49 FL
10	1		*REAR BUMPER	Dented	608.50 FL	*321.40 FL
11	2		*REAR BUMPER REFLECTOR	Serviceable	222.64 FL	*- FL
12	2		*REAR BUMPER RETAINER	Necessary	54.56 FL	*54.56 FL
13	2		*REAR BOOT TAIL LAMP	Cracked	680.00 FL	*580.00 FL
14	2		*REAR BUMPER END CORNER	Serviceable	429.44 FL	*- FL
15	1		*REAR TAIL LAMP	N/S Serviceable / O/S Cracked	1,436.16 FL	*428.70 FL
16	1		*REAR BOOT WEATHER STRIP	Crushed	149.16 FL	*96.80 FL
17	1		*REAR UNDERCARRIAGE GARNISH	Crushed	250.80 FL	*200.00 FL
18	1		*REAR SPARE TYRES TANK	Serviceable	662.20 FL	*- FL
19	1		*REAR BONNET LOCK	Jammed	173.20 FL	*173.20 FL
20	1		*REAR COMPARTMENT CENTRAL BOARD	Distorted	267.10 FL	*185.00 FL
21	1		*REAR BOOT INNER TRIM BOARD	Serviceable	277.97 FL	*- FL
22	1		*REAR BUZZLE SENSOR	Cracked	165.00 FL	*85.00 FL
23	1		*REAR TOOL BOX FORM	Cracked	195.00 FL	*120.00 FL
24	1		*SET TAILGATE OUTER GARNISH CLIP	Necessary	28.00 FS	*15.00 FS
25	1		*SET TAILGATE INNER TRIM BOARD CLIP	Necessary	34.00 FS	*15.00 FS
26	1		*SET REAR BUMPER END CLIP	Necessary	32.00 FS	*10.00 FS
27	1		*SET REAR END PANEL GARNISH CLIP	Necessary	24.00 FS	*10.00 FS
28	1		*SET REAR UNDERCARRIAGE GARNISH CLIP	Necessary	34.00 FS	*15.00 FS
29	1		*SET REVERSE SENSOR (4PCS)	Shorted	280.00 FS	*200.00 FS
30	1		*SET REAR FENDER INNER CUSION CLIP	Necessary	34.00 FS	*15.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,800.36	4,494.76
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,666.87	842.95
Total Parts (\$\$)	7,133.49	3,651.81

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, REFIX REAR WINDSCREEN	New	200.00	100.00
2	TO REMOVE, REFIX SEAT & INTERIOR TRIM GARNISH	New	160.00	40.00
3	TO REMOVE, REFIX REVERSE SENSOR / CAMERA	New	120.00	30.00
4	TO VACUUM, WAXING & CLEANING INTERIOR	New	180.00	0.00
5	TO CHECK REAR WIRING	New	80.00	20.00
6	TO SPRAY UNDERCOATING	New	250.00	30.00
7	TO SPRAY PAINTING ACCIDENT AREA	New	1,800.00	700.00
8	PANEL BEATING, REMOVE, REFIX, CUT, WILDING & ETC	New	2,000.00	900.00
Gross Labour Cost (S\$)			4,790.00	1,820.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >