



SERVICE REQUESTS

MESSAGES

CLAIMS



Service Request Details

Claim	S9M01Y9L
Reference	CS/ASM19015164/Eqd3e2 
Loss Date	23 August 2019
Report Date	26 Aug 2019 9:25:55 AM
Request Date	27 August 2019
Due Date	
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (OD)
Type of Loss	Own Damage
Services	Accelerated survey and authorize

Actions

Next Step Wait for: Approve
invoice

Add Invoice

Insured

TAN HUI SEE
3 FLORA DRIVE, #01-16 DAHLIA PARK
CONDOMINIUM, 507010, Singapore

CS@DAGLEN.COM

Vehicle Information

Incident SKM9402R
Vehicle
Registration #

Make MERCEDES

Model E250

Service Address

, , ,

Primary Contact

SAT MOTORS
24 Defu Lane 12, 539131, Singapore

Claim Handler

ANG Richard

richard.angbs@axa.com.sg

Additional Instructions

1) SATS Motor (Defu) 2) Excess - Nil

Messages

Invoices

History


Documents

Assessment

Metrics

Notes

Add

REFERENCE #	DESCRIPTION	TOTAL AMOUNT	SUBMITTED	STATUS	PAID DATE	WITHDRAW
AC1909773	Final Invoice	\$267.50	27/9/19 4:04 PM	Waiting for Approval		

Totals

Outstanding Invoices	\$267.50	Rejected and Withdrawn	\$0.00
Payments Made	\$0.00		
Total	\$267.50		