



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM19015185/Aga3q2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 07-08-2020



ATTN:SAW THENG

Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLS 7237X	Veh. Inspected	SJW 341B
Policy No.	VA1/GA422436	Coverage (\$)	0.00
Claim No.	S9M01YGY	Excess (\$)	0.00
Assign From		Assign Date	27/08/2019

2. Vehicle Particulars & Condition

Make & Model	KIA CERATO	c.c	1591
Engine No.	HIDDEN	Year of Reg.	2010
Chassis No.	KNAFW411MA5185903	Colour	GREY
Odometer	189104	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/45 R17	KUMHO	6 mm
L/H Front Tyre	215/45 R17	KUMHO	6 mm
R/H Rear Tyre	215/45 R17	KUMHO	6 mm
L/H Rear Tyre	215/45 R17	KUMHO	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	26/08/2019	Inspection Date	27/08/2019
Survey held at	96 MOTORSPORTS PTE LTD 62/64 KAKI BUKIT AVENUE 6 SINGAPORE 417893 ARK @ KB		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------