

ASS. REC. BY:

REF: CS/INC19013219/Kqf3ⁿ² Special InstructionSurveyor: Kenneth

ASSIGNMENT (Office)

28/08/2019

From (Person): Daniel Koh of INC Date/Time: 9:31am

Estimated Cost: _____ Bill to: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No: SQB3566X Insured: SJR 5894Rat Workshop n/s: Car Times Autolution Pte Ltd Tel: 64715111of 160 Sin Ming Drive #02-04Policy No: _____ Claim No: MT/1059411-002

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 29/08/2019
(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: _____

Date/Time: 10:11am @ 28/8/19 Person Contacted: Yuki Vehicle: IN OUT

Date/Time	Action/Instruction
	<u>SQB 3566X - CS/MSG/16213223/49km2</u>
	<u>SJR 5894R - X</u>
	<u>16/9 6/12y 8295ol email & confirm used \$ 6730.40, 68%.)</u>

ASS. REC. BY:

REF: INC1

ASSIGNMENT

From: _____

Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

~5 days

Res.: Yes or No

Lum Sum: _____

1.3.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Date / Time

Action / Instruction

1 File pass to

Veh No: SLB 3566XYr Regn: 07.16Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Hondac.c. 1496Colour: M. Black

A/C: _____

Insured / Std / NI / NA

Sp. Reading: 89942

T/Radio: _____

Insured / Std / NI / NA

Eng/No: _____

C/No: RU1

1117166

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: NI / S/Rim / STD / A/Rim or

Tyre Size: F: _____

R: _____

215/60R16

BS / BUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal. _____

2 mm

R/Bal. _____

3 mm

L/Bal. _____

2 mm

L/Bal. _____

3 mm

D.O.A. 29/8/19D.O.I. 28/8/19

Survey held at _____

11:50am

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

RECEIVED 21 SEP 2019

Date/Time, File Pass to?

1) 24/9 11:50

Date/Time, File Return to?

2)

☐

: Prelim. Report

☐

: Final Report

Days Of Repair: 5

Resurvey No. of Trlp: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐

: Site Insp (\$ _____)

☐

: Interview (\$ _____)

☐

: Tech Invs (\$ _____)

☐

: Weekend (\$ _____)

: Fuel (\$ _____)

: Others (\$ _____)

TOTAL

250

Report Format: _____

Lump Sum / I.B.F. (\$ _____)

TP
2950

Nivitha (LKK Auto)

From: Daniel Koh <daniel.koh@income.com.sg>
Sent: Wednesday, 28 August 2019 11:37 AM
To: 'assignments@lkkauto.com'
Cc: admin-d@lkkauto.com
Subject: FW: TP CASES FARMED OUT TO LKK ON 28/8/2019

Dear LKK,

Resend with claim numbers & OIC

From: Daniel Koh
Sent: Wednesday, 28 August 2019 9:34 AM
To: 'assignments@lkkauto.com' <assignments@lkkauto.com>
Cc: 'admin-d@lkkauto.com' <admin-d@lkkauto.com>; Teng Ken Leong <kenleong.teng@income.com.sg>; Thio Tse Kiat <tsekiat.thio@income.com.sg>
Subject: FW: TP CASES FARMED OUT TO LKK ON 28/8/2019

Dear LKK,

Please assist to survey the following vehicles as per Mr Teng's instruction :-

SN	OIC	Claim No.	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	Survey Time	OIV	DOA	Additional Remarks
1	SERENE LIM	MT/1059411-002	SGB3566X	CAR TIMES AUTOLUTION PTE LTD	160 SIN MING DRIVE #02-	Yuki Peck / 64715111		SJRS5894R	24/8/2019	

2	CHARLOTTE CHEW	MT/1059685- 001	SLX1004P	H C AUTO PTE LTD	160 SIN MING DRIVE, #05- 09 SIN MING AUTO CITY	Mr. Joe Chee / 94570678	XE4322J	26/8/2019		
3	FIONA SHEN	MT/1059662- 002	SLK5186P	KUM CHEW MOTOR WORKSHOP	160 SIN MING DRIVE, 05- 08 SIN MING AUTOCITY	Mdm Lim / 64536256	YN5036U	26/8/2019		
4	DAVID PHUA	MT/1059521- 002	SKZ1120M	LEE HONG & CO MOTOR SERVICE	BLK 9 #01- 36 SIN MING INDUSTRIAL EST SECTOR C SINGAPORE 575644	William Saw / 6458- 8460	GR1565C	24/8/2019	6552-5192	

Please contact workshops.

Please revert to officer-in-charge after survey.

Thank you.

Daniel Koh
Senior Admin Assistant
Motor Insurance
T +65 6430 7901
www.income.com.sg

income
made different



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.
Find out more at Income.com.sg/careers

in with you

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Singapore NRIC
Owner ID:	407E

Vehicle Details

Vehicle No.:	SGB3566X
Vehicle to be Exported:	No
Intended Deregistration Date:	27 Aug 2019
Vehicle Make:	HONDA
Vehicle Model:	VEZEL 1.5X CVT
Primary Colour:	Black
Manufacturing Year:	2016
Engine No.:	L15B4037134
Chassis No.:	RU11117166
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$19,968.00
Original Registration Date:	27 Jul 2016
First Registration Date:	27 Jul 2016
Transfer Count:	0
Actual ARF Paid:	\$9,968.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Jul 2026
PARF Rebate Amount:	\$7,476.00

Intended COE Rebate Details

COE Expiry Date:	26 Jul 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$55,200.00
COE Rebate Amount:	\$38,151.00
Total Rebate Amount:	\$45,627.00

The information contained herein is correct as at 27 Aug 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	26/08/2019 14:26
Date Of Accident	24/08/2019 16:55
Exact Location Of Accident	B.BATOK WEST AVE 3 TWRDS B.BATOK ST 11
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGB3566X
Insured/Policyholder	
Name Of Registered Owner	SEAH KIT SAN (XIE JIESHAN)
NRIC No	S7249407E
Email Address	JASLYN_SEAH@YAHOO.COM.SG
Mobile Phone No	(LOCAL) +65-96922992
Alternative Phone No	OTHERS-96922992

Vehicle Particulars

Manufacturer	HONDA
Model	VEZEL 1.5X CVT

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5082589870-03
Cover Note Number	

Driver

Name of Driver	SEAH KIT SAN (XIE JIESHAN)
NRIC No	S7249407E
Date Of Birth	31/12/1972
Occupation	INDOOR
Date Of Driving Pass	21/08/1995
Driving Experience	24 YEARS AND 0 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-96922992
Fax Number	
Contact Number	OTHERS-96922992
Email Address	JASLYN_SEAH@YAHOO.COM.SG

Address	BLK 142 #10-01 BUKIT BATOK STREET 11
Postcode	650142
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	BUKIT BATOK NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 21 BUKIT BATOK EAST AVE 4 , POSTCODE: 659840 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-6659999 - FAX NO: 66655793
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT ATTACHED;

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	WITH OWNER
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJR5894R
Vehicle Make/Model/Colour	TOYOTA / COROLLA ALTIS 1.6 AUTO
Details Of Properties	
Vehicle Category	PRIVATE HIRE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

IDAC KAKI BUKIT (VAC)
Reporting Centre
Name: **23 Kaki Bukit Ave 4**
Singapore 415933
Tel: 67416697 Fax: 67492305
Email: yockb@singnet.com.sg

Common Statement Pg. 1

SKETCH PLAN BUKIT BATOK WEST AVE 3 TND BUKIT BATOK ST 11



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

refer to police statement

DECLARATION

(We declare the foregoing particulars are true in every respect.)

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

IDAC KAKI BUKIT (VAC)

Reporting Centre: 23 Kaki Bukit Ave 4
Name: Singapore 415933
NRIC/Tel: 67416697 Fax: 67492305
Email: yackb@singnet.com.sg

Accident Sketch Plan

NOTICE OF REPORTING

Annex D

This is to confirm that Seah Kit San, NRIC/FIN: S7249407E has reported to the Police a traffic accident which happened on 24/08/2019 at about 1655hrs. Accident occurred along T-Junction of Bukit Batok West Ave 3 (Towards Bukit Batok Central) and Bukit Batok Street 11.

The traffic accident does not consist of the below following criteria:

- i) Involvement with foreign vehicle
- ii) Involvement with Pedestrian/Cyclist
- iii) Involving parties obtained more than 3 days of Medical Leave
- iv) Government property damage
- v) Hit and Run Accident

Involving the following vehicles:

V1) SGB3566X driven by Seah Kit San, NRIC/FIN: S7249407E, HP: 96922992.

V2) SJR5894R driven by Mui Mun Long Raymond, NRIC/FIN: S7147202G, HP: 81442713.

Brief Facts:

On 24/08/2019 at about 1655hrs, V1 was along Bukit Batok West Ave 3 wanting to turn right to Bukit Batok Street 11. V1's right signal light was on and while waiting for the traffic to clear, V2 hit onto the rear of V1. The male Chinese driver admitted his fault. We exchange details and left the location.

2 If this accident was reported to the Police within 24 hours of its occurrence, then he/she has complied with Sec 84(2) of the Road Traffic Act, Cap 276.

Rank/Name of Issuing Officer: SSS T03316 Shaniza Binte Sital

Date: 24/08/2019 Time: 1540hrs

S/D Ref: 119

Police Post/Unit: Bukit Batok NPC

BUKIT BATOK NPC
NO. 21 BUKIT BATOK WEST AVENUE
SINGAPORE 659585
TEL: 65610000

24/8/19

AUTOLUTION

CARTIMES

CarTimes Autolution Pte Ltd
160 Sin Ming Drive AutoCity
#02-04 Singapore 575722
Tel : 6471 5111
Email : claims@cartimes.com.sg

Vehicle No. 5GB3566X

Car Model : HONDA VEZEL

DESCRIPTION	REPAIRER ESTIMATE(S\$)	SURVEYORS ADJUSTMENT(S\$)
LIST ITEM		
REAR BUMPER <i>865.00</i>	<i>Bu</i> 1209.00	<i>✓</i>
REAR BUMPER REFLECTOR RHS & LHS	<i>Sn</i> 302.00	<i>X</i>
REAR BUMPER SIDE RETAINER LH & RH	<i>Sn</i> 78.00	<i>X</i>
REAR END PANEL	<i>Bu</i> 451.00	<i>✓</i>
REAR END PANEL TOP GARNISH	<i>MBN</i> 55.00	<i>✓</i>
TAILGATE	<i>Bu</i> 953.00	<i>✓</i>
TAILGATE LAMP RHS & LH	<i>Sn</i> 1160.00	<i>X</i>
REAR TAILGATE WEATHER STRIP	<i>Sn</i> 278.00	<i>X</i>
REAR WINDSCREEN MOULDING	<i>Sn</i> 175.00	<i>✓</i>
TAIL GATE INNER TRIM	<i>Sn</i> 195.00	<i>X</i>
SMART BUZZER	<i>CM</i> 95.00	<i>✓</i>
FENDER INNER RH SIDE PANEL	<i>R</i> 980.00	<i>X</i>
KEY ANTENNA	<i>CM</i> 110.00	<i>✓</i>
RHS & LHS TAILLAMP	<i>Sn</i> 1187.00	<i>X</i>
TAILGATE CENTRE GARNISH	<i>Sn</i> 450.00	<i>X</i>
"HONDA" LOGO	<i>Sn</i> 65.00	<i>X</i>
HEADLAMP PANEL RH	<i>Sn</i> 950.00	<i>X</i>
"VEZEL" WORDING	<i>Sn</i> 45.00	<i>✓</i>
	\$ 8,138.00	
	20%	
	\$ 1,627.60	
	\$ 6,510.40	
Special Nett items		
REVERSE SENSOR	<i>Shen</i> \$ 200.00	<i>✓</i>
REVERSE CAMERA	<i>Sn</i> \$ 350.00	<i>X</i>
REAR BUMPER CLIP	<i>Sn</i> \$ 30.00	<i>✓</i>
REAR TAILGATE INNER TRIM CLIP	<i>Sn</i> \$ 30.00	<i>✓</i>
REAR WINDSCREEN SEALANT	<i>Sn</i> \$ 30.00	<i>✓</i>
	\$ 640.00	
	\$ 7,150.40	

Not Authorized

Survey Repair

11/11/2020

5 days

XXX Auto Consultants hereby notify the Repairer of the following:

- To display damaged parts during survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No legal proceedings to be filed
- Survey report should not be submitted and used without the approval from insurance Company

Additional notes required

Signature

Date

Vehicle No. SGB3566X

Car Model : HONDA VEZEL

S/N	DESCRIPTION	REPAIRER'S ESTIMATE
	LABOUR	
1	To remove the affected parts & fittings to commence repairs; replace damaged parts and components	\$ 1,000.00
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	\$ 800.00
3	To remove and re-fix wiring and check all electrical components at damaged areas for proper functions	\$ 50.00
4	To remove & replace reverse camera reverse sensor check for proper function	\$ 60.00
5	To remove and refix rear windscreen	\$ 120.00
Labour Total :		\$ 2,030.00
TOTAL (PARTS & LABOUR):		\$ 9,180.40

8900.40



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC19015219/Kqf3n2

73 BRAS BASAH ROAD
#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556

Date: 24-09-2019



ATTN: SERENE LIM

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJR 5894R	Veh. Inspected	SGB 3566X
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1059411-002	Excess (\$)	0.00
Assign From	DANIEL KOH	Assign Date	28/08/2019

2. Vehicle Particulars & Condition

Make & Model	HONDA VEZEL (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	RU11117166	Colour	METALLIC BLACK
Odometer	89942 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60 R16	DUNLOP	2 mm
L/H Front Tyre	215/60 R16	DUNLOP	2 mm
R/H Rear Tyre	215/60 R16	DUNLOP	3 mm
L/H Rear Tyre	215/60 R16	DUNLOP	3 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	24/08/2019	Inspect Date / Time	28/08/2019 (11:50 AM)
Survey held at	CAR TIMES AUTOLUTION PTE LTD 13 KAKI BUKIT ROAD 4 #03-29/30 BARTLEY BIZ CENTRE SINGAPORE 417807		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGB 3566X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	BUCKLED	1,209.00	865.00
2	REAR BUMPER REFLECTOR RHS & LHS	SERVICEABLE	302.00	-
2	REAR BUMPER SIDE RETAINER LH & RH	SERVICEABLE	78.00	-
1	REAR END PANEL	BENT	451.00	451.00
1	REAR END PANEL TOP GARNISH	MTG DISTORTED	55.00	55.00
1	TAILGATE	BENT	953.00	953.00
2	TAILGATE LAMP RHS & LH	SERVICEABLE	1,160.00	-
1	REAR TAILGATE WEATHER STRIP	SERVICEABLE	278.00	-
1	REAR WINDSCREEN MOULDING	NECESSARY	175.00	175.00
1	TAIL GATE INNER TRIM	SERVICEABLE	195.00	-
1	SMART BUZZER	CRACKED	95.00	95.00
1	FENDER INNER RH SIDE PANEL	TO REPAIR SEE LABOUR	980.00	-
1	KEY ANTENNA	CRACKED	110.00	110.00
2	RHS & LHS TAILLAMP	SERVICEABLE	1,187.00	-
1	TAILGATE CENTRE GARNISH	SERVICEABLE	450.00	-
1	"HONDA" LOGO	NOT NECESSARY	65.00	-
1	"VEZEL" WORDING	NECESSARY	45.00	45.00
	LESS 20% DISCOUNT		-1,557.60	-549.80
			6,230.40	2,199.20
SPECIAL NETT ITEMS				
1	REVERSE SENSOR (SN)	SHORTED	200.00	200.00
1	REVERSE CAMERA (SN)	SERVICEABLE	350.00	-
1	REAR BUMPER CLIP (SN)	NECESSARY	30.00	30.00
1	REAR TAILGATE INNER TRIM CLIP (SN)	NECESSARY	30.00	30.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	30.00	30.00
			640.00	290.00

Report Ref No. CS/INC19015219/Kqf3n2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6258 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS;REPLACE DAMAGED PARTS AND COMPONENTS.INCLUSIVE OF THE REPAIR OF FENDER INNER RH SIDE PANEL.		1,000.00	600.00
	TO SUPPLY PAINT MATERIALS,EXPANDABLE ITEMS & PUTTY,RESPRAY PAINT ON PARTS REPLACED & REPAIRED.		800.00	450.00
	TO REMOVE AND RE-FIX WIRING AND CHECK ALL ELECTRICAL COMPONENTS AT DAMAGED AREAS FOR PROPER FUNCTIONS.		50.00	20.00
	TO REMOVE & REPLACE REVERSE CAMERA REVERSE SENSOR CHECK FOR PROPER FUNCTION.		60.00	50.00
	TO REMOVE AND REFIX REAR WINDSCREEN.		120.00	120.00
			2,030.00	1,240.00
	GRAND TOTAL		8,900.40	3,729.20
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				2,950.00

Report Ref No. CS/INC19015219/Kqf3n2

KONG SENG CHEONG

Licensed Appraiser

K.K.LAU CPT(RET)**BEng(Hons),B.Bus,MBA,PEng,PE,
MinstAEA,MASME,MIRTE****REGD Auto Consultant-SAE, Licensed Appraiser**

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.