

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Reg. No: 199607198R GST Reg. No. 19-9607198-R			
DAMAGE ASSESSMENT REPORT			
 C INCOME INSUR	RANCE CO-OPERATIVE LTD	Ref: CS/INC19015220/Gtd3s2	
RAS BASAH ROA	D	Date: 11-05-2020	
01 NTUC TRADE 56	UNION HOUSESINGAPORE		
N: DAVID PHUA		Code: INC	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GR 1565C	Veh. Inspected	SKZ 1120M
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1059521-002	Excess (\$)	0.00
Assign From	DANIEL KOH	Assign Date	28/08/2019
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA COROLLA 1.6	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2006
Chassis No.	MR053ZEC107113145	Colour	SILVER
Odometer	185970 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	185/55 R15	MICHELIN	6 mm
L/H Front Tyre	185/55 R15	MICHELIN	6 mm
R/H Rear Tyre	185/55 R15	MICHELIN	6 mm
L/H Rear Tyre	185/55 R15	MICHELIN	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	24/08/2019	Inspect Date / Time	28/08/2019 (06:00 PM)
Survey held at	LEE HONG & COMPANY MOTOR SERVICES		
	BLK 9, SIN MING ROAD, #01-36 SINGAPORE 575644.		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
	RAS BASAH ROAD 1 NTUC TRADE 156 N: DAVID PHUA Insured Veh. Policy No. Claim No. Assign From Make & Model Engine No. Chassis No. Odometer Brakes General R/H Front Tyre L/H Front Tyre R/H Rear Tyre L/H Rear Tyre THE VEHICLE SUSUNDERCARRIAGE DAMAGES SEE D Accident Date Survey held at	CINCOME INSURANCE CO-OPERATIVE LTD RAS BASAH ROAD DI NTUC TRADE UNION HOUSESINGAPORE 56 R: DAVID PHUA Policy Particulars Insured Veh. GR 1565C Policy No. Claim No. MT/1059521-002 Assign From DANIEL KOH Vehicle Particulars Make & Model TOYOTA COROLLA 1.6 Engine No. HIDDEN Chassis No. MR053ZEC107113145 Odometer 185970 KM Brakes IN ORDER General GOOD Conditive Size R/H Front Tyre 185/55 R15 L/H Front Tyre 185/55 R15 L/H Rear Tyre 185/55 R15 L/H Rear Tyre 185/55 R15 L/H Rear Tyre 185/55 R15 THE VEHICLE SUSTAINED DAMAGES AT THE N/S UNDERCARRIAGE AFFECTED DUE TO COLLISION DAMAGES SEE DETAILS. General Accident Date 24/08/2019 Survey held at LEE HONG & COMPANY MOTO BLK 9, SIN MING ROAD, #01-36 SINGAPORE 575644. Real A)THE INSPECTION WAS CONDUCTED ON A "WITT B)IN ACCORDANCE TO YOUR INSTRUCTIONS, W	DAMAGE ASSESSMENT REPORT C INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC19015220. RAS BASAH ROAD Date: 11-05-2020 Date: 11-0

7 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: