



Your Ref: 19/19/19/VC05/022034

Date: 12th Sep 2019

Our Ref: CS1/LPC19015235/Qtd3e2

M/s Lonpac Insurance Bhd

300 Beach Road

#17-04/07 The Concourse

Singapore 199555

(The Motor Claims Department)

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SLG 1790S

INSURED VEHICLE: GX 5826S

ACCIDENT DATE: 06/07/2019

We thank you for your instruction on 27/08/2019.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SLG 1790S from M/s Prominent Appraiser Services Pte Ltd.
- b) Singapore Accident Statement of Vehicles SLG 1790S and GX 5826S.
- c) Colour damaged vehicle photographs of SLG 1790S.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SLG 1790S
Make & Model	: Honda Shuttle 1.5G A
Year of Registration	: 2016
Chassis Number	: GK81003995
Engine Capacity	: 1496 cc

2. We recommend that the repairs of the entire damage require about 7 (Seven) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.