

COMFORTDELGRO ENGINEERING PTE LTD

Date: 28.08.2019

REPAIR ESTIMATE

Tokio Marine (L/S)

Time: 10:21:09

Page: 1/2

LKK - kalvin

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305328248
 REGN NO : SHD6827B
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : I-40
 DATE OF REGN : 25.09.2015
 DATE/TIME IN : 27.08.2019 16:55
 ACCIDENT DATE : 27.08.2019

Tyre : Han/Kook
 205/60R16

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-0593-G FRT DOOR LH 1 2,256.40 20.00 1,805.12 ✓

0002 28-01-0103-0003-A Frt Door COMFORTDELGRO LH 1 75.00 75.00 ✓

0003 04-01-0103-0596-G REAR DOOR LH 1 2,201.10 20.00 1,760.88 ✓

0004 28-01-0103-2013-A Rear Door APPS Sticker LH 1 80.00 80.00 ✓

SUB-TOTAL : 3,721.00

JOB NATURE

0000 20-05 Frt Door Adv.Sticker LH 100.00 ✓

0001 20-05 Rear Door Adv.Sticker LH 100.00 ✓

0002 PB PANEL BEATING ~~280.00~~ 2000003 SP SPRAYPAINT-Rocker Panel Garnish LH ~~650.00~~ 6000004 20-00 TUFF COAT ON AFFECTED PARTS. ~~80.00~~ 500005 L TRANSFER OF DOORS ~~240.00~~ 100

0006 20-05 TP MERIMEN 11.00 ✓

REPAIR ESTIMATE

Page: 2

JOB NO	:	305328248
REGN NO	:	SHD6827B
MILEAGE	:	0000000000
MAKE	:	HYUNDAI
MODEL	:	I-40
DATE OF REGN	:	25.09.2015
DATE/TIME IN	:	27.08.2019 16:55
ACCIDENT DATE	:	27.08.2019

JOB / PARTS DESCRIPTION

QTY	IND	UNIT-PRICE	DISC%	AMOUNT
-----	-----	------------	-------	--------

SUB-TOTAL : 1,461.00

TOTAL : 5,182.00

MVA NAME & SIGNATURE
DATE :

SURVEYOR NAME & SIGNATURE _____
DATE : _____

Ka / h (10k)

28/8/19 1120 L

3 days.

2/5

After Repair photo

ack photo

Below are items that must hence notify
the repair shop of the following:

- Repairs to be done after spray painting
- Repairs to damaged parts during resurvey
- Repairs must be subject to confirmation
- The repair shop is on a "Without Prejudice" basis
- No illegal modifications are allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: