

22/03/2003

ASS. REC. BY:

REF: (S3) A1G19015259/GCF3

Special Instruction:

Surveyor:

GK

ASSIGNMENT (Office)

From (Person):

chin Lee Yling

of

A1G

Date/Time:

29.8.19 12.56p.m

Estimated Cost:

Bill to:

OD TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJN 4025K

Insured:

SM L 6813P

at Workshop m/s

Black Eagle Auto

Tel:

9247 3881

of 25 Raki Bukit Road 4 #05-80

Policy No:

Claim No:

8985311120SG

Sum Insured:

Excess:

Make of Veh:

D.O.A.

28.8.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time:

29.8.19 1.45pm

Person Contacted:

Ray

H.O.D. Endorsement:

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SML 6813P: X

SJN 4025K: NS/INC 16024658/H2VBN2 D.O.A. 29/12/2016

30/08/19

@ 15:45 pm checked with Ray (repur?),
no estimate

PRS
Orl.

REF: AIG

ASSIGNMENT

From: Date: 29.8.2019

Estimated Cost:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SJN 4025K
at Workshop n/s Black Eagle Auto
of 25 Kaki Buta Road 4 #05-80

Insured

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAG Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lump Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Demolite: 30/8/2019
After repair: 3/9/2019

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 3

Resurvey No. of Trip: 2

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

Report Format : DAR

Lump Sum / I.B.I: (\$

Veh No: SJN4025K Yr Reg: Feb 09

Type: M.Gas / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai Avante 1.6 1591

Colour: white A/C: Insured / Std / NI / NA

Sp. Reading: - T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: KMHDU41BR94688666

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/65 R15

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. D.O.I. 28-08-19

Survey held at w/s

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or 4pm

The U/C / Chassis frame / Body Structure affected due to collision.

Survey Fee:

Transportation

) S + RS. 91

) Photos

) Others

TOTAL

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	29 Aug 2019 Edit Reg		29 Aug 2019 00:00 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	Lim Hui Hui (Lin Huihui), ID: S7641495E		
Main Claimant:	NA		
Vehicle Reg. No.:	SJN4025K	Date of Loss:	28/08/2019 08:00 - :59
Claim Type:	TP / 8985311120SG	Policy/Cover Note No.:	(Comprehensive)
Vehicle Reg. No. (Insured):	SML6813P	Policy No. (Claimant):	
		Excess:	
Repairer:	Black Eagles Auto Pte Ltd (HQ) 25 Kaki Bukit Road, #05-80 Synergy Building, 417800 Kaki Bukit - Tel:		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Chan, Kian-Meng] Kianmeng.Chan1@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 09/09/2019]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG_SG (30/08/2019): No OI GIA Report
- AIG_SG (30/08/2019): Request To Upload TP GIA Report

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									


PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHIC...

From: Chin, Lee-Ying

To: assignments, Admin A

Cc: Fong, Andy-SY

Sent: 8/29/2019 12:56:44 PM

Attachments:  Notification of accident.docx

Hi LKK,

Kindly assist to survey.

Thanks.

Best Regards

Lee Ying, Chin

AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1947

Lee-Ying.Chin@aig.com | www.aig.sg

P. Roy

T: 1.09 p.m

V: 1h

E: V

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.



BLACK EAGLE AUTO PTE LTD

SYNERGY@KB
25 KAKI BUKIT ROAD 4
#05-80
SINGAPORE 417800
Tel: 6951 3770
Blackeagleauto@gmail.com

Date: 28/08/2019

To: AIG Asia Pacific Insurance Pte. Ltd.
Motor Claims Department

Dear Sir/Mdm,

NOTIFICATION OF ACCIDENT

Please be informed that an accident involving my/our vehicle no. SJN4025K and vehicle(s) no. SML6813P had taken place at/along KPE towards ECP before airport road exit on date 28/08/2019 at time 0820hrs.

Kindly let us know within 2 working days from the date of this notice if you wish to carry out or waive a pre-repair inspection.

If we do not hear from you within 2 working days, we shall proceed to repair vehicle without further notice and our client shall claim for the additional loss of use arising from the giving of this notification to you.

Please call 6951 3770 / 9247 3881 to arrange.

Yours sincerely,

PRI

Date / Time	
Company Name	
Surveyor	
Contact No.	
Signature	

DISMANTLED PARTS

Date / Time	
Surveyor	

AFTER REPAIR

Date / Time	
Surveyor	

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	28/08/2019 12:05
Date Of Accident	28/08/2019 08:20
Exact Location Of Accident	KPE TUNNEL TOWARDS ECP
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJN4025K
Insured/Policyholder	
Name Of Registered Owner	BLACK EAGLE RENTAL LLP
Co Reg No	T17LL1043L
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-98711104

Vehicle Particulars

Manufacturer	HYUNDAI
Model	AVANTE-1.6 (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE HIRE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	5108075248
Cover Note Number	THIRD PARTY, FIRE & THEFT

Driver

Name of Driver	LEE HONG JIE
NRIC No	S8900615E
Date Of Birth	06/01/1989
Occupation	INDOOR
Date Of Driving Pass	19/10/2011
Driving Experience	7 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96902286
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 659A PUNGGOL EAST #05-771
Postcode	821659
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : PASSENGER GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

VEHICLE IN FRONT OF ME JAMMED BRAKE SUDDENLY AND I FOLLOWED SUIT. I MANAGED TO BRAKE IN TIME BUT VEHICLE B HIT INTO THE REAR PORTION OF MY VEHICLE.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SML6813P
Vehicle Make/Model/Colour	RED MITSUBISHI ATTRAGE
Details Of Properties	FRONT PORTION
Vehicle Category	PRIVATE CAR
Name of Driver	TAY TZE KEE ALICIA
NRIC/Passport Number	S9938959A
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

NTUC Income Motor Service Centre

Report No: MT

D.O.A.

Vehicle No:

Make : Model:

Report Date: 28/8/2019 Start Time: 12:05 PM

Reporting Type: TP End Time:

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **reudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonable required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, law or court orders.




Policyholder's Signature
Date & Time:

Driver's Signature (If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: Eric Woo Jun Kiat
NRIC/ Fin No: S992753

Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

VEHICLE IN FRONT OF ME JAMMED BRAKE SUDDENLY AND I FOLLOWED SUIT. I MANAGED TO BRAKE IN TIME BUT VEHICLE B HIT INTO THE REAR PORTION OF MY VEHICLE.

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time:

28/8/2019 12:05

Driver's Signature (if driver is not the policyholder)
Date & Time:

28/8/2019 12:05

Reporting Centre Personnel's Signature
Name: Eric Woo Jun Kiat
NRIC/ Fin No: S992753

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Limited Liability Partnership
Owner ID:	043L
Vehicle Details	
Vehicle No.:	SJN4025K
Vehicle to be Exported:	No
Intended Deregistration Date:	11 Sep 2019
Vehicle Make:	HYUNDAI
Vehicle Model:	HD AVANTE 1.6 A
Primary Colour:	White
Manufacturing Year:	2009
Engine No.:	G4FC9U595110
Chassis No.:	KMH DU41BR9U688666
Maximum Power Output:	89.7 kW (120 bhp)
Open Market Value:	\$11,635.00
Original Registration Date:	13 Feb 2009
First Registration Date:	13 Feb 2009
Transfer Count:	5
Actual ARF Paid:	\$11,635.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	12 Feb 2024
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$12,864.00
COE Rebate Amount:	\$11,370.00
Total Rebate Amount:	\$11,370.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 11 Sep 2019

OK

(01) Bent (2) Dented (3) Distorted (4) Cracked (5) Cut (6) Scratched
(07) Deformed (08) Shifted (09) Buckled (10) Broken (11) Necessary
(12) Missing (13) Torn (14) Unconfirmed (15) Not Working

MOTORCAR (Rear)

(1) Replace (✓) (2) Repair (X) (3) Check (C)
(4) Not Consistent (NC)

Rear Portion

Vehicle No: **SIN/4025K**

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	ee	✓	
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips	ee	✓	
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer	PH	ee	✓
1149	993045	Rear Bumper Reinforcement			
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge	CRA	✓	
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector			
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor			
1159	993327	Rear End Panel	Repair	X	
1160	993339	Rear End Panel Top Garnish			
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp			
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp			
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid	Repair	X	
1171	991328	Bootlid Emblem	ee	✓	
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock			
1178	990377	Bootlid Rubber			
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate			
1182	991328	Tailgate Emblem			
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board			

NAC	INC	Item	CON	AC	Qty
1202	993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel			
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe			
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim			
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993401	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1136	990247	Sticker			

No of Items: _____

Assessor: _____

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	29 Aug 2019 Edit Reg		29 Aug 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	Lim Hui Hui (Lin Huihui), ID: S7641495E		
Main Claimant:	NA		
Vehicle Reg. No.:	SJN4025K	Date of Loss:	28/08/2019 08:00 - :59 [126 Months and 15 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 8985311120SG	Policy/Cover Note No.:	(Comprehensive)
Vehicle Reg. No. (Insured):	SML6813P	Policy No. (Claimant):	
		Excess:	
Repairer:	Black Eagles Auto Pte Ltd (HQ) 25 Kaki Bukit Road, #05-80 Synergy Building, 417800 Kaki Bukit - Tel:		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Chan, Kian-Meng]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 09/09/2019]		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

- AIG_SG (30/08/2019): No OI GIA Report
- AIG_SG (30/08/2019): Request To Upload TP GIA Report

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									









































Claim Documents


































***SJN4025K (8985311120SG)**
[SML6813P]

TP

NA

Aug 28 2019 8:20AM
[Lim Hui Hui (Lin Huihui)]
Black Eagles Auto Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View		View in Browser ▼	
Photos/Images										3 per page ▼		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)									Thumbnail	Print	
1	30/08/19 10:14	General View									Load JPG	<input checked="" type="checkbox"/>	
2	30/08/19 10:14	General View									Load JPG	<input checked="" type="checkbox"/>	
3	30/08/19 10:14	General View									Load JPG	<input checked="" type="checkbox"/>	
4	30/08/19 10:14	General View									Load JPG	<input checked="" type="checkbox"/>	
5	30/08/19 10:14	General View									Load JPG	<input checked="" type="checkbox"/>	
6	30/08/19 10:14	General View									Load JPG	<input checked="" type="checkbox"/>	
7	30/08/19 10:14	General View									Load JPG	<input checked="" type="checkbox"/>	
8	30/08/19 10:14	General View									Load JPG	<input checked="" type="checkbox"/>	
9	30/08/19 10:14	General View									Load JPG	<input checked="" type="checkbox"/>	
10	30/08/19 10:14	General View									Load JPG	<input checked="" type="checkbox"/>	
11	30/08/19 10:14	General View									Load JPG	<input checked="" type="checkbox"/>	
12	30/08/19 10:14	General View									Load JPG	<input checked="" type="checkbox"/>	
13	30/08/19 10:14	General View									Load JPG	<input checked="" type="checkbox"/>	
14	30/08/19 10:14	General View									Load JPG	<input checked="" type="checkbox"/>	
15	30/08/19 10:14	General View									Load JPG	<input checked="" type="checkbox"/>	
16	30/08/19 10:14	General View									Load JPG	<input checked="" type="checkbox"/>	
17	30/08/19 10:14	General View									Load JPG	<input checked="" type="checkbox"/>	
18	30/08/19 10:14	General View									Load JPG	<input checked="" type="checkbox"/>	
19	30/08/19 10:14	General View									Load JPG	<input checked="" type="checkbox"/>	
20	30/08/19 10:14	General View									Load JPG	<input checked="" type="checkbox"/>	
21	30/08/19 10:14	General View									Load JPG	<input checked="" type="checkbox"/>	
22	30/08/19 10:14	General View									Load JPG	<input checked="" type="checkbox"/>	
23	30/08/19 10:14	General View									Load JPG	<input checked="" type="checkbox"/>	
24	30/08/19 10:14	General View									Load JPG	<input checked="" type="checkbox"/>	
25	30/08/19 10:14	General View									Load JPG	<input checked="" type="checkbox"/>	
26	30/08/19 10:14	General View									Load JPG	<input checked="" type="checkbox"/>	
27	30/08/19 10:14	General View									Load JPG	<input checked="" type="checkbox"/>	
28	30/08/19 10:14	General View									Load JPG	<input checked="" type="checkbox"/>	
29	30/08/19 10:14	General View									Load JPG	<input checked="" type="checkbox"/>	
30	30/08/19 10:14	General View									Load JPG	<input checked="" type="checkbox"/>	
31	30/08/19 10:14	General View									Load JPG	<input checked="" type="checkbox"/>	
32	30/08/19 10:14	General View									Load JPG	<input checked="" type="checkbox"/>	
33	30/08/19 10:14	General View									Load JPG	<input checked="" type="checkbox"/>	
34	30/08/19 10:14	General View									Load JPG	<input checked="" type="checkbox"/>	
35	30/08/19 10:14	General View									Load JPG	<input checked="" type="checkbox"/>	
36	30/08/19 10:14	General View									Load JPG	<input checked="" type="checkbox"/>	
37	30/08/19 10:14	General View									Load JPG	<input checked="" type="checkbox"/>	
38	30/08/19 10:14	General View									Load JPG	<input checked="" type="checkbox"/>	
39	30/08/19 10:14	General View									Load JPG	<input checked="" type="checkbox"/>	
40	30/08/19 10:14	General View									Load JPG	<input checked="" type="checkbox"/>	

Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
41	30/08/19 10:14	General View	 Load JPG	<input checked="" type="checkbox"/>
42	30/08/19 10:14	General View	 Load JPG	<input checked="" type="checkbox"/>
43	30/08/19 10:14	General View	 Load JPG	<input checked="" type="checkbox"/>
44	30/08/19 10:14	General View	 Load JPG	<input checked="" type="checkbox"/>
45	30/08/19 10:14	General View	 Load JPG	<input checked="" type="checkbox"/>
46	30/08/19 10:15	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
47	30/08/19 14:15	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
48	30/08/19 14:15	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
49	30/08/19 14:15	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
50	30/08/19 14:15	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
51	30/08/19 14:15	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
52	30/08/19 14:15	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
53	30/08/19 14:15	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
54	30/08/19 14:15	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
55	30/08/19 14:15	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
56	30/08/19 14:15	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
57	30/08/19 14:15	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
58	30/08/19 14:15	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
59	30/08/19 14:15	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
60	30/08/19 14:15	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
61	30/08/19 14:15	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
62	30/08/19 14:15	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
63	11/09/19 12:30	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
64	11/09/19 12:30	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
65	11/09/19 12:30	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
66	11/09/19 12:30	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
67	11/09/19 12:30	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
68	11/09/19 12:30	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
69	11/09/19 12:30	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
70	11/09/19 12:30	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
71	11/09/19 12:30	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
72	11/09/19 12:30	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
73	11/09/19 12:30	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid #ccc; height: 150px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CCS3/AIG19015259/GCF3S2
Date: 12/09/2019

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	
Claimant Vehicle No :	SJN4025K	Insured Vehicle No :	SML6813P
Date of Loss:	28/08/2019	Nature of Claim:	TP
		Claim No:	8985311120SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJN4025K	Engine No:	G4FC9U595110
Make & Model:	HYUNDAI AVANTE, 1.6 (A)	Chassis No:	KMH DU41BR9U688666
Reg. Date:	13/02/2009 (Man. Year: 2009)	Odometer:	0 km
Colour:	White		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	185/65 R15	Rear Tyre Size:	185/65 R15
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	29/08/2019	
Date Inspected:	29/08/2019	Inspected At: Black Eagles Auto Pte Ltd (HQ) 25 Kaki Bukit Road, #05-80 Synergy Building Singapore 417800
Estimated Period of Repair:	3.0 days	

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	0.00 F	*- F
2	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
3	1		*REAR BUMPER SIDE RETAINER RH	Deformed	0.00 F	*- F
4	1		*REAR BUMPER SPONGE	Cracked	0.00 F	*- F
5	1		*REAR END PANEL	Repair	0.00 F	*- F
6	1		*BOOTLID	Repair	0.00 F	*- F
7	3		*BOOTLID EMBLEM	Necessary	0.00 F	*- F
				Total Parts (S\$)	0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >