

FORM 2001

ASS. REC. BY:

REF:

033/11919015261 / Fcd30r

Special Instruction:

Surveyor: Ram

ASSIGNMENT (Office)

Menmen

From (Person): chin lee ying

of

119

Date/Time:

29/8/19 12.23pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJW 1191K

Insured:

SMF 2835J

at Workshop n/s

Xin Yun Auto

Tel:

9839 1555

of

8 kcalci Bukit Ave 4 # 05-23

Policy No:

1800130876

Claim No:

232462209186

Sum Insured:

Excess:

Make of Veh:

D.O.A.

24/08/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

12.34pm 29/8/19

Person Contacted:

Yi xin

Vehicle:

IN / OUT

Date/Time

Action/Instruction Estimate (X)

SJW 1191K - X

SMF 2835J - X

Dismantle: 30/8/2019

After repair: 2/9/2019

ASSIGNMENT

From: RS Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJW 1191K

at Workshop m/s: XIN YUN AUTO

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 7 days Res.: Yes or No

Lump Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SJW1191K Yr Regn: MAR / 2010

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Primo Mover /

Truck / Tractor or

Make: Kia Cerato Forte Koup C.C. 1591

Colour: Red A/C: Insured / Std / NI / NA

Sp. Reading: 165140 T/Radio: Insured / Std / NI / NA

Eng/No: -

C/No: KNAFW611M45203299

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/45 R17

R: 215/45 R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. 5 mm L/Bal. 5 mm

D.O.A. 24/08/2019 D.O.I. 29/08/2019

Survey held at XIN YUN AUTO

Des. of Damages: Frnt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Range: \$3000 - \$4000

Repair day: 7 days

MV: \$12000

PV: \$8745

NV: \$3000

Date/Time, File Pass to?

: Preli. Report

Days Of Repair: 7

1)

: Final Report

Resurvey No. of Trip: 2

Date/Time, File Return to?

2)

Add Fee: : Site Insp (\$

: Interview (\$

: Tech. Invs (\$

: Weekend (\$

Survey Fee:

Transportation:

\$ + RS, \$

Photos

Others

TOTAL

180
11
191

Report Format: DAR

Lump Sum / I.B.I: (\$

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	26 Aug 2019 Edit Reg		29 Aug 2019 00:00 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by adjuster]	
Insured:	MR NG YING YI, ID: S8413213F		
Main Claimant:	NA		
Vehicle Reg. No.:	SJW1191K	Date of Loss:	24/08/2019 00:00 - :59
Claim Type:	TP / 2324622091SG	Policy/Cover Note No.:	1800130876 (Comprehensive)
Vehicle Reg. No. (Insured):	SMF2835J	Policy No. (Claimant):	
		Excess:	
Repairer:	Xin Yun Auto Private Limited (HQ) 1 Kaki Bukit Avenue 6, #01-59 Autobay @ Kaki Bukit, 417883 Kaki Bukit - Tel: 8226 5945 / 9136 8884		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Chew, Mavis] Chew.Mavis@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by PARASURAM SHANMUGAM] ... [Final Rpt due 09/09/2019]		
Claimant's Solicitor:	ISLAND LAW LLC - Tel: 62213211		

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
<ul style="list-style-type: none"> • AIG_SG (30/08/2019): Request To Upload TP GIA Report 		

ALL ASSOCIATED TASKS <input type="checkbox"/>										View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHIC...

From: Chin, Lee-Ying

To: assignments, Admin A

Cc: Fong, Andy-SY

Sent: 8/29/2019 12:23:23 PM

Attachments:  SJW 1191K (PRE-REPAIR SURVEY REQUEST).pdf

Hi LKK,

Kindly assist to survey, vehicle in workshop.

Thanks.

Best Regards

Lee Ying, Chin

AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1947

Lee-Ying.Chin@aig.com | www.aig.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

ISLAND LAW LLC

Advocates & Solicitors

(UEN No. 200918269D)

(GST Reg No. 200918269D)

KIRPAL SINGH SHARMA
NG KWONG LOONG

SUNITA CARMEL NETTO

Our Ref : FS.01191K.19.20(XYA)

Your Ref : SMF 2835J

101 Upper Cross Street
#04-04 People's Park Centre
Singapore 058357
Tel: (65) 6221 3211
Fax: (65) 6225 3210
(65) 6225 3054

Date: 26/8/2019

RIG ASIA PACIFIC INSURANCE PTE. LTD.

(By fax: 6835 7417)

Attn: Motor Claims Department

Dear Sirs,

ACCIDENT INVOLVING SJW 1191K, SMF 2835J & SJF 25482 ALONG
KALLANG PAYA LEBAR EXPRESSWAY ON 24/08/2019 AT 1000 HRS

(NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS
PURSUANT TO PARAGRAPH 6.2 OF PRE-ACTION PROTOCOL FOR NIMA CASES)

We act for OOH CHWEI SENG MICHAEL who has appointed the undermentioned
workshop to repair his/her motor vehicle no. SJW 1191K.

Please be informed that the said vehicle can be inspected at:

Name : XIN YUN AUTO PRIVATE LIMITED
Address : BLK 8 KAKI BUKIT AVENUE 4
#05-23 PREMIER @ KAKI BUKIT
SINGAPORE 415675
Person to contact : YI XIN
Tel : 9839 1555

If you failed to conduct the pre-repair inspection within the next 2 working days excluding any
intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter
without further reference to you.

Yours faithfully

For Surveyor
Please initial here after completion
of pre-repair inspection. Thank you.

Appointed surveyor :
(Name & Signature)

ISLAND LAW LLC By email:
cc: Client (SJW 1191K) (xinyunauto1@gmail.com)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	916F
Vehicle Details	
Vehicle No.:	SJW1191K
Vehicle to be Exported:	No
Intended Deregistration Date:	30 Aug 2019
Vehicle Make:	KIA
Vehicle Model:	CERATO FORTE KOUP 1.6 AT SX ABS D/AB SR
Primary Colour:	Red
Manufacturing Year:	2009
Engine No.:	G4FCAH365689
Chassis No.:	KNAFW611MA5203299
Maximum Power Output:	92.7 kW (124 bhp)
Open Market Value:	\$15,754.00
Original Registration Date:	03 Mar 2010
First Registration Date:	03 Mar 2010
Transfer Count:	2
Actual ARF Paid:	\$15,754.00 x 50% = <u>\$7877</u>
Intended PARF Rebate Details	
PARF Eligibility:	Yes ✓
PARF Eligibility Expiry Date:	02 Mar 2020
PARF Rebate Amount:	\$7,877.00
Intended COE Rebate Details	
COE Expiry Date:	02 Mar 2020
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$17,189.00
COE Rebate Amount:	\$868.00
Total Rebate Amount:	\$8,745.00

The information contained herein is correct as at 30 Aug 2019

remaining months of COE: 6 months 9 days (6.3 months) OK
Depn: \$8000/yearly = \$666.66 (monthly)

$$6.3 \times \$666.66 = \underline{\underline{\$4199.95}}$$

$$\underline{\underline{\$4199.95}} + \$7877 = \underline{\underline{\$12076.95}}$$

Das WeltAuto.
Used cars you can trust. Guaranteed.

Visit the **sgCarMart Carnival @ Downtown East**
for exclusive deals on our certified pre-owned cars!
From 31 Aug to 1 Sep 2019



Kia Forte koup Price Range Depreciation 2010 Vehicle Type Advanced Search

Home » Used Cars » Car Auto Connection Pte Ltd » Kia Cerato Forte Koup 1.6A SX

Kia Cerato Forte Koup 1.6A SX

Overview Financial Accessories Similar Research Photos Map

Price	\$12,999	Reg Date	06-Apr-2010 (7mths 6days COE left)
Depreciation ⓘ	\$8,700 /yr View models with similar depre	Manufactured ⓘ	2010
Mileage	N.A.	Transmission	Auto
Road Tax ⓘ	\$738 /yr	OMV ⓘ	\$15,553
Dereg Value ⓘ	\$9,480 as of today (change)	ARF ⓘ	\$15,553
COE ⓘ	\$28,389	Power	92.7 kW (124 bhp)
Engine Cap	1,591 cc	No. of Owners ⓘ	3
Curb Weight ⓘ	1,232 kg		
Type of Vehicle	Sports Car		



Features

1.6L 4 Cylinders DOHC 16 Valves Engine, 124 BHP, 5 Speed Auto Transmission With Steptronic, ABS, ABS, Knockdown Rear Seats, Keyless Entry/Start/Stop. View specs of the Kia Cerato Forte Koup (2009-2013)

Accessories

Sunroof, Leather Seats, Pioneer DVD Player, Steering Controls, Retractable Side Mirrors, Reverse Sensors, Solar Film, Fog Lights.

Description

Sunroof Model! Well Maintained! Minimum PARF Value At \$7,776! Road Tax Till Oct 2019! Excellent Condition! Trade-In And Loan Available! Do Call To Arrange For Viewing!

Category

PARF Car

Status

Available

Resources



Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. Find out more



Car Valuation - Free

Find out the market value of your existing car for free. Get started

Posted on: 25-Aug-2019 | Last Updated on: 28-Aug-2019

Upfront Payment

→ more Financial Info

Transf \$25

Price Chart

Click on the point to view the vehicle

Summary

Shortlist Compare Add note

Report Error More Actions

Seller Information

Company	Car Auto Connection Pte Ltd » dealer's pricelist » 15 vehs sold 5 vehs available
Address	229 Mountbatten Road #02-41 Search cars nearby this location
Location	Mountbatten Square

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	26/08/2019 12:44
Date Of Accident	24/08/2019 10:00
Exact Location Of Accident	KPE TO ECP (BEFORE TUNNEL ENTRANCE)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJW1191K
Insured/Policyholder	
Name Of Registered Owner	OON CHWEE SENG MICHAEL
NRIC No	S7433916F
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98255666
Alternative Phone No	OTHERS-96800122

Vehicle Particulars

Manufacturer	KIA
Model	CERATO FORTE KOUP-1.6 SX ABS D/AB SR (A)
Exact Purpose for which vehicle was being used at time of accident	PERSONAL USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	TOKIO MARINE INSURANCE SINGAPORE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	MT105559
Cover Note Number	

Driver

Name of Driver	GOH SOO FENG SHIRLINE
NRIC No	S7919828E
Date Of Birth	23/06/1979
Occupation	OUTDOOR
Date Of Driving Pass	24/12/2004
Driving Experience	14 YEARS AND 8 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-96800122
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address 1 SENGKANG EAST AVENUE #03-06
 Postcode 544811
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured SPOUSE
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident CHAIN COLLISION
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 3
 Was any body injured in the Accident? YES
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? YES
 If Yes, Please state which Police Station
 Police Station Name PASIR RIS NEIGHBOURHOOD POLICE CENTRE
 Police Station Address ROAD: 1 PASIR RIS DRIVE 4 , POSTCODE: 519457 , COUNTRY: SINGAPORE
 Police Station Contact TEL NO: 1800-5852999 - FAX NO: 65855261
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

AS PER POLICE REPORT, T/20190825/2093 (PASIR RIS NPC)

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Remarks/ Reasons: WITH SJW 1191K DRIVER
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SMF2835J
 Vehicle Make/Model/Colour MAZDA6
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SJF2548Z | *Honda Civic*
Vehicle Make/Model/Colour HONDA CIVIC
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name GOH SOO PENG SHIRLINE
Approximate Age 40
Injuries Sustain CHEST & BACK
Injured person in which vehicle? SJW1191K
Were seat belts worn? YES
Was this injured conveyed to hospital by ambulance? NO
Address 1 SENGKANG EAST AVENUE #03-06
Postcode 544811

Accident Sketch Plan

SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.


8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:


Driver's Signature
(if driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Accident Sketch Plan

SKETCH PLAN



A: SJW1191K - Stop
B: SMF 2835J - Stop
C: SJF 2548Z

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Please refer to police report.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

[Signature]

Policyholder's Signature
Date & Time:

[Signature]

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



**SINGAPORE
POLICE FORCE**



T/20190825/2093

Police Station Of Origin:
Pasir Ris N.P.C
1 Pasir Ris Drive 4 #01-01 SINGAPORE
519457
Tel No: 1800-5852999

2 of 3

Report No. T/20190825/2093

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	GOH SOO FENG SHIRLINE	ID No.	S7919828E
Related Vehicle	SJW1191K (Car)	Contact No.	96800122
Hospital/Clinic	SENGKANG GENERAL HOSPITAL PTE. LTD.	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	24/08/2019	Date Discharge	24/08/2019
No. of Days granted Medical Leave	05	Degree of Injury	Slight

Brief Details.

On 24/08/2019 at 10am, I am the driver of motor vehicle with plate bearing SJW1191K and was on my way to Tai Seng area for a meeting. At that point in time, my vehicle was travelling along lane 1 of Kallang Paya Lebar Expressway (KPE) heading towards the direction of ECP. The traffic volume was heavy and all the vehicles were moving slowly. Just when my vehicle entered the tunnel of KPE, the vehicle with plate bearing SJF2548Z that was in front of my vehicle suddenly brake abruptly which caused me to follow suit. My vehicle then managed to stop in time behind the said vehicle. However, when my vehicle was already in stationary position, a vehicle with plate bearing SMF2835J that was travelling behind me collided onto the rear bumper of my vehicle. The impact of the collision causes my vehicle to move forward and hit the front vehicle. In total the chain collision accident involves three vehicles.

The drivers from all three vehicles then came out and we exchanged our details for insurance claims. At that point time, everyone at scene informed that they were not injured. None of the vehicles involves were seriously damaged. As such, no police or ambulance assistance was required and all parties then left after securing photos of the accident scene and details of the drivers.. After the accident, I continued my journey to my destination and when I arrived at Tai Seng, I felt pain on my back and chest area. I then went for a medical checkup at Sengkang General Hospital and was discharged on the same day itself with medications. The doctor gave me 5 days of medical leave vide MC number: EMD201987074. Thus, I was advised by my insurance company to lodge to police accident report. I wish to state that my vehicle has an IN car camera and I have already downloaded it for record purpose.



**SINGAPORE
POLICE FORCE**



T/20190825/2093

Police Station Of Origin:
Pasir Ris N.P.C
1 Pasir Ris Drive 4 #01-01 SINGAPORE
519457
Tel No: 1800-5852999

3 of 3

Report No. T/20190825/2093

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: G / Sgt 3 MUHAMMAD FIRDAUS BIN ABDULLAH SHAFI-IE	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 25/08/2019 19:06
Officer In Charge Of Case: TP / AEIT / Sgt 2 SHARIFAH NOR FARIZAN BINTE SYED MOHD SAID Contact No.: 65476172	Classification Of Case: 
Authentication Stamp NP168	

MOTOR CAR (Frt)

Front Portion

Vehicle No: SW 1191K

NAC	INC	Item	CON	AC	Qty
1001	991886	Frt Number Plate			
1002	991887	Frt Number Plate Base			
1003	991889	Frt Number Plate Garnish			
1004	991300	Frt Bumper			
1005	992341	Frt Bumper Clips	SCR	R	
1006	991325	Frt Bumper Bracket			
1007	991462	Frt Bumper Side Retainer	REC	2	
1008	991433	Frt Bumper Reinforcement			
1009	991318	Frt Bumper Beam	DD	R	
1010	991468	Frt Bumper Sponge			
1011	991427	Frt Bumper Protector	CRA		
1012	991420	Frt Bumper Pad			
1013	991363	Frt Bumper Grille			
1014	991301	Frt Bumper Moulding	SCR		
1015	991407	Frt Bumper Lower Spoiler			
1016	991438	Frt Bumper Sensor			
1017	995100	Frt LH Bumper Fog Lamp Cover			
1018	991355	Frt RH Bumper Fog Lamp Cover	CRA		
1019	995079	Frt LH Bumper Fog Lamp			
1020	995080	Frt RH Bumper Fog Lamp			
1021	991793	Frt Grille			
1022	991328	Frt Grille Emblem			
1023	991799	Frt Grille Chrome Moulding			
1024	991222	Frt Apron Panel			
1025	992013	Frt Support Panel			
1026	992025	Frt Support Panel Top Garnish Cover			
1027	992416	Horn			
1028	991277	Frt Brace Panel			
1029	995153	Frt LH Headlamp Assy			
1030	991821	Frt RH Headlamp Assy	CRA		
1031	995088	Frt LH Side Lamp	CRA		
1032	995089	Frt RH Side Lamp			
1033	990248	Bonnet			
1034	991328	Bonnet Emblem	DD		
1035	990287	Bonnet Lock			
1036	990285	Bonnet Insulator	BT		
1037	990273	Bonnet Hinge			
1038	990261	Bonnet Damper	RL		
1039	990305	Bonnet Rubber			
1040	990252	Bonnet Cable			
1041	990311	Bonnet Stand			
1042	990119	Air Con Condenser			
1043	990122	Air Con Fan Assy			
1044	990134	Air Con Suction Pipe (Low Pressure)			
1045	990118	Air Con Suction Hose			
1046	990133	Air Con Discharge Pipe (High Pressure)			
1047	990114	Air Con Discharge Hose			
1048	990149	Air Con Liquid Pipe			
1049	995066	Air Con Receiver Drier			
1050	990111	Air Con Compressor Assy			
1051	995294	Air Con Belt			
1052	995074	Radiator			
1053	992738	Radiator Cowling			
1054	992742	Radiator Fan Assy			
1055	992745	Radiator Fan Clutch			
1056	992758	Radiator Hose Top			
1057	992757	Radiator Hose Bottom			
1058	992741	Radiator Expansion Tank			
1059	990151	Air Duct			
1060	990070	Air Cleaner Assy	CRA		
1061	990056	Air Cleaner Hose	CRA		
1062	990089	Air Cleaner Resonator			
1063	991712	Frt Exhaust Manifold			
1064	991713	Frt Exhaust Manifold Cover			
1065	991054	Frt Exhaust Manifold Sensor (Oxygen)			
1066	991714	Front Exhaust Pipe			
1067	990219	Battery			
1068	990224	Battery Cover			
1069	990223	Battery Bracket			
1070	990229	Battery Tray			

NAC	INC	Item	CON	AC	Qty
1071	992205	Fuse Box			
1072	994011	Relay Box			
1073	995053	Wiper Washer Tank			
1074	995052	Wiper Washer Tank Motor			
1075	990159	Alternator Assy			
1076	990160	Alternator Belt			
1077	992688	Power Steering Pump			
1078	992669	Power Steering Belt			
1079	994431	Power Steering Cooler Pipe			
1080	992692	Power Steering Hose			
1081	990010	ABS Pump Control Unit			
1082	990427	Brake Master Pump Assy			
1083	990403	Brake Booster Pump Assy			
1084	991005	Engine Top Cover			
1085	991011	Engine Under Cover			
1086	990948	Engine Mounting			
1087	990949	Engine Mounting Frt			
1088	990950	Engine Mounting LH			
1089	990952	Engine Mounting RH			
1090	990951	Engine Mounting Rear			
1091	992234	Gear Box Mounting			
1092	991520	Frt LH Chassis Member			
1093	991520	Frt RH Chassis Member			
1094	990728	Frt Vertical Cross Member			
1095	991863	Frt Lower Cross Member			
1096	995070	Frt LH Fender			
1097	995072	Frt LH Fender Inner Panel			
1098	995147	Frt LH Fender Lamp			
1099	995148	Frt LH Fender Protector			
1100	991740	Frt LH Fender Inner Shield			
1101	995179	Frt LH Mudflap			
1102	995170	Frt LH Wheel Rim			
1103	994025	Frt LH Rim Cover			
1104	995065	Frt LH Tyre			
1105	995071	Frt RH Fender			
1106	991739	Frt RH Fender Inner Panel			
1107	991744	Frt RH Fender Lamp			
1108	991752	Frt RH Fender Protector			
1109	991740	Frt RH Fender Inner Shield			
1110	991884	Frt RH Mudflap			
1111	992087	Frt RH Wheel Rim			
1112	994025	Frt RH Rim Cover			
1113	995065	Frt RH Tyre			
1114	992093	Frt Windscreen Glass			
1115	992117	Frt Windscreen Rubber			
1116	992108	Frt Windscreen Moulding			
1117	992098	Frt Windscreen Sealant			
1118	991019	ERP Bracket			
1119	991020	ERP Unit			
1120	992140	Frt Wiper Arm			
1121	992142	Frt Wiper Blade			
1122	995045	Wiper Panel Garnish			
1123	991126	Firewall Panel			
1124	990753	Dashboard Assy			
1125	992282	Glove Box Cover			
1126	992281	Glove Box Compartment			
1127	994483	Steering Wheel Airbag			
1128	994485	Steering Wheel Airbag Sensor			
1129	990749	Dashboard Airbag			
1130	990750	Dashboard Airbag Sensor			
1131	990029	Airbag Control Unit			
1132	990864	Frt Driver Seat			
1133	991923	Frt RH Seat Belt Assy			
1134	991899	Frt Passenger Seat			
1135	995182	Frt LH Seat Belt Assy			
1136	990247	Sticker			

No of Items: _____

APPROVED: _____

[Handwritten Signature]
 30/8/2019

MOTORCAR (Rear)

Rear Portion

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate	CRA		
1138	993627	Rear Number Plate Base	BY		
1139	993630	Rear Number Plate Garnish	CRA		
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	CUT		
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips	REC		6
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer	REC		2
1149	993045	Rear Bumper Reinforcement	CRA		
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge	CRA		
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector	CRA		
1157	993023	Rear Bumper Lower Spoiler	CRA		
1158	994023	Reverse Sensor	SC		
1159	993327	Rear End Panel	DD		
1160	993339	Rear End Panel Top Garnish	CRA		
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp			
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp			
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid			
1171	991328	Bootlid Emblem			
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock	SC		
1178	990377	Bootlid Rubber	TU		
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate			
1182	991328	Tailgate Emblem			
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board			

Vehicle No: SJW1191K

NAC	INC	Item	CON	A
1202	993784	Spare Tyre Board		
1203	994328	Spare Tyre Panel		
1204	995065	Spare Tyre		
1205	994326	Spare Tyre Lock Screw		
1206	993787	Spare Tyre Cover		
1207	995323	Triangle Breakdown Sign		
1208	990507	CD Changer Assy		
1209	990164	Antenna		
1210	990534	Centre Exhaust Pipe Assy		
1211	990532	Centre Exhaust Mounting		
1212	993364	Rear Exhaust Pipe		
1213	993357	Rear Exhaust Chrome Pipe		
1214	993361	Rear Exhaust Mounting		
1215	993358	Rear Exhaust Heat Shield		
1216	995223	Rear LH Chassis Member		
1217	993165	Rear RH Chassis Member		
1218	993436	Rear LH Fender		
1219	993449	Rear LH Fender Protector		
1220	993420	Rear LH Fender Inner Panel		
1221	993431	Rear LH Fender Inner Trim		
1222	993415	Rear LH Fender Inner Garnish		
1223	993425	Rear LH Fender Inner Shield		
1224	993621	Rear LH Mudflap		
1225	993933	Rear LH Wheel Rim		
1226	994025	Rear LH Rim Cover		
1227	995065	Rear LH Tyre		
1228	993456	Rear RH Fender		
1229	993450	Rear RH Fender Protector		
1230	993420	Rear RH Fender Inner Panel		
1231	993431	Rear RH Fender Inner Trim		
1232	993415	Rear RH Fender Inner Garnish		
1233	993425	Rear RH Fender Inner Shield		
1234	993622	Rear RH Mudflap		
1235	993934	Rear RH Wheel Rim		
1236	994025	Rear RH Rim Cover		
1237	995065	Rear RH Tyre		
1238	995162	Rear Fender Extension Panel LH		
1239	993401	Rear Fender Extension Panel RH		
1240	993430	Rear Fender Inner Top Garnish		
1241	993673	Rear Fender 1/4 Glass		
1242	993452	Rear Fender 1/4 Glass Rubber		
1243	993453	Rear Fender 1/4 Glass Sealant		
1244	993949	Rear Windscreen Glass		
1245	993976	Rear Windscreen Rubber		
1246	993961	Rear Windscreen Moulding		
1247	993955	Rear Windscreen Sealant		
1248	994729	Third Brake Light		
1249	993385	Rear Fender Air Grille		
1250	992167	Fuel Lid		
1251	992168	Fuel Neck		
1252	992179	Fuel Tank		
1253	992184	Fuel Tank Bracket		
1254	992191	Fuel Tank Float		
1255	990247	Sticker		

No of Items: _____ Assessor: _____

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	26 Aug 2019 Edit Reg		29 Aug 2019 00:00 Edit Adj Rpt	\$0.00 Edit Estimates	\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS				[Created by adjuster]					
Insured:	MR NG YING YI, ID: S8413213F								
Main Claimant:	NA								
Vehicle Reg. No.:	SJW1191K	Date of Loss:	24/08/2019 00:00 - :59 [113 Months and 21 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 2324622091SG	Policy/Cover Note No.:	1800130876 (Comprehensive)						
Vehicle Reg. No. (Insured):	SMF2835J	Policy No. (Claimant):							
Repairer:	Xin Yun Auto Private Limited (HQ) 1 Kaki Bukit Avenue 6, #01-59 Autobay @ Kaki Bukit, 417883 Kaki Bukit - Tel: 8226 5945 / 9136 8884								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Chew, Mavis] Chew.Mavis@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by PARASURAM SHANMUGAM] ... [Final Rpt due 09/09/2019]								
Claimant's Solicitor:	ISLAND LAW LLC - Tel: 62213211								
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail					
<ul style="list-style-type: none"> AIG_SG (30/08/2019): Request To Upload TP GIA Report 									
ALL ASSOCIATED TASKS				View All Search Tasks Create New Task Complete					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJW1191K (2324622091SG)
 [SMF2835J]
 TP
 NA
 Aug 24 2019 12:00AM
 [MR NG YING YI]
 Xin Yun Auto Private Limited

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View <input type="button" value="View in Browser"/>	
Photos/Images										3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	29/08/19 17:56	General View							Load JPG <input checked="" type="checkbox"/>		
2	29/08/19 17:56	General View							Load JPG <input checked="" type="checkbox"/>		
3	29/08/19 17:56	General View							Load JPG <input checked="" type="checkbox"/>		
4	29/08/19 17:56	General View							Load JPG <input checked="" type="checkbox"/>		
5	29/08/19 17:56	General View							Load JPG <input checked="" type="checkbox"/>		
6	29/08/19 17:56	General View							Load JPG <input checked="" type="checkbox"/>		
7	29/08/19 17:56	General View							Load JPG <input checked="" type="checkbox"/>		
8	29/08/19 17:56	General View							Load JPG <input checked="" type="checkbox"/>		
9	29/08/19 17:56	General View							Load JPG <input checked="" type="checkbox"/>		
10	29/08/19 17:56	General View							Load JPG <input checked="" type="checkbox"/>		
11	29/08/19 17:56	General View							Load JPG <input checked="" type="checkbox"/>		
12	29/08/19 17:56	General View							Load JPG <input checked="" type="checkbox"/>		
13	29/08/19 17:56	General View							Load JPG <input checked="" type="checkbox"/>		
14	29/08/19 17:56	General View							Load JPG <input checked="" type="checkbox"/>		
15	29/08/19 17:56	General View							Load JPG <input checked="" type="checkbox"/>		
16	03/09/19 10:06	Photographs of Damaged Parts							Load JPG <input checked="" type="checkbox"/>		
17	03/09/19 10:06	Photographs of Damaged Parts							Load JPG <input checked="" type="checkbox"/>		
18	03/09/19 10:06	Photographs of Damaged Parts							Load JPG <input checked="" type="checkbox"/>		
19	03/09/19 10:06	Photographs of Damaged Parts							Load JPG <input checked="" type="checkbox"/>		
20	03/09/19 10:06	Photographs of Damaged Parts							Load JPG <input checked="" type="checkbox"/>		
21	03/09/19 10:06	Photographs of Damaged Parts							Load JPG <input checked="" type="checkbox"/>		
22	03/09/19 10:06	Photographs of Damaged Parts							Load JPG <input checked="" type="checkbox"/>		
23	03/09/19 10:06	Photographs of Damaged Parts							Load JPG <input checked="" type="checkbox"/>		
24	03/09/19 10:06	Photographs of Damaged Parts							Load JPG <input checked="" type="checkbox"/>		
25	03/09/19 10:06	Photographs of Damaged Parts							Load JPG <input checked="" type="checkbox"/>		
26	03/09/19 10:06	Photographs of Damaged Parts							Load JPG <input checked="" type="checkbox"/>		
27	03/09/19 10:06	Photographs of Damaged Parts							Load JPG <input checked="" type="checkbox"/>		
28	03/09/19 10:06	Photographs of Damaged Parts							Load JPG <input checked="" type="checkbox"/>		
29	03/09/19 10:06	Photographs of Damaged Parts							Load JPG <input checked="" type="checkbox"/>		
30	03/09/19 10:06	Photographs of Damaged Parts							Load JPG <input checked="" type="checkbox"/>		
31	03/09/19 10:06	Photographs of Damaged Parts							Load JPG <input checked="" type="checkbox"/>		
32	03/09/19 10:06	Photographs of Damaged Parts							Load JPG <input checked="" type="checkbox"/>		
33	03/09/19 10:06	Photographs of Damaged Parts							Load JPG <input checked="" type="checkbox"/>		
34	03/09/19 10:06	Photographs of Damaged Parts							Load JPG <input checked="" type="checkbox"/>		
35	03/09/19 10:06	Photographs of Damaged Parts							Load JPG <input checked="" type="checkbox"/>		
36	03/09/19 10:06	Photographs of Damaged Parts							Load JPG <input checked="" type="checkbox"/>		
37	03/09/19 10:06	Photographs of Damaged Parts							Load JPG <input checked="" type="checkbox"/>		
38	03/09/19 10:06	Photographs of Damaged Parts							Load JPG <input checked="" type="checkbox"/>		
39	03/09/19 10:06	Photographs of Damaged Parts							Load JPG <input checked="" type="checkbox"/>		
40	03/09/19 10:06	Photographs of Damaged Parts							Load JPG <input checked="" type="checkbox"/>		
41	03/09/19 10:06	Photographs of Damaged Parts							Load JPG <input checked="" type="checkbox"/>		
42	03/09/19 10:06	Photographs of Damaged Parts							Load JPG <input checked="" type="checkbox"/>		
43	03/09/19 10:06	Photographs of Damaged Parts							Load JPG <input checked="" type="checkbox"/>		

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
44	03/09/19 10:06	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
45	03/09/19 10:06	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
46	03/09/19 10:06	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
47	03/09/19 10:06	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
48	03/09/19 10:06	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
49	03/09/19 10:06	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
50	03/09/19 10:06	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
51	03/09/19 10:06	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
52	03/09/19 10:06	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
53	03/09/19 10:06	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
54	03/09/19 10:06	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
55	03/09/19 10:06	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
56	03/09/19 10:06	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
57	03/09/19 10:06	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
58	03/09/19 10:06	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
59	03/09/19 10:06	Photo After Spray		<input checked="" type="checkbox"/>
60	03/09/19 10:06	Photo After Spray		<input checked="" type="checkbox"/>
61	03/09/19 10:06	Photo After Spray		<input checked="" type="checkbox"/>
62	03/09/19 10:06	Photo After Spray		<input checked="" type="checkbox"/>
63	03/09/19 10:06	Photo After Spray		<input checked="" type="checkbox"/>
64	03/09/19 10:06	Photo After Spray		<input checked="" type="checkbox"/>
65	03/09/19 10:06	Photo After Spray		<input checked="" type="checkbox"/>
66	03/09/19 10:06	Photo After Spray		<input checked="" type="checkbox"/>
67	03/09/19 10:06	Photo After Spray		<input checked="" type="checkbox"/>
68	03/09/19 10:06	Photo After Spray		<input checked="" type="checkbox"/>
69	03/09/19 10:06	Photo After Spray		<input checked="" type="checkbox"/>
70	03/09/19 10:06	Photo After Spray		<input checked="" type="checkbox"/>
71	03/09/19 10:06	Photo After Spray		<input checked="" type="checkbox"/>
72	03/09/19 10:06	Photo After Spray		<input checked="" type="checkbox"/>
73	03/09/19 10:06	Photo After Spray		<input checked="" type="checkbox"/>
74	03/09/19 10:06	Photo After Spray		<input checked="" type="checkbox"/>
75	03/09/19 10:06	Photo After Spray		<input checked="" type="checkbox"/>
76	03/09/19 10:06	Photo After Spray		<input checked="" type="checkbox"/>
77	03/09/19 10:06	Photo After Spray		<input checked="" type="checkbox"/>
78	03/09/19 10:06	Photo After Spray		<input checked="" type="checkbox"/>
79	03/09/19 10:06	Photo After Spray		<input checked="" type="checkbox"/>
80	03/09/19 10:06	Photo After Spray		<input checked="" type="checkbox"/>
81	03/09/19 10:06	Photo After Spray		<input checked="" type="checkbox"/>
82	03/09/19 10:06	Photo After Spray		<input checked="" type="checkbox"/>
83	03/09/19 10:06	Photo After Spray		<input checked="" type="checkbox"/>
84	03/09/19 10:06	Photo After Spray		<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	30/08/19 11:10	OI GIA REPORT		<input type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer
 Note: Remarks are private unless you show it to other parties.



LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19015261/FCD3E2

Date: 18/09/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800130876
Claimant		
Vehicle No : SJW1191K	Insured Vehicle No :	SMF2835J
Date of Loss: 24/08/2019	Nature of Claim: TP	Claim No: 2324622091SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJW1191K		
Make & Model:	KIA CERATO FORTE KOUP, 1.6 SX ABS D/AB SR (A)	Engine No:	G4FCAH365689
Reg. Date:	03/03/2010 (Man. Year: 2009)	Chassis No:	KNAFW611MA5203299
Colour:	Red	Odometer:	165140 km
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/45 R17	Rear Tyre Size:	215/45 R17
Front Left Side:	Pirelli 5 mm	Rear Left Side:	Pirelli 5 mm
Front Right Side:	Pirelli 5 mm	Rear Right Side:	Pirelli 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	29/08/2019	
Date Inspected:	29/08/2019 Inspected At:	8 KAKI BKT AVE 4# 05-23 Repairer : Xin Yun Auto Private Limited (HQ)
Estimated Period of Repair:	7.0 days	

Adjuster: PARASURAM SHANMUGAM

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT NUMBER PLATE	Cracked	0.00 F	*- F
2	1		*FRT BUMPER	Repair	0.00 F	*- F
3	2		*FRT BUMPER BRACKET	Necessary	0.00 F	*- F
4	1		*FRT BUMPER REINFORCEMENT	Repair	0.00 F	*- F
5	1		*FRT BUMPER SPONGE	Cracked	0.00 F	*- F
6	1		*FRT BUMPER GRILLE	Scratched	0.00 F	*- F
7	1		*FRT RH BUMPER FOG LAMP COVER	Cracked	0.00 F	*- F
8	1		*FRT LH HEADLAMP ASSY	Cracked	0.00 F	*- F
9	1		*FRT RH HEADLAMP ASSY	Cracked	0.00 F	*- F
10	1		*BONNET	Dented	0.00 F	*- F
11	1		*BONNET LOCK	Bent	0.00 F	*- F
12	1		*BONNET HINGE	Bent	0.00 F	*- F
13	1		*AIR DUCT	Cracked	0.00 F	*- F
14	1		*AIR CLEANER ASSY	Cracked	0.00 F	*- F
15	1		*REAR NUMBER PLATE	Cracked	0.00 F	*- F
16	1		*REAR NUMBER PLATE BASE	Broken	0.00 F	*- F
17	1		*REAR NUMBER PLATE GARNISH	Cracked	0.00 F	*- F
18	1		*REAR BUMPER	Cut	0.00 F	*- F
19	6		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
20	2		*REAR BUMPER SIDE RETAINER	Necessary	0.00 F	*- F
21	1		*REAR BUMPER REINFORCEMENT	Cracked	0.00 F	*- F
22	1		*REAR BUMPER SPONGE	Cracked	0.00 F	*- F
23	1		*REAR BUMPER REFLECTOR	Cracked	0.00 F	*- F
24	1		*REAR BUMPER LOWER SPOILER	Cut	0.00 F	*- F
25	1		*REVERSE SENSOR	Short Circuit	0.00 F	*- F
26	1		*REAR END PANEL	Repair	0.00 F	*- F
27	1		*REAR END PANEL TOP GARNISH	Cracked	0.00 F	*- F
28	1		*BOOTLID LOCK	Short Circuit	0.00 F	*- F
29	1		*BOOTLID RUBBER	Twisted	0.00 F	*- F
30	1		*SPARE TYRE PANEL	Repair	0.00 F	*- F

F=Franchise part.

Total Parts (\$\$)	0.00	0.00
---------------------------	-------------	-------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >